

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-SW-44-AD; Amendment 39-10245; AD 97-26-02]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland GmbH (ECD) Model BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3 Helicopters and Eurocopter Canada Ltd. Model BO-105LS A-3 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to Eurocopter Deutschland GmbH (ECD) (Eurocopter Deutschland) Model BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3 helicopters; and Eurocopter Canada Ltd. Model BO-105LS A-3 helicopters. This action requires visual inspections for cracks in the ribbed area of the main rotor mast flange (flange). This amendment is prompted by a report of an operator discovering a crack in the flange after experiencing in-flight vibrations. The actions specified in this AD are intended to detect cracks in the flange, which, if not detected, could result in failure of the flange and subsequent loss of control of the helicopter.

DATES: Effective December 31, 1997.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 31, 1997.

Comments for inclusion in the Rules Docket must be received on or before February 17, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of Regional Counsel, Southwest Region, Attention: Rules Docket No. 97-SW-44-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

The service information referenced in this AD may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. This information may be examined at the FAA, Office of Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Richard Monschke, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5116, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for the Federal Republic of Germany recently notified the FAA that an unsafe condition may exist on Eurocopter Deutschland Model BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3 helicopters. The Federal Republic of Germany advises that a main rotor mast was found to have cracks of critical magnitude in the area of the flange. Additionally, Transport Canada, the airworthiness authority for Canada, recently notified the FAA that the same unsafe condition may exist on Eurocopter Canada Ltd. Model BO-105LS A-3 helicopters. The cause of the cracks is under investigation. Until the cause of the crack has been determined, the flange must be subjected to an immediate inspection and repetitive visual crack inspection at intervals not to exceed 100 hours time-in-service until further notice.

Eurocopter Deutschland has issued Eurocopter Deutschland GmbH Alert Service Bulletin No. ASB-BO 105-10-110, dated August 27, 1997, which specifies visually inspecting the area of the holes on the underside of the flange for cracks, especially in the ribbed area between the holes. The LBA classified this service bulletin as mandatory and issued AD 97-275, dated September 25, 1997, in order to assure the continued airworthiness of these helicopters in the Federal Republic of Germany. Eurocopter Canada Ltd. has issued Eurocopter Canada Ltd. Alert Service Bulletin No. ASB-BO 105 LS-10-9, dated September 11, 1997, for similar inspection. Transport Canada has classified this service bulletin mandatory and issued AD CF-97-18, dated September 30, 1997, in order to assure the continued airworthiness of these helicopters in Canada.

This helicopter model is manufactured in the Federal Republic of Germany and Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA and Transport Canada have kept the FAA informed of the situation described above. The FAA has examined the findings of the LBA and Transport

Canada, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other Eurocopter Deutschland Model BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3 helicopters and Eurocopter Canada Ltd. BO-105LS A-3 helicopters of the same type designs registered in the United States, this AD is being issued to detect cracks in the flange, which, if not detected, could result in failure of the flange and subsequent loss of control of the helicopter. The flange is a part of the main rotor mast assembly and therefore a critical component of the flight control system. Due to the criticality of the flange to the continued safe flight of the affected helicopters, and the required inspection before further flight, this rule must be issued immediately to correct an unsafe condition in the affected helicopters. This AD requires, before further flight, a visual inspection of the ribbed area of the flange for cracks using a 5-power or higher magnifying glass, and thereafter, repeated visual inspections at intervals not to exceed 100 hours time-in-service. The actions are required to be accomplished in accordance with the service bulletins described previously.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether

additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 97-SW-44-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

97-26-02 Eurocopter Deutschland GmbH (ECD) and Eurocopter Canada LTD.:
Amendment 39-10245. Docket No. 97-SW-44-AD.

Applicability: Eurocopter Deutschland GmbH Model BO-105A, BO-105C, BO-105S, BO-105LS A-1, and BO-105LS A-3 helicopters and Eurocopter Canada Ltd. BO-105LS A-3 helicopters, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To detect cracks in the main rotor mast flange (flange), which, if not detected, could result in failure of the flange and subsequent loss of control of the helicopter, accomplish the following:

(a) Before further flight and thereafter at intervals not to exceed 100 hours time-in-service, visually inspect the flange in the ribbed area for cracks using a 5-power or higher magnifying glass in accordance with paragraphs 2.A.1. and 2.A.2. of the Accomplishment Instructions of Eurocopter Deutschland GmbH Alert Service Bulletin No. ASB-BO 105-10-110, dated August 27, 1997, or Eurocopter Canada Alert Service Bulletin No. ASB-BO 105 LS-10-9, dated September 11, 1997, as applicable.

(b) If a crack is found, remove the cracked main rotor mast and replace it with an airworthy main rotor mast.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft Standards Staff, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Standards Staff.

Note 2: Information concerning the existence of approved alternative methods of

compliance with this AD, if any, may be obtained from the Rotorcraft Standards Staff.

(d) Special flight permits will not be issued.

(e) The inspection shall be done in accordance with Eurocopter Deutschland GmbH Alert Service Bulletin No. ASB-BO 105-10-110, dated August 27, 1997, or Eurocopter Canada Alert Service Bulletin No. ASB-BO 105 LS-10-9, dated September 11, 1997, as applicable. These incorporations by reference were approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on December 31, 1997.

Note 3: The subject of this AD is addressed in Luftfahrt-Bundesamt (Germany) AD 97-275, dated September 25, 1997, and in Transport Canada AD CF-97-18, dated September 30, 1997.

Issued in Fort Worth, Texas, on December 5, 1997.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 97-32720 Filed 12-15-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-SW-45-AD; Amendment 39-10246; AD 97-26-03]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland GmbH (ECD) (Eurocopter Deutschland) Model MBB-BK 117 A-1, A-3, A-4, B-1, B-2, and C-1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to Eurocopter Deutschland Model MBB-BK 117 A-1, A-3, A-4, B-1, B-2, and C-1 helicopters. This action requires visual inspections for cracks in the ribbed area of the main rotor mast flange (flange). This amendment is prompted by one report of cracks in a flange. The actions specified in this AD are intended to detect cracks in the