

propeller de-ice system, this proposal would require the repair of the EICAS to be accomplished in accordance with a method approved by the FAA.

#### Cost Impact

The FAA estimates that 50 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the inspection proposed by this AD on U.S. operators is estimated to be \$3,000, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

#### Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Dornier Luftfahrt GmbH:** Docket 98–NM–112–AD.

**Applicability:** All Model 328–100 series airplanes, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the engine indication and crew alert system (EICAS) to provide a warning to the flightcrew in the event of failure of the propeller de-ice system, which could result in damage to the airplane and consequent loss of controllability of the airplane, accomplish the following:

(a) Within 30 days after the effective date of this AD, perform a one-time inspection of the propeller de-ice system to verify the proper functioning of the EICAS for the de-ice system, in accordance with Dornier Alert Service Bulletin ASB–328–013, Revision 1, dated February 21, 1997.

(b) If the inspection required by paragraph (a) of this AD indicates that the EICAS is malfunctioning, prior to further flight, repair the EICAS in accordance with a method approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to

a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in German airworthiness directive 97–066, dated March 13, 1997.

Issued in Renton, Washington, on May 20, 1998.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 98–14027 Filed 5–27–98; 8:45 am]

BILLING CODE 4910–13–P

### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97–NM–100–AD]

RIN 2120–AA64

#### Airworthiness Directives; Boeing Model 747–100, 747–200, and 747–SP Series Airplanes and Military Type E–4B Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747–100, –200, and 747–SP series airplanes and military type E–4B airplanes. This proposal would require repetitive inspections to detect cracking of the wing front spar web, and repair of cracked structure. This proposal also provides for optional terminating action for the repetitive inspection requirements. This proposal is prompted by reports indicating that fatigue cracks were found on the aft surface of the wing front spar web. The actions specified by the proposed AD are intended to detect and correct such fatigue cracking, which could result in a fuel leak, and consequent increased risk of a fire.

**DATES:** Comments must be received by July 13, 1998.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 97–NM–100–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from

Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Tamara L. Anderson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2771; fax (425) 227-1181.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-100-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-100-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

**Discussion**

The FAA has received reports indicating that operators have found numerous fatigue cracks on the aft surface of the front spar web on Boeing Model 747 series airplanes. The cracks were found inside the wing fuel tank at Front Spar Station Inboard (FSSI) 688

where the inboard nacelle rib post and the 670 rib post attach to the web of the front spar. All of the cracks were found between these two rib posts inside the wing fuel tank. Metallurgical analyses indicate that the cracks were initiated by fatigue on the aft surface of the front spar web. The analyses also indicate that the various fatigue cracks initiated on the web itself, and not at the edges of the adjacent fastener holes. Such fatigue cracking, if not detected and corrected, could result in a fuel leak and consequent increased risk of a fire.

**Explanation of Relevant Service Information**

The FAA has reviewed and approved Boeing Service Bulletin 747-57A2303, Revision 1, dated September 25, 1997, which describes procedures for repetitive ultrasonic inspections to detect cracking of the wing front spar web at the fastener rows behind and between the upper link fittings for the number 2 and 3 engine struts; and repair, if necessary. The service bulletin also describes procedures for an optional terminating modification, which, if accomplished, would eliminate the need for the repetitive inspections. The optional terminating modification involves replacing the cracked spar web with a shot-peened spar web. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

**Explanation of Requirements of Proposed Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

**Differences Between Proposed Rule and Service Bulletin**

Operators should note that, although the service bulletin specifies that the manufacturer may be contacted for disposition of certain repair conditions, this proposal would require the repair of those conditions to be accomplished in accordance with a method approved by the FAA.

**Optional Terminating Modification**

This proposed AD also would provide for an optional terminating modification of the wing front spar web. The FAA has determined that the repetitive inspections proposed by this AD can be allowed to continue in lieu of accomplishment of a terminating action.

In making this determination, the FAA considers that, in this case, long-term continued operational safety will be adequately assured by accomplishing the repetitive inspections to detect fatigue cracking before it represents a hazard to the airplane.

**Cost Impact**

There are approximately 190 airplanes of the affected design in the worldwide fleet. The FAA estimates that 95 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 64 work hours per airplane to accomplish the proposed inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the inspection proposed by this AD on U.S. operators is estimated to be \$364,800, or \$3,840 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Should an operator elect to accomplish the optional terminating modification, it would take approximately 518 work hours per airplane to accomplish the modification, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$17,000 per airplane. Based on these figures, the cost impact of the optional terminating modification proposed by this AD is estimated to be \$48,080 per airplane.

**Regulatory Impact**

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft

regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Boeing:** Docket 97–NM–100–AD.

**Applicability:** Model 747–100, 747–200, and 747–SP series airplanes and military type E–4B airplanes; as listed in Boeing Service Bulletin 747–57A2303, Revision 1, dated September 25, 1997; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To detect and correct fatigue cracking of the wing front spar web, which could result in a fuel leak, and consequent increased risk of a fire, accomplish the following:

(a) Perform an ultrasonic inspection to detect cracking of the wing front spar web at the fastener rows behind and between the upper link fittings for the number 2 and 3 engine struts, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747–57A2303, Revision 1, dated September 25, 1997, at the time specified in paragraph (a)(1) or (a)(2) of this AD, as applicable.

(1) For airplanes identified as Group 1, 2, 3, or 5 in the alert service bulletin: Inspect prior to the accumulation of 12,500 total flight cycles, or within 15 months after the effective date of this AD, whichever occurs later. Repeat the inspection thereafter at intervals not to exceed 2,200 flight cycles.

(2) For airplanes identified as Group 4, 6, 7, 8, 9, or 10 in the alert service bulletin: Inspect prior to the accumulation of 18,000 total flight cycles, or within 15 months after the effective date of this AD, whichever occurs later. Repeat the inspection thereafter at intervals not to exceed 3,000 flight cycles.

(b) If any crack is found during any inspection required by paragraph (a) of this AD, prior to further flight, accomplish either paragraph (b)(1) or (b)(2) of this AD.

(1) Accomplish the terminating action in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747–57A2303, Revision 1, dated September 25, 1997. Accomplishment of this action constitutes terminating action for the repetitive inspection requirements of this AD; or

(2) Repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate.

(c) Replacement of the affected wing front spar web with a new shot-peened wing front spar web in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747–57A2303, Revision 1, dated September 25, 1997, constitutes terminating action for the repetitive inspection requirements of this AD.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on May 20, 1998.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 98–14028 Filed 5–27–98; 8:45 am]

BILLING CODE 4910–13–U

#### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98–NM–116–AD]

RIN 2120–AA64

#### Airworthiness Directives; Airbus Model A300, A310, and A300–600 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A300, A310, and A300–600 series airplanes. This proposal would require repetitive detailed visual inspections to detect cracks in the pylon thrust and sideload fitting of the wing, and replacement of any cracked pylon thrust and sideload fitting with a new fitting. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to detect and correct cracks in the pylon thrust and sideload fitting of the wing, which could result in reduced structural integrity of the airplane.

**DATES:** Comments must be received by June 29, 1998.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 98–NM–116–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Norman B. Martenson, Manager,