

adverse changes in handling characteristics, use of the autopilot is prohibited when any of the visual cues specified above exist, or when unusual lateral trim requirements or autopilot trim warnings are encountered while the airplane is in icing conditions.

- All wing icing inspection lights must be operative prior to flight into known or forecast icing conditions at night. [NOTE: This supersedes any relief provided by the Master Minimum Equipment List (MMEL).]"

(2) Revise the FAA-approved AFM by incorporating the following into the Normal Procedures Section of the AFM. This may be accomplished by inserting a copy of this AD in the AFM.

"THE FOLLOWING WEATHER CONDITIONS MAY BE CONDUCTIVE TO SEVERE IN-FLIGHT ICING

- Visible rain at temperatures below 0 degrees Celsius ambient air temperature.
- Droplets that splash or splatter on impact at temperatures below 0 degrees Celsius ambient air temperature.

PROCEDURES FOR EXITING THE SEVERE ICING ENVIRONMENT

These procedures are applicable to all flight phases from takeoff to landing. Monitor the ambient air temperature. While severe icing may form at temperatures as cold as -18 degrees Celsius, increased vigilance is warranted at temperatures around freezing with visible moisture present. If the visual cues specified in the Limitations Section of the AFM for identifying severe icing conditions are observed, accomplish the following:

- Immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the severe icing conditions in order to avoid extended exposure to flight conditions more severe than those for which the airplane has been certificated.
- Avoid abrupt and excessive maneuvering that may exacerbate control difficulties.
- Do not engage the autopilot.
- If the autopilot is engaged, hold the control wheel firmly and disengage the autopilot.
- If an unusual roll response or uncommanded roll control movement is observed, reduce the angle-of-attack.
- Do not extend flaps when holding in icing conditions. Operation with flaps extended can result in a reduced wing angle-of-attack, with the possibility of ice forming on the lower surface further aft on the wing than normal, possibly aft of the protected area.
- If the flaps are extended, do not retract them until the airframe is clear of ice.
- Report these weather conditions to Air Traffic Control."

(b) Incorporating the AFM revisions, as required by this AD, may be performed by the owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), and must be entered into the aircraft records showing compliance with this AD in accordance with section 43.11 of the Federal Aviation Regulations (14 CFR 43.11).

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(e) All persons affected by this directive may examine information related to this AD at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on May 29, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-15081 Filed 6-5-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-ANE-23-AD]

RIN 2120-AA64

Airworthiness Directives; Allison Engine Company 250-B and 250-C Series Turboshift Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Allison Engine Company 250-B and 250-C series turboshift engines. This proposal would require replacing existing beryllium copper main fuel control (MFC) bellows assemblies with Inconel 718 stainless steel welded MFC bellows assemblies. This proposal is prompted by reports of leaking MFC bellows assemblies resulting in an uncommanded minimum fuel flow condition, loss of engine fuel flow control and subsequent forced landing. The actions specified by the proposed AD are intended to prevent MFC bellows assembly leakage, which can result in an uncommanded minimum

fuel flow condition and subsequent loss of engine fuel flow control.

DATES: Comments must be received by August 7, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-ANE-23-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may also be sent via the Internet using the following address: "9-ad-engineprop@faa.dot.gov". Comments sent via the Internet must contain the docket number in the subject line. Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Allison Engine Company, P.O. Box 420, Speed Code U-15, Indianapolis, IN 46206-0420, telephone (317) 230-6674. This information may be examined at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: John Tallarovic, Aerospace Engineer, Chicago Aircraft Certification Office, FAA, Small Airplane Directorate, 2350 E. Devon Avenue, Room 323, Des Plaines, IL 60018; telephone (847) 294-8180, fax (847) 294-7834.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments

submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-ANE-23-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-ANE-23-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

The Federal Aviation Administration (FAA) has received reports of inflight engine shutdowns due to main fuel control (MFC) beryllium copper bellows assembly leakage on Allison Engine Company engines. This same design is used on Allison Engine Company 250-B15, 250-B17, 250-B17F, 250-C18, 250-C20, 250-C20R, 250-C28, and 250-C30 series turboshaft engines. The investigation revealed that the MFC bellows assemblies leaked due to corrosion. This AD requires the replacement of existing beryllium copper MFC bellows assemblies with Inconel 718 stainless steel welded MFC bellows assemblies, a material that is less susceptible to corrosion. The compliance schedule balanced the need to remove the highest risk bellows assemblies first with the ability to manufacture replacement parts at the required rate. This condition, if not corrected, could result in MFC bellows assembly leakage, which can result in an uncommanded minimum fuel flow condition and subsequent loss of engine fuel flow control.

The FAA has reviewed and approved the technical contents of Allison Commercial Engine Bulletins (CEBs) No. CEB-A-282 (250-C18 series), No. CEB-A-1329 (250-C20 series), No. CEB-A-73-2053 (250-C28 series), No. CEB-A-73-3068 (250-C30 series), No. CEB-A-73-4029 (250-C20R series), No. TP CEB-A-158 (250-B15G series), No. TP CEB-A-1286 (250-B17 series), and TP CEB-A-73-2014 (250-B17F series), all Revision 2, all dated April 15, 1998, that describe procedures for replacing existing beryllium copper MFC bellows assemblies with Inconel 718 stainless steel welded MFC bellows assemblies.

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require replacing the existing beryllium copper MFC bellows assemblies at the next repair or overhaul of the MFC

bellows assembly, or, since corrosion was a factor, by the calendar end-dates specified, whichever occurs first. The actions would be required to be accomplished in accordance with the CEBs described previously.

The FAA estimates that 2,500 engines installed on aircraft of U.S. registry would be affected by this proposed AD, that it would take no additional work hours per engine to accomplish the proposed actions at regularly scheduled overhaul, and required parts would cost approximately \$1,495 per engine. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$3,737,500.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Allison Engine Company: Docket No. 98-ANE-23-AD.

Applicability: Allison Engine Company 250-B15, 250-B17, 250-B17F, 250-C18, 250-C20, 250-C20R, 250-C28, and 250-C30 series turboshaft engines, installed on but not limited to Bell Models 206, 230, 406; Enstrom Model TH28/480; and Boeing Models 500, 520N, 530F rotorcraft.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD.

For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent main fuel control (MFC) bellows assembly leakage, which can result in an uncommanded minimum fuel flow condition and subsequent loss of engine fuel flow control, accomplish the following:

(a) Replace existing beryllium copper MFC bellows assemblies, part numbers (P/Ns) 2523722, 2539647, 2540539, 2540767, and 2542526, with Inconel 718 stainless steel welded MFC bellows assemblies, P/N 2543598, in accordance with the applicable Allison Commercial Engine Bulletins (CEBs) referenced in paragraph (b) of this AD, at the earlier of the following:

(1) The next time after the effective date of this AD the MFC is being repaired or overhauled; or

(2) The following populations of MFCs, as applicable

(i) All MFCs listed by P/Ns in Tables 1 and 2 of the Allison CEBs referenced in paragraph (b) of this AD by March 31, 1999; or

(ii) All MFCs listed by P/Ns in Table 3 of the Allison CEBs referenced in paragraph (b) of this AD by August 31, 1999.

(iii) All MFCs listed by P/Ns in Tables 4 and 5 of the Allison CEBs referenced in paragraph (b) of this AD by October 31, 1999.

(b) Perform the replacement of MFC bellows assemblies required by paragraph (a) of this AD in accordance with the applicable Allison CEB from among the following:

(1) CEB-A-282 Revision 2, dated April 15, 1998 (250-C18 series), or

(2) CEB-A-1329 Revision 2, dated April 15, 1998 (250-C20 series), or

(3) CEB-A-73-2053 Revision 2, dated April 15, 1998 (250-C28 series), or

(4) CEB-A-73-3068 Revision 2, dated April 15, 1998 (250-C30 series), or

(5) CEB-A-73-4029 Revision 2, dated April 15, 1998 (250-C20R series), or

(6) TP (Turboprop) CEB-A-158 Revision 2, dated April 15, 1998 (250-B15G series), or

(7) TP CEB-A-1286 Revision 2, dated April 15, 1998 (250-B17 series), or

(8) TP CEB-A-73-2014 Revision 2, dated April 15, 1998 (250-B17F series).

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Chicago Aircraft Certification Office. Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Chicago Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Chicago Aircraft Certification Office.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on May 29, 1998.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 98-15087 Filed 6-5-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-134-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2B19 (Regional Jet Series 100) Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Bombardier Model CL-600-2B19 (Regional Jet Series 100) airplanes. This proposal would require repetitive inspections of the inboard and outboard flap actuators to measure the rotational freedom of the actuator ball screw adjacent to the actuator housing, and replacement of the flap actuators with new or serviceable actuators, if necessary. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent premature wear

of the internal gears on the flap actuators, which could result in complete disconnection of the actuator gear set and a mechanical jam of the flap system. This condition could cause structural damage and/or significant twist of a flap panel, which could lead to reduced controllability of the airplane.

DATES: Comments must be received by July 8, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-134-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

FOR FURTHER INFORMATION CONTACT:

Anthony E. Gallo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7510; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by

interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-134-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-134-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

Transport Canada Aviation (TCA), which is the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on certain Bombardier Model CL-600-2B19 (Regional Jet Series 100) airplanes. TCA advises that there have been several in-service reports of premature wear of the internal gears on the inboard and outboard flap actuators on airplanes returned from service. Such deterioration could result in complete disconnection of the actuator gear set and a mechanical jam of the flap system, which could cause structural damage and/or significant twist of a flap panel, and result in reduced controllability of the airplane.

Explanation of Relevant Service Information

EEMCO has issued Service Bulletin 852D100-27-03, Revision A, dated February 27, 1997, including Appendices 1 and 2. This service bulletin describes procedures for repetitive inspections of the inboard and outboard flap actuators to measure the rotational freedom of the actuator ball screw adjacent to the actuator housing to determine the allowable intervals for backlash measurement; and replacement of the flap actuators with new or serviceable actuators, if necessary. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. TCA classified this service bulletin as mandatory and issued Canadian airworthiness directive CF-97-05, dated May 5, 1997, in order to assure the continued airworthiness of these airplanes in Canada.