

PART 9003—ELIGIBILITY FOR PAYMENTS

1. The authority citation for part 9003 would continue to read as follows:

Authority: 26 U.S.C. 9003 and 9009(b).

2. In § 9003.1, paragraph (b) introductory text is republished and new paragraph (b)(11) would be added to read as follows:

§ 9003.1 Candidate and committee agreements.

* * * * *

(b) *Conditions.* The candidates shall:

* * * * *

(11) Agree that they and their authorized committee(s) shall file all reports with the Commission in an electronic format that meets the requirements of 11 CFR 104.18 if the candidate or the candidate's authorized committee(s) maintain or use computerized information containing any of the information described in 11 CFR 104.3.

PART 9033—ELIGIBILITY FOR PAYMENTS

3. The authority citation for Part 9033 would continue to read as follows:

Authority: 26 U.S.C. 9003(e), 9033 and 9039(b).

4. In section 9033.1, paragraph (b) introductory text is republished and new paragraph (b)(13) would be added to read as follows:

§ 9033.1 Candidate and committee agreements.

* * * * *

(b) *Conditions.* The candidate shall agree that:

* * * * *

(13) The candidate and the candidate's authorized committee(s) will file all reports with the Commission in an electronic format that meets the requirements of 11 CFR 104.18 if the candidate or the candidate's authorized committee(s) maintain or use computerized information containing any of the information described in 11 CFR 104.3.

Dated: June 11, 1998.

Joan D. Aikens,

Chairman, Federal Election Commission.

[FR Doc. 98-16006 Filed 6-16-98; 8:45 am]

BILLING CODE 6715-01-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 98-CE-52-AD]

RIN 2120-AA64

Airworthiness Directives; Schempp-Hirth K.G. Models Standard-Cirrus, Nimbus-2, JANUS, and Mini-Nimbus HS-7 Sailplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain Schempp-Hirth K.G. (Schempp-Hirth) Models Standard-Cirrus, Nimbus-2, JANUS, and Mini-Nimbus HS-7 sailplanes. The proposed AD would require installing a safety device for the tailplane locking hook. The proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. The actions specified by the proposed AD are intended to prevent the locking hook on the tailplane attachment bracket from disengaging, which could result in the horizontal tailplane coming loose from the fin with possible loss of longitudinal control of the sailplane.

DATES: Comments must be received on or before July 21, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-52-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Schempp-Hirth Flugzeugbau GmbH, Postbox 14 43, D-73222 Kirchheim unter Teck, Federal Republic of Germany. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-52-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-52-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on certain Schempp-Hirth Models Standard-Cirrus, Nimbus-2, JANUS, and Mini-Nimbus HS-7 sailplanes. The LBA reports instances where the locking hook on the tailplane attachment bracket disengaged to the point that the horizontal tailplane was no longer securely attached to the fin.

This condition, if not corrected, could result in the horizontal tailplane coming loose from the fin with possible loss of longitudinal control of the sailplane.

Relevant Service Information

Schempp-Hirth has issued Technical Note No. 278-36, 286-33, 295-26, 328-11, 798-3, dated November 11, 1994,

which specifies installing a safety device for the tailplane locking hook. The procedures for accomplishing this installation are included with the Appendix to Technical Note No. 278-36, 286-33, 295-26, 328-11, 798-3, dated November 11, 1994.

The LBA classified this service information as mandatory and issued German AD 95-015, dated December 15, 1994, in order to assure the continued airworthiness of these sailplanes in Germany.

The FAA's Determination

This sailplane model is manufactured in Germany and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has kept the FAA informed of the situation described above.

The FAA has examined the findings of the LBA; reviewed all available information, including the service information referenced above; and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of the Provisions of the Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop in other Schempp-Hirth Models Standard-Cirrus, Nimbus-2, JANUS, and Mini-Nimbus HS-7 sailplanes of the same type design registered in the United States, the FAA is proposing AD action. The proposed AD would require installing a safety device for the tailplane locking hook.

Accomplishment of the proposed action would be required in accordance with Schempp-Hirth Appendix to Technical Note No. 278-36, 286-33, 295-26, 328-11, 798-3, dated November 11, 1994.

Compliance Time of the Proposed AD

Although the unsafe condition identified in this proposed AD occurs during flight and is a direct result of sailplane operation, the FAA has no way of determining how much time will elapse before the tailplane is not securely attached to the fin. For example, the condition could exist on a sailplane with 200 hours time-in-service (TIS), but could be developing on a sailplane with 50 hours TIS and not actually exist on this sailplane until 300 hours TIS. For this reason, the FAA has determined that a compliance based on calendar time should be utilized in the proposed AD in order to assure that the

unsafe condition is addressed on all sailplanes in a reasonable time period.

Differences Between the Technical Note, German AD, and This Proposed AD

Both Schempp-Hirth Technical Note No. 278-36, 286-33, 295-26, 328-11, 798-3, dated November 11, 1994, and German AD 95-015, dated December 15, 1994, apply to the Model Nimbus-2M sailplanes. This sailplane model is not type certificated for operation in the United States and therefore is not covered by the applicability of the proposed AD.

The Model Nimbus-2M sailplanes could be operating in the United States with an experimental certificate. The FAA is including a NOTE in the proposed AD to recommend that any person operating a Model Nimbus-2M sailplane in the United States with an experimental certificate accomplish the actions specified in the technical note.

Cost Impact

The FAA estimates that 90 sailplanes in the U.S. registry would be affected by the proposed AD, that it would take approximately 3 workhours per sailplane to accomplish the proposed action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$35 per sailplane. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$19,350, or \$215 per sailplane.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the

location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

Schempp-Hirth K.G.: Docket No. 98-CE-52-AD.

Applicability: The following sailplane models and serial numbers, certificated in any category:

Models	Serial numbers
Standard Cirrus.	573, 586, 593, 595, 597 through 599, 601 through 701.
Nimbus-2	86, 93, and 96 through 131.
JANUS	1 through 55, and 59.
Mini-Nimbus HS-7.	1 through 60, and 65.

Note 1: Both Schempp-Hirth Technical Note No. 278-36, 286-33, 295-26, 328-11, 798-3, dated November 11, 1994, and German AD 95-015, dated December 15, 1994, apply to the Model Nimbus-2M sailplanes. This sailplane model is not type certificated for operation in the United States, and therefore is not covered by the applicability of this AD. The Model Nimbus-2M sailplanes could be operating in the United States with an experimental certificate. The FAA recommends that any person operating a Model Nimbus-2M sailplane in the United States with an experimental certificate accomplish the actions specified in the technical note.

Note 2: This AD applies to each sailplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For sailplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not

been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 6 calendar months after the effective date of this AD, unless already accomplished.

To prevent the locking hook on the tailplane attachment bracket from disengaging, which could result in the horizontal tailplane coming loose from the fin with possible loss of longitudinal control of the sailplane, accomplish the following:

(a) Install a safety device for the tailplane locking hook in accordance with Schempp-Hirth Appendix to Technical Note No. 278-36, 286-33, 295-26, 328-11, 798-3, dated November 11, 1994.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the sailplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) Questions or technical information related to the service information referenced in this document should be directed to Schempp-Hirth Flugzeugbau GmbH, Postbox 14 43, D-73222 Kirchheim unter Teck, Federal Republic of Germany. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Note 4: The subject of this AD is addressed in German AD 95-015, dated December 15, 1994.

Issued in Kansas City, Missouri, on June 9, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-16016 Filed 6-16-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-47-AD]

RIN 2120-AA64

Airworthiness Directives; Mooney Aircraft Corporation Models M20J, M20K, M20M, and M20R Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain Mooney Aircraft Corporation (Mooney) Models M20J, M20K, M20M, and M20R airplanes. The proposed AD would require grinding the surface of the main landing gear (MLG) leg bracket, inspecting this area for cracks, and replacing any cracked MLG leg bracket. The proposed AD is the result of the manufacturing of several of the MLG leg brackets using laser pattern cutting. The brackets, when manufactured using this process, develop minor cracks at the bends, which could propagate over time. The actions specified by the proposed AD are intended to prevent failure of the MLG side brace bolt caused by cracking of the MLG leg bracket, which could result in MLG collapse with consequent loss of control of the airplane during taxi, takeoff, or landing operations.

DATES: Comments must be received on or before August 21, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-47-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Mooney Aircraft Corporation, Louis Schreiner Field, Kerrville, Texas 78028. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. Bob D. May, Aerospace Engineer, FAA, Airplane Certification Office, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150; telephone: (817) 222-5156; facsimile: (817) 222-5960.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may

be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-47-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-47-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

The FAA has received a report that the design service life of the part number (P/N) 510010 MLG leg bracket on certain Mooney Models M20J, M20K, M20M, and M20R airplanes may not be achieved. Eleven of these brackets were produced using a laser pattern cutting process. The brackets, when manufactured using this process, develop minor cracks at the bends, which could propagate over time.

The P/N 510010 bracket supports the MLG side brace bolt. Failure of the MLG side brace bolt would cause the MLG to collapse with consequent loss of control of the airplane during taxi, takeoff, or landing operations.

Relevant Service Information

Mooney has issued Service Bulletin M20-265, dated 1 April 13, 1998, which specifies procedures for grinding the surface of the MLG leg bracket, P/N 510010, and inspecting this area for cracks.

The FAA's Determination

After examining the circumstances and reviewing all available information related to the incidents described above, including the referenced service information, the FAA has determined that AD action should be taken to prevent failure of the MLG side brace bolt caused by cracking of the MLG leg