

levers below the flight idle stop while the airplane is in flight, and to add a statement of the consequences of positioning the power levers below the flight idle stop while the airplane is in flight.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Interim Action

This is considered interim action until final action is identified, at which time the FAA may consider further rulemaking.

Cost Impact

There are approximately 143 Gulfstream Model G-159 (G-I) airplanes of the affected design in the worldwide fleet. The FAA estimates that 63 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$3,780, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT

Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-13-30 Gulfstream Aerospace

Corporation (Formerly Grumman): Amendment 39-10621. Docket 97-NM-302-AD.

Applicability: All Model G-159 (G-I) airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of airplane controllability or engine overspeed with consequent loss of engine power, caused by the power levers being positioned below the flight idle stop while the airplane is in flight, accomplish the following:

(a) For turbopropeller-powered Gulfstream Model G-159 (G-I) airplanes: Within 30 days after the effective date of this AD, revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the

following statements. This action may be accomplished by inserting a copy of this AD into the AFM.

"Positioning of the propeller flight fine pitch lock selector to the ground interlock position in flight is PROHIBITED. Such positioning may lead to loss of airplane control."

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office (ACO). Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on July 29, 1998.

Issued in Renton, Washington, on June 16, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-16493 Filed 6-23-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-304-AD; Amendment 39-10620; AD 98-13-29]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-120 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all EMBRAER Model EMB-120 series airplanes, that requires revising the Airplane Flight Manual (AFM) to prohibit positioning the power levers below the flight idle stop. This amendment is prompted by incidents and accidents involving airplanes equipped with turboprop engines in which the ground propeller beta range was used improperly during flight. The actions specified by this AD are intended to prevent loss of airplane

controllability or engine overspeed with consequent loss of engine power caused by the power levers being positioned below the flight idle stop while the airplane is in flight.

EFFECTIVE DATE: July 29, 1998.

ADDRESSES: Information pertaining to this rulemaking action may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia.

FOR FURTHER INFORMATION CONTACT: Wayne A. Shade, Aerospace Engineer, Airframe and Propulsion Branch, ACE-117A, the FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-7337; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all EMBRAER Model EMB-120 series airplanes was published in the **Federal Register** on April 27, 1998 (63 FR 20550). That action proposed to require revising the Limitations Section of the Airplane Flight Manual (AFM) to prohibit the positioning of the power levers below the flight idle stop while the airplane is in flight, and to add a statement of the consequences of positioning the power levers below the flight idle stop while the airplane is in flight.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Interim Action

This is considered interim action until final action is identified, at which time the FAA may consider further rulemaking.

Cost Impact

The FAA estimates that 235 EMBRAER Model EMB-120 series airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane

to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$14,100, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-13-29 Embraer: Amendment 39-10620. Docket 97-NM-304-AD.

Applicability: All Model EMB-120 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of airplane controllability or engine overspeed with consequent loss of engine power caused by the power levers being positioned below the flight idle stop while the airplane is in flight, accomplish the following:

(a) Within 30 days after the effective date of this AD, revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following statements. This action may be accomplished by inserting a copy of this AD into the AFM.

"Positioning of power levers below the flight idle stop in flight is prohibited. Such positioning may result in an engine overspeed condition with consequent loss of engine and potential excessive asymmetric propeller drag reducing aircraft controllability."

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office (ACO). Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on July 29, 1998.

Issued in Renton, Washington, on June 16, 1998.

Darrell M. Pederson,

*Acting Manager, Transport Airplane
Directorate, Aircraft Certification Service.*

[FR Doc. 98-16492 Filed 6-23-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-178-AD; Amendment
39-10611; AD 98-11-52]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-100, -200, -300, -400, and -500 Series Airplanes

AGENCY: Federal Aviation
Administration, DOT.

ACTION: Final rule; request for
comments.

SUMMARY: This document publishes in the **Federal Register** an amendment adopting airworthiness directive (AD) T98-11-52 that was sent previously to all known U.S. owners and operators of Boeing Model 737-100, -200, -300, -400, and -500 series airplanes by individual telegrams. This AD requires removal of the fuel boost pump wiring in the conduits of the wing and center fuel tanks; an inspection to detect damage of the wiring, and corrective action, if necessary; and eventual installation of teflon sleeving over the electrical cable. This action is prompted by reports of severe wear of the fuel boost pump wiring due to chafing between the wiring and the surrounding conduit inside the fuel tank; pin-hole-sized holes in the conduit that appear to be the result of arc-through of the conduit; and exposure of the main tank boost pump wire conductor inside a conduit and signs of arcing to the wall of the conduit. The actions specified by this AD are intended to detect and correct chafing and electrical arcing between the fuel boost pump wiring and the surrounding conduit, which, if not corrected, could result in arc-through of the conduit, and consequent fire or explosion of the fuel tank.

DATES: Effective June 29, 1998, to all persons except those persons to whom it was made immediately effective by telegraphic AD T98-11-52, issued on May 14, 1998, which contained the requirements of this amendment.

The incorporation by reference of certain publications listed in the regulations is approved by the Director

of the Federal Register as of June 29, 1998.

Comments for inclusion in the Rules Docket must be received on or before August 24, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-178-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The applicable service information may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC. **FOR FURTHER INFORMATION CONTACT:** Dorr Anderson, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2684; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Issuance of Telegraphic AD T98-10-51

On May 7, 1998, the FAA issued telegraphic AD T98-10-51, applicable to all Model 737-100, -200, -300, -400, and -500 series airplanes, to require removal of the fuel boost pump wiring in the conduits of the wing fuel tanks; a one-time detailed visual inspection to detect damage of the wiring; reinstallation of the wiring with teflon sleeving, or replacement of damaged wiring with new wiring and teflon sleeving; and submission of damaged parts to Boeing. Telegraphic AD T98-10-51 was prompted by reports of severe wear of the fuel boost pump wiring due to chafing between the in-tank fuel boost pump wiring and the surrounding conduit inside the fuel tank, and pin-hole-sized holes in two sections of the fuel boost pump conduit that appeared to be the result of arc-through of the conduit. The actions required by that telegraphic AD were intended to detect and correct such chafing, which could result in arc-through of the conduit, and consequent fire or explosion of the fuel tank.

Issuance of Telegraphic AD T98-11-51

On May 10, 1998, the FAA issued telegraphic AD T98-11-51, which is applicable to all Model 737-100, -200, -300, -400, and -500 series airplanes. That AD superseded telegraphic AD T98-10-51 to continue to require

removal of the fuel boost pump wiring in the conduits of the wing fuel tanks; a detailed visual inspection to detect damage of the wiring; and corrective action, if necessary. Additionally, that telegraphic AD required eventual installation of teflon sleeving over the electrical cable, which terminated the requirements of the telegraphic AD.

Telegraphic AD T98-11-51 was prompted by a report indicating that the left main tank boost pump power wire conductor was exposed at three areas inside the conduit. At least one of the areas exhibited signs of arcing to the wall of the conduit. In addition, several reports of severe chafing had been received since the issuance of telegraphic AD T98-10-51. The actions required by telegraphic AD T98-11-51 were intended to detect and correct chafing and electrical arcing between the fuel boost pump wiring and the surrounding conduit, which, if not corrected, could result in arc-through of the conduit, and consequent fire or explosion of the fuel tank.

In telegraphic AD T98-11-51, the FAA required inspection of airplanes that had accumulated between 40,000 and 50,000 total flight hours based on the significance of the problems on the high-time airplanes reported at that time, and the lack of available data for airplanes that had accumulated between 40,000 and 50,000 total flight hours. However, the FAA indicated in that telegraphic AD that it would continue to monitor inspection reports to determine whether an adjustment to the compliance time was warranted.

Issuance of Telegraphic AD T98-11-52

Since the issuance of telegraphic AD T98-11-51, the FAA has received inspection results indicating that exposed copper wire and significant chafing was found on other Model 737-200 series airplanes that had accumulated flight hours below those specified in earlier reports.

The FAA has determined that it is necessary to expand the inspection requirement to airplanes that have accumulated less than 40,000 total flight hours. This is necessary to ensure that these airplanes have not also developed a problem with chafing and electrical arcing between the fuel boost pump wiring and the surrounding conduit.

When telegraphic AD T98-11-51 superseded telegraphic AD T98-10-51, the FAA had received inspection reports indicating that the center fuel tank boost pump wiring was not showing chafing and did not present a safety of flight problem on Model 737-100 and -200 series airplanes. (It should be noted that the center fuel tank boost pump wiring