

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

**98-14-10 Boeing:** Amendment 39-10643. Docket 98-NM-155-AD.

**Applicability:** Model 747-400, 757, 767, and 777 series airplanes; equipped with AlliedSignal RIA-35B Instrument Landing System (ILS) receivers, part number (P/N) 066-50006-0101; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To detect and correct faulty ILS receivers, and to ensure that the flightcrew is advised of the potential hazard of performing ILS approaches using a localizer deviation from a faulty ILS receiver and also advised of the procedures necessary to address that hazard, accomplish the following:

(a) Within 10 days after the effective date of this AD, revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following statement. This may be accomplished by inserting a copy of this AD into the AFM.

Any Instrument Landing System (ILS) or Localizer approach with only one operative AlliedSignal ILS receiver, P/N 066-50006-0101, installed is prohibited.

**Note 2:** On Model 747-400 and 777 series airplanes, the existence of only one operative ILS receiver is indicated by the Engine Indication and Crew Alerting System

advisory message, "SNGL SOURCE ILS." On Model 757 and 767 series airplanes, failure of an ILS receiver is indicated by an ILS flag on the display of the Electronic Flight Instrument System when approach mode is selected.

(b) Within 30 days after the effective date of this AD, accomplish the requirements of either paragraph (b)(1) or (b)(2) of this AD.

(1) Perform a visual inspection of the 64 flight legs of the internal fault memory of all AlliedSignal RIA-35B ILS receivers, P/N 066-50006-0101, for fault codes "NI" (glide slope antialias fault) or "Nm" (localizer antialias fault). Repeat the inspection thereafter at intervals not to exceed 64 flight cycles. If any fault code "NI" or "Nm" is found, prior to further flight, replace the existing ILS receiver with a new or serviceable ILS receiver having the same P/N; or with an ILS receiver that has been modified to P/N 066-50006-1101 in accordance with AlliedSignal Electronic and Avionics Systems Service Bulletin M-4426 (RIA-35B-34-6), Revision 3, dated May 1998. Installation of an ILS receiver that has been modified (and the P/N converted) in accordance with the service bulletin constitutes terminating action for the inspection requirement of paragraph (b)(1) of this AD for that part.

(2) Accomplish the actions required by paragraphs (b)(2)(i) and (b)(2)(ii) of this AD.

(i) Revise the Limitations Section of the FAA-approved AFM to include the following statement. This may be accomplished by inserting a copy of this AD into the AFM.

Category II and III operations are prohibited with AlliedSignal ILS receiver P/N 066-50006-0101 installed.

(ii) Install a placard on the forward instrument panel of the cockpit in clear view of the pilots, which states:

"Category II and III operations are prohibited."

(c) Replacement of all existing RIA-35B ILS receivers, P/N 066-50006-0101, with RIA-35B ILS receivers that have been modified in accordance with AlliedSignal Electronic and Avionics Systems Service Bulletin M-4426 (RIA-35B-34-6), Revision 3, dated May 1998; and that have had their P/N's converted to 066-50006-1101; constitutes terminating action for the requirements of this AD. After the replacement has been accomplished, the AFM limitations required by paragraphs (a) and (b)(2)(i) of this AD may be removed from the AFM, and the placard required by (b)(2)(ii) may be removed from the cockpit.

**Note 3:** Modification of all AlliedSignal RIA-35B ILS receivers, P/N 066-50006-0101, prior to the effective date of this AD in accordance with AlliedSignal Electronic and Avionics Systems Service Bulletin M-4426 (RIA-35B-34-6), dated December 1997; Revision 1, dated January 1998; or Revision 2, dated April 1998; is considered acceptable for compliance with the applicable action specified in this amendment.

(d) As of the effective date of this AD, no person shall install on any airplane an RIA-35B ILS receiver, P/N 066-50006-0101, that has been found to be discrepant (that is, on which fault codes "NI" or "Nm" were found during an inspection of the internal fault

memory) unless the discrepancy has been corrected by modifying the ILS receiver in accordance with AlliedSignal Electronic and Avionics Systems Service Bulletin M-4426 (RIA-35B-34-6), Revision 3, dated May 1998.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 4:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(f) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(g) The modification, if accomplished, shall be done in accordance with AlliedSignal Electronic and Avionics Systems Service Bulletin M-4426 (RIA-35B-34-6), Revision 3, dated May 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from AlliedSignal Aerospace, Technical Publications, Dept. 65-70, P.O. Box 52170, Phoenix, Arizona 85072-2170. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective on July 22, 1998.

Issued in Renton, Washington, on June 29, 1998.

**Vi L. Lipski,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 98-17914 Filed 7-6-98; 8:45 am]

BILLING CODE 4910-13-U

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 97-NM-139-AD; Amendment 39-10648; AD 98-14-15]

RIN 2120-AA64

**Airworthiness Directives; Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 Series Airplanes, and Model F27 Mark 050 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to all Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes, and Model F27 Mark 050 series airplanes, that requires revising the Airplane Flight Manual to modify the limitation that prohibits positioning the power levers below the flight idle stop during flight, and to provide a statement of the consequences of positioning the power levers below the flight idle stop during flight. This amendment is prompted by incidents and accidents involving airplanes equipped with turboprop engines in which the ground propeller beta range was used improperly during flight. The actions specified by this AD are intended to prevent loss of airplane controllability caused by the power levers being positioned below the flight idle stop while the airplane is in flight.

**EFFECTIVE DATE:** Effective August 11, 1998.

**ADDRESSES:** Information pertaining to this rulemaking action may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Mark Quam, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (425) 227-2145; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes, and Model F27 Mark 050 series airplanes, was published in the **Federal Register** on March 20, 1998 (63 FR 13569). That action proposed to require revising the FAA-approved Airplane Flight Manual to modify the limitation that prohibits positioning the power levers below the flight idle stop during flight, and to provide a statement of the consequences of positioning the power levers below the flight idle stop during flight.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

#### **Request to Install Automatic Flight Idle Stop Mechanical System**

The commenter supports the proposed rule, but remarks that, as an added measure of safety, the FAA should consider the addition of a

mechanical means to preclude such selection. The mechanical means referenced by the commenter would be in the form of an automatic flight idle stop. The FAA acknowledges the commenter's concern, and may consider additional rulemaking to address that concern in the future on certain airplanes. However, until such final action is identified, the FAA considers it appropriate to proceed with issuance of this final rule. No change to the final rule is required.

#### **Conclusion**

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### **Interim Action**

This is considered interim action until final action is identified, at which time the FAA may consider further rulemaking.

#### **Cost Impact**

The FAA estimates that 49 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$2,940, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

#### **Regulatory Impact**

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory

Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

#### **Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

##### **98-14-15 Fokker Services B.V.:**

Amendment 39-10648. Docket 97-NM-139-AD.

**Applicability:** All Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes, and Model F27 Mark 050 series airplanes; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent loss of airplane controllability caused by the power levers being positioned below the flight idle stop while the airplane is in flight, accomplish the following:

(a) Within 30 days after the effective date of this AD, revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following statements as specified in paragraph (a)(1) or (a)(2) of this AD, as applicable. This action may be accomplished by inserting a copy of this AD into the AFM.

(1) For Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes, insert the following:

"Warning: Ground fine pitch must not be selected in flight. This may lead to loss of

control from which recovery may not be possible.”

(2) For Model F27 Mark 050 series airplanes, insert the following:

“Warning: Do not attempt to select ground idle in flight. In case of failure of the flight idle stop, this would lead to loss of control from which recovery may not be possible.”

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on August 11, 1998.

Issued in Renton, Washington, on June 30, 1998.

**Vi L. Lipski,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 98-17948 Filed 7-6-98; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-NM-72-AD; Amendment 39-10647; AD 98-14-14]

RIN 2120-AA64

#### **Airworthiness Directives; Turbopropeller-Powered McDonnell Douglas Model DC-3 and DC-3C Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-3 and DC-3C series airplanes, that requires revising the Airplane Flight Manual (AFM) to modify the limitation that prohibits positioning the power levers below the flight idle stop during flight, and to provide a statement of the consequences of positioning the power levers below the flight idle stop during flight. This

amendment is prompted by incidents and accidents involving airplanes equipped with turboprop engines in which the ground propeller beta range was used improperly during flight. The actions specified by this AD are intended to prevent loss of airplane controllability, or engine overspeed and consequent loss of engine power caused by the power levers being positioned below the flight idle stop while the airplane is in flight.

**EFFECTIVE DATE:** August 11, 1998.

**ADDRESSES:** Information pertaining to this amendment may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

#### **FOR FURTHER INFORMATION CONTACT:**

Frank Hoerman, Aerospace Engineer, Flight Test Branch, ANM-160L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (562) 527-5371; fax (562) 625-5210.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-3 and DC-3C series airplanes was published in the **Federal Register** on January 8, 1998 (63 FR 1072). That action proposed to require revising the Limitations Section of the Airplane Flight Manual (AFM) to prohibit the positioning of the power levers below the flight idle stop while the airplane is in flight, and to add a statement of the consequences of positioning the power levers below the flight idle stop while the airplane is in flight.

#### **Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

#### **Conclusion**

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### **Interim Action**

This is considered interim action until final action is identified, at which time the FAA may consider further rulemaking.

#### **Cost Impact**

There are approximately 21 turbopropeller-powered McDonnell Douglas Model DC-3 and DC-3C series airplanes of the affected design in the worldwide fleet. The FAA estimates that 5 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$300, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

#### **Regulatory Impact**

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

#### **Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows: