

Proposed Rules

Federal Register

Vol. 63, No. 129

Tuesday, July 7, 1998

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-179-AD]

RIN 2120-AA64

Airworthiness Directives; de Havilland Model DHC-8-100, -200, and -300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all de Havilland Model DHC-8-100, -200, and -300 series airplanes. This proposal would require installation of a placard on the instrument panel of the cockpit to advise the flightcrew that positioning of the power levers below the flight idle stop during flight is prohibited. This proposal also would require eventual installation of a system that would prevent such positioning of the power levers during flight. Such installation would terminate the requirement for installation of a placard. This proposal is prompted by reports of operation of the airplane with the power levers positioned below the flight idle stop during flight. The actions specified by the proposed AD are intended to prevent such positioning of the power levers below the flight idle stop during flight, which could cause engine overspeed, possible engine damage or failure, and consequent reduced controllability of the airplane.

DATES: Comments must be received by October 5, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-179-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this

location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

Information concerning this proposed rule may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

FOR FURTHER INFORMATION CONTACT: James E. Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7521; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-179-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the

FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-179-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports of operation of the airplane with the power levers positioned below the flight idle stop during flight on de Havilland Model DHC-8-100, -200, and -300 series airplanes. One report indicated that such operation resulted in significant engine damage.

When the power levers are positioned below the flight idle stop during flight, the propellers operate in the beta range. Under these conditions, it is possible for air loads to back-drive the propeller, which could result in overspeed of the propeller and power turbine of the engine. ("Beta," as defined in this proposed rule, is the range of propeller operation intended for use during taxi, ground idle, or reverse operations, as controlled by the power lever settings aft of the flight idle stop.)

Operation of the propellers in the beta range during flight due to positioning of the power levers below the flight idle stop, could result in engine overspeed, possible engine damage or failure, and consequent reduced controllability of the airplane.

U.S. Type Certification of the Airplane

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations and the applicable bilateral airworthiness agreement. The FAA has reviewed all available information and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require installation of a placard on the instrument panel of the cockpit to advise the flightcrew that positioning of the power levers below the flight idle stop during flight is prohibited. Additionally, the proposed AD would require eventual installation of an FAA-approved system that would prevent

such positioning of the power levers during flight. Installation of that system would eliminate the requirement for installation of the placard. Installation of such an FAA-approved system would be required to be accomplished in accordance with a method approved by the FAA.

Additionally, the FAA has included a provision [paragraph (c) of the proposal] for Master Minimum Equipment List (MMEL) relief in the event the system proposed in paragraph (b) of the proposal malfunctions or the use of an override (if installed) has been necessary. If provision is not made for MMEL relief, the system required by paragraph (b) would be required all of the time. Absence of such MMEL relief could create a burden for operators if required maintenance or repair was not readily available at certain airports or locations. The proposed MMEL relief is based on the condition that the existing manual power lever flight idle gate and lifting finger trigger latch design is retained and remains fully functional. This is consistent with the current MMEL that makes no mention of the flight idle gate and lifting finger trigger latch design, which means these devices must be operational at all times.

Cost Impact

The FAA estimates that 185 de Havilland Model DHC-8-100, and -200, and -300 series airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the installation of the placard, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed placard installation on U.S. operators is estimated to be \$11,100, or \$60 per airplane.

Since the manufacturer has not yet developed a specific system commensurate with the requirements of this proposal, the FAA is unable to provide specific information as to the number of work hours or cost of parts that would be required to accomplish the proposed installation. However, based on similar installations of such systems accomplished previously on other airplane models, the FAA can reasonably estimate that approximately 130 work hours per airplane may be necessary to accomplish the system installation. The FAA also estimates that required parts would cost approximately \$10,000 per airplane. Based on these figures, the cost impact of the proposed system installation on U.S. operators is estimated to be \$3,293,000, or \$17,800 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The FAA recognizes that the obligation to maintain aircraft in an airworthy condition is vital, but sometimes expensive. Because AD's require specific actions to address specific unsafe conditions, they appear to impose costs that would not otherwise be borne by operators. However, because of the general obligation of operators to maintain aircraft in an airworthy condition, this appearance is deceptive. Attributing those costs solely to the issuance of this AD is unrealistic because, in the interest of maintaining safe aircraft, prudent operators would accomplish the required actions even if they were not required to do so by the AD.

A full cost-benefit analysis has not been accomplished for this proposed AD. As a matter of law, in order to be airworthy, an aircraft must conform to its type design and be in a condition for safe operation. The type design is approved only after the FAA makes a determination that it complies with all applicable airworthiness requirements. In adopting and maintaining those requirements, the FAA already has made the determination that they establish a level of safety that is cost-beneficial. When the FAA, as in this proposed AD, makes a finding of an unsafe condition, this means that the original cost-benefit level of safety is no longer being achieved and that the proposed actions are necessary to restore that level of safety. Because this level of safety has already been determined to be cost-beneficial, a full cost-benefit analysis for this proposed AD would be redundant and unnecessary.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT

Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

De Havilland: Docket 98-NM-179-AD.

Applicability: All Model DHC-8-100, -200, and -300 airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent positioning of the power levers below the flight idle stop during flight, which could cause engine overspeed, possible engine damage or failure, and consequent reduced controllability of the airplane, accomplish the following:

(a) Within 30 days after the effective date of this AD, install a placard in a prominent location on the instrument panel of the cockpit that states:

Positioning of the power levers below the flight idle stop during flight is prohibited.

Such positioning may lead to loss of airplane control, or may result in an engine overspeed condition and consequent loss of engine power.

(b) Within 1 year after the effective date of this AD, install a system that would prevent positioning the power levers below the flight idle stop during flight, in accordance with a method approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Following accomplishment of that installation, the placard required by paragraph (a) of this AD may be removed.

(c) In the event that the system required by paragraph (b) of this AD malfunctions, or if the use of an override (if installed) has been necessary, the airplane may be operated for two days to a location where required maintenance/repair can be performed, provided the system required by paragraph (b) of this AD has been properly deactivated and placarded for flightcrew awareness, in accordance with the FAA-approved Master Minimum Equipment List (MMEL).

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on June 29, 1998.

Vi L. Lipski,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-17915 Filed 7-6-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-157-AD]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Dornier Model 328-100 series airplanes.

This proposal would require repetitive lubrication of the engine control push-pull cables. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent ice from building up on the engine control push-pull cables, which could result in friction or jamming of the engine controls, and consequent reduced controllability of the airplane.

DATES: Comments must be received by August 6, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-157-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Fairchild Dornier, Dornier Luftfahrt GmbH, P.O. Box 1103, D-82230 Wessling, Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this

proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-157-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-157-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on all Dornier Model 328-100 series airplanes. The LBA advises that it has received several reports of ice building up on the engine control push-pull cables during flight, which prompted operators to descend to a lower altitude (higher temperature) to melt off any build-up. Investigation revealed that the ice builds up on and around the conduit seal housing for the engine control push-pull cables. Such build-up of ice on the engine control push-pull cables, if not corrected, could result in friction or jamming of the engine controls, and consequent reduced controllability of the airplane.

Explanation of Relevant Service Information

Dornier has issued Alert Service Bulletins ASB-328-76-022, dated December 22, 1997, and ASB-328-76-015, Revision 3, dated January 9, 1998, which describe procedures for repetitive lubrication of the engine control push-pull cables at two locations along the cables. The LBA classified these alert service bulletins as mandatory and issued German airworthiness directives 1998-105, dated January 30, 1998, and 1997-148/3, dated February 26, 1998, in order to assure the continued airworthiness of these airplanes in Germany.

FAA's Conclusions

This airplane model is manufactured in Germany and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement,