

Proposed Rules

Federal Register

Vol. 63, No. 131

Thursday, July 9, 1998

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-72-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-100 and -200 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Boeing Model 737-100 and -200 series airplanes, that currently requires replacement of certain outboard and inboard wheel halves with improved wheel halves; cleaning and inspecting certain outboard and inboard wheel halves for corrosion, missing paint in large areas, and cracks; and repair or replacement of the wheel halves with serviceable wheel halves, if necessary. That AD was prompted by a review of the design of the flight control systems on Model 737 series airplanes. This action would require that the actions be accomplished in accordance with revised service information. The actions specified by the proposed AD are intended to prevent failure of the wheel flanges, which could result in damage to the hydraulics systems, jammed flight controls, loss of electrical power, or other combinations of failures; and consequent reduced controllability of the airplane.

DATES: Comments must be received by August 24, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-72-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this

location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Allied Signal Aerospace Company, Bendix Wheels and Brakes Division, South Bend, Indiana 46624; and Bendix, Aircraft Brake and Strut Division, 3520 Westmoor Street, South Bend, Indiana 46628-1373. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: David Herron, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2672; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-72-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-72-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On August 4, 1997, the FAA issued AD 97-17-01, amendment 39-10102 (62 FR 43067, August 12, 1997), applicable to certain Boeing Model 737-100 and -200 series airplanes, to require replacement of certain outboard and inboard wheel halves with improved wheel halves; cleaning and inspecting certain outboard and inboard wheel halves for corrosion, missing paint in large areas, and cracks; and repair or replacement of the wheel halves with serviceable wheel halves, if necessary. That action was prompted by a review of the design of the flight control systems on Model 737 series airplanes. The requirements of that AD are intended to prevent failure of the wheel flanges, which could result in damage to the hydraulics systems, jammed flight controls, loss of electrical power, or other combinations of failures; and consequent reduced controllability of the airplane.

Explanation of Revised Service Information

Since the issuance of that AD, the FAA has been advised that Allied Signal Service Bulletin No. 737-32-026, dated April 26, 1988, which was referenced as the appropriate source of service information for accomplishment of the actions specified in that original AD, was incorrect. Subsequently, the FAA has reviewed and approved Allied Signal Service Bulletin No. 737-32-026, dated June 27, 1988. The procedures described in that revision are similar to those described in the earlier version of the service bulletin. However, among other things, this new version of the service bulletin differs from the original version in the following respects:

1. The effectivity listing in the revised service bulletin includes a new part number for inboard wheel halves.
2. The revised service bulletin provides a new option for repainting the wheels.
3. The revised service bulletin identifies specific serial numbers of wheel halves on which "beef-ups" were

accomplished, but inspections are still necessary.

Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would supersede AD 97-17-01 to continue to require replacement of certain outboard and inboard wheel halves with improved wheel halves; cleaning and inspecting certain outboard and inboard wheel halves for corrosion, missing paint in large areas, and cracks; and repair or replacement of the wheel halves with serviceable wheel halves, if necessary. The actions would be required to be accomplished in accordance with the revised service bulletin described previously.

Cost Impact

There are approximately 634 Boeing Model 737-100 and -200 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 241 airplanes of U.S. registry would be affected by this proposed AD.

Because this proposed AD would merely require that the actions currently required by AD 97-17-01 be accomplished in accordance with revised service information, the proposed AD would add no additional costs, and would require no additional work to be performed by affected operators. The current costs associated with this amendment are reiterated in their entirety (as follows) for the convenience of affected operators.

The FAA estimates that it will take approximately 4 work hours per airplane to accomplish the required replacement of wheel halves at an average labor rate of \$60 per work hour. Required parts will cost approximately \$20,212 per airplane. Based on these figures, the cost impact of the required replacement on U.S. operators is estimated to be \$4,928,932, or \$20,452 per airplane.

The FAA also estimates that it will take approximately 2 work hours per airplane to accomplish the required cleaning and inspection at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the required cleaning and inspection on U.S. operators is estimated to be \$28,920, or \$120 per airplane.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10102 (62 FR 43067, August 12, 1997), and by adding a new airworthiness directive (AD), to read as follows:

Boeing: Docket 98-NM-72-AD. Supersedes AD 97-17-01, amendment 39-10102.

Applicability: Model 737-100 and -200 series airplanes equipped with Bendix main wheel assemblies having part number (P/N) 2601571-1, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or

repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the wheel flanges, which could result in damage to the hydraulics systems, jammed flight controls, loss of electrical power, or other combinations of failures; and consequent reduced controllability of the airplane; accomplish the following:

Note 2: Allied Signal, Aircraft Landing Systems, Service Information Letter (SIL) #619, dated February 26, 1997, is an additional source of service information for appropriate wheel half serial numbers.

(a) For airplanes equipped with a Bendix main wheel assembly having P/N 2601571-1 with an inboard wheel half with serial number (S/N) B-5898 or lower, or S/N H-1721 or lower; or with an outboard wheel half with S/N B-5898 or lower, or S/N H-0863 or lower; accomplish the following:

(1) Within 180 days after September 16, 1997 (the effective date of AD 97-17-01, amendment 39-10102, 62 FR 43067), and thereafter at each tire change until the replacement required by paragraph (b) of this AD is accomplished: Accomplish the actions specified in paragraphs (a)(1)(i), (a)(1)(ii), and (a)(1)(iii) of this AD, in accordance with the Accomplishment Instructions of Allied Signal Service Bulletin No. 737-32-026, dated June 27, 1988.

(i) Clean any inboard and outboard wheel half specified in paragraph (a) of this AD. And

(ii) Inspect the wheel halves for corrosion or missing paint. If any corrosion is found, or if any paint is missing in large areas, prior to further flight, strip or remove paint, and remove any corrosion. And

(iii) Perform an eddy current inspection to detect cracks of the bead seat area.

(2) If any cracking is found during the inspections required by this paragraph, prior to further flight, repair or replace the wheel halves with serviceable wheel halves in accordance with procedures specified in the Component Maintenance Manual.

(b) For airplanes equipped with a Bendix main wheel assembly having P/N 2601571-1 with an inboard wheel half with S/N B-5898 or lower, or S/N H-1721 or lower; or with an outboard wheel half with S/N B-5898 or lower, or S/N H-0863 or lower; accomplish the following: Within 2 years after September 16, 1997, accomplish the actions specified in paragraphs (b)(1) and (b)(2) of this AD, in accordance with Bendix SIL 392, Revision 1, dated November 15, 1979. Accomplishment of the replacement constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD.

(1) Remove any inboard wheel half specified in paragraph (b) of this AD, and

replace it with an inboard wheel half having P/N 2607046, S/N 5899 or greater, or S/N H-1722 or greater. And

(2) Remove any outboard wheel half specified in paragraph (b) of this AD, and replace it with an outboard wheel half having P/N 2607047, S/N B-5899 or greater, or S/N H-0864 or greater.

(c)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(c)(2) Alternative methods of compliance, approved previously in accordance with AD 97-17-01, amendment 39-10102, are approved as alternative methods of compliance with this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 1, 1998.

Stewart R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-18159 Filed 7-8-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket 97-NM-242-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-8 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Model DC-8 series airplanes. Among other things, this proposal would require repetitive leak tests of the lavatory drain systems and repair, if necessary; installation of a lever lock cap, vacuum breaker check valve or flush/fill line ball valve on the flush/fill line; periodic seal changes; and replacement of "donut" type waste drain valves installed in the waste drain

system. This proposal is prompted by continuing reports of damage to engines, airframes, and to property on the ground, caused by "blue ice" that forms from leaking lavatory drain systems on transport category airplanes and subsequently dislodges from the airplane fuselage. The actions specified by this proposed AD are intended to prevent such damage associated with the problems of "blue ice."

DATES: Comments must be received by August 24, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-242-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Walter Eierman, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4317; telephone (562) 627-5336; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-242-AD." The

postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-242-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

Over the past several years, the FAA has received numerous reports of leakage from the lavatory service systems on in-service transport category airplanes that resulted in the formation of "blue ice" on the fuselage. In some instances, the "blue ice" subsequently dislodged from the fuselage and was ingested into an engine. In several of these incidents, the ingestion of "blue ice" into an engine resulted in the loss of an engine fan blade, severe engine damage, and the inflight shutdown of the engine. In two cases, the loads created by the "blue ice" being ingested into the engine resulted in the engine being physically torn from the airplane. Damage to an engine, or the separation of an engine from the airplane, could result in reduced controllability of the airplane.

The FAA also has received reports of at least three incidents of damage to the airframe of various models of transport category airplanes that was caused by foreign objects dislodged from the forward toilet drain valve and flush/fill line. One report was of a dent on the right horizontal stabilizer leading edge on a Boeing Model 737 series airplane that was caused by "blue ice" that had formed from leakage through a flush/fill line; in this case, the flush/fill cap was missing from the line at the forward service panel. Numerous operators have stated that leakage from the flush/fill line is a significant source of problems associated with "blue ice." Such damage caused by "blue ice" could adversely affect the integrity of the fuselage skin or surface structures.

Additionally, there have been numerous reports of "blue ice" dislodging from airplanes and striking houses, cars, buildings, and other occupied areas on the ground. Although there have been no reports of any person being struck by "blue ice," the FAA considers that the large number of reported cases of "blue ice" falling from lavatory drain systems is sufficient to support the conclusion that "blue ice" presents an unsafe condition to people on the ground. Demographic studies have shown that population density has increased around airports, and probably will continue to increase. These are