Reconstruction of taxiway Bravo. Reconstruction of taxiway Echo.

Decision date: June 26, 1998. For Further Information Contact: Lorna Sandridge, Central Region Airports Division, (816) 426–4730.

Public Agency: Metropolitan Knoxville Airport Authority, Knoxville, Tennessee.

Application Number: 98–06–C–00–TYS. .

Application Type: Impose and use a PFC.

PFC Level: \$3.00.

Total PFC Revenue Approved in This Decision: \$57,921,122.

Earliest Charge Effective Date: May 1, 1999.

Estimated Charge Expiration Date: July 1, 2021.

Class of Air Carriers Not Required To Collect PFC's: Nonscheduled, wholeplane charter operators by air taxi/ commercial operators filing FAA Form 1800–31.

Determination: Approved. Based on information contained in the public agency's application, the FAA has

determined that the proposed class accounted for less than 1 percent of the total annual enplanements at McGhee Tyson Airport.

Brief Description of Projects Approved for Collection and Use: Terminal construction/rehabilitation.

Decision Date: June 26, 1998. For Further Information Contact: Jerry Bowers, Memphis Airports District

Office, (901) 544–3495.

Public Agency: Tri-State Airport
Authority, Huntington, West Virginia.

Application Number: 98–03–C–00–HTS.

Application Type: Impose and use a PFC.

PFC Level: \$3.00.

Total PFC Revenue Approved in This Decision: \$365,138.

Earliest Charge Effective Date: February 1, 1999.

Estimated Charge Expiration Date: March 1, 2001.

Class of Air Carriers Not Required To Collect PFC's: (1) Unscheduled Part 135 charter operators for hire to the general public; and (2) unscheduled Part 121 charter operators for hire to the general public.

Determination: Approved. Based on information contained in the public agency's application, the FAA has determined that the proposed class accounted for less than 1 percent of the total annual enplanements at Tri-State Airport.

Brief Description of Projects Approved for Collection and Use:

Prepare PFC application number 3.
Design and construct SRE building.
Purchase aircraft de-icing truck.
Purchase four-wheel drive pickup with snowplow.

Acquire security vehicle.
Acquire self propelled access lift.
Drainage/de-icing study and drainage rehabilitation.

Reseal and rehabilitate airline ramp.

Decision Date: June 26, 1998. For Further Information Contact: Elonza Turner, Beckley Airports Field Office, (304) 252–6216.

Amendments to PFC Approvals

Amendment No. city, state	Amendment approved date	Original Approved net PFC revenue	Amended Approved Net PFC revenue	Original esti- mated charge exp. date	Amended esti- mated charge exp. date
94–02–C–03–DAY, Dayton, OH	06/16/98	\$58,377,638	\$45,742,740	04/01/11	01/01/10
	06/22/98	2,242,569	1,895,024	06/01/06	12/01/01
	06/29/98	19,418,406	21,290,023	01/01/06	04/01/10

Issued in Washington, DC, on July 15, 1998.

Eric Gabler,

Manager, Passenger Facility Charge Branch. [FR Doc. 98–19296 Filed 7–17–98; 8:45 am] BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

Denial of Motor Vehicle Defect Petition, DP98-004

AGENCY: National Highway Traffic Safety Administration (NHTSA), United States Department of Transportation. **ACTION:** Denial of petition for a defect investigation.

SUMMARY: This notice sets forth the reasons for the denial of a petition submitted to NHTSA under 49 U.S.C. 30162, requesting that the agency commence a proceeding to determine the existence of a defect related to motor vehicle safety. The petition is hereinafter identified as DP98–004.

FOR FURTHER INFORMATION CONTACT: Dr. George Chiang, Office of Defects

Investigation (ODI), NHTSA, 400 Seventh Street, SW, Washington, DC 20590. Telephone: (202) 366–5206.

SUPPLEMENTARY INFORMATION: Mr. Edward J. Lucas of Richardson, Texas, submitted a petition dated May 4, 1998, requesting that an investigation be initiated to determine whether Model Year (MY) 1995 Ford Windstar minivans contain a defect related to motor vehicle safety within the meaning of 49 U.S.C. Chapter 301. The petition alleges that MY 1995 Ford Windstars have a defective automatic transmission that can fail, creating a safety hazard. In support of his petition, the petitioner included not only a description of the problems he experienced with his vehicle, but also a printout of transmission complaints registered by other Windstar owners on one Internet

MY 1995 Ford Windstars equipped with an AX4S automatic transaxle are the subject vehicles. The transaxle combines a torque converter, fully automatic 4-speed transmission, final drive gearing, and differential into a front wheel drive system.

A review of agency data files, including information reported to

NHTSA's Auto Safety Hotline by consumers, indicated that aside from the petition, there were 27 reports concerning failure or malfunction of the transmission in the subject vehicles. These reports address issues of inadvertent downshifting, transmission gear slippage, difficult shifting, noise, and economic/quality problems. There were no reports of injuries or crashes resulting from these transmission failures. These reports appear to be similar in nature to those Internet complaints included with the petition.

It appears that the failure or malfunction of the transmission on the subject vehicles primarily resulted from a cracked forward drive clutch aluminum piston inside the transaxle assembly. Ford Motor Company (Ford) addressed this issue in Technical Service Bulletin (TSB) No. 94–24–7.

The forward clutch piston may crack on its outside diameter, seal groove or bottom. The crack allows transmission fluid to leak through the crack, causing slippage in forward drive and disability of forward drive.

When the transmission is hot, the transmission fluid viscosity becomes low. When the clutch piston is cracked

at a high temperature inside the transaxle, it can lead to faster transmission fluid leaks through the crack. At the same time, the hydraulic pressure decreases until the clutch begins to slip. At worst, the hydraulic pressure in the transmission could drop to a level that could not hold the forward drive clutch engaged, causing no forward drive. Ford was aware of the cracking piston problem, as shown by TSB No. 94–24–7, and replaced the aluminum piston with a steel one for 1996 and later model Windstars.

The petitioner alleged that the cracked piston is a safety hazard because it can disable forward drive function of the transmission and cause sudden loss of drive and subsequent unexpected engagement of the transmission.

Loss of forward drive function due to the cracked piston is not a sudden occurrence. Many transmission slippages will occur prior to the loss of forward drive. Further, this type of clutch disengagement is generally temporary. If the temperature inside transmission drops and the hydraulic pressure in the transmission increased, the forward drive clutch may engage again. The clutch re-engagement is noticeable to the driver, who is able to control the vehicle.

The agency has analyzed the available information concerning the problem alleged in the petition. Based on the information obtained from the evaluation of the ODI complaints and analysis of potential failure modes of the transmission, NHTSA believes that cracking of the forward clutch piston on the subject transaxle does not constitute a safety hazard within the meaning of Chapter 301.

For the reasons presented above, it is unlikely that NHTSA would issue an order for the notification and remedy of a safety-related defect in the subject vehicles at the conclusion of the investigation requested in the petition. Therefore, in view of the need to allocate and prioritize NHTSA's limited resources to best accomplish the agency's safety mission, the petition is denied.

Authority: 49 U.S.C. 30162(d); delegations of authority at CFR 1.50 and 501.8. Issued on: July 9, 1998.

Kenneth N. Weinstein,

Associate Administrator for Safety Assurance.

[FR Doc. 98–19152 Filed 7–17–98; 8:45 am] BILLING CODE 4910–59–P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-98-4074]

Decision That Nonconforming 1998 Mercedes-Benz Gelaendewagen Type 463 Multi-Purpose Passenger Vehicles Are Eligible for Importation

AGENCY: National Highway Traffic Safety Administration (NHTSA), DOT. ACTION: Notice of decision by NHTSA that nonconforming 1998 Mercedes-Benz Gelaendewagen Type 463 multipurpose passenger vehicles (MPVs) are eligible for importation.

SUMMARY: This notice announces the decision by NHTSA that 1998 Mercedes-Benz Gelaendewagen Type 463 MPVs not originally manufactured to comply with all applicable Federal motor vehicle safety standards are eligible for importation into the United States because they have safety features that comply with, or are capable of being altered to comply with, all such standards.

DATES: The decision is effective as of July 20, 1998.

FOR FURTHER INFORMATION CONTACT: George Entwistle, Office of Vehicle Safety Compliance, NHTSA (202–366– 5306).

SUPPLEMENTARY INFORMATION:

Background

Under 49 U.S.C. 30141(a)(1)(A) (formerly section 108(c)(3)(A)(i)(I) of the National Traffic and Motor Vehicle Safety Act (the Act)), a motor vehicle that was not originally manufactured to conform to all applicable Federal motor vehicle safety standards shall be refused admission into the United States unless NHTSA has decided that the motor vehicle is substantially similar to a motor vehicle originally manufactured for importation into and sale in the United States, certified under 49 U.S.C. 30115 (formerly section 114 of the Act), and of the same model year as the model of the motor vehicle to be compared, and is capable of being readily altered to conform to all applicable Federal motor vehicle safety standards. Where there is no substantially similar U.S.-certified motor vehicle, 49 U.S.C. 30141(a)(1)(B) (formerly section 108(c)(3)(A)(i)(II) of the Act, 15 U.S.C. 1397(c)(3)(A)(i)(II)) permits a nonconforming motor vehicle to be admitted into the United States if its safety features comply with, or are capable of being altered to comply with, all applicable Federal motor vehicle

safety standards based on destructive test data or such other evidence as NHTSA decides to be adequate.

Petitions for eligibility decisions may be submitted by either manufacturers or importers who have registered with NHTSA pursuant to 49 CFR Part 592. As specified in 49 CFR 593.7, NHTSA publishes notice in the Federal Register of each petition that it receives, and affords interested persons an opportunity to comment on the petition. At the close of the comment period, NHTSA decides, on the basis of the petition and any comments that it has received, whether the vehicle is eligible for importation. The agency then publishes this determination in the Federal Register.

Europa International, Inc. of Santa Fe, New Mexico (Registered Importer No. R-91-002) petitioned NHTSA to decide whether 1998 Mercedes-Benz Gelaendewagen Type 463 MPVs are eligible for importation into the United States. NHTSA published notice of the petition on May 15, 1998 (63 FR 27118) to afford an opportunity for public comment. The reader is referred to that notice for a thorough description of the petition. No comments were received in response to the notice. Based on its review of the information submitted by the petitioner, NHTSA has decided to grant the petition.

Vehicle Eligibility Number for Subject Vehicles

The importer of a vehicle admissible under any final determination must indicate on the form HS-7 accompanying entry the appropriate vehicle eligibility number indicating that the vehicle is eligible for entry. VCP-16 is the vehicle eligibility number assigned to vehicles admissible under this determination.

Final Decision

Accordingly, on the basis of the foregoing, NHTSA hereby decides that 1998 Mercedes-Benz Gelaendewagen Type 463 MPVs are eligible for importation into the United States because they have safety features that comply with, or are capable of being altered to comply with, all applicable Federal motor vehicle safety standards.

Authority: 49 U.S.C. 30141(a)(1)(B) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: July 15, 1998.

Marilynne Jacobs,

Director, Office of Vehicle Safety Compliance. [FR Doc. 98–19249 Filed 7–17–98; 8:45 am] BILLING CODE 4910–59–P