

jackscrews, which could result in reduced controllability of the airplane, accomplish the following:

Restatement of Requirements of Paragraphs (a) and (b) of AD 98-05-09

(a) Perform an inspection of the trim actuator of the horizontal stabilizer to verify jackscrew integrity and to detect excessive wear of the tie rod, in accordance with Commodore Jet Service Bulletin SB 1121-27-023, dated August 14, 1996, or Revision 1, dated May 28, 1997 (for Model 1121, 1121A, and 1121B series airplanes); Westwind Service Bulletin SB 1123-27-046, dated August 14, 1996, or Revision 1, dated May 28, 1997 (for Model 1123 series airplanes); or Westwind Service Bulletin SB 1124-27-133, dated August 14, 1996, or Revision 1, dated May 28, 1997 (for Model 1124 and 1124A series airplanes); as applicable; at the time specified in paragraph (a)(1) or (a)(2) of this AD, as applicable.

(1) For airplanes that have accumulated 6,000 or more total flight cycles, or on which the horizontal trim actuator has accumulated 2,000 or more flight cycles, as of April 10, 1998 (the effective date of AD 98-05-09, amendment 39-10370): Inspect within 50 flight hours after April 10, 1998. Repeat the inspection thereafter at intervals not to exceed 300 flight hours (for Model 1121, 1121A, 1121B, and 1123 series airplanes); or 400 flight hours (for Model 1124 and 1124A series airplanes); as applicable.

(2) For airplanes that have accumulated less than 6,000 total flight cycles, and on which the horizontal trim actuator has accumulated less than 2,000 total flight cycles, as of April 10, 1998: Inspect at the time specified in paragraph (a)(2)(i) or (a)(2)(ii) of this AD, as applicable.

(i) For Model 1121, 1121A, 1121B, and 1123 series airplanes: Inspect within 300 flight hours after April 10, 1998. Repeat the inspection thereafter at intervals not to exceed 300 flight hours.

(ii) For Model 1124 and 1124A series airplanes: Inspect within 400 flight hours after April 10, 1998. Repeat the inspection thereafter at intervals not to exceed 400 flight hours.

(b) If any discrepancy is found during any inspection required by paragraph (a) of this AD, prior to further flight, replace the actuator or tie rod, as applicable, in accordance with Commodore Jet Service Bulletin SB 1121-27-023, dated August 14, 1996, or Revision 1, dated May 28, 1997 (for Model 1121, 1121A, and 1121B series airplanes); Westwind Service Bulletin SB 1123-27-046, dated August 14, 1996, or Revision 1, dated May 28, 1997 (for Model 1123 series airplanes); or Westwind Service Bulletin 1124-27-133, dated August 14, 1996, or Revision 1, dated May 28, 1997 (for Model 1124 and 1124A series airplanes); as applicable.

New Requirements of this AD

(c) Within 18 months after the effective date of this AD, replace the trim actuator of the horizontal stabilizer with a modified trim actuator with modified jackscrew assemblies (part number 21164-362 and -363 for Model 1121, 1121A, and 1121B series airplanes; part

number 21164-360 and -361 for Model 1123 series airplanes; or part number 21164-360 and -361 for Model 1124 and 1124A series airplanes), in accordance with Commodore Jet Service Bulletin SB 1121-27-025, dated December 22, 1997 (for Model 1121, 1121A, and 1121B series airplanes); Westwind Service Bulletin SB 1123-27-047, dated September 1, 1997 (for Model 1123 series airplanes); or Westwind Service Bulletin SB 1124-27-136, dated September 1, 1997 (for Model 1124 and 1124A series airplanes); as applicable. Accomplishment of this replacement terminates the repetitive inspections required by this AD.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Manager, International Branch, ANM-116.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Israeli airworthiness directive 27-97-09-02, dated September 4, 1997.

Issued in Renton, Washington, on July 29, 1998.

D. L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-20835 Filed 8-4-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-53-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 767 series airplanes. This proposal would require a detailed visual inspection to detect corrosion inside the forward trunnion

joint of the main landing gear (MLG); follow-on actions; and repair, if necessary. The proposal also provides for optional terminating action for the repetitive inspections. This proposal is prompted by reports of corrosion at the forward trunnion thrust face, tabs, and the internal threads of the forward trunnion of the MLG due to moisture in the forward trunnion joint. The actions specified by the proposed AD are intended to prevent corrosion of the forward trunnion joint, which could lead to a stress corrosion fracture of the forward trunnion and possible consequent collapse of the MLG.

DATES: Comments must be received by September 21, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-53-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: James G. Rehr, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (425) 227-2783; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by

interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-53-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-53-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received several reports of corrosion at the forward trunnion thrust face and tabs, and at the internal threads of the forward trunnion of the outer cylinder of the main landing gear (MLG) on Boeing Model 767 series airplanes. During the first overhaul of those airplanes, similar corrosion damage was found on several of the MLG's that were removed from these airplanes. These MLG's had accumulated between 20,000 and 26,000 total hours time-in-service, and between 7,000 and 9,000 total landings. The presence of corrosion, due to moisture in the trunnion joint, could lead to stress corrosion cracking of the forward trunnion. Such stress corrosion cracking, if not corrected, could result in a stress corrosion fracture of the forward trunnion and possible consequent collapse of the MLG.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 767-32A0127, dated January 29, 1996, which describes procedures for performing a detailed visual inspection to detect corrosion inside the forward trunnion joint of the MLG; follow-on actions; and repair, if necessary. The follow-on actions include either application of chrome plating to the forward trunnion, or application of corrosion-inhibiting compound to the forward trunnion and repetitive inspections for corrosion thereafter. Application of the chrome plating to the forward trunnion would eliminate the need for the repetitive inspections.

The service bulletin references Component Maintenance Manual 32-

11-40, dated June 1, 1994, as an additional source of service information.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the alert service bulletin described previously.

Cost Impact

There are approximately 455 Boeing Model 767 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 151 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 8 work hours per airplane to accomplish the proposed visual inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the proposed inspection on U.S. operators is estimated to be \$72,480, or \$480 per airplane, per inspection cycle.

The cost impact figures above do not account for the time to gain access to the forward trunnion joint or to return a main landing gear to service. In this case, however, the access and close-up work hours may account for the predominant portion of the total cost impact of this proposed AD. It is estimated that it would take approximately 65 work hours to gain access to both forward trunnion joints, and 89 work hours to return the airplane to service. If these costs are included, the cost impact for the proposed visual inspections would be approximately \$1,467,720, or \$9,720 per airplane, per inspection cycle.

The repair of the forward trunnions (two per airplane), which would include both corrosion blend-out repairs as well as the application of chrome plate to certain portions of the forward trunnion, would take approximately 72 work hours to accomplish, at an average labor rate of \$60 per work hour. The cost of the repair kits would be approximately \$16,000 per airplane. Based on these figures, the cost impact of the proposed repair on U.S. operators is estimated to be \$3,068,320, or \$20,320 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects

on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 97-NM-53-AD.

Applicability: Model 767 series airplanes, manufacturer's line positions 001 through 455 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not

been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent corrosion of the forward trunnion joint of the main landing gear (MLG), which could lead to a stress corrosion fracture of the forward trunnion and possible consequent collapse of the MLG, accomplish the following:

(a) Within 6 years since the outer cylinder of the MLG was new, last overhauled, or installed (replaced) after the last corrosion repair in accordance with Boeing Alert Service Bulletin 767-32A0127, dated January 29, 1996; or within 18 months after the effective date of this AD; whichever occurs later: Perform a detailed visual inspection to detect corrosion inside the forward trunnion joint and the internal threads of the MLG; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 767-32A0127, dated January 29, 1996.

(1) If no corrosion of the forward trunnion joint is found, prior to further flight, accomplish either paragraph (a)(1)(i) or (a)(1)(ii) of this AD.

(i) Apply chrome plating to the forward trunnion thrust and tab faces in accordance with the alert service bulletin. Accomplishment of this application of chrome plating constitutes terminating action for the requirements of this AD.

(ii) Apply corrosion-inhibiting compound to the forward trunnion joint in accordance with the Accomplishment Instructions of the alert service bulletin. Repeat the detailed visual inspection thereafter at intervals not to exceed six years or until chrome plating is applied to the forward trunnion thrust and tab faces in accordance with the alert service bulletin.

(2) If any corrosion of the forward trunnion joint is found, prior to further flight, accomplish either paragraph (a)(2)(i) or (a)(2)(ii) of this AD.

(i) Repair the forward trunnion and apply chrome plating to the forward trunnion thrust and tab faces in accordance with the alert service bulletin. Accomplishment of this application of chrome plating constitutes terminating action for the requirements of this AD.

(ii) Repair the forward trunnion and apply corrosion-inhibiting compound to the forward trunnion joint in accordance with the alert service bulletin. Repeat the detailed visual inspection thereafter at intervals not to exceed six years or until chrome plating is applied to the forward trunnion thrust and tab faces in accordance with the alert service bulletin.

(b) Replacement, repair, or overhaul of the outer cylinder of the MLG that includes the application of chrome plating to the forward trunnion thrust and tab faces in accordance with Boeing Alert Service Bulletin 767-32A0127, dated January 29, 1996, constitutes terminating action for the requirements of this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators

shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 29, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-20834 Filed 8-4-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-04-AD]

RIN 2120-AA64

Airworthiness Directives; de Havilland Model DHC-8-100, -200, and -300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Supplemental notice of proposed rulemaking; reopening of comment period.

SUMMARY: This document revises an earlier proposed airworthiness directive (AD), applicable to certain de Havilland Model DHC-8-100, -200, and -300 series airplanes, that would have required modification of the flight compartment door. That proposal was prompted by a report that the door lock mechanism of the flight compartment door jammed and could not be opened using the alternate release mechanism. This new action would add repetitive inspections for wear of the flight compartment door hinges following modification, and repair or replacement of the hinges with new hinges, if necessary. This new action also revises the applicability of the existing AD. The actions specified by this new proposed AD are intended to prevent failure of the alternate release mechanism of the flight compartment door, which could delay or impede the evacuation of the flightcrew during an emergency. Such failure also could result in the flightcrew not being able to assist passengers in the event of an emergency.

DATES: Comments must be received by August 31, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-04-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

FOR FURTHER INFORMATION CONTACT: Ezra Sasson, Aerospace Engineer, Systems and Equipment Branch, ANE-172, FAA, New York Aircraft Certification Office, Engine and Propeller Directorate, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7520; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following