

Page No.	Revision level shown on page	Date shown on page
1, 2 .....	2 .....	March 20, 1997.
3-5 .....	1 .....	December 11, 1996.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from AI(R) American Support, Inc., 13850 McLearn Road, Herndon, Virginia 20171. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in British airworthiness directive 004-12-96.

(e) This amendment becomes effective on September 11, 1998.

Issued in Renton, Washington, on July 31, 1998.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 98-21105 Filed 8-6-98; 8:45 am]  
BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98-NM-146-AD; Amendment 39-10698; AD 98-16-21]

RIN 2120-AA64

#### Airworthiness Directives; Aerospatiale Model ATR42 and ATR72 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Aerospatiale Model ATR42 and ATR72 series airplanes, that requires one-time inspections to verify the correct shape of the stiffeners for the upper engine cowl and to detect wear of the aft upper fittings of the rear engine mounts, and corrective actions, if necessary. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent wear (scratches or grooving) of the aft upper fittings of the rear engine mount, and consequent

reduced structural integrity of the engine mounts.

**DATES:** Effective September 11, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 11, 1998.

**ADDRESSES:** The service information referenced in this AD may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:**

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:**

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Aerospatiale Model ATR42 and ATR72 series airplanes was published in the **Federal Register** on June 12, 1998 (63 FR 32152). That action proposed to require one-time inspections to verify the correct shape of the stiffeners for the upper engine cowl and to detect wear of the aft upper fittings of the rear engine mounts, and corrective actions, if necessary.

**Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

**Conclusion**

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

**Cost Impact**

The FAA estimates that 152 airplanes of U.S. registry will be affected by this AD, that it will take approximately 15 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$136,800, or \$900 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of

the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

**Regulatory Impact**

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

**98-16-21 Aerospatiale:** Amendment 39-10698. Docket 98-NM-146-AD.

*Applicability:* Model ATR42 and Model ATR72 series airplanes, as listed in Avions de Transport Regional Service Bulletins ATR42-54-0019 (for Model ATR42 series airplanes) and ATR72-54-1011 (for Model ATR72 series airplanes), both dated March 9, 1998; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent wear (scratches or grooving) of the aft upper fittings of the rear engine mount, and consequent reduced structural integrity of the engine mounts, accomplish the following:

(a) Within 10 months after the effective date of this AD, perform a one-time visual inspection of the stiffeners for the upper left and right engine cowls to ensure the stiffeners have the correct lower edge profile, in accordance with the Accomplishment Instructions of Avions de Transport Regional Service Bulletin ATR42-54-0019 or ATR72-54-1011, both dated March 9, 1998, as applicable.

(1) If the lower edge profile of the stiffener meets the specifications of the applicable service bulletin, no further action is required by this paragraph.

(2) If the lower edge profile of the stiffener does not meet the specifications of the applicable service bulletin, prior to further flight, modify or replace the stiffener with a new stiffener in accordance with the applicable service bulletin.

(b) Within 10 months after the effective date of this AD, perform a one-time detailed visual inspection for wear (scratches or grooving) of the aft upper fittings of the left- and right-hand rear engine mounts, in accordance with Avions de Transport Regional Service Bulletin ATR42-54-0019 (for Model ATR42 series airplanes) or ATR72-54-1011 (for Model ATR72 series airplanes), both dated March 9, 1998, as applicable.

(1) If no wear is detected, no further action is required by this paragraph.

(2) If any wear is detected that cannot be removed with a Type I or II blend-out as described in the applicable service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate.

(3) If any wear other than that specified in paragraph (b)(2) of this AD is detected, prior to further flight, repair in accordance with the Accomplishment Instructions of the applicable service bulletin.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance

Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) Except as provided by paragraph (b)(2) of this AD, the actions shall be done in accordance with Avions de Transport Regional Service Bulletin ATR42-54-0019, dated March 9, 1998, or Avions de Transport Regional Service Bulletin ATR72-54-1011, dated March 9, 1998, as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, edex 03, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in French airworthiness directives 98-069-073(B) (for Model ATR42 series airplanes), dated February 11, 1998; and 98-071-035(B) (for Model ATR72 series airplanes), dated February 11, 1998, as revised by Erratum 98-071-35(B), dated February 25, 1998.

(f) This amendment becomes effective on September 11, 1998.

Issued in Renton, Washington, on July 31, 1998.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 98-21102 Filed 8-6-98; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 98-AEA-10]

#### Amendment to Class E Airspace; Dunkirk, NY

**AGENCY:** Federal Aviation Administration (FAA) DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends Class E airspace extending upward from 700 feet Above Ground Level (AGL) at Dunkirk, NY. The development of a Standard Instrument Approach Procedure (SIAP) based on the Global Positioning System (GPS) at Angola Airport, NY, has made this action necessary. This action is intended to

provide adequate Class E airspace to contain instrument flight rules (IFR) operations for aircraft executing the GPS Runway (RWY) 1 SIAP to Angola Airport.

**EFFECTIVE DATE:** 0901 UTC, October 8, 1998.

**FOR FURTHER INFORMATION CONTACT:**

Mr. Francis Jordan, Airspace Specialist, Airspace Branch, AEA-520, Air Traffic Division, Eastern Region, Federal Aviation Administration, Federal Building #111, John F. Kennedy International Airport, Jamaica, New York 11430; telephone (718) 553-4521.

**SUPPLEMENTARY INFORMATION:**

**History**

On June 4, 1998, a proposal to amend Part 71 of the Federal Aviation Regulations (14 CFR Part 71) to amend the Class E airspace at Dunkirk, NY, was published in the **Federal Register** (63 FR 30428). The development of the GPS RWY 1 SIAP for Angola Airport, NY, requires the amendment of the Class E airspace at Dunkirk, NY. The proposal was to amend controlled airspace extending upward from 700 feet AGL to contain IFR operations in controlled airspace during portions of the terminal operation and while transitioning between the enroute and terminal environments.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments to the proposal were received. The rule is adopted as proposed.

The coordinates for this airspace docket are based on North American Datum 83. Class E airspace areas designations for airspace extending upward from 700 feet AGL are published in paragraph 6005 of FAA Order 7400.9E, dated September 10, 1997, and effective September 16, 1997, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

**The Rule**

This amendment to Part 71 of the Federal Aviation Regulations (14 CFR Part 71) amends Class E airspace at Dunkirk, NY, to provide controlled airspace extending upward from 700 feet AGL for aircraft executing the GPS RWY 1 SIAP to Angola Airport.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation—(1)