#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. 98-CE-07-AD; Amendment 39-10705; AD 98-17-03]

RIN 2120-AA64

#### Airworthiness Directives; Glaser-Dirks Flugzeugbau GmbH Model DG-400 Gliders

AGENCY: Federal Aviation Administration, DOT. ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all Glaser-Dirks Flugzeugbau GmbH (Glaser-Dirks) Model DG-400 gliders. This AD requires replacing the propeller shaft, the bearings, and the front drive belt retaining rings with ones of improved design. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. The actions specified by this AD are intended to prevent failure of the propeller shaft caused by an ineffective design, which could result in loss of glider propulsion during critical phases of flight.

DATES: Effective September 26, 1998. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 26, 1998.

ADDRESSES: Service information that applies to this AD may be obtained from Glaser-Dirks Flugzeugbau GmbH, Im Schollengarten 19–20, 7520 Bruchsal 4, Germany; telephone: +49 7257–89–0; facsimile: +49 7257–8922. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98–CE–07–AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.

#### SUPPLEMENTARY INFORMATION:

# **Events Leading to the Issuance of This AD**

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR

part 39) to include an AD that would apply to all Glaser-Dirks Model DG-400 gliders was published in the **Federal** Register as a notice of proposed rulemaking (NPRM) on May 21, 1998 (63 FR 27870). The NPRM proposed to require replacing the propeller shaft, the bearings, and the front drive belt retaining rings with parts of improved design. Accomplishment of the proposed action as specified in the NPRM would be in accordance with DG Flugzeugbau Technical Note No. 826/ 32, dated July 19, 1996, and DG Flugzeugbau WORKING INSTRUCTION No. 1 for TN 826/32, dated July, 1996.

The NPRM was the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

#### The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

#### **Cost Impact**

The FAA estimates that 35 gliders in the U.S. registry will be affected by this AD, that it will take approximately 5 workhours per glider to accomplish this action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$460 per glider. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$26,600, or \$760 per glider.

#### **Compliance Time of this AD**

The compliance time of this AD is in calendar time instead of hours time-inservice (TIS). The average monthly usage of the affected glider ranges throughout the fleet. For example, one owner may operate the glider 25 hours TIS in one week, while another operator may operate the glider 25 hours TIS in one year. In order to ensure that all of the owners/operators of the affected glider have replaced the propeller shaft, bearings and front drive belt retaining rings within a reasonable amount of time, the FAA is utilizing a compliance

time of 4 calendar months after the effective date of this AD.

#### **Regulatory Impact**

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

## **98–17–03 Glaser-Dirks Flugzeugbau GMBH:** Amendment 39–10705; Docket No. 98–CE–07–AD.

Applicability: Model DG-400 gliders, all serial numbers, certificated in any category.

**Note 1:** This AD applies to each glider identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For gliders that have been modified, altered, or repaired so that the performance of the

requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 4 calendar months after the effective date of this AD, unless already accomplished.

To prevent failure of the propeller shaft caused by an ineffective design, which could result in loss of glider propulsion during critical phases of flight, accomplish the following:

(a) Replace the propeller shaft, the bearings, and the front drive belt retaining rings with parts of improved design in accordance with paragraph 2 of the Instructions section of DG Flugzeugbau Technical Note No. 826/32, dated July 19, 1996, and WORKING INSTRUCTION No. 1 for TN 826/32, dated July, 1996.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the glider to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) Questions or technical information related to DG Flugzeugbau Technical Note No. 826/32, dated July 19, 1996, and DG Flugzeugbau WORKING INSTRUCTION No. 1 for TN 826/32, dated July, 1996, should be directed to DG Flugzeugbau GmbH, P.O. Box 4120, 76625 Bruchsal, Germany; telephone: +49 7257–89–0; facsimile: +49 7257–8922. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(e) The replacements required by this AD shall be done in accordance with DG Flugzeugbau Technical Note No. 826/32, dated July 19, 1996, and DG Flugzeugbau WORKING INSTRUCTION No. 1 for TN 826/ 32, dated July, 1996. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from DG Flugzeugbau GmbH, P.O. Box 4120, 76625 Bruchsal, Germany. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in German AD 96–243 DG-Flugzeugbau, dated August 29, 1996.

(f) This amendment becomes effective on September 26, 1998.

Issued in Kansas City, Missouri, on August 4, 1998.

#### Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–21493 Filed 8–11–98; 8:45 am] BILLING CODE 4910–13–U

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 71

[Airspace Docket No. 98-AWP-3]

# Modification of Class E Airspace; Fortuna, CA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

SUMMARY: This action modifies the Class E airspace area at Fortuna, CA. Additional controlled airspace extending upward from 700 feet or more above the surface of the earth is needed to contain aircraft executing the Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 29 at Rohnerville Airport. The intended effect of this action is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Rohnerville Airport, Fortuna. CA.

**EFFECTIVE DATE:** 0901 UTC October 8, 1998.

#### FOR FURTHER INFORMATION CONTACT:

Larry Tonish, Airspace Specialist, Airspace Branch, AWP–520, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California 90261, telephone (310) 725–6539.

#### SUPPLEMENTARY INFORMATION:

#### History

On July 13, 1998, the FAA proposed to amend 14 CFR part 71 by modifying the Class E airspace area at Fortuna, CA (63 FR 37510). Additional controlled airspace extending upward from 700 feet above the surface is needed to contain aircraft executing the GPS RWY 29 SIAP at Rohnerville Airport. This action will provide adequate controlled airspace for IFR operations at Rohnerville Airport, Fortuna, CA.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments to the proposal were received. Class E airspace designations for airspace extending from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9E dated September 10, 1997, and effective September 16, 1997, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

#### The Rule

This amendment to 14 CFR part 71 modifies the Class E airspace area at Fortuna, CA. The development of a GPS SIAP has made this action necessary. The effect of this action will provide adequate airspace for aircraft executing the GPS RWY 29 SIAP at Rohnerville Airport, Fortuna, CA.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### **Adoption of the Amendment**

In consideration of the foregoing, the Federal Administration amends 14 CFR part 71 as follows:

#### PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389; 14 CFR 11.69.

#### §71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9E, Airspace Designations and Reporting Points, dated September 10, 1997, and effective