

**PART 39—AIRWORTHINESS  
DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

**98-18-17 McDonnell Douglas:** Amendment 39-10733. Docket 98-NM-10-AD.

**Applicability:** All Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) series airplanes; and Model MD-88 and MD-90-30 airplanes; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the tailcone emergency evacuation slide to deploy automatically due to incorrect diameter of the swaged balls on the wire rope of the harness assembly, accomplish the following:

(a) Within 180 days after the effective date of this AD, perform a one-time inspection of the harness assembly of the tailcone emergency evacuation slide to determine the diameter of the swaged balls; in accordance with McDonnell Douglas Alert Service Bulletin MD80-25A364 [for Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) series airplanes, and Model MD-88 airplanes]; or MD90-25A030 (for Model MD-90-30 airplanes); both dated October 30, 1997.

(1) If the swaged balls are within the limits specified in the applicable alert service bulletin, prior to further flight, reidentify and reinstall the harness assembly in accordance with the applicable alert service bulletin.

(2) If the swaged balls are outside the limits specified in the applicable alert service bulletin, prior to further flight, replace the harness assembly having part number (P/N) 8370024-3 with a new harness assembly having P/N 8370024-9 or 8370024-3H, as applicable, in accordance with the applicable alert service bulletin.

(b) As of the effective date of this AD, no person shall install a harness assembly, (P/N) 8370024-3, on any airplane.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los

Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) The actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD80-25A364, dated October 30, 1997, or McDonnell Douglas Alert Service Bulletin MD90-25A030, dated October 30, 1997, as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from The Boeing Company, Douglas Products Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on October 8, 1998.

Issued in Renton, Washington, on August 26, 1998.

**Vi L. Lipski,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 98-23603 Filed 9-2-98; 8:45 am]

**BILLING CODE 4910-13-U**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. 98-NM-01-AD; Amendment 39-10732; AD 98-18-16]**

**RIN 2120-AA64**

**Airworthiness Directives; Airbus Model A320 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), applicable to certain Airbus Model A320-111, -211, -212, and -231 series airplanes, that currently requires reinforcement of the tail section of the

fuselage at frames 68 and 69. This amendment adds a requirement for reinforcement of the tail section of the fuselage at frames 65 to 67. This action also revises the applicability of the existing AD. This amendment is prompted by reports indicating that the tail section has struck the runway during takeoffs and landings. The actions specified by this AD are intended to prevent structural damage to the tail section when it strikes the runway, which could result in depressurization of the fuselage during flight.

**DATES:** Effective October 8, 1998.

The incorporation by reference of Airbus Service Bulletin A320-53-1110, Revision 1, dated November 27, 1995, and Airbus Service Bulletin A320-53-1131, dated July 24, 1997, as listed in the regulations, is approved by the Director of the Federal Register as of October 8, 1998.

The incorporation by reference of Airbus Service Bulletin A320-53-1110, dated August 28, 1995, was approved previously by the Director of the Federal Register as of May 15, 1997 (62 FR 17532, April 10, 1997).

**ADDRESSES:** The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 97-08-04, amendment 39-9992 (62 FR 17532, April 10, 1997), which is applicable to certain Airbus Model A320-111, -211, -212, and -231 series airplanes, was published in the **Federal Register** on July 9, 1998 (63 FR 37078). The action proposed to supersede AD 97-08-04 to continue to require reinforcement of the tail section of the fuselage at frames 68 and 69. It also proposed to add a requirement for reinforcement of the tail section of the fuselage at frames 65 to 67. The action also proposed to revise the applicability of the existing AD.

## Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

## Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

## Cost Impact

There are approximately 118 airplanes of U.S. registry that will be affected by this AD.

The actions that are currently required by AD 97-08-04, and retained in this AD, take approximately 196 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$1,387,680, or \$11,760 per airplane.

The new actions that are required by this new AD will take approximately 488 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the new requirements of this AD on U.S. operators is estimated to be \$3,455,040, or \$29,280 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

## Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-9992 (62 FR 17532, April 10, 1997), and by adding a new airworthiness directive (AD), amendment 39-10732, to read as follows:

**98-18-16 Airbus Industrie:** Amendment 39-10732. Docket 98-NM-01-AD. Supersedes AD 97-08-04, Amendment 39-9992.

**Applicability:** Model A320 series airplanes on which Airbus Modification 22764 has not been installed, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of

the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent structural damage to the tail section when it strikes the runway, which could result in depressurization of the fuselage during flight, accomplish the following:

## Restatement of Requirement of AD 97-08-04

(a) For airplanes listed in Airbus Service Bulletin A320-53-1110, dated August 28, 1995: Within 6 years after May 15, 1997 (the effective date of AD 97-08-04, amendment 39-9992), modify the fuselage by reinforcing frames 68 and 69 in accordance with Airbus Service Bulletin A320-53-1110, dated August 28, 1995; or Revision 1, dated November 27, 1995.

## New Requirements of this AD

(b) For airplanes other than those identified in paragraph (a) of this AD: Within 5 years after the effective date of this AD, modify the fuselage by reinforcing frames 68 and 69 in accordance with Airbus Service Bulletin A320-53-1110, dated August 28, 1995, or Revision 1, dated November 27, 1995.

(c) For all airplanes: Within 5 years after the effective date of this AD, modify the fuselage by reinforcing frames 65 to 67 in accordance with Airbus Service Bulletin A320-53-1131, dated July 24, 1997.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) The modifications shall be done in accordance with Airbus Service Bulletin A320-53-1131, dated July 24, 1997; Airbus Service Bulletin A320-53-1110, dated August 28, 1995; and Airbus Service Bulletin A320-53-1110, Revision 1, dated November 27, 1995, which contains the following list of effective pages:

Page No.	Revision level shown on page	Date shown on page
1-8, 10-13, 15-20, 23-40, 42, 44-45	Original	August 28, 1995.

Page No.	Revision level shown on page	Date shown on page
9, 14, 21–22, 41, 43 .....	Revision 1 .....	November 27, 1995.

(1) The incorporation by reference of Airbus Service Bulletin A320–53–1110, Revision 1, dated November 27, 1995, and Airbus Service Bulletin A320–53–1131, dated July 24, 1997, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Airbus Service Bulletin A320–53–1110, dated August 28, 1995, was approved previously by the Director of the Federal Register as of May 15, 1997 (62 FR 17532, April 10, 1997).

(3) Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in French airworthiness directive 97–315–109(B), dated October 22, 1997.

(g) This amendment becomes effective on October 8, 1998.

Issued in Renton, Washington, on August 26, 1998.

**Vi L. Lipski,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 98–23604 Filed 9–2–98; 8:45 am]

BILLING CODE 4910–13–U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98–NM–183–AD; Amendment 39–10743; AD 94–13–02 R1]

RIN 2120–AA64

#### **Airworthiness Directives; Boeing Model 757–200, –200PF, and –200CB Series Airplanes Equipped with Rolls-Royce Model RB211–535E4/E4B Engines**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment revises an existing airworthiness directive (AD), applicable to certain Boeing Model 757 series airplanes, that currently requires tests of the thrust reverser system, and repair, if necessary; installation of a modification that terminates those tests; and repetitive operational checks of that installation, and repair, if necessary.

This amendment limits the applicability of the existing AD by including the specific series of the affected airplanes. This amendment is prompted by the upcoming type certification of the Model 757–300 series airplane, which will address the requirements of this amendment during the type certification process. The actions specified in this AD are intended to prevent deployment of a thrust reverser in flight and subsequent reduced controllability of the airplane.

**DATES:** September 18, 1998.

The incorporation by reference of certain publications, as listed in the regulations, was approved previously by the Director of the Federal Register as of July 20, 1994 (59 FR 31512, June 20, 1994).

Comments for inclusion in the Rules Docket must be received on or before November 2, 1998.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 98–NM–183–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.

The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124–2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Katherine Rask, Aerospace Engineer, Propulsion Branch, ANM–140S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–1547; fax (425) 227–1181.

**SUPPLEMENTARY INFORMATION:** On June 13, 1994, the FAA issued AD 94–13–02, amendment 39–8942 (59 FR 31512, June 20, 1994), applicable to certain Boeing Model 757 series airplanes, to require tests of the thrust reverser system, and repair, if necessary; installation of a modification that terminates those tests; and repetitive operational checks of that installation, and repair, if necessary. That action was prompted by results of a safety review, which revealed that in-flight deployment of a thrust reverser

could result in a significant reduction in the controllability of the airplane. The actions required by that AD are intended to prevent deployment of a thrust reverser in flight and subsequent reduced controllability of the airplane.

#### **Actions Since Issuance of Previous Rule**

Since the issuance of that AD, Boeing has developed the Model 757–300 series airplane, equipped with Rolls-Royce Model RB211–535E4/E4B engines. This model is expected to be type certificated in early 1999. As part of the type certification of the Model 757–300 series airplane, the requirements of this amendment will be addressed during the type certification process. Therefore, the FAA has revised the applicability of the existing AD to include the specific series of the affected airplanes as Model 757–200 series airplanes.

#### **Explanation of Requirements of Proposed Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, this AD revises AD 94–13–02 to continue to require tests of the thrust reverser system, and repair, if necessary; installation of a modification that terminates those tests; and repetitive operational checks of that installation, and repair, if necessary. This AD limits the applicability of the existing AD by including the specific series of the affected airplanes.

#### **Cost Impact**

There are approximately 376 Model 757–200 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 95 airplanes of U.S. registry will be required to accomplish the restow and integrity tests required by this AD, that it will take approximately 1 work hour per airplane to accomplish those tests, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators to accomplish each operational test is estimated to be \$5,700, or \$60 per airplane.

The FAA estimates that 95 airplanes of U.S. registry will be required to accomplish either modification specified in paragraphs (b)(1) or (b)(2) of this AD. It will take approximately 506 work hours per airplane to accomplish either of those modifications, and the