

FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-20-15 Saab Aircraft AB: Amendment 39-10782. Docket 98-NM-176-AD.

Applicability: Model SAAB 340B series airplanes, manufacturer serial numbers 380 through 499 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a short circuit caused by fluid leakage, which could result in inability to retract the landing gear or require the use of emergency extension, accomplish the following:

(a) Within 400 flight hours after the effective date of this AD, accomplish the actions required by paragraphs (a)(1), (a)(2), (a)(3), and (a)(4) of this AD, in accordance with Saab Service Bulletin 340-32-115, dated April 7, 1998, or Revision 01, dated

August 12, 1998. As of the effective date of this AD, Revision 01 of the service bulletin shall be used.

(1) Perform a detailed visual inspection to detect moisture or other contamination of the electrical wiring harness above relay consoles 305VU and 306VU. If any moisture or other contamination is found, prior to further flight, clean the wiring harness.

(2) Perform a detailed visual inspection to detect moisture or other contamination of electrical relay 15GA and its socket. If any moisture or other contamination is found, prior to further flight, accomplish corrective actions.

(3) Perform a detailed visual inspection for electrical damage of electrical relay 15GA and its socket. If any sign of electrical damage (arcing, discoloration, or charring) is detected, prior to further flight, replace the existing relay and socket with new parts.

(4) Replace the existing nut plates on the floor of the cockpit with new, improved nut plates, on the left and right sides of the airplane.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The actions shall be done in accordance with Saab Service Bulletin 340-32-115, dated April 7, 1998, or Saab Service Bulletin 340-32-115, Revision 01, dated August 12, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Swedish airworthiness directive SAD 1-125, dated April 7, 1998.

(e) This amendment becomes effective on October 27, 1998.

Issued in Renton, Washington, on September 14, 1998.

Dorenda D. Baker,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-25121 Filed 9-21-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-172-AD; Amendment 39-10781; AD 98-20-14]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Bombardier Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 series airplanes, that requires a one-time inspection to detect chafing of electrical wires in the cable trough below the cabin floor; repair, if necessary; installation of additional tie-mounts and tie-wraps; and application of sealant to rivet heads. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent chafing of electrical wires, which could result in an uncommanded shutdown of an engine during flight.

DATES: Effective October 27, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 27, 1998.

ADDRESSES: The service information referenced in this AD may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Peter Cuneo, Senior Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York

11581; telephone (516) 256-7506; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Bombardier Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 series airplanes was published in the **Federal Register** on July 31, 1998 (63 FR 40852). That action proposed to require a one-time inspection to detect chafing of electrical wires in the cable trough below the cabin floor; repair, if necessary; installation of additional tie-mounts and tie-wraps; and application of sealant to rivet heads.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Explanation of Change Made to This Final Rule

The FAA has revised the final rule to reflect a change of the manufacturer's name from de Havilland to Bombardier.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule with the change previously described. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of this AD.

Cost Impact

The FAA estimates that 225 airplanes of U.S. registry will be affected by this AD.

For the 210 Model DHC-8-102, -103, -106, -201, and -202 series airplanes affected, it will take approximately 70 work hours per airplane to accomplish the required actions, at an average labor rate of \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the required AD for these airplanes on U.S. operators is estimated to be \$882,000, or \$4,200 per airplane.

For the 15 Model DHC-8-301, -311, and -315 series airplanes affected, it will take approximately 100 work hours per airplane to accomplish the required actions, at an average labor rate of \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the required AD for these airplanes on U.S. operators is

estimated to be \$90,000, or \$6,000 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-20-14 Bombardier, Inc. (Formerly de Havilland, Inc.): Amendment 39-10781. Docket 98-NM-172-AD.

Applicability: Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 series

airplanes; serial numbers 3 through 519 inclusive, excluding serial number 462; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent chafing of electrical wires, which could result in an uncommanded shutdown of an engine during flight, accomplish the following:

(a) Within 36 months after the effective date of this AD, perform a one-time visual inspection to detect chafing of electrical wires in the cable trough below the cabin floor; install additional tie-mounts and tie-wraps; and apply sealant to rivet heads (reference Bombardier Modification 8/2705); in accordance with Bombardier Service Bulletin S.B. 8-53-66, dated March 27, 1998. If any chafing is detected during the inspection required by this paragraph, prior to further flight, repair in accordance with the service bulletin.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The actions shall be done in accordance with Bombardier Service Bulletin S.B. 8-53-66, dated March 27, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Canadian airworthiness directive CF-98-08, dated March 26, 1998.

(e) This amendment becomes effective on October 27, 1998.

Issued in Renton, Washington, on September 14, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-25119 Filed 9-21-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-246-AD; Amendment 39-10750; AD 98-19-08]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Airbus Model A321 series airplanes. This action requires revising the Airplane Flight Manual (AFM) to prohibit automatic landings and Category III operations on runways with a magnetic orientation of 170 degrees through 190 degrees inclusive. This amendment also provides for optional terminating action for the AFM revision. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified in this AD are intended to prevent the use of erroneous automatic roll-out guidance generated by the flight management and guidance computer, which could result in the airplane departing the runway upon landing.

DATES: Effective October 7, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 7, 1998.

Comments for inclusion in the Rules Docket must be received on or before October 22, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-246-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, recently notified the FAA that an unsafe condition may exist on certain Airbus Model A321 series airplanes. The DGAC advises that the flight management and guidance computer (FMGC) can generate erroneous roll-out guidance due to software calculation errors. The software calculation errors may affect the roll-out guidance generated by the FMGC when an automatic landing is performed on runways with a magnetic orientation of 170 degrees through 190 degrees inclusive. Use of erroneous automatic roll-out guidance, if not corrected, could result in the airplane departing the runway upon landing.

Explanation of Relevant Service Information

Airbus has issued A319/320/321 Airplane Flight Manual (AFM) Temporary Revision (TR) 9.99.99/44, Issue 2, dated March 3, 1998, which prohibits automatic landings and Category III operations on runways with a magnetic orientation of 170 degrees through 190 degrees inclusive.

Airbus also has issued Service Bulletins A320-22-1054, Revision 01, dated December 3, 1997 (for airplanes equipped with CFM engines); and A320-22-1062, dated October 6, 1997 (for airplanes equipped with IAE engines); which describe procedures for modifying the flight management and guidance computer software. Accomplishment of the software modifications eliminates the need for the AFM revision. Accomplishment of the actions specified in the AFM revision or service bulletins is intended to adequately address the identified unsafe condition.

The DGAC classified Airbus A319/320/321 AFM TR 9.99.99/44, Issue 2, dated March 3, 1998, as mandatory and issued French airworthiness directive

98-226-119(B), dated June 17, 1998, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD is being issued to prevent the use of erroneous automatic roll-out guidance generated by the flight management and guidance computer, which could result in the airplane departing the runway upon landing. This AD requires revising the Limitations Section of the FAA-approved AFM to prohibit automatic landings and Category III operations on runways with a magnetic orientation of 170 degrees through 190 degrees inclusive. This AD also provides for optional terminating action for the AFM revision.

Interim Action

This is considered to be interim action until final action is identified, at which time the FAA may consider further rulemaking.

Determination of Rule's Effective Date

Since this AD action does not affect any airplane that is currently on the U.S. register, it has no adverse economic impact and imposes no additional burden on any person. Therefore, prior notice and public procedures hereon are unnecessary and the amendment may be made effective in less than 30 days after publication in the **Federal Register**.

Cost Impact

None of the airplanes affected by this action are on the U.S. Register. All airplanes included in the applicability of this rule currently are operated by non-U.S. operators under foreign registry; therefore, they are not directly affected by this AD action. However, the