

repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the levers and bracket assembly, which could result in uncommanded retraction of the inner flap assembly and consequent reduced controllability of the airplane, accomplish the following:

(a) Within 90 days after the effective date of this AD: Perform a visual inspection of the levers and bracket assembly of the inner flap sub-assembly of the left and right wings to detect discrepancies (i.e., corrosion, cracking, protective coating breakdown, and inadequate clearances between the forward face of the lower levers and the bracket web), in accordance with the applicable Shorts service bulletin specified below, all dated January 14, 1997:

- SD360-27-26 (for Model SD3-60 series airplanes);
- SD360 Sherpa 27-1 (for Model SD3-60 SHERPA series airplanes);
- SD3 Sherpa 27-2 (for Model SD3 SHERPA series airplanes); and
- SD3-27-36 (for Model SD3-30 series airplanes).

(1) If no discrepancy is detected, repeat the visual inspection thereafter at intervals not to exceed 4,800 flight hours or 24 months, whichever occurs earlier.

(2) If any discrepancy is detected, prior to further flight, rework the affected area, and accomplish follow-on corrective actions, in accordance with the applicable service bulletin.

(i) If the reworked parts remain within the allowable rework limits specified in the applicable service bulletin, repeat the visual inspection of the levers and bracket assembly thereafter at intervals not to exceed 1,200 flight hours or 6 months, whichever occurs earlier.

(ii) If any reworked part is outside the allowable rework limits specified in the applicable service bulletin, prior to further flight, replace the reworked part with a new part. Thereafter, repeat the inspection at intervals not to exceed 4,800 flight hours or 24 months, whichever occurs earlier.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The actions shall be done in accordance with the Shorts service bulletins specified below, as applicable:

- SD360-27-26, dated January 14, 1997;
- SD360 Sherpa 27-1, dated January 14, 1997;
- SD3 Sherpa 27-2, dated January 14, 1997; and
- SD3-27-36, dated January 14, 1997.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Short Brothers, Airworthiness & Engineering Quality, P.O. Box 241, Airport Road, Belfast BT3 9DZ, Northern Ireland. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in British airworthiness directives 008-01-97, 010-01-97, 011-01-97, and 009-01-97.

(e) This amendment becomes effective on November 10, 1998.

Issued in Renton, Washington, on September 28, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-26392 Filed 10-5-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-173-AD; Amendment 39-10812; AD 98-21-04]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to all Dornier Model 328-100 series airplanes, that currently requires repetitive visual inspections for signs of fuel leakage on the outer wing beginning with Rib 21 and continuing outward; and corrective action, if necessary. This amendment adds a requirement for modification of the lower panels of the outer wing area, which terminates the repetitive inspection requirements. This action also limits the applicability of the

existing AD. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent fuel leakage on the outboard wing, which could result in a fuel explosion and fire.

DATES: Effective November 10, 1998.

The incorporation by reference of Dornier Service Bulletin SB-328-57-255, dated January 21, 1998, as listed in the regulations, is approved by the Director of the Federal Register as of November 10, 1998.

The incorporation by reference of Dornier Alert Service Bulletin ASB-328-57-020, dated October 28, 1997, was approved previously by the Director of the Federal Register as of February 25, 1998 (63 FR 6642, February 10, 1998).

ADDRESSES: The service information referenced in this AD may be obtained from Fairchild Dornier, Dornier Luftfahrt GmbH, P.O. Box 1103, D-82230 Wessling, Germany. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 98-04-06, amendment 39-10319 (63 FR 6642, February 10, 1998), which is applicable to all Dornier Model 328-100 series airplanes, was published in the **Federal Register** on August 13, 1998 (63 FR 43347). The action proposed to continue to require repetitive visual inspections for signs of fuel leakage of the outer wing beginning with Rib 21 and continuing outward; and corrective action, if necessary. The action also proposed to add a requirement for modification of the lower panels of the outer wing area, which would terminate the repetitive inspection requirements. In addition, the action proposed to limit the applicability of the existing AD.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response

to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 50 airplanes of U.S. registry that will be affected by this AD.

The repetitive inspection that is currently required by AD 98-04-06, and retained in this AD, takes approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the currently required inspection on U.S. operators is estimated to be \$6,000, or \$120 per airplane, per inspection cycle.

The new modification that is required in this AD action takes approximately 7 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the modification required by this AD on U.S. operators is estimated to be \$21,000, or \$420 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10319 (63 FR 6642, February 10, 1998), and by adding a new airworthiness directive (AD), amendment 39-10812, to read as follows:

98-21-04 Dornier Luftfahrt GMBH:

Amendment 39-10812. Docket 98-NM-173-AD. Supersedes AD 98-04-06, amendment 39-10319.

Applicability: Model 328-100 series airplanes, serial numbers 3005 through 3098 inclusive, excluding serial number 3089; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fuel leakage on the outboard wing, which could result in a fuel explosion and fire, accomplish the following:

Restatement of Requirements of AD 98-04-06

(a) Within 30 days after February 25, 1998 (the effective date of AD 98-04-06, amendment 39-10319), perform a visual inspection of the left- and right-hand outer wings, beginning with Rib 21 and continuing outward, for signs of fuel leakage, in accordance with Dornier Alert Service Bulletin ASB-328-57-020, dated October 28, 1997. If any sign of fuel leakage is detected, prior to further flight, re-seal the respective fuel tank in accordance with the alert service bulletin. Repeat the inspection at intervals

not to exceed 1,500 flight hours or 6 months, whichever occurs first, until the actions required by paragraph (b) of this AD are accomplished.

New Requirements of this AD

(b) Within 6 months after the effective date of this AD, drill a drainhole in the lower panels of the left- and right-hand outer wings, in accordance with Dornier Service Bulletin SB-328-57-255, dated January 21, 1998. Accomplishment of the requirements of this paragraph constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD.

(c)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

(2) Alternative methods of compliance, approved previously in accordance with AD 98-04-06, amendment 39-10319, are approved as alternative methods of compliance with this AD.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) The actions shall be done in accordance with Dornier Alert Service Bulletin ASB-328-57-020, dated October 28, 1997, and Dornier Service Bulletin SB-328-57-255, dated January 21, 1998.

(1) The incorporation by reference of Dornier Service Bulletin SB-328-57-255, dated January 21, 1998, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Dornier Alert Service Bulletin ASB-328-57-020, dated October 28, 1997, was approved previously by the Director of the Federal Register as of February 25, 1998 (63 FR 6642, February 10, 1998).

(3) Copies may be obtained from Fairchild Dornier, Dornier Luftfahrt GmbH, P.O. Box 1103, D-82230 Wessling, Germany. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in German airworthiness directive 1998-218, dated May 7, 1998.

(f) This amendment becomes effective on November 10, 1998.

Issued in Renton, Washington, on September 28, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-26393 Filed 10-5-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-168-AD; Amendment 39-10811; AD 98-21-03]

RIN 2120-AA64

Airworthiness Directives; British Aerospace (Jetstream) Model 4101 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain British Aerospace (Jetstream) Model 4101 airplanes, that requires replacement of the existing load limitation labels located in the main baggage compartment with new reduced load limitation labels. This amendment also provides for optional modification of the internal access door of the main baggage compartment, which, if accomplished, terminates the requirement for reduced load limitations. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent failure of the internal access door latches of the main baggage compartment in the event of an emergency landing, which could delay or impede passenger evacuation due to baggage spilling into the aisle and blocking the emergency exit door.

DATES: Effective November 10, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of November 10, 1998.

ADDRESSES: The service information referenced in this AD may be obtained from AI(R) American Support, Inc., 13850 Mclearen Road, Herndon, Virginia 20171. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain British Aerospace (Jetstream) Model 4101 airplanes was published in the **Federal Register** on August 13, 1998 (63 FR 43345). That action proposed to require replacement of the existing load limitation labels located in the main baggage compartment with new reduced load limitation labels. That action also provides for optional modification of the internal access door of the main baggage compartment, which, if accomplished, would terminate the requirement for reduced load limitations.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 57 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required replacement, and that the average labor rate is \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the replacement required by this AD on U.S. operators is estimated to be \$3,420, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in

accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-21-03 British Aerospace Regional

Aircraft [Formerly Jetstream Aircraft Limited; British Aerospace (Commercial Aircraft) Limited]; Amendment 39-10811. Docket 98-NM-168-AD.

Applicability: Jetstream Model 4101 airplanes, as listed in Jetstream Service Bulletin J41-11-010, dated August 9, 1997; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not