

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on October 5, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-27603 Filed 10-14-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-250-AD]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Mark 0100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Fokker Model F.28 Mark 0100 series airplanes. This proposal would require modification of the aft cabin sidewall area to improve decompression venting. For certain airplanes, this proposal also would require modification of the aft wardrobe/stowage area door and installation of decompression panels to improve decompression venting. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent damage to the cabin floor in the event of sudden decompression in the cargo compartment, which could result in injury to passengers, reduced structural integrity of the airplane, and the loss of airplane systems.

DATES: Comments must be received by November 16, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-250-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this

location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Fokker Services B.V., Technical Support Department, P.O. Box 75047, 1117 ZN Schiphol Airport, the Netherlands. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-250-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-250-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Rijksluchtvaartdienst (RLD), which is the airworthiness authority for

the Netherlands, notified the FAA that an unsafe condition may exist on certain Fokker Model F.28 Mark 0100 series airplanes. The RLD advises that the decompression venting provisions in the aft cabin sidewall area and in the aft wardrobe/stowage area are inadequate in reducing the pressure differential between the passenger and cargo compartments in the event of a sudden decompression of the cargo compartment. Such inadequate reduction in the pressure differential could result in damage to the cabin floor. This condition, if not corrected, could result in injury to passengers, reduced structural integrity of the airplane, and loss of airplane systems.

Explanation of Relevant Service Information

Fokker has issued Service Bulletin SBF100-25-082, Revision 1, dated May 7, 1998, which describes procedures for modification of the aft cabin sidewall area to improve decompression venting. For airplanes equipped with an aft service/emergency door, Fokker also has issued Service Bulletin SBF100-25-083, dated April 30, 1998, which describes procedures for modification of the aft wardrobe/stowage area door and installation of decompression panels to improve decompression venting.

Accomplishment of the actions specified in these service bulletins is intended to adequately address the identified unsafe condition. The RLD classified these service bulletins as mandatory and issued Dutch airworthiness directive BLA 1998-065 (A), dated May 29, 1998, in order to assure the continued airworthiness of these airplanes in the Netherlands.

FAA's Conclusions

This airplane model is manufactured in the Netherlands and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the RLD has kept the FAA informed of the situation described above. The FAA has examined the findings of the RLD, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same

type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously.

Cost Impact

The FAA estimates that 127 airplanes of U.S. registry would be affected by this proposed AD.

For all airplanes, it would take approximately 12 work hours per airplane to accomplish the proposed modification of the aft cabin sidewall area, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$3,450 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$529,590, or \$4,170 per airplane.

For airplanes equipped with an aft service/emergency door (70 airplanes), it would take approximately 6 work hours per airplane to accomplish the modification of the aft wardrobe/stowage area door and installation of decompression panels, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$9,000 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$655,200, or \$9,360 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this

action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Fokker Services B.V.: Docket 98–NM–250–AD.

Applicability: Model F.28 Mark 0100 series airplanes, serial numbers 11244 through 11504 inclusive, 11506, 11507, 11509, 11512 through 11515 inclusive, 11517, 11519, 11520, 11522, 11523, and 11527; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent damage to the cabin floor in the event of sudden decompression in the cargo compartment, which could result in injury to passengers, reduced structural integrity of the airplane, and the loss of airplane systems, accomplish the following:

(a) For airplanes listed in Fokker Service Bulletin SBF100–25–082, Revision 1, dated May 7, 1998: Within 26 months after the effective date of this AD, modify the aft cabin sidewall area to improve decompression venting in accordance with Fokker Service Bulletin SBF100–25–082, Revision 1, dated May 7, 1998.

(b) For airplanes listed in Fokker Service Bulletin SBF100–25–083, dated April 30, 1998: Within 26 months after the effective

date of this AD, modify the aft wardrobe/stowage area door and install decompression panels to improve decompression venting in accordance with Fokker Service Bulletin SBF100–25–083, dated April 30, 1998.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Dutch airworthiness directive BLA 1998–065 (A), dated May 29, 1998.

Issued in Renton, Washington, on October 5, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–27602 Filed 10–14–98; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98–NM–239–AD]

RIN 2120–AA64

Airworthiness Directives; Saab Model SAAB 2000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Saab Model SAAB 2000 series airplanes. This proposal would require replacement of the end-pieces of the expansion chamber attenuator (ECA) for the standby pump of the Number 2 hydraulic system with new, improved end-pieces. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent leakage of hydraulic fluid from the Number 2