

implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-25-53 Airbus Industrie: Amendment 39-10956. Docket 98-NM-361-AD.

Applicability: All Model A300 B4-600R and A300 F4-600R series airplanes; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect damage to the fuel pump and fuel pump canister, which could result in loss of flame trap capability and could provide a fuel ignition source in the center tank, accomplish the following:

(a) Perform a one-time visual inspection for damage of the center fuel pumps and fuel pump canisters, in accordance with Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998. Perform the inspection at the time specified in paragraph (a)(1), (a)(2), (a)(3), or (a)(4) of this AD, as applicable.

(1) For airplanes that have accumulated 20,000 or more total hours time-in-service as of the effective date of this AD: Inspect within 10 flight cycles after the effective date of this AD.

(2) For airplanes that have accumulated 12,000 or more total hours time-in-service, but less than 20,000 total hours time-in-service, as of the effective date of this AD: Inspect within 100 hours time-in-service after the effective date of this AD.

(3) For airplanes that have accumulated 4,500 or more total hours time-in-service, but less than 12,000 total hours time-in-service as of the effective date of this AD: Inspect within 500 hours time-in-service after the effective date of this AD.

(4) For airplanes that have accumulated less than 4,500 total hours time-in-service as of the effective date of this AD: Inspect prior to the accumulation of 4,500 total hours time-in-service, or within 500 hours time-in-service after the effective date of this AD, whichever occurs later.

(b) If any damage is detected during the inspection required by paragraph (a) of this AD, prior to further flight, replace the damaged fuel pump or fuel pump canister with a new or serviceable part in accordance with Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998.

(c) Within 5 days after accomplishing the inspection required by this AD or within 5 days after the effective date of this AD, whichever occurs later: Report inspection findings, positive or negative, to Airbus, Mr. F. Poveda, AI/SE-E31, Sita Code TLSBW7X, fax number +33/(0)5.61.93.32.73. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB control number 2120-0056.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR

21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) The inspection and replacement shall be done in accordance with Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in French telegraphic airworthiness directive T98-476-272(B), dated November 30, 1998.

(g) This amendment becomes effective on December 28, 1998, to all persons except those persons to whom it was made immediately effective by telegraphic AD T98-25-53, issued on December 4, 1998.

Issued in Renton, Washington, on December 15, 1998.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-33692 Filed 12-21-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-75-AD; Amendment 39-10960; AD 98-26-17]

RIN 2120-AA64

Airworthiness Directives; British Aerospace Jetstream Model 3201 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all British Aerospace Jetstream Model 3201 airplanes. This AD requires accomplishing both a routine visual inspection and either a detailed visual inspection or x-ray inspection of the main landing gear (MLG) bay auxiliary spar booms for cracks or fuel leaks on both the left and right sides of the airplane. This AD also requires obtaining and incorporating repair procedures for the MLG bay auxiliary spar where fuel leaks or cracks are found. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by this

AD are intended to prevent wing failure caused by cracks or fuel leaks in the area of the MLG bay auxiliary spar booms, which could result in loss of control of the airplane.

DATES: Effective February 5, 1999.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 5, 1999.

ADDRESSES: Service information that applies to this AD may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-75-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. S.M. Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6932; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Events Leading to the Issuance of This AD

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all British Aerospace Jetstream Model 3201 airplanes was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on October 13, 1998 (63 FR 54635). The NPRM proposed to require accomplishing both a routine visual inspection and either a detailed visual inspection or x-ray inspection of the MLG bay auxiliary spar booms for cracks or fuel leaks on both the left and right sides of the airplane. The NPRM proposed to also require obtaining and incorporating repair procedures for the MLG bay auxiliary spar where fuel leaks or cracks are found. Accomplishment of the proposed actions as specified in the NPRM would be required in accordance with British Aerospace Jetstream Alert Service Bulletin 57-A-JA 980441, ORIGINAL ISSUE: April 28, 1998, REVISION NO. 1: July 7, 1998.

The NPRM was the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

Compliance Time of This AD

Although the cracks on the MLG bay auxiliary spar booms could occur as a result of repetitive airplane operation, the FAA believes that the residual stresses in the component are originating from a manufacturing fault during the machining/heat treatment stages. The cracks could exist, but not be noticed, after just a few hours of airplane operation. The stress incurred during flight operations or temperature changes could then cause rapid crack growth. In order to assure that even very small cracks in the MLG bay auxiliary spar booms do not go undetected, the FAA is utilizing a compliance based on calendar time.

Cost Impact

The FAA estimates that 124 airplanes in the U.S. registry will be affected by this AD.

Accomplishing the routine visual inspection required in this AD will take approximately 1 workhour per airplane, at an average labor rate of approximately \$60 an hour. Based on these figures, the total cost impact of the routine visual inspection on U.S. operators is estimated to be \$7,440, or \$60 per airplane.

Accomplishing the detailed visual inspection required in this AD will take approximately 16 workhours per airplane, at an average labor rate of \$60 per hour. Accomplishing the x-ray inspection required in this AD will take approximately 12 workhours per airplane, at an average labor rate of approximately \$60 an hour. Based on these figures, the total cost impact of the detailed inspection on U.S. operators is estimated to be \$119,040, or \$960 per airplane, and \$89,280, or \$720 per airplane for the x-ray inspection.

These figures only take into account the costs of inspections and do not take

into account the costs for repairing any MLG bay auxiliary spar boom where fuel leaks or cracks are found during the inspections.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

98-26-17 British Aerospace: Amendment 39-10960; Docket No. 98-CE-75-AD.

Applicability: Jetstream Model 3201 airplanes, all serial numbers, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For

airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent wing failure caused by cracks or fuel leaks in the area of the main landing gear (MLG) bay auxiliary spar booms, which could result in loss of control of the airplane, accomplish the following:

(a) Within the next 45 calendar days after the effective date of this AD, accomplish the following:

(1) Perform a routine visual inspection of the MLG bay auxiliary spar booms for cracks or fuel leaks on both the left and right sides of the airplane. Accomplish this inspection in accordance with Part 1 of the Accomplishment Instructions section of British Aerospace Jetstream Alert Service Bulletin 57-A-JA 980441, Original Issue: April 28, 1998, Revision No. 1: July 7, 1998.

(2) Perform either a detailed visual inspection or x-ray inspection of the MLG bay auxiliary spar booms for cracks or fuel leaks on both the left and right sides of the airplane. Accomplish this inspection in accordance with Part 2 of the Accomplishment Instructions section of British Aerospace Jetstream Alert Service Bulletin 57-A-JA 980441, Original Issue: April 28, 1998, Revision No. 1: July 7, 1998.

(b) If cracks or leaks are found during any inspection required by paragraphs (a)(1) and (a)(2) of this AD, prior to further flight, accomplish the following:

(1) Obtain repair instructions from the manufacturer through the FAA, Small Airplane Directorate, at the address specified in paragraph (d) of this AD; and

(2) Incorporate these repair instructions.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(e) Questions or technical information related to British Aerospace Jetstream Alert Service Bulletin 57-A-JA 980441, Original

Issue: April 28, 1998, Revision No. 1: July 7, 1998, should be directed to British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(f) The inspections required by this AD shall be done in accordance with British Aerospace Jetstream Alert Service Bulletin 57-A-JA 980441, Original Issue: April 28, 1998, Revision No. 1: July 7, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in British AD 001-04-98, dated May 7, 1998.

(g) This amendment becomes effective on February 5, 1999.

Issued in Kansas City, Missouri, on December 15, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-33689 Filed 12-21-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 95

[Docket No. 29418; Amdt. No. 413]

IFR Altitudes; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts miscellaneous amendments to the required IFR (instrument flight rules) altitudes and changeover points for certain Federal airways, jet routes, or direct routes for which a minimum or maximum en route authorized IFR altitude is prescribed. This regulatory action is needed because of changes occurring in the National Airspace System. These changes are designed to provide for the safe and efficient use of the navigable airspace under instrument conditions in the affected areas.

EFFECTIVE DATE: 0901 UTC, January 28, 1999.

FOR FURTHER INFORMATION CONTACT: Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420),

Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 95 of the Federal Aviation Regulations (14 CFR part 95) amends, suspends, or revokes IFR altitudes governing the operation of all aircraft in flight over a specified route or any portion of that route, as well as the changeover points (COPs) for Federal airways, jet routes, or direct routes as prescribed in part 95.

The Rule

The specified IFR altitudes, when used in conjunction with the prescribed changeover points for those routes, ensure navigation aid coverage that is adequate for safe flight operations and free of frequency interference. The reasons and circumstances that create the need for this amendment involve matters of flight safety and operational efficiency in the National Airspace System, are related to published aeronautical charts that are essential to the user, and provide for the safe and efficient use of the navigable airspace. In addition, those various reasons or circumstances require making this amendment effective before the next scheduled charting and publication date of the flight information to assure its timely availability to the user. The effective date of this amendment reflects those considerations. In view of the close and immediate relationship between these regulatory changes and safety in air commerce, I find that notice and public procedure before adopting this amendment are impracticable and contrary to the public interest and that good cause exists for making the amendment effective in less than 30 days. The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current.

It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities