

(i) Expiration of a contract or agreement with a vendor and the State agency's determination regarding participant access shall not be subject to administrative review; and

(ii) Disqualification of a vendor as a result of disqualification from the Food Stamp Program shall not be subject to administrative or judicial review.

* * * * *

(3) Except for disqualifications assessed under § 246.12(k)(1)(i), which shall be made effective on the date of receipt of the notice of administrative action, the State agency may take adverse action against a vendor after the 15-day advance notification period mandated by paragraph (b)(1) of this section has elapsed. * * *

(b) * * *

(1) Written notification of the administrative action, the procedures to file for an administrative review, if any, the cause(s) for and the effective date of the action. Such notification shall be provided to participating vendors not less than 15 days in advance of the effective date of the action. When a vendor is disqualified due in whole or in part to violations specified in § 246.12(k)(1), such notification shall include the following statement: "This disqualification from WIC may result in disqualification as a retailer in the Food Stamp Program. Such disqualification may not be subject to administrative or judicial review under the Food Stamp Program." In the case of disqualification of local agencies, the State agency shall provide not less than 60 days advance notice of pending action.

* * * * *

Dated: March 12, 1999.

Samuel Chambers, Jr.,
Administrator.

[FR Doc. 99-6465 Filed 3-17-99; 8:45 am]

BILLING CODE 3410-30-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-92-AD; Amendment 39-11075; AD 99-06-11]

RIN 2120-AA64

Airworthiness Directives; British Aerospace HP137 Mk1, Jetstream Series 200, and Jetstream Models 3101 and 3201 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes. This AD requires inspecting the elevator bias spring assembly for correct installation and to assure that the correctly manufactured bias spring is installed. This AD also requires replacing any incorrectly manufactured bias spring, reworking any incorrectly installed bias spring assembly, inspecting the link assembly for distortion or damage, and replacing any distorted and/or damaged parts. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by this AD are intended to prevent failure of the bearings in the elevator down bias spring assembly caused by the installation of an incorrectly manufactured bias spring or damage or distortion to the assembly, which could result in reduced or loss of control of the airplane.

DATES: Effective April 26, 1999.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 26, 1999.

ADDRESSES: Service information that applies to this AD may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-92-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. S.M. Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6932; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Events Leading to the Issuance of This AD

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes was published in the **Federal Register** as a notice of proposed rulemaking (NPRM)

on December 8, 1998 (63 FR 67631). The NPRM proposed to require inspecting the elevator bias spring assembly for correct installation and to assure that the correctly manufactured bias spring is installed. The NPRM also proposed to require replacing any incorrectly manufactured bias spring, reworking any incorrectly installed bias spring assembly, inspecting the link assembly for distortion or damage, and replacing any distorted and/or damaged parts. Accomplishment of the proposed actions as specified in the NPRM would be in accordance with Jetstream Alert Service Bulletin 27-A-JA980606, Original Issue: July 6, 1998, Revision 1: July 31, 1998.

The NPRM was the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

Cost Impact

The FAA estimates that 350 airplanes in the U.S. registry will be affected by this AD, that it will take approximately 1 workhour per airplane to accomplish this action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$40 per airplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$35,000, or \$100 per airplane.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism

implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

99-06-11 British Aerospace: Amendment 39-11075; Docket No. 98-CE-92-AD.

Applicability: HP137 Mk1, Jetstream Series 200, and Jetstream Models 3101 and 3201 airplanes, all serial numbers, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent failure of the bearings in the elevator down bias spring assembly caused

by the installation of an incorrectly manufactured bias spring or damage or distortion to the assembly, which could result in reduced or loss of control of the airplane, accomplish the following:

(a) Within the next 100 hours time-in-service after the effective date of this AD, inspect the elevator bias spring assembly for correct installation and to assure that the correctly manufactured bias spring is installed, in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Jetstream Alert Service Bulletin 27-A-JA980606, Original Issue: July 6, 1998, Revision 1: July 31, 1998.

(b) If an incorrectly manufactured bias spring is installed or the elevator bias spring assembly is incorrectly installed, prior to further flight, accomplish the following in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Jetstream Alert Service Bulletin 27-A-JA980606, Original Issue: July 6, 1998, Revision 1: July 31, 1998.

(1) Rework any incorrectly installed bias spring assembly;

(2) Replace any incorrectly manufactured bias spring; and

(3) Inspect the link assembly for distortion or damage, and replace any distorted and/or damaged parts.

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(e) Questions or technical information related to British Aerospace Jetstream Alert Service Bulletin 27-A-JA980606, (Original Issue: July 6, 1998) Revision 1: July 31, 1998, should be directed to British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(f) The inspections, modifications, and replacements required by this AD shall be done in accordance with Jetstream Alert Service Bulletin 27-A-JA980606, Original Issue: July 6, 1998, Revision 1: July 31, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. Copies may be

inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in British Aerospace Jetstream Alert Service Bulletin 27-A-JA980606, Original Issue: July 6, 1998, Revision 1: July 31, 1998. This service bulletin is classified as mandatory by the United Kingdom Civil Aviation Authority (CAA).

(g) This amendment becomes effective on April 26, 1999.

Issued in Kansas City, Missouri, on March 5, 1999.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-6101 Filed 3-17-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-102-AD; Amendment 39-11076; AD 99-06-12]

RIN 2120-AA64

Airworthiness Directives; British Aerospace HP137 Mk1, Jetstream Series 200, and Jetstream Models 3101 and 3201 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes. This AD requires replacing the nose wheel steering jack seals with seals of an improved design. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by this AD are intended to prevent the nose landing gear steering from locking up due to deterioration of the original design nose landing gear steering jack seals, which could result in reduced or loss of control of the airplane during takeoff, landing, and taxi operations.

DATES: Effective April 26, 1999.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 26, 1999.

ADDRESSES: Service information that applies to this AD may be obtained from