

Model	Serial Nos.
SA227-TT	TT421 through TT541.
SA227-TT(300)	TT(300)447, TT(300)465, TT(300)471, TT(300)483, TT(300)512, TT(300)518, TT(300)521, TT(300)527, TT(300)529, and TT(300)536.
SA227-AC	AC406, AC415, AC416, and AC420 through AC785.
SA227-AT	AT423 through AT631 and AT695.
SA227-BC	BC762, BC764, BC766, and BC770 through BC789.
SA227-CC/DC	CC/DC784 and CC/DC790 through CC/DC896.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To detect and correct fatigue cracking of the wing spar center web cutout area, which could result in structural failure of the wing spar to the point of failure with consequent loss of control of the airplane, accomplish the following:

(a) Upon accumulating 6,500 hours time-in-service (TIS) on each wing spar; within the next 2,000 hours TIS after the last inspection accomplished per the applicable Airworthiness Limitations Manual (referenced in the paragraphs below); or within the next 500 hours TIS after the effective date of this AD, whichever occurs later, unless already accomplished (accomplishment of AD 99-06-02, including any FAA-approved alternative methods of compliance with AD 99-06-02); and thereafter at intervals not to exceed 2,000 hours TIS, inspect each wing spar center web cutout for cracks between Wing Station (WS) 8 and WS 17.5. Accomplish this inspection in accordance with one of the following, as applicable:

(1) *For Models SA227-TT, SA227-AT, SAA227-AC, and SA227-BC airplanes:* In accordance with Fairchild Airframe Airworthiness Limitations Manual ST-UN-M001, Rev. No. C-6, dated April 7, 1998;

(2) *For Models SA226-T, SA226-T(B), SA226-AT, and SA226-TC airplanes:* In accordance with Fairchild Airframe Inspection Manual ST-UN-M002, Rev. No. A-6, dated December 8, 1997; or

(3) *For Models SA227-CC and SA227-DC airplanes:* In accordance with Fairchild Airframe Airworthiness Limitations Manual ST-UN-M003, Rev. No. 5, dated April 7, 1998.

(b) If any crack(s) is/are found during any inspection required by paragraph (a) of this AD, prior to further flight, repair the crack(s) in accordance with one of the following, as applicable. This repair eliminates the

repetitive inspections (2,000 hours TIS intervals) required in paragraph (a) of this AD for that particular wing spar.

(1) *For Models SA226-T, SA226-T(B), SA226-AT, SA226-TC, SA227-TT, SA227-AT, SA227-AC, and SA227-BC airplanes:* In accordance with Fairchild SA226/227 Series Structural Repair Manual, part number (P/N) 27-10054-079, pages 57 through 90; Initial Issue: March 1, 1983; Revision 28, dated June 24, 1998; or

(2) *For Models SA227-CC and SA227-DC airplanes:* In accordance with Fairchild SA227 Series Structural Repair Manual, P/N 27-10054-127, pages 47 through 60; Initial Issue: December 1, 1991; Revision 7, dated June 24, 1998.

(c) The repetitive inspections required by paragraph (a) of this AD may be terminated if the wing spar center web repair specified in paragraph (b) of this AD has been accomplished on both the left and right wing spar. If one wing spar center web has been repaired, then repetitive inspections are still required on the other one if the repair has not been incorporated.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, FAA, Airplane Certification Office (ACO), 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150.

(1) The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Fort Worth ACO.

(2) Alternative methods of compliance approved in accordance with AD 99-06-02 are considered approved as alternative methods of compliance for this AD.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Fort Worth ACO.

(f) All persons affected by this directive may obtain copies of the documents referred to herein upon request to Field Support Engineering, Fairchild Aircraft, Inc., P.O. Box 790490, San Antonio, Texas 78279-0490; or may examine these documents at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(g) This amendment supersedes AD 99-06-02, Amendment 39-11066.

Issued in Kansas City, Missouri, on April 15, 1999.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-10170 Filed 4-22-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-115-AD]

RIN 2120-AA64

Airworthiness Directives; British Aerospace HP137 Mk1, Jetstream Series 200, and Jetstream Models 3101 and 3201 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes. The proposed AD would require repetitively removing the nose landing gear steering selector valve and installing either a new nose landing gear steering selector valve or one that has been overhauled in accordance with the appropriate component maintenance manual. The proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by the proposed AD are intended to prevent the inability to steer the airplane because of wear in the nose landing gear steering selector differential, which could result in loss of control of the airplane during take-off, landing, or taxi operations.

DATES: Comments must be received on or before May 28, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-

115-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. S.M. Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6932; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-115-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-115-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

The Civil Airworthiness Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes. The CAA reports a recent incident where the operator of one of the affected airplanes lost control while the airplane was on the ground and veered off the runway. Investigation of this incident revealed an unacceptable amount of free play in the nose landing gear steering linkage because of an excessive amount of wear in the steering selector differential.

This condition, if not corrected in a timely manner, could result in loss of control of the airplane during take-off, landing, or taxi operations.

Relevant Service Information

British Aerospace has issued the following:

- Jetstream Service Bulletin 32-JA980841, Original Issue: October 28, 1998, which specifies removing the nose landing gear steering selector valve and installing either a new nose landing gear steering selector valve or one that has been overhauled in accordance with the appropriate component maintenance manual; and
- Jetstream Alert Service Bulletin 32-A-JA980840, Original Issue: October 28, 1998, Revision No. 2: December 17, 1998, which specifies procedures for inspecting the nose wheel steering system to assure that the free play between the steering handle or knob and the nose wheels is within acceptable limits, and adjusting as necessary.

The CAA classified these service bulletins as mandatory in order to assure the continued airworthiness of these airplanes in the United Kingdom. The CAA classifying a service bulletin as mandatory is the same in the United Kingdom as the FAA issuing an AD in the United States.

The FAA's Determination

These airplane models are manufactured in the United Kingdom and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above.

The FAA has examined the findings of the CAA; reviewed all available

information, including the service information referenced above; and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of the Provisions of the Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop in other British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes of the same type design registered in the United States, the FAA is proposing AD action. The proposed AD would require repetitively removing the nose landing gear steering selector valve and installing either a new nose landing gear steering selector valve or one that has been overhauled in accordance with the appropriate component maintenance manual. Accomplishment of the proposed action would be in accordance with the applicable maintenance manual, as specified in British Aerospace Jetstream Service Bulletin 32-JA980841, Original Issue: October 28, 1998.

The FAA is proposing in another action (Docket No. 98-CE-117-AD) a one-time inspection of the nose wheel steering system to assure that the free play between the steering handle or knob and the nose wheels is within acceptable limits, with adjustment as necessary.

Cost Impact

The FAA estimates that 350 airplanes in the U.S. registry would be affected by the proposed initial replacement, that it would take approximately 4 workhours per airplane to accomplish the proposed action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$2,500 per airplane. Based on these figures, the total cost impact of the proposed initial replacement on U.S. operators is estimated to be \$959,000, or \$2,740 per airplane.

These figures only take into account the cost of the initial overhaul or replacement and do not take into account the cost of subsequent overhauls or replacements. The FAA has no way of determining the number of overhauls or replacements that each owner/operator of the affected airplanes would incur over the life of his/her airplane.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and

the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

British Aerospace: Docket No. 98-CE-115-AD.

Applicability: HP137 Mk1, Jetstream Series 200, and Jetstream Models 3101 and 3201 airplanes, all serial numbers, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not

been eliminated, the request should include specific proposed actions to address it.

Compliance: Upon accumulating 10,000 hours time-in-service (TIS) on the nose landing gear selector valve or within the next 12 calendar months after the effective date of this AD, whichever occurs later, unless already accomplished; and thereafter each time 10,000 hours TIS is accumulated on a nose landing gear selector valve.

To prevent the inability to steer the airplane because of wear in the nose landing gear steering selector differential, which could result in loss of control of the airplane during take-off, landing, or taxi operations, accomplish the following:

(a) Remove the nose landing gear steering selector valve, part number (P/N) 8668C or AIR86002-0 (or FAA-approved equivalent part number), and install one of the following in accordance with the applicable maintenance manual, as specified in British Aerospace Jetstream Service Bulletin 32-JA980841, Original Issue: October 28, 1998:

- (1) A new steering selector valve, P/N 8668C or AIR86002-0 (or FAA-approved equivalent part number); or
- (2) An FAA-approved nose landing gear steering selector valve that has been overhauled in accordance with the appropriate component maintenance manual.

Note 2: The FAA is proposing in another action (Docket No. 98-CE-117-AD) a one-time inspection of the nose wheel steering system to assure that the free play between the steering handle or knob and the nose wheels is within acceptable limits, with adjustment as necessary.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) Questions or technical information related to British Aerospace Jetstream Service Bulletin 32-JA980841, Original Issue: October 28, 1998, should be directed to British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Note 4: The subject of this AD is addressed in British Aerospace Jetstream Alert Service Bulletin 32-JA980841, Original Issue:

October 28, 1998. This service bulletin is classified as mandatory by the United Kingdom Civil Aviation Authority (CAA).

Issued in Kansas City, Missouri, on April 15, 1999.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-10168 Filed 4-22-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-371-AD]

RIN 2120-AA64

Airworthiness Directives; Lockheed Model 382 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Lockheed Model 382 series airplanes. This proposal would require a one-time visual inspection of the under floor to ring fittings at fuselage station 817E to verify installation of the correct sized fasteners; and follow-on corrective actions, if necessary. This proposal is prompted by notification from the manufacturer indicating that during production incorrect sized fasteners were installed on the under floor to ring fittings at fuselage station 817E. The actions specified by the proposed AD are intended to prevent fatigue cracking of the fastener holes and adjacent fuselage structure due to installation of the incorrect sized fasteners, which could result in reduced structural integrity of the airplane.

DATES: Comments must be received by June 7, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-371-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Lockheed Martin Aeronautical Systems Support Company (LMASSC), Field Support Department, Dept. 693, Zone