

believed that the undersized rule change was needed to expedite that reduction. With the excess tonnage of dried prunes, the Committee also considered establishing a reserve pool and diversion program to reduce the oversupply situation. These initiatives were not supported because they would not specifically eliminate the smallest, least valuable prunes which are in oversupply. Instead, the reserve pool and diversion program would eliminate larger size prunes from human consumption outlets. Reserve pools for prunes have historically been implemented on dried prunes regardless of the size of the prunes. While the marketing order also allows handlers to remove the larger prunes from the pool by replacing them with small prunes and the value difference in cash, this exchange would be cumbersome and expensive to administer compared to this rule.

Section 8e of the Act requires that when certain domestically produced commodities, including prunes, are regulated under a Federal marketing order, imports of that commodity must meet the same or comparable grade, size, quality, or maturity requirements for the domestically produced commodity. This action does not impact the dried prune import regulation because the action to be implemented is for volume control, not quality control, purposes. The smaller diameter openings of $2\frac{3}{32}$ of an inch for French prunes and $2\frac{8}{32}$ of an inch for non-French prunes were implemented for the purpose of improving product quality. The increases to $2\frac{4}{32}$ of an inch in diameter for French prunes and $3\frac{0}{32}$ of an inch in diameter for non-French prunes are for purposes of volume control.

Therefore, the increased diameters will not be applied to imported prunes.

This action will not impose any additional reporting or recordkeeping requirements on either small or large California dried prune handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies. In addition, as noted in the initial regulatory flexibility analysis, the Department has not identified any relevant Federal rules that duplicate, overlap, or conflict with this rule.

In addition, the Committee's meeting was widely publicized throughout the prune industry and all interested persons were invited to attend the meeting and participate in Committee deliberations on all issues. Like all Committee meetings, the December 1,

1998, meeting was a public meeting and all entities, both large and small, were able to express views on this issue. The Committee itself is composed of twenty-two members, of which seven are handlers, fourteen are producers, and one is a public member. Moreover, the Committee and its Supply Management Subcommittee have been reviewing this supply management problem for the second year, and this rule reflects their deliberations completely.

A proposed rule concerning this action was published in the **Federal Register** on January 25, 1999 (64 FR 3660). Copies of this rule were mailed or sent via facsimile to all Committee members, alternates and dried prune handlers. Finally, the rule was made available through the Internet by the U.S. Government Printing Office. The rule provided a comment period which ended April 15, 1999. No comments were received.

After consideration of all relevant material presented, including the information and recommendation submitted by the Committee and other available information, it is hereby found that this rule, as hereinafter set forth, will tend to effectuate the declared policy of the Act.

List of Subjects in 7 CFR Part 993

Marketing agreements, Plums, Prunes, Reporting and recordkeeping requirements.

For the reasons set forth in the preamble, 7 CFR part 993 is amended as follows:

PART 993—DRIED PRUNES PRODUCED IN CALIFORNIA

1. The authority citation for 7 CFR part 993 continues to read as follows:

Authority: 7 U.S.C. 601–674.

2. A new § 993.406 is added to read as follows:

Note: This section will not appear in the Code of Federal Regulations.

§ 993.406 Undersized prune regulation for the 1999–2000 crop year.

Pursuant to §§ 993.49(c) and 993.52, an undersized prune regulation for the 1999–2000 crop year is hereby established. Undersized prunes are prunes which pass through openings as follows: For French prunes, $2\frac{4}{32}$ of an inch in diameter; for non-French prunes, $3\frac{0}{32}$ of an inch in diameter.

Dated: April 27, 1999.

Robert C. Keeney,

Deputy Administrator, Fruit and Vegetable Programs.

[FR Doc. 99–11078 Filed 5–3–99; 8:45 am]

BILLING CODE 3410–02–P

NUCLEAR REGULATORY COMMISSION

10 CFR Part 50

RIN 3150–AF96

Codes and Standards: IEEE National Consensus Standard; Correction

AGENCY: Nuclear Regulatory Commission.

ACTION: Final rule: Correction.

SUMMARY: This document corrects a final rule appearing in the **Federal Register** on April 13, 1999 (64 FR 17944), that incorporates by reference IEEE Std. 603–1991, a national consensus standard for power, instrumentation, and control portions of safety systems in nuclear power plants. This action is necessary to correct an erroneous reference.

EFFECTIVE DATE: The final rule is effective on May 13, 1999.

FOR FURTHER INFORMATION CONTACT: Michael T. Lesar, **Federal Register** Liaison Officer, telephone (301) 415–7163.

SUPPLEMENTARY INFORMATION: On page 17946, in the third column, in the codified text at § 50.55a(h)(1), on the fourteenth and twenty-first lines from the top, and at § 50.55a(h)(2) on the twenty-eighth line from the top “Std. 279–1971” should be corrected to read “Std. 279.”

Dated at Rockville, Maryland, this 28th day of April, 1999.

For the Nuclear Regulatory Commission.

Annette L. Vietti-Cook,

Secretary of the Commission.

[FR Doc. 99–11111 Filed 5–3–99; 8:45 am]

BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98–NM–202–AD; Amendment 39–11151; AD 99–09–18]

RIN 2120–AA64

Airworthiness Directives; Fokker Model F.28 Mark 0070 and Mark 0100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to certain Fokker Model F.28 Mark 0070 and Mark 0100 series

airplanes, that currently requires a one-time inspection for heat damage of the fuselage skin and stubwing structure; either repetitive tests of certain seals or repair of heat damage, as necessary; and eventual replacement of corrugated seals with new, improved seals. This amendment adds a requirement for repetitive inspections for heat damage of the subject area, and provides for a new optional terminating action for the repetitive inspections. This action is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent leakage of hot air from the corrugated seals of certain valves in the stubwings, and subsequent heat damage of the fuselage skin and stubwing structure, which could result in reduced structural integrity of the airplane.

DATES: Effective June 8, 1999.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the **Federal Register** as of June 8, 1999.

The incorporation by reference of certain other publications as listed in the regulations, was approved previously by the Director of the **Federal Register** as of May 14, 1998 (63 FR 17318, April 9, 1998).

ADDRESSES: The service information referenced in this AD may be obtained from Fokker Services B.V., Technical Support Department, P.O. Box 75047, 1117 ZN Schiphol Airport, the Netherlands. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the **Federal Register**, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 98-08-01, amendment 39-10450 (63 FR 17318, April 9, 1998), which is applicable to certain Fokker Model F.28 Mark 0070 and Mark 0100 series airplanes, was published in the **Federal Register** on November 10, 1998 (63 FR 62970). The action proposed to continue to require a one-time visual inspection to detect heat damage of the fuselage skin and

stubwing structure; either repetitive leak tests of the seals of the bleed air system or repair of any heat-damaged structure, as necessary; and replacement of corrugated seals with new, improved seals. Additionally, that action proposed to require repetitive inspections of the fuselage skin and stubwing connection angles to detect heat damage, and an additional detailed inspection of the fuselage and stubwing structure and repair when heat damage is detected. That action also proposed to provide for a new optional terminating action for the repetitive inspections.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Support for the Proposal

One commenter supports the proposal.

Request to Delay Requiring Repetitive Testing

One commenter, an airline operator, requests that data derived from the initial inspection mandated by AD 98-08-01, which has a May 1999 compliance time, be analyzed before a decision is made in regard to the need for additional testing.

The commenter states that it has no objection to accomplishing the repetitive inspections specified in the proposal, if they are required. However, the commenter contends that mandating those repetitive inspections at this time would be acting prematurely, since all data from the initial inspections are not available to analyze.

The FAA does not concur with the commenter's request to delay requiring repetitive inspections. The Rijksluchtvaartdienst (RLD), which is the airworthiness authority for the Netherlands, advised the FAA that a sufficient number of operators have already accomplished the one-time inspection described in Fokker Service Bulletin SBF100-53-084, dated July 6, 1996 (the referenced source of service information in the proposal and AD 98-08-01). Consequently, the RLD included requirements for repetitive inspections in Revision 3 of the Dutch airworthiness directive BLA 1995-076/3 (A), dated November 28, 1997, to ensure continued airworthiness. That revision is referenced in this AD.

Therefore, the FAA has determined that the repetitive inspections required by this AD are necessary in order to adequately address the identified unsafe condition. However, as specified in paragraph (h) of this AD, operators have the option of modifying the airplane in

accordance with Fokker Proforma Service Bulletin F100-36-027, dated March 21, 1997, which would provide terminating action for the repetitive inspection requirements of this AD.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 141 Fokker Model F.28 Mark 0070 and Mark 0100 series airplanes of U.S. registry that will be affected by this AD.

The one-time visual inspection that is currently required by AD 98-08-01, and retained in this AD, takes approximately 3 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the one-time inspection requirement of this AD on U.S. operators is estimated to be \$180 per airplane.

The seal replacement that is currently required by AD 98-08-01, and retained in this AD, takes approximately 7 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts cost approximately \$80 per airplane. Based on these figures, the cost impact of the seal replacement requirement of this AD on U.S. operators is estimated to be \$500 per airplane.

The new actions that are required by this new AD will take approximately 3 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the new requirements of this AD on U.S. operators is estimated to be \$25,380, or \$180 per airplane, per inspection cycle.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10450 (63 FR 17318, April 9, 1998), and by adding a new airworthiness directive (AD), amendment 39-11151, to read as follows:

99-09-18 Fokker Services B.V.:

Amendment 39-11151. Docket 98-NM-202-AD. Supersedes AD 98-08-01, Amendment 39-10450.

Applicability: Model F.28 Mark 0070 and Mark 0100 series airplanes equipped with any corrugoint seal having part number (P/N) BE20061 (Rolls-Royce P/N 3405891) or on which Fokker Proforma Service Bulletin SBF100-36-027, including Appendix I, both dated March 21, 1997, has not been accomplished; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (i)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by

this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent leakage of hot air from the corrugoint seals of the low- and high-pressure check valves located in the stubwings, and subsequent heat damage of fuselage skin and stubwing structure adjacent to bleed air system components in the stubwings, which could result in reduced structural integrity of the airplane, accomplish the following:

Restatement of Requirements of AD 98-08-01, Amendment 39-10450:

(a) For Model F28 Mark 0070 and Mark 0100 series airplanes as listed in Fokker Service Bulletin SBF100-53-084, dated July 6, 1996; if equipped with any corrugoint seal having P/N BE20061 (Rolls-Royce P/N 3405891): Within 3,000 flight hours or 12 months after May 14, 1998 (the effective date of AD 98-08-01, amendment 39-10450), whichever occurs first, perform a one-time visual inspection of the fuselage skin in the left- and right-hand stubwings to detect heat damage; in accordance with Part 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-084, dated July 6, 1996.

(b) If no heat damage is found during the inspection required by paragraph (a) of this AD, prior to further flight, accomplish either paragraph (b)(1) or (b)(2) of this AD.

(1) Replace all corrugoint seals having P/N BE20061 (Rolls-Royce P/N 3405891) at the 7th stage low-pressure and 12th stage high-pressure check valves of the left- and right-hand bleed air systems with new, improved corrugoint seals having P/N EU15969, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-36-026, Revision 1, dated July 6, 1996.

(2) Perform a leak test of each corrugoint seal at the 7th stage low-pressure and 12th stage high-pressure check valves of the left- and right-hand bleed air systems, in accordance with Part 3 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-084, dated July 6, 1996.

(i) If any leakage is found at a seal, prior to further flight, replace that seal with a new, improved seal having part number EU15969, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-36-026, Revision 1, dated July 6, 1996.

(ii) If no leakage is found at a seal, perform an additional leak test of that seal within 250 flight hours after the initial test.

(A) If no leakage is found during the additional test of the seal, within 3,000 flight hours after the additional test, replace the seal with an improved seal having P/N EU15969, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-36-026, Revision 1, dated July 6, 1996.

(B) If any leakage is found during the additional test of the seal, prior to further flight, replace the seal with a new, improved seal having P/N EU15969, in accordance with the Accomplishment Instructions of Fokker

Service Bulletin SBF100-36-026, Revision 1, dated July 6, 1996; and inspect the fuselage skin in the applicable left- or right-hand stubwing to detect heat damage, in accordance with Part 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-084, dated July 6, 1996.

(c) If any heat damage is found during the inspection required by paragraph (a) or paragraph (b)(2)(ii)(B) of this AD, prior to further flight, perform a detailed inspection of the fuselage skin and stubwing structure to detect the extent of heat damage, in accordance with Parts 4 and 5 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-084, dated July 6, 1996; and accomplish paragraphs (c)(1) and (c)(2) of this AD.

(1) Except as provided by paragraph (g) of this AD: Repair the affected structure in accordance with Part 6 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-084, dated July 6, 1996. And

(2) Replace all corrugoint seals having P/N BE20061 (Rolls-Royce P/N 3405891) at the 7th stage low-pressure and 12th stage high-pressure check valves of the left- and right-hand bleed air systems with new, improved corrugoint seals having P/N EU15969, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-36-026, Revision 1, dated July 6, 1996.

(d) As of May 14, 1998, no person shall install a corrugoint seal having P/N BE20061 (Rolls-Royce P/N 3405891) on any airplane.

New Requirements for This AD

(e) For Model F.28 Mark 0070 and Mark 0100 series airplanes on which Fokker Proforma Service Bulletin SBF100-36-027, including Appendix I, both dated March 21, 1997, has not been accomplished: Perform a visual inspection of the fuselage skin in the left- and right-hand stubwings to detect heat damage, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-087, dated November 17, 1997, at the latest of the times specified in paragraphs (e)(1), (e)(2), and (e)(3) of this AD, as applicable. Repeat the inspection required by paragraph (e) of this AD thereafter at intervals not to exceed 6,000 landings.

(1) Within 6,000 landings after the effective date of this AD.

(2) Within 6 months after the effective date of this AD.

(3) Within 6,000 landings after accomplishment of the inspection required by paragraph (a) of this AD.

(f) If any heat damage is detected during any inspection required by paragraph (e) of this AD, prior to further flight, perform a detailed visual inspection to determine the extent of heat damage, in accordance with paragraph 2.B.(2) of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-087, dated November 17, 1997. Except as provided by paragraph (g) of this AD, prior to further flight, repair in accordance with the service bulletin.

Note 2: Fokker Service Bulletin SBF100-53-087, dated November 17, 1997, refers to

Fokker Service Bulletin SBF100-53-084, dated July 6, 1996, as an additional source of service information for the detailed inspection procedures, repair limits, and repair procedures.

(g) If any damage is found during accomplishment of any action specified by paragraph (c)(1) or (f) of this AD, and Fokker Service Bulletin SBF100-53-084, dated July 6, 1996, or Fokker Service Bulletin SBF100-53-087, dated November 17, 1997, specifies to contact the manufacturer for an appropriate action: Prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the RLD (or its delegated agent).

(h) Installation of new heat shields, relocation of the aft bay overheat switch, and replacement of the insulation blankets of the bleed air ducts with new, improved insulation blankets, in accordance with Fokker Proforma Service Bulletin SBF100-36-027, including Appendix I, both dated March 21, 1997, constitutes terminating action for the repetitive inspection requirements of paragraph (e) of this AD.

Alternative Method of Compliance

(i)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

(2) Alternative methods of compliance, approved previously in accordance with AD 98-08-01, amendment 39-10450, are approved as alternative methods of compliance with paragraphs (a), (b), and (c) of this AD.

(3) Airplanes repaired in accordance with alternative methods of compliance, approved previously in accordance with AD 98-08-01, amendment 39-10450, are not considered exempt from the repetitive inspection requirements of paragraph (e) of this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(j) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(k) Except for the actions specified in paragraphs (g) and (h) of this AD, the actions shall be done in accordance with Fokker Service Bulletin SBF100-53-084, dated July 6, 1996; Fokker Service Bulletin SBF100-36-026, Revision 1, dated July 6, 1996; or Fokker Service Bulletin SBF100-53-087, dated November 17, 1997. The terminating action specified in paragraph (h) of this AD, if accomplished, shall be accomplished in

accordance with Fokker Proforma Service Bulletin SBF100-36-027, including Appendix I, both dated March 21, 1997.

(1) The incorporation by reference of Fokker Service Bulletin SBF100-53-087, dated November 17, 1997; and Fokker Proforma Service Bulletin SBF100-36-027, including Appendix I, both dated March 21, 1997; is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Fokker Service Bulletin SBF100-53-084, dated July 6, 1996; and Fokker Service Bulletin SBF100-36-026, Revision 1, dated July 6, 1996; was approved previously by the Director of the Federal Register as of May 14, 1998 (63 FR 17318, April 9, 1998).

(3) Copies may be obtained from Fokker Services B.V., Technical Support Department, P.O. Box 75047, 1117 ZN Schiphol Airport, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in Dutch airworthiness directive 1995-076/3 (A), dated November 28, 1997.

(l) This amendment becomes effective on June 8, 1999.

Issued in Renton, Washington, on April 21, 1999.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 99-10605 Filed 5-3-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-50-AD; Amendment 39-11152; AD 99-09-19]

RIN 2120-AA64

Airworthiness Directives; Aerospatiale Model ATR42 and ATR72 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to all Aerospatiale Model ATR42 and ATR72 series airplanes. This action requires revising the Airplane Flight Manual to provide the flightcrew with modified procedures and limitations for operating in severe icing conditions. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority.

The actions specified in this AD are intended to prevent the airplane from stalling due to prolonged exposure to severe icing conditions, which could result in reduced performance and controllability of the airplane.

DATES: Effective May 19, 1999.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 19, 1999.

Comments for inclusion in the Rules Docket must be received on or before June 3, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-50-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on all Aerospatiale Model ATR42 and ATR72 series airplanes. The DGAC advises that during an in-flight incident an ATR airplane stalled in severe icing conditions and lost 4,000 feet of altitude before recovery.

Experience has shown that the currently recommended airspeeds in icing conditions provide adequate stall margins when flying in normal icing conditions, but provide little margin to stall speeds when the airplane has accreted a large amount of ice following prolonged flight in severe icing conditions. The current procedures in the FAA-approved Airplane Flight Manual (AFM) require immediate exit when severe icing conditions are detected. However, even if the exit maneuver is initiated immediately, a few minutes may elapse before the airplane is out of the severe icing conditions. Late detection of severe icing conditions and nonapplication or