

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Fredrick A. Guerin, Aerospace Engineer, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone: (562) 627-5232; facsimile: (562) 627-5210.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Eagle Service Bulletin No. 1059, dated January 21, 1999, and Eagle Service Bulletin No. 1076, Rev. 2, dated December 14, 1999. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Eagle Aircraft Pty. Ltd., Lot 700 Cockburn Road, Henderson WA 6166 Australia. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on June 29, 2001.

**Note 2:** The subject of this AD is addressed in Australian AD Number X-TS/2, effective December 24, 2000.

Issued in Kansas City, Missouri, on May 1, 2001.

**James E. Jackson,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-11457 Filed 5-9-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-NM-85-AD; Amendment 39-12222; AD 2001-09-15]

**RIN 2120-AA64**

#### **Airworthiness Directives; Boeing Model 737-200 and -300 Series Airplanes Equipped with Cargo Doors Installed in Accordance With Supplemental Type Certificate (STC) SA2969SO**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), applicable to certain Boeing Model 737-200 and -300 series airplanes, that

currently requires repetitive inspections to detect cracking in the radii on the support angles on the lower jamb (latch lug fittings) of the main deck cargo door, and replacement of cracked parts. This amendment adds a requirement for installation of redesigned lower jamb latch support angles in the main cargo door surround structure, which would terminate the repetitive inspections. This amendment is prompted by the development of a modification that will provide better protection of the subject area against effects of structural fatigue. The actions specified by this AD are intended to prevent in-flight separation of the main deck cargo door from the airplane due to fatigue cracking on the support angles on the lower door jamb.

**DATES:** Effective June 14, 2001.

The incorporation by reference of Pemco Service Bulletin 737-53-0003, Revision 4, dated February 22, 1995; and Pemco Service Bulletin 737-53-0003, Revision 5, dated March 25, 1999; as listed in the regulations, is approved by the Director of the Federal Register as of June 14, 2001.

The incorporation by reference of Pemco Alert Service Letter 737-53-0003, Revision 3, dated December 22, 1994, as listed in the regulations, was approved previously by the Director of the Federal Register as of January 24, 1995 (60 FR 2323, January 9, 1995).

**ADDRESSES:** The service information referenced in this AD may be obtained from Pemco Aeroplex, Inc., P.O. Box 2287, Birmingham, Alabama 35201-2287. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** William Culler, Airframe and Propulsion Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30337-2748; telephone (770) 703-6084; fax (770) 703-6097.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 95-01-06 R1, amendment 39-9449 (60 FR 62192, December 5, 1995), which is applicable to certain Boeing Model 737-200 and -300 series airplanes, was published in the **Federal Register** on November 22, 1999 (64 FR 63757). The action

proposed to continue to require repetitive inspections to detect cracking in the radii on the support angles on the lower jamb (latch lug fittings) of the main deck cargo door, and replacement of cracked parts. That action also adds a requirement for installation of redesigned lower jamb latch support angles in the main cargo door surround structure, which would terminate the repetitive inspections.

#### **Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received. Two commenters state that the airplanes they operate would not be affected by the proposed rule.

#### **Include Additional Service Information**

One commenter asks that Pemco Service Bulletin 737-53-0005, dated November 18, 1997, which specifies alignment of the door latch base and frames, be included as an alternative method of compliance in paragraph (c)(1) of the proposed rule. The commenter also asks that the actions specified in that service bulletin be added to the proposed rule as terminating action for the requirements of AD 95-01-06 R1 (above). The commenter states that its fleet was modified per the service bulletin referenced in the proposed rule, but one airplane was misaligned between the door latch base and fuselage framing at FS 490.8. The commenter accomplished the alignment specified in service bulletin 737-53-0005.

The FAA does not concur with the commenter's requests. The FAA does not find it necessary to revise this AD to include special instructions for airplanes modified with another service bulletin. Operators should note that most AD actions address modifications affecting the subject area of the AD using the note that appears as Note 1 of this AD, which states, "For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance (AMOC) in accordance with paragraph (c)(1) of this AD." The AMOC letter would be issued to the operator by the appropriate office, as stated in paragraph (c)(1).

Additionally, the service bulletin referenced in the final rule specifies installation of redesigned lower jamb latch support angles in the main cargo door surround structure, which would terminate the repetitive inspections.

Modification of the door latch base for better alignment is a separate issue that was not addressed in the proposed rule, and would not meet the requirements for the terminating action. No change to the final rule is necessary in this regard.

### Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

### Cost Impact

There are approximately 32 airplanes of the affected design in the worldwide fleet. The FAA estimates that 2 airplanes of U.S. registry will be affected by this AD.

The inspection that is currently required by AD 95-01-06 R1, and retained in this AD, takes approximately 8 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$480 per airplane, per inspection cycle.

The new installation that is required by this AD takes approximately 500 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts will cost approximately \$9,700 per airplane. Based on these figures, the cost impact of the requirements of this AD on U.S. operators is estimated to be \$79,400, or \$39,700 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-9449 (60 FR 62192, December 5, 1995), and by adding a new airworthiness directive (AD), amendment 39-12222, to read as follows:

**2001-09-15 Boeing:** Amendment 39-12222. Docket 99-NM-85-AD. Supersedes AD 95-01-06 R1, Amendment 39-9449.

**Applicability:** Model 737-200 and -300 series airplanes equipped with main deck cargo doors installed in accordance with supplemental type certificate (STC) SA2969SO, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent in-flight separation of the main deck cargo door from the airplane, accomplish the following:

**Note 2:** This AD references Pemco Alert Service Letter 737-53-0003, Revision 3, dated December 22, 1994; Pemco Service Bulletin 737-53-0003, Revision 4, dated February 22, 1995; and Pemco Service Bulletin 737-53-0003, Revision 5, dated March 25, 1999; for information concerning inspection and replacement procedures. In addition, this AD specifies replacement requirements different from those included in the service letter or service bulletin. Where there are differences between the AD and the service letter or service bulletin, the AD prevails.

### Restatement of Requirements AD 95-01-06 R1

#### Repetitive Inspections

(a) Within 50 flight cycles after January 24, 1995 (the effective date of AD 95-01-06, amendment 39-9117), or within 50 flight cycles after installation of STC SA2969SO, whichever occurs later, perform a detailed visual inspection to detect cracking in the radii on the support angles on the lower jamb of the main deck cargo door, in accordance with Pemco Alert Service Letter 737-53-0003, Revision 3, dated December 22, 1994.

(1) If no cracking is detected, repeat the detailed visual inspection thereafter at intervals not to exceed 450 flight cycles.

(2) If any cracking is detected, prior to further flight, replace the cracked part with a new part in accordance with the alert service letter. Repeat the detailed visual inspection thereafter at intervals not to exceed 450 flight cycles.

**Note 3:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

### New Requirements of This AD

#### Terminating Action

(b) Within 1,500 flight cycles after the effective date of this AD, install redesigned lower jamb latch lug support angles in the main cargo door surround structure in accordance with Pemco Service Bulletin 737-53-0003, Revision 4, dated February 22, 1995, or Revision 5, dated March 25, 1999. This action constitutes terminating action for the requirements of this AD.

#### Alternative Methods of Compliance

(c)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance

Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 95-01-06 R1, amendment 39-9449, are approved as alternative methods of compliance with paragraphs (a) and (b) of this AD.

**Note 4:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

#### Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(e) The actions shall be done in accordance with Pemco Alert Service Letter 737-53-0003, Revision 3, dated December 22, 1994; Pemco Service Bulletin 737-53-0003, Revision 4, dated February 22, 1995, or Pemco Service Bulletin 737-53-0003, Revision 5, dated March 25, 1999; as applicable.

(1) The incorporation by reference of Pemco Service Bulletin 737-53-0003, Revision 4, dated February 22, 1995; and Pemco Service Bulletin 737-53-0003, Revision 5, dated March 25, 1999; is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Pemco Alert Service Letter 737-53-0003, Revision 3, dated December 22, 1994, was approved previously by the Director of the Federal Register as of January 24, 1995 (60 FR 2323, January 9, 1995).

(3) Copies may be obtained from Pemco Aeroplex, Inc., P.O. Box 2287, Birmingham, Alabama 35201-2287. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta ACO, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### Effective Date

(f) This amendment becomes effective on June 14, 2001.

Issued in Renton, Washington, on May 1, 2001.

**Donald L. Riggins,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 01-11455 Filed 5-9-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-389-AD; Amendment 39-12221; AD 2001-09-14]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A330-243, -341, -342, and -343 Series Airplanes Equipped With Rolls Royce Trent 700 Series Engines

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to Airbus Model A330-243, -341, -342, and -343 series airplanes equipped with Rolls Royce Trent 700 series engines. This action requires repetitive inspections of certain components, and corrective action, if necessary. This action is necessary to detect and correct fatigue cracking of the hinge assemblies and the 12 o'clock beam structure of the thrust reverser C-duct, which could cause failure of the thrust reverser hinge, resulting in separation of the thrust reverser from the airplane. This action is intended to address the identified unsafe condition.

**DATES:** Effective May 25, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 25, 2001.

Comments for inclusion in the Rules Docket must be received on or before June 11, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-389-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-389-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Airbus

Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Tim Backman, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2797; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on Airbus Model A330-243, -341, -342, and -343 series airplanes equipped with Rolls Royce Trent 700 series engines. The DGAC advises that, during flight tests, unexpectedly high fatigue loads were measured on the hinges integrated on the 12 o'clock beam which forms the upper edge of the thrust reverser C-duct. The hinges are unable to withstand these high fatigue loads for the design life of the airplane. Resulting fatigue cracks, if not detected and corrected, could cause failure of the thrust reverser hinge, which could result in separation of the thrust reverser from the airplane.

#### Explanation of Relevant Service Information

Airbus has issued Service Bulletin A330-78-3006, Revision 05, dated March 6, 2001, which describes procedures for a general visual inspection of the hinge assemblies and the beam structure of the upper extreme edge of the thrust reverser unit C-duct for cracks, and corrective action, if necessary; a detailed visual inspection, if applicable, of hinges 2, 3, 4, and 5 in the same area for cracks, and corrective action, if necessary; and repetitions of these inspections, as applicable, at applicable intervals. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 1997-118-047(B) R2, dated September 20, 2000, in order to assure the continued airworthiness of these airplanes in France.

Airbus Service Bulletin A330-78-3006, Revision 05, dated March 6, 2001, references Rolls Royce Service Bulletin RB.211-78-B115, Revision 2, dated October 29, 1999, as an additional source of service information for