

interested parties to submit views that may not have been submitted in response to the prior opportunities for comment described above.

#### List of Subjects in 14 CFR Part 35

Air transportation, Aircraft, Aviation safety, Safety.

The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701–44702, 44704.

#### The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for the Hartzell Propeller Incorporated model HC–E5A–2/E8991 propeller.

In addition to the requirements of part 35, the following requirements apply to the propeller:

(a) *Definitions.* Unless otherwise approved by the Administrator and documented in the appropriate manuals and certification documents, for the purpose of these special conditions the following definitions apply to the propeller:

(1) Hazardous propeller effects. The following are regarded as hazardous propeller effects:

- (i) Significant overspeed of the propeller.
- (ii) Development of excessive drag.
- (iii) Thrust in the direction opposite to that commanded by the pilot.
- (iv) Release of the propeller or any major portion of the propeller.
- (v) Failure that results in excessive unbalance.
- (vi) Unintended movement of the propeller blades below the established minimum in-flight low pitch position.

(2) Major propeller effects. The following are regarded as major propeller effects:

- (i) Inability to feather the propeller (for feathering propellers).
- (ii) Inability to command a change in propeller pitch.
- (iii) Significant uncommanded change in pitch.
- (iv) Significant uncontrollable torque or speed fluctuation.

(b) *Centrifugal load tests.* It must be demonstrated that a propeller, accounting for environmental degradation expected in service, complies with paragraphs (b)(1), (b)(2) and (b)(3) of these special conditions without evidence of failure, malfunction, or permanent deformation that would result in a major or hazardous propeller effect. Environmental degradation may be

accounted for by adjustment of the loads during the tests.

(1) The hub, blade retention system, and counterweights must be tested for a period of one hour to a load equivalent to twice the maximum centrifugal load to which the propeller would be subjected during operation at the maximum rated rotational speed.

(2) If appropriate, blade features associated with transitions to the retention system (e.g., a composite blade bonded to a metallic retention) may be tested either during the test required by paragraph (b)(1) or in a separate component test.

(3) Components used with or attached to the propeller (e.g., spinners, de-icing equipment, and blade erosion shields) must be subjected to a load equivalent to 159 percent of the maximum centrifugal load to which the component would be subjected during operation at the maximum rated rotational speed. This must be performed by either:

(i) Testing at the required load for a period of 30 minutes; or

(ii) Analysis based on test.

(c) *Fatigue limits and evaluation.*

(1) Fatigue limits must be established by tests or analysis based on tests, for propeller:

- (i) Hubs;
- (ii) Blades; and
- (iii) Blade retention components.

(2) The fatigue limits must take the following into account:

(i) All known and reasonably foreseeable vibration and cyclic load patterns that are expected in service; and

(ii) Expected service deterioration, variations in material properties, manufacturing variations, and environmental effects.

(3) A fatigue evaluation of the propeller must be conducted to show that hazardous propeller effects due to fatigue will be avoided throughout the intended operational life of the propeller on either:

(i) The intended aircraft, by complying with §§ 23.907 or 25.907 as applicable; or

(ii) A typical aircraft.

(d) *Bird impact.* It must be demonstrated, by tests or analysis based on tests or experience on similar designs, that the propeller is capable of withstanding the impact of a four pound bird at the critical location(s) and critical flight condition(s) of the intended aircraft without causing a major or hazardous propeller effect.

(e) *Lightning strike.* It must be demonstrated, by tests or analysis based on tests or experience on similar designs, that the propeller is capable of

withstanding a lightning strike without causing a major or hazardous propeller effect.

Issued in Burlington, Massachusetts on September 17, 2001.

**Jay J. Pardee,**

*Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 01–24429 Filed 10–2–01; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000–SW–37–AD; Amendment 39–12449; AD 2001–20–03]

**RIN 2120–AA64**

#### **Airworthiness Directives; Bell Helicopter Textron Canada Model 206L–4 Helicopters**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) for Bell Helicopter Textron Canada (BHTC) Model 206L–4 helicopters that requires installing a high altitude tail rotor static stop yield indicator (indicator) to allow operators to detect excessive bending loads sustained by the tail rotor yoke. A preflight check of the indicator is also required. This amendment is prompted by a determination that a tail rotor yoke with a high altitude rotor system is susceptible to a static and dynamic overload. Static overload could occur after the tail rotor yoke sustains an excessive bending load due to a strike from a ground vehicle. Dynamic overload could occur as a result of a hard landing. The actions specified by this AD are intended to prevent failure of the tail rotor yoke in flight and subsequent loss of control of the helicopter.

**DATES:** Effective November 7, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of November 7, 2001.

**ADDRESSES:** The service information referenced in this AD may be obtained from Bell Helicopter Textron Canada, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4, telephone (450) 437–2862 or (800) 363–8023, fax (450) 433–0272. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or

at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Sharon Miles, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5122, fax (817) 222-5961.

**SUPPLEMENTARY INFORMATION:** A proposal to amend 14 CFR part 39 to include an AD for BHTC Model 206L-4 helicopters was published in the **Federal Register** on June 25, 2001 (66 FR 33649). That action proposed to require installing an indicator, P/N 206-011-752-101, within 100 hours time-in-service. Requiring a preflight visual check for damage to the indicator was also proposed.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 16 helicopters of U.S. registry will be affected by this AD, that it will take approximately 0.5 work hour per helicopter to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$1,753. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$28,528.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various

levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

#### 2001-20-03 Bell Helicopter Textron

**Canada:** Amendment 39-12449. Docket No. 2000-SW-37-AD.

**Applicability:** Model 206L-4 helicopters, with High Altitude Tail Rotor Kit, part number (P/N) 206-704-722-101 (BHT-206-SI-2054), installed, certificated in any category.

**Note 1:** This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.


**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the tail rotor yoke in flight and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 100 hours time-in-service, install a high altitude tail rotor static stop yield indicator (indicator), P/N 206-011-752-101, in accordance with the Accomplishment Instructions, Part II, Bell Helicopter Textron Alert Service Bulletin No. 206L-96-104, Revision B, dated July 24, 1998.

(b) Before each engine start, check the indicator for damage in accordance with Figure 1 of this AD. If damage is found, before further flight, replace the damaged indicator with an airworthy indicator, and replace the tail rotor yoke, P/N 406-012-102-107, with an airworthy tail rotor yoke.

**BILLING CODE 4910-13-U**



**Normal and Deformed (damaged) Indications of the  
High Altitude Tail Rotor Static Stop Yield Indicator (P/N 206-011-752-101)**

**Figure 1**

**BILLING CODE 4910-13-C**

(c) An owner/operator (pilot) holding at least a private pilot certificate may perform the visual check required by paragraph (b) of this AD and must record compliance in the helicopter maintenance records in accordance with 14 CFR 43.11 and 91.417(a)(2)(v)).

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft Certification Office, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Certification Office.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Certification Office.

(e) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

(f) The modification shall be done in accordance with the Accomplishment Instructions, Part II, Bell Helicopter Textron Alert Service Bulletin No. 206L-96-104, Revision B, dated July 24, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bell Helicopter Textron Canada, 12,800 Rue de l'Avenir, Mirabel, Quebec J7Y1R4, telephone

(450) 437-2862 or (800) 363-8023, fax (450) 433-0272. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) This amendment becomes effective on November 7, 2001.

**Note 3:** The subject of this AD is addressed in Transport Canada (Canada) AD CF-98-11, dated June 16, 1998.

Issued in Fort Worth, Texas, on September 24, 2001.

**David A. Downey,**

*Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 01-24622 Filed 10-2-01; 8:45 am]

**BILLING CODE 4910-13-U**

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) for Agusta S.p.A. (Agusta) Model A109E helicopters that requires modifying the passenger compartment sliding doors by installing certain locking mechanism kits. This amendment is prompted by accidental opening of a passenger compartment sliding door (door) in flight due to a door locking mechanism that is too easy to accidentally open. The actions specified by this AD are intended to prevent accidental opening of a door in flight and subsequent loss of objects that could damage the rotor system.

**DATES:** Effective November 7, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of November 7, 2001.

**ADDRESSES:** The service information referenced in this AD may be obtained from Agusta, 21017 Cascina Costa di Samarate (VA) Italy, Via Giovanni Agusta 520, telephone 39 (0331) 229111, fax 39 (0331) 229605-222595. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. 2001-SW-09-AD; Amendment 39-12450; AD 2001-20-04]**

**RIN 2120-AA64**

**Airworthiness Directives; Agusta S.p.A. Model A109E Helicopters**

**AGENCY:** Federal Aviation Administration, DOT.