

federally-insured credit unions. Such entities are referred to in this appendix as "the credit union."

B. *Definitions.* 1. *In general.* Except as modified in the Guidelines or unless the context otherwise requires, the terms used in these Guidelines have the same meanings as set forth in 12 CFR part 716.

2. For purposes of the Guidelines, the following definitions apply:

a. *Member* means any member of the credit union as defined in 12 CFR 716.3(n).

b. *Member information* means any records containing nonpublic personal information, as defined in 12 CFR 716.3(q), about a member, whether in paper, electronic, or other form, that is maintained by or on behalf of the credit union.

c. *Member information system* means any method used to access, collect, store, use, transmit, protect, or dispose of member information.

d. *Service provider* means any person or entity that maintains, processes, or otherwise is permitted access to member information through its provision of services directly to the credit union.

II. Standards for Safeguarding Member Information

A. *Information Security Program.* A comprehensive written information security program includes administrative, technical, and physical safeguards appropriate to the size and complexity of the credit union and the nature and scope of its activities. While all parts of the credit union are not required to implement a uniform set of policies, all elements of the information security program must be coordinated.

B. *Objectives.* A credit union's information security program should be designed to: ensure the security and confidentiality of member information; protect against any anticipated threats or hazards to the security or integrity of such information; and protect against unauthorized access to or use of such information that could result in substantial harm or inconvenience to any member. Protecting confidentiality includes honoring members' requests to opt out of disclosures to nonaffiliated third parties, as described in 12 CFR 716.1(a)(3).

III. Development and Implementation of Member Information Security Program

A. *Involve the Board of Directors.* The board of directors or an appropriate committee of the board of each credit union should:

1. Approve the credit union's written information security policy and program; and
2. Oversee the development, implementation, and maintenance of the credit union's information security program, including assigning specific responsibility for its implementation and reviewing reports from management.

B. *Assess Risk.* Each credit union should:

1. Identify reasonably foreseeable internal and external threats that could result in unauthorized disclosure, misuse, alteration, or destruction of member information or member information systems;
2. Assess the likelihood and potential damage of these threats, taking into

consideration the sensitivity of member information; and

3. Assess the sufficiency of policies, procedures, member information systems, and other arrangements in place to control risks.

C. *Manage and Control Risk.* Each credit union should:

1. Design its information security program to control the identified risks, commensurate with the sensitivity of the information as well as the complexity and scope of the credit union's activities. Each credit union must consider whether the following security measures are appropriate for the credit union and, if so, adopt those measures the credit union concludes are appropriate:

a. Access controls on member information systems, including controls to authenticate and permit access only to authorized individuals and controls to prevent employees from providing member information to unauthorized individuals who may seek to obtain this information through fraudulent means;

b. Access restrictions at physical locations containing member information, such as buildings, computer facilities, and records storage facilities to permit access only to authorized individuals;

c. Encryption of electronic member information, including while in transit or in storage on networks or systems to which unauthorized individuals may have access;

d. Procedures designed to ensure that member information system modifications are consistent with the credit union's information security program;

e. Dual controls procedures, segregation of duties, and employee background checks for employees with responsibilities for or access to member information;

f. Monitoring systems and procedures to detect actual and attempted attacks on or intrusions into member information systems;

g. Response programs that specify actions to be taken when the credit union suspects or detects that unauthorized individuals have gained access to member information systems, including appropriate reports to regulatory and law enforcement agencies; and

h. Measures to protect against destruction, loss, or damage of member information due to potential environmental hazards, such as fire and water damage or technical failures.

2. Train staff to implement the credit union's information security program.

3. Regularly test the key controls, systems and procedures of the information security program. The frequency and nature of such tests should be determined by the credit union's risk assessment. Tests should be conducted or reviewed by independent third parties or staff independent of those that develop or maintain the security programs.

D. *Oversee Service Provider Arrangements.* Each credit union should:

1. Exercise appropriate due diligence in selecting its service providers;

2. Require its service providers by contract to implement appropriate measures designed to meet the objectives of these guidelines; and

3. Where indicated by the credit union's risk assessment, monitor its service providers

to confirm that they have satisfied their obligations as required by paragraph D.2. As part of this monitoring, a credit union should review audits, summaries of test results, or other equivalent evaluations of its service providers.

E. *Adjust the Program.* Each credit union should monitor, evaluate, and adjust, as appropriate, the information security program in light of any relevant changes in technology, the sensitivity of its member information, internal or external threats to information, and the credit union's own changing business arrangements, such as mergers and acquisitions, alliances and joint ventures, outsourcing arrangements, and changes to member information systems.

F. *Report to the Board.* Each credit union should report to its board or an appropriate committee of the board at least annually. This report should describe the overall status of the information security program and the credit union's compliance with these guidelines. The report should discuss material matters related to its program, addressing issues such as: risk assessment; risk management and control decisions; service provider arrangements; results of testing; security breaches or violations and management's responses; and recommendations for changes in the information security program.

G. *Implement the Standards.*

1. *Effective date.* Each credit union must implement an information security program pursuant to the objectives of these Guidelines by July 1, 2001.

2. *Two-year grandfathering of agreements with service providers.* Until July 1, 2003, a contract that a credit union has entered into with a service provider to perform services for it or functions on its behalf satisfies the provisions of paragraph III.D., even if the contract does not include a requirement that the servicer maintain the security and confidentiality of member information, as long as the credit union entered into the contract on or before March 1, 2001.

[FR Doc. 01-2494 Filed 1-29-01; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. NM182; Special Conditions No. 25-172-SC]

Special Conditions: Honeywell International, Inc.; Boeing Model 747-300 Series Airplanes; High-Intensity Radiated Fields (HIRF)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final special conditions; request for comments.

SUMMARY: These special conditions are issued for Boeing Model 747-300 series airplanes modified by Honeywell

International, Inc. These modified airplanes will have novel or unusual design features associated with the installation of new navigation management system that includes electronic flight instrument system (EFIS) displays. The EFIS displays will use electrical and electronic systems that perform critical functions. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for the protection of these systems from the effects of high-intensity-radiated fields (HIRF). These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

DATES: The effective date of these special conditions is January 16, 2001. Comments must be received on or before March 1, 2001.

ADDRESSES: Comments on these special conditions may be mailed in duplicate to: Federal Aviation Administration, Transport Airplane Directorate, Attention: Rules Docket (ANM-114), Docket No. NM182, 1601 Lind Avenue SW., Renton, Washington 98055-4056; or delivered in duplicate to the Transport Airplane Directorate at that address. All comments must be marked: "Docket No. NM182." Comments may be inspected in the Rules Docket weekdays, except Federal holidays, between 7:30 a.m. and 4:00 p.m.

FOR FURTHER INFORMATION CONTACT: For information concerning the certification program for the Boeing Model 747-300 series airplanes modified by Honeywell International, Inc., contact: Ross Landes, Standardization Branch, ANM-113, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (425) 227-145; fax (425) 227-1149.

For information on the general subject of HIRF, contact: Massoud Sadeghi, Federal Aviation Administration, Transport Airplane Directorate, Airplane and Flight Crew Interface Branch, ANM-111, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (425) 227-2117; fax (425) 227-1320.

SUPPLEMENTARY INFORMATION: The FAA has determined that notice and opportunity for prior public comment hereon are impracticable because these procedures would significantly delay issuance of the approval design and thus delivery of the affected aircraft. In addition, the substance of these special conditions has been subject to the public comment process in several prior

instances with no substantive comments received. The FAA, therefore, finds that good cause exists for making these special conditions effective upon issuance.

Comments Invited

Although these special conditions are being issued as final special conditions without prior public notice, interested persons are invited to submit such written data, views, or arguments as they may desire. Communications should identify the regulatory docket number and be submitted in duplicate to the address specified above. All communications received on or before the closing date for comments will be considered by the Administrator. The special conditions may be changed in light of the comments received. All comments received will be available in the Rules Docket for examination by interested persons, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerning this rulemaking will be filed in the docket. Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to these special conditions must include a self-addressed, stamped postcard on which the following statement is made: "Comments to NM182." The postcard will be date stamped and returned to the commenter.

Background

On October 20, 2000, Honeywell International Inc., 15001 N.E. 36th Street, P.O. Box 97001, Redmond, Washington 98073-9701, applied for a Supplemental Type Certificate (STC) for the Boeing Model 747-300 series airplanes operated by South African Airways (SAA). Honeywell plans to install upgraded avionics equipment on these airplanes. This equipment includes an electronic flight instrument system (EFIS) that displays attitude and heading information, and is manufactured by Astronautics. The modified airplanes are scheduled for certification in January 2001.

The Astronautics EFIS provides a critical function that displays attitude and heading information. The EFIS must be designed and installed to ensure that its operation is not adversely affected by high intensity radiated fields (HIRF). These functions can be susceptible to disruption of both command and response signals as a result of electrical and magnetic interference caused by HIRF external to the airplane. This disruption of signals could result in loss of critical flight displays and annunciations, or could

present misleading information to the pilot.

The subject Boeing Model 747-300 series airplanes are four-engine transport category airplanes with a wingspan of 195 ft. 8 in. (59.6 m) and an overall length of 231 ft. 10.2 in. (70.6 m). They are essentially identical to the earlier Model 747-200 series, but have a stretched upper deck. Their maximum takeoff weight is 833,000 lbs. (374,850 kg) and typical cruise speed at 35,000 feet is Mach 0.85/565 mph (910 km/h)

Type Certification Basis

Under the provisions of 14 CFR 21.101, Honeywell must show that the Boeing Model 747-300 series airplanes, as modified, continue to meet the applicable provisions of the regulations incorporated by reference in Type Certificate No. A20WE, or the applicable regulations in effect on the date of application for the modification. The regulations incorporated by reference in the type certificate are commonly referred to as the "original type certification basis."

The regulations incorporated by reference in Type Certificate No. A20WE for the Boeing Model 747-300 series airplanes are as follows:

1. Regulations

- 14 CFR parts 1, 21, 34 (fuel vent and exhaust emission requirements), and 36 (noise certification requirements).
- 14 CFR part 25, effective February 1, 1965.
- Amendments 25-1 through 25-8, plus 25-15, 25-17, 25-18, 25-20, and 25-39 (transmitted by FAA letter dated February 4, 1977).
- Amendment 25-36, re: RB211 engine oil filter system compliance with § 25.1019 and § 25.1305(c)(7).
- Amendment 25-46, § 25.803(d) (Transmitted by FAA letter to The Boeing Company, dated September 2, 1983. This is limited to all passenger configurations and 6/7 palet combi configurations.)

2. Special Conditions

- Special conditions summarized for record purposes as enclosed with FAA letter to The Boeing Company dated February 20, 1970.
- Special Conditions 4A, revised to apply to airplanes with the landing gear load evener system deleted (recorded as attachment to an FAA letter to The Boeing Company dated May 12, 1971).
- Special Conditions No. 25-61-NW-1 for occupancy not to exceed 32 passengers on the upper deck of airplanes with spiral staircase

(transmitted to The Boeing Company by FAA letter dated February 26, 1975).

- Special Conditions No. 25-71-NW-3 for occupancy not to exceed 45 passengers on the upper deck of airplanes with straight segmented stairway (transmitted to The Boeing Company by FAA letter dated September 8, 1976).

- Modification of Special Conditions No. 25-71-NW-3 for occupancy not to exceed 110 passengers on the upper deck of airplanes with segmented stairway (transmitted to The Boeing Company by FAA letter dated August 3, 1981).

- Special Conditions No. 25-77-NW-4—modification of the autopilot system to approve the airplane for use of the system under category IIb landing conditions (transmitted to The Boeing Company by FAA letter dated July 8, 1977).

- Special Condition No. 25-ANM-16 for installation of an overhead crew rest area, occupancy not to exceed 10 crewmembers. (The FAA-approved procedures required for compliance with paragraph 13 of the Special Condition are located in Boeing Document D926U303, Appendix D.)

3. Exemptions From 14 CFR Part 25

- Exemption No. 1013A, dated December 24, 1969.
- Exemption No. 1870D, dated April 3, 1991.
- Exemption No. 3035 dated September 9, 1980.

4. Compliance With the Following Optional Requirements

- § 25.801, "Ditching."
- § 25.1419, "Ice protection."

5. Equivalent Safety Findings With Respect to the Following Regulations

- § 25.773(b)(2)(i), amendments 25-1 through 25-67, "Pilot compartment view."

- § 25.811(f), "Emergency exit marking."

- § 25.812(k)(2), "Emergency lighting."

- § 25.815, "Width of aisle."

- § 25.1415(d) "Ditching equipment" [re: Emergency Locator Transmitter (ELT)].

If the Administrator finds that the applicable airworthiness regulations (i.e., 14 CFR part 25, as amended) do not contain adequate or appropriate safety standards for the Boeing Model 747-300 series airplanes modified by Honeywell because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

Special conditions, as appropriate, are issued in accordance with § 11.19, as

required by § 11.38, and become part of the airplane's type certification basis in accordance with § 21.101(b)(2).

The special conditions approved in this new document will form an additional part of the type certification basis for these airplanes.

Special conditions are initially applicable to the model for which they are issued. Should Honeywell apply for a supplemental type certificate to modify any other model included on the same type certificate to incorporate the same novel or unusual design features, these special conditions would also apply to the other model under the provisions of § 21.101(a)(1).

Novel or Unusual Design Features

The Boeing Model 747-300 series airplanes modified by Honeywell will incorporate the Astronautics EFIS system, which performs critical functions. The EFIS system contains electronic equipment for which the current airworthiness standards (14 CFR part 25) do not contain adequate or appropriate safety standards that address protecting this equipment from the adverse effects of HIRF. This system may be vulnerable to HIRF external to the airplane. Accordingly, this system is considered to be a novel or unusual design feature.

Discussion

There is no specific regulation that addresses the requirements for protection of electrical and electronic systems from HIRF. Increased power levels from ground-based radio transmitters and the growing use of sensitive electrical and electronic systems to command and control airplanes have made it necessary to provide adequate protection.

To ensure that a level of safety is achieved that is equivalent to that intended by the regulations incorporated by reference, special conditions are needed for the Boeing Model 747-300 airplanes modified by Honeywell to include the Astronautics EFIS system. These special conditions will require that this system, which performs critical functions, be designed and installed to preclude component damage and interruption of function due to both the direct and indirect effects of HIRF.

High-Intensity Radiated Fields (HIRF)

With the trend toward increased power levels from ground-based transmitters, plus the advent of space and satellite communications coupled with electronic command and control of the airplane, and the use of composite material in the airplane structure, the

immunity of critical avionics/electronics and electrical systems to HIRF must be established.

It is not possible to precisely define the HIRF to which the airplane will be exposed in service. There is also uncertainty concerning the effectiveness of airframe shielding for HIRF.

Furthermore, coupling of electromagnetic energy to cockpit-installed equipment through the cockpit window apertures is undefined. Based on surveys and analysis of existing HIRF emitters, an adequate level of protection exists when compliance with the HIRF protection special condition is shown with either paragraph 1. or, alternatively, paragraph 2., below:

1. A minimum threat of 100 volts rms per meter electric field strength from 10 KHz to 18 GHz.

a. The threat must be applied to the system elements and their associated wiring harnesses without the benefit of airframe shielding.

b. Demonstration of this level of protection is established through system tests and analysis.

Or

2. A threat external to the airframe for both of the following field strengths for the frequency ranges indicated. Both peak and average field strength components from *Table 1* are to be demonstrated.

TABLE 1

Frequency	Field Strength (volts per meter)	
	Peak	Average
10 kHz–100 kHz	50	50
100 kHz–500 kHz	50	50
500 kHz–2 MHz	50	50
2 MHz–30 MHz	100	100
30 MHz–70 MHz	50	50
70 MHz–100 MHz	50	50
100 MHz–200 MHz	100	100
200 MHz–400 MHz	100	100
400 MHz–700 MHz	700	50
700 MHz–1 GHz	700	100
1 GHz–2 GHz	2000	200
2 GHz–4 GHz	3000	200
4 GHz–6 GHz	3000	200
6 GHz–8 GHz	1000	200
8 GHz–12 GHz	3000	300
12 GHz–18 GHz	2000	200
18 GHz–40 GHz	600	200

The field strengths are expressed in terms of peak of the root-mean-square (rms) over the complete modulation period.

The threat levels identified in *Table 1* are the result of an FAA review of existing studies on the subject of HIRF, in light of the ongoing work of the Electromagnetic Effects Harmonization Working Group of the Aviation Rulemaking Advisory Committee.

Applicability

As discussed above, these special conditions are applicable to the Boeing Model 747-300 series airplanes modified by Honeywell International, Inc., to include the Astronautics EFIS system. Should Honeywell apply at a later date for a supplemental type certificate to modify any other model included on Type Certificate A20WE to incorporate the same novel or unusual design features, these special conditions would apply to that model as well under the provisions of § 21.101(a)(1).

Conclusion

This action affects only certain novel or unusual design features on the Boeing Model 747-300 series airplanes modified by Honeywell International, Inc. It is not a rule of general applicability and affects only the applicant who applied to the FAA for approval of these features on the airplanes.

As stated previously, the substance of the special conditions has been subjected to the notice and comment period in several prior instances and has been derived without substantive change from those previously issued. It is unlikely that prior public comment would result in a significant change from the substance contained herein. For this reason, and because a delay would significantly affect the certification of the airplane, which is imminent, the FAA has determined that prior public notice and comment are unnecessary and impracticable, and good cause exists for adopting these special conditions upon issuance. The FAA is requesting comments to allow interested persons to submit views that may not have been submitted in response to the prior opportunities for comment described above.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the supplemental type certification basis for the Boeing Model 747-300 series airplanes modified by Honeywell International, Inc.

1. *Protection from Unwanted Effects of High-Intensity Radiated Fields (HIRF)*. Each electrical and electronic

system that performs critical functions must be designed and installed to ensure that the operation and operational capability of these systems to perform critical functions are not adversely affected when the airplane is exposed to high-intensity radiated fields.

2. For the purpose of these special conditions, the following definition applies: *Critical Functions*: Functions whose failure would contribute to or cause a failure condition that would prevent the continued safe flight and landing of the airplane.

Issued in Renton, Washington, on January 16, 2001.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 01-2037 Filed 1-29-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NE-03-AD; Amendment 39-12097; AD 2001-02-12]

RIN 2120-AA64

Airworthiness Directives; CFM International (CFMI) Model CFM56-7B Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to CFMI model CFM56-7B turbofan engines. This action requires a one-time on-wing torque inspection, and torque if needed, of all the PS3 pressure line fittings to insure proper torque. This amendment is prompted by service events which resulted in two in-flight shutdowns (IFSD's) and an aborted takeoff due to the disconnection of one of the PS3 line fittings. The actions specified in this AD are intended to prevent air leakage from incorrectly torqued fittings of the PS3 line, which could result in engine power loss.

DATES: Effective February 14, 2001.

Comments for inclusion in the Rules Docket must be received on or before April 2, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2001-NE-

03-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov." Comments sent via the Internet must contain the docket number in the subject line.

FOR FURTHER INFORMATION CONTACT:

Diane Cook, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone 781-238-7133, fax 781-238-7199.

SUPPLEMENTARY INFORMATION: The FAA has received reports of two in-flight shutdowns and one aborted take-off on three different Boeing 737NG airplanes powered by CFM56-7B turbofan engines. In all of these cases, the engine rolled back to idle speed and would not accelerate. The investigation revealed that the PS3 pressure line B-nut fitting at the 6 o'clock position had disconnected in two of these events and the PS3 pressure B-nut fitting at the combustion case port location had disconnected in the third event. An operator, involved in one of the IFSD events, completed on-wing torque inspections of the PS3 pressure line fittings of its CFMI CFM56-7B fleet. As a result of these inspections, one engine was found with a loose B-nut fitting at the 6 o'clock location and two engines were found with loose cap fittings at the 6 o'clock location. The two engines with loose caps were on the same airplane. The investigation also initiated PS3 pressure line fitting torque inspections on 10 engines that were on Boeing's flight line. These inspections revealed one engine with a loose B-nut fitting at the 6 o'clock position and one engine with a loose cap fitting at the 6 o'clock position. General Electric and SNECMA also inspected CFM56-7B engines that were in assembly. No loose fittings were found. The investigation to determine the cause of the loose PS3 pressure line fittings continues. Action to insure correct torque of these fittings on current production engines has been initiated by adding a new torque inspection requirement for the PS3 pressure line fittings at the end of the main engine assembly process. However, based on the inspection results indicated above, it has been determined that mandating action on in-service engines to ensure that the PS3 pressure line fittings are correctly torqued is required.

Requirements of This AD

Since an unsafe condition has been identified that is likely to exist or develop on other engines of the same