

impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator,

the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-05-16 Boeing: Amendment 39-13511. Docket 2003-NM-49-AD.

Applicability: Model 767-200 and -300 series airplanes, line numbers 1 through 423 inclusive; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct fatigue cracks in the aft pressure bulkhead web, which could result in uncontrolled rapid decompression, accomplish the following:

Initial and Repetitive Inspections

(a) Do high frequency eddy current inspections of the aft pressure bulkhead web, per the Work Instructions of Boeing Alert Service Bulletin 767-53A0087, dated October 21, 1999; at the later of the applicable "Threshold" and "Grace Period" times specified in Table 1 of this AD. Table 1 is as follows:

TABLE 1.—COMPLIANCE TIMES FOR INSPECTION

For—	Compliance times—	
	Threshold—	Grace period—
(1) Group 1 airplanes as identified in the service bulletin.	Prior to the accumulation of 37,500 total flight cycles.	Within 18 months or within 3,000 flights after the effective date of this AD, whichever comes first
(2) Group 2 airplanes as identified in the service bulletin.	Prior to the accumulation of 50,000 total flight cycles.	Within 18 months or within 3,000 flights after the effective date of this AD, whichever comes first

(b) If no crack is found during any inspection required by paragraph (a) of this AD, repeat the high frequency eddy current inspections thereafter at intervals not to exceed 6,000 flight cycles, per the Work Instructions of Boeing Alert Service Bulletin 767-53A0087, dated October 21, 1999.

Corrective Actions

(c) If any crack is found during any inspection required by paragraph (a) or (b) of this AD and Boeing Alert Service Bulletin 767-53A0087, dated October 21, 1999, specifies to contact Boeing for repair: Before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

Previously Installed Repairs

(d) If previously installed repairs are installed in the inspection area, and Boeing Alert Service Bulletin 767-53A0087, dated October 21, 1999, specifies to contact Boeing for inspection details, an alternative method of compliance must be approved as required by sections 39.15, 39.17, and 39.19 of the Code of Federal Regulations (14 CFR 39.15, 39.17, 39.19).

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, Seattle ACO, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(f) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 767-53A0087, dated October 21, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(g) This amendment becomes effective on April 13, 2004.

Issued in Renton, Washington, on February 25, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04-4922 Filed 3-8-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-04-AD; Amendment 39-13491; AD 2004-04-10]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B2 and A300 B4 Series Airplanes; A300 B4-600, B4-600R, C4-605R Variant F, and F4-600R (Collectively Called A300-600); and A310 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all Airbus Model A300 B2 and A300 B4 series airplanes; A300 B4-600, B4-600R, C4-605R Variant F, and F4-600R (collectively called A300-600); and A310 series airplanes. This AD requires, for certain airplanes, identifying the part number of the landing gear selector valves. For all airplanes, this AD requires repetitive maintenance tasks or operational tests of the landing gear selector valves, and replacing discrepant valves with certain new valves. This action is necessary to prevent failure of the landing gear selector valves, which could result in residual pressure on the retraction chamber side of the electro-hydraulic

selector, and consequent uncommanded retraction of the landing gear when the airplane is on the ground. This action is intended to address the identified unsafe condition.

DATES: Effective April 13, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 13, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer; International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601

Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1503; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Airbus Model A300 B2 and A300 B4 series airplanes; A300 B4-600, B4-600R, C4-605R Variant F, and F4-600R (collectively called A300-600); and A310 series airplanes; was published in the **Federal Register** on December 22, 2003 (68 FR 71045). That action proposed to require, for certain airplanes, identifying the part number of the landing gear selector valves. For all airplanes, that action proposed to require repetitive maintenance tasks or operational tests of the landing gear selector valves, and replacing discrepant valves with certain new valves.

Comments

We provided the public the opportunity to participate in the

development of this AD. No comments have been submitted on the proposed AD or on the determination of the cost to the public.

Change to Proposed AD

We have slightly revised the description of Model A300-600 series airplanes in this final rule. The revised description more accurately reflects the listing on the type certificate data sheet and identifies the model/series as "A300 B4-600, B4-600R, C4-605R Variant F, and F4-600R (collectively called A300-600)" series airplanes.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD with the change described above.

Cost Impact

The following table provides the estimated costs to do the actions specified in this AD.

Model	Action	Work hours	Average hourly labor rate	Cost per airplane	Number of U.S. airplanes	Fleet cost
A300 B2 A300 B4	Part number identification	1	\$65	\$65	32	\$2,080
	MPD task	1	65	65, per task cycle	32	2,080, per task cycle
	Operational test	1	65	65, per test cycle	32	2,080, per test cycle
A300-600	Operational test	1	65	65, per test cycle	89	5,785, per test cycle
A310	Operational test	1	65	65, per test cycle	47	3,055, per test cycle

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a

"significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-04-10 Airbus: Amendment 39-13491. Docket 2002-NM-04-AD.

Applicability: All Airbus Model A300 B2 and A300 B4 series airplanes; A300 B4-600, B4-600R, C4-605R Variant F, and F4-600R (collectively called A300-600); and A310 series airplanes; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the landing gear selector valves, which could result in residual pressure on the retraction chamber side of the electro-hydraulic selector, and consequent uncommanded retraction of the landing gear when the airplane is on the ground, accomplish the following:

Part Number Identification

(a) For Model A300 B2 and A300 B4 series airplanes: Before the accumulation of 32,000 total flight cycles on the landing gear selector

valves, or within 600 flight hours after the effective date of this AD, whichever occurs later, do the actions required by paragraphs (a)(1) and (a)(2) of this AD.

(1) Inspect to determine whether any selector valve having part number (P/N) A25199-0-2 is installed.

(2) Replace any selector valve having P/N A25199-0-2 with a new selector valve having P/N A25199-0-3, in accordance with Airbus Service Bulletin A300-32-0438, Revision 01, dated November 20, 2001.

Operational Test

(b) For airplanes installed with selector valves having P/N A25199-0-3 only: Before the accumulation of 32,000 total flight cycles on the landing gear selector valves, or within 600 flight hours after the effective date of this AD, whichever occurs later, perform an operational test of the selector valves. Do the test in accordance with the Accomplishment Instructions of Airbus Service Bulletins A300-32-0438 (for Model A300 B2 and A300 B4 series airplanes), A300-32-6082 (for Model A300-600 series airplanes and Model A300 C4-605R Variant F airplanes), and A310-32-2118 (for Model A310 series airplanes); all Revision 01, dated November 20, 2001; as applicable. Before further flight, replace any valve that fails the operational test with a new valve having P/N A25199-0-3, in accordance with the applicable service bulletin.

Follow-on and Corrective Actions

(c) For Model A300 B2 and A300 B4 series airplanes that have not been modified in accordance with Airbus Modification 3083 (Airbus Service Bulletin A300-32-0269): Within 3,000 flight hours after the accumulation of 32,000 total flight cycles on the valve, or within 3,000 flight hours after performing the operational test required by paragraph (b) of this AD, whichever occurs later, do task 323112-0503-2 of the Airbus A300 Maintenance Planning Document (MPD). Repeat the MPD task thereafter at intervals not to exceed 3,000 flight hours.

(d) For Model A300 B2 and A300 B4 series airplanes that have been modified in accordance with Airbus Modification 3083 (Airbus Service Bulletin A300-32-0269), and for Model A300-600 and A310 series airplanes and Model A300 C4-605R Variant F airplanes: Repeat the operational test specified in paragraph (b) of this AD at the later of the times specified by paragraphs (d)(1) and (d)(2) of this AD. Thereafter, repeat the test at intervals not to exceed 18 months or 2,800 flight cycles, whichever occurs first.

(1) Within 18 months or 2,800 flight cycles, whichever occurs first, after the accumulation of 32,000 total flight cycles on the valve.

(2) Within 18 months or 2,800 flight cycles, whichever occurs first, after performing the initial operational test required by paragraph (b) of this AD.

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(f) Unless otherwise specified in this AD, the actions must be done in accordance with Airbus Service Bulletin A300-32-0438, Revision 01, including Appendix 01, dated November 20, 2001; Airbus Service Bulletin A300-32-6082, Revision 01, including Appendix 01, dated November 20, 2001; and Airbus Service Bulletin A310-32-2118, Revision 01, including Appendix 01, dated November 20, 2001; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 1: The subject of this AD is addressed in French airworthiness directive 2001-603(B), dated December 12, 2001.

Effective Date

(g) This amendment becomes effective on April 13, 2004.

Issued in Renton, Washington, on February 27, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-4921 Filed 3-8-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2004-NM-03-AD; Amendment 39-13514; AD 2004-05-19]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, -800, and -900 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to all Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. This action requires an inspection of the rear spar attach pins and front spar attach bolts that attach the horizontal stabilizers to the horizontal stabilizer center section for damage; and follow-on or corrective actions, as applicable. This action is necessary to detect and correct damaged rear spar attach pins or front spar attach bolts, which may lead to failure of the

bolts or pins, and consequent loss of the stabilizer and loss of controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective March 24, 2004.

The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of March 24, 2004.

Comments for inclusion in the Rules Docket must be received on or before May 10, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2004-NM-03-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2004-NM-03-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6440; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: The FAA has received numerous reports indicating that, during incorporation of Boeing Service Bulletin 737-55-1074, damaged rear spar attach pins and front spar attach bolts that attach the horizontal stabilizers to the horizontal stabilizer center section were found on Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. The damaged bolts and pins have premature wear, corrosion, pitting, and galling. Such damaged rear spar attach pins or front spar attach bolts, if not corrected, may lead to failure of the bolts or pins, which could result in loss of the