

Rules and Regulations

Federal Register

Vol. 69, No. 6

Friday, January 9, 2004

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002–NM–252–AD; Amendment 39–13420; AD 2004–01–06]

RIN 2120–AA64

Airworthiness Directives; Fokker Model F.28 Mark 0070 and 0100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Fokker Model F.28 Mark 0070 and 0100 series airplanes. This AD requires a one-time general visual inspection of the left and right sides of the pedestal side cover adjacent to the rudder pedal on the cockpit floor for proper installation of the attachment bracket, and corrective actions if necessary. This action is necessary to prevent restricted movement of the rudder pedal due to a loose pedestal side cover causing interference, which could result in reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective February 13, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 13, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton,

Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez; Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–1137; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Fokker Model F.28 Mark 0070 and 0100 series airplanes was published in the **Federal Register** on October 14, 2003 (68 FR 59136). That action proposed to require a one-time general visual inspection of the left and right sides of the pedestal side cover adjacent to the rudder pedal on the cockpit floor for proper installation of the attachment bracket, and corrective actions if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

We estimate that 76 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required inspections, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$4,940, or \$65 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time

required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004–01–06 Fokker Services B.V.

Amendment 39–13420. Docket 2002–NM–252–AD.

Applicability: Model F.28 Mark 0070 and 0100 series airplanes, having serial numbers 11244 through 11585 inclusive; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent restricted movement of the rudder pedal due to a loose pedestal side cover causing interference, which could result in reduced controllability of the airplane, accomplish the following:

Inspection and Corrective Actions

(a) Within 12 months after the effective date of this AD, do a one-time general visual inspection of the left and right sides of the pedestal side cover adjacent to the rudder pedal on the cockpit floor for proper installation of the attachment brackets, in accordance with Part 1 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-25-092, dated February 4, 2002.

Note 1: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(1) If both brackets are present and the pedestal side cover is properly installed, no further action is required by this AD.

(2) If one or both brackets are missing, or the pedestal side cover is improperly installed, before further flight, accomplish all of the applicable corrective actions in accordance with Part 2 of the Accomplishment Instructions of the service bulletin.

Alternative Methods of Compliance

(b) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(c) The actions shall be done in accordance with Fokker Service Bulletin SBF100-25-092, dated February 4, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 2: The subject of this AD is addressed in Dutch airworthiness directive 2002-111, dated July 31, 2002.

Effective Date

(d) This amendment becomes effective on February 13, 2004.

Issued in Renton, Washington, on December 29, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-127 Filed 1-8-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-231-AD; Amendment 39-13419; AD 2004-01-05]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 2000 and 900EX, and Dassault Model Mystere-Falcon 900 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Dassault Model Falcon 2000 and 900EX, and Dassault Model Mystere-Falcon 900 series airplanes. This AD requires measuring the paint thickness on the upper and lower surfaces of the left and right sides of the horizontal stabilizer, performing corrective actions if necessary, and installing maintenance caution placards on the upper surface of the left and right sides of the horizontal stabilizer. This action is necessary to prevent structural damage to the horizontal stabilizer after a direct lightning strike, which could result in reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective February 13, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 13, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington

98055-4056; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Dassault Model Falcon 2000 and 900EX, and Dassault Model Mystere-Falcon 900 series airplanes, was published in the **Federal Register** on November 13, 2003 (68 FR 64286). That action proposed to require measuring the paint thickness on the upper and lower surfaces of the left and right sides of the horizontal stabilizer, performing corrective actions if necessary, and installing maintenance caution placards on the upper surface of the left and right sides of the horizontal stabilizer.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

After careful review of the available data, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

We estimate that 29 airplanes of U.S. registry will be affected by this AD.

It will take approximately 16 work hours per airplane to measure the paint thickness, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact on U.S. operators for measuring the paint thickness is estimated to be \$30,160, or \$1,040 per airplane.

It will take approximately 3 work hours per airplane, at an average labor rate of \$65 per work hour, to install the placards. Required parts will be provided to operators at no cost. Based on these figures, the cost impact on U.S. operators for the installation of the placards is estimated to be \$5,655, or \$195 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up,