

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this AD action by April 7, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A320 series airplanes, certificated in any category; equipped with Hamilton Sundstrand airborne ground check module (AGCM) having part number 769104, 769105, or 760106 installed; except those airplanes on which Airbus Modification 27189 has been done in production and on which Airbus Modification 28413 has not been done.

Unsafe Condition

(d) This AD was prompted by reports of unsuccessful in-flight ram air turbine (RAT) tests during which a deployed RAT failed to pressurize the blue hydraulic circuit of the RAT system. We are issuing this AD to prevent failure of the RAT system during an in-flight emergency, which could lead to loss of hydraulic and electrical power and reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

RAT System Bleeding/Functional Test

(f) For airplanes on which maintenance has been performed on the blue hydraulic circuit as of the effective date of this AD: Within 3 days or 20 flight hours after the effective date of this AD, whichever occurs first, bleed accumulated air from, or perform a ground functional test of, the RAT system; by accomplishing all the actions specified in Airbus All Operators Telex (AOT) A320-29A1112, Revision 01, dated April 8, 2004. Thereafter, bleed the blue hydraulic circuit as specified in the AOT within 3 days or 20 flight hours after performing any maintenance on the blue hydraulic circuit.

(g) For airplanes on which maintenance has not been performed on the blue hydraulic circuit as of the effective date of this AD: Bleed the blue hydraulic circuit as specified in the AOT within 3 days or 20 flight hours after performing any maintenance on the blue hydraulic circuit.

Replacement of AGCM and Reducer

(h) Within 35 months after the effective date of this AD, replace the AGCM with a modified and reidentified AGCM; and replace the reducer with a new reducer as applicable; in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-29-1111, dated June 29, 2004. Replacing the AGCM, and the reducer as applicable, ends the actions required by paragraphs (f) and (g) of this AD.

Note 1: Airbus Service Bulletin A320-29-1111 refers to Hamilton Sundstrand Service Bulletin ERPS13GCM-29-5, dated June 29, 2004, as an additional source of service information for modifying and reidentifying the AGCM.

Alternative Methods of Compliance (AMOCs)

(i) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(j) French airworthiness directive F-2004-150, dated September 1, 2004, also addresses the subject of this AD.

Issued in Renton, Washington, on February 28, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-4408 Filed 3-7-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2005-20501; Directorate Identifier 2004-NM-251-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 170 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all EMBRAER Model ERJ 170 series airplanes. This proposed AD would require inspecting the engine fire handles of the overhead panel in the cockpit, and replacing the engine fire handles if necessary. This proposed AD is prompted by reports of failure of the internal circuit of the engine fire handles of the overhead panel in the cockpit. We are proposing this AD to prevent failure of the internal circuit of the engine fire handles, which could result in failure of the fuel shut-off valves to close and failure of the fire extinguishing agent to discharge in the event of an engine fire.

DATES: We must receive comments on this proposed AD by April 7, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-20501; the directorate identifier for this docket is 2004-NM-251-AD.

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1503; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-20501; Directorate Identifier 2004-NM-251-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of our docket Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can

review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

The Departamento de Aviacao Civil (DAC), which is the airworthiness authority for Brazil, notified us that an unsafe condition may exist on all EMBRAER Model ERJ 170 series airplanes. The DAC advises that the internal circuit of the engine fire handles of the overhead panel in the cockpit failed due to a design error of the flex circuit subassembly that was introduced with the engine fire handles. This condition, if not corrected, could result in failure of the fuel shut-off valves to close and failure of the fire extinguishing agent to discharge in the event of an engine fire.

Relevant Service Information

EMBRAER has issued Service Bulletin 170-26-0001, Revision 02, dated January 11, 2005. The service bulletin describes procedures for inspecting the engine fire handles of the overhead panel in the cockpit to determine the part number (P/N) installed, and replacing the engine fire handles with new ones if necessary. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The DAC mandated the service information and issued Brazilian airworthiness directive 2004-10-02, dated October 30, 2004, to ensure the continued airworthiness of these airplanes in Brazil.

FAA's Determination and Requirements of the Proposed AD

This airplane model is manufactured in Brazil and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DAC has kept the FAA informed of

the situation described above. We have examined the DAC's findings, evaluated all pertinent information, and determined that we need to issue an AD for products of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

This proposed AD would affect about 24 airplanes of U.S. registry. The proposed inspection would take about 1 work hour per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$1,560, or \$65 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Empresa Brasileira De Aeronautica S.A. (EMBRAER): Docket No. FAA-2005-20501; Directorate Identifier 2004-NM-251-AD.

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this AD action by April 7, 2005.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to all EMBRAER Model ERJ 170 series airplanes, certificated in any category.

Unsafe Condition

(d) This AD was prompted by reports of failure of the internal circuit of the engine fire handles of the overhead panel in the cockpit. We are issuing this AD to prevent failure of the internal circuit of the engine fire handles, which could result in failure of the fuel shut-off valves to close and failure of the fire extinguishing agent to discharge in the event of an engine fire.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection

(f) Within 600 flight hours or 180 days after the effective date of this AD, whichever occurs first, inspect the engine fire handles of the overhead panel in the cockpit to determine the part number (P/N) installed, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 170-26-0001, Revision 02, dated January 11, 2005.

(1) If only engine fire handles having P/N 1-7054-1 (left-hand side) and P/N 2-7054-1 (right-hand side) are found installed, no further action is required by this paragraph.

(2) If any engine fire handle having P/N 1-7054-2 (left-hand side) or P/N 2-7054-2 (right-hand side) is found installed, before further flight, replace the engine fire handle with a new engine fire handle having P/N 1-7054-1 (left-hand side) or P/N 2-7054-1 (right-hand side), as applicable, in accordance with the Accomplishment Instructions of the service bulletin.

(g) Applicable actions done before the effective date of this AD in accordance with EMBRAER Service Bulletin 170-26-0001, dated October 6, 2004; or Revision 01, dated November 3, 2004; are acceptable for compliance with the corresponding requirements of paragraph (f) of this AD.

Parts Installation

(h) As of the effective date of this AD, no person may install a engine fire handle having P/N 1-7054-2 (left-hand side) or P/N 2-7054-2 (right-hand side), on any airplane.

Alternative Methods of Compliance (AMOCs)

(i) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(j) Brazilian airworthiness directive 2004-10-02, dated October 30, 2004, also addresses the subject of this AD.

Issued in Renton, Washington, on February 28, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 05-4409 Filed 3-7-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Alcohol and Tobacco Tax and Trade Bureau

27 CFR Part 9

[Notice No. 34]

RIN 1513-AA64

Proposed Fort Ross-Seaview Viticultural Area (2003R-191T)

AGENCY: Alcohol and Tobacco Tax and Trade Bureau, Treasury.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Alcohol and Tobacco Tax and Trade Bureau proposes to establish the 27,500-acre Fort Ross-Seaview viticultural area in western Sonoma County, California. We designate viticultural areas to allow vintners to better describe the origin of their wines and to allow consumers to better

identify wines they may purchase. We invite comments on this proposed addition to our regulations.

DATES: We must receive written comments on or before May 9, 2005.

ADDRESSES: You may send comments to any of the following addresses:

- Chief, Regulations and Procedures Division, Alcohol and Tobacco Tax and Trade Bureau, Attn: Notice No. 34, P.O. Box 14412, Washington, DC 20044-4412.
- 202-927-8525 (facsimile).
- nprm@ttb.gov (e-mail).
- <http://www.ttb.gov/alcohol/rules/index.htm>. An online comment form is posted with this notice on our Web site.
- <http://www.regulations.gov> (Federal e-rulemaking portal; follow instructions for submitting comments).

You may view copies of this notice, the petition, the appropriate maps, and any comments we receive about this notice by appointment at the TTB Library, 1310 G Street, NW., Washington, DC 20220. To make an appointment, call 202-927-2400. You may also access copies of the notice and comments online at <http://www.ttb.gov/alcohol/rules/index.htm>.

See the Public Participation section of this notice for specific instructions and requirements for submitting comments, and for information on how to request a public hearing.

FOR FURTHER INFORMATION CONTACT: N. A. Sutton, Regulations and Procedures Division, Alcohol and Tobacco Tax and Trade Bureau, 925 Lakeville St., No. 158, Petaluma, California 94952; telephone 415-271-1254.

SUPPLEMENTARY INFORMATION:

Background on Viticultural Areas

TTB Authority

Section 105(e) of the Federal Alcohol Administration Act (the FAA Act, 27 U.S.C. 201 *et seq.*) requires that alcohol beverage labels provide the consumer with adequate information regarding a product's identity and prohibits the use of misleading information on those labels. The FAA Act also authorizes the Secretary of the Treasury to issue regulations to carry out its provisions. The Alcohol and Tobacco Tax and Trade Bureau (TTB) administers these regulations.

Part 4 of the TTB regulations (27 CFR part 4) allows the establishment of definitive viticultural areas and the use of their names as appellations of origin on wine labels and in wine advertisements. Part 9 of the TTB regulations (27 CFR part 9) contains the list of approved viticultural areas.

Definition

Section 4.25(e)(1)(i) of the TTB regulations (27 CFR 4.25(e)(1)(i)) defines a viticultural area for American wine as a delimited grape-growing region distinguishable by geographical features, the boundaries of which have been recognized and defined in part 9 of the regulations. These designations allow vintners and consumers to attribute a given quality, reputation, or other characteristic of a wine made from grapes grown in an area to its geographic origin. The establishment of viticultural areas allows vintners to describe more accurately the origin of their wines to consumers and helps consumers to identify wines they may purchase. Establishment of a viticultural area is neither an approval nor an endorsement by TTB of the wine produced in that area.

Requirements

Section 4.25(e)(2) of the TTB regulations outlines the procedure for proposing an American viticultural area and provides that any interested party may petition TTB to establish a grape-growing region as a viticultural area. Section 9.3(b) of the TTB regulations requires the petition to include—

- Evidence that the proposed viticultural area is locally and/or nationally known by the name specified in the petition;
- Historical or current evidence that supports setting the boundary of the proposed viticultural area as the petition specifies;
- Evidence relating to the geographical features, such as climate, elevation, physical features, and soils, that distinguish the proposed viticultural area from surrounding areas;
- A description of the specific boundary of the proposed viticultural area, based on features found on United States Geological Survey (USGS) maps; and
- A copy of the appropriate USGS map(s) with the proposed viticultural area's boundary prominently marked.

Fort Ross-Seaview Petition

Patrick Shabram, on his own behalf and on behalf of David Hirsch of Hirsch Vineyards, submitted a petition to establish the "Fort Ross-Seaview" American viticultural area in western Sonoma County, California. The proposed Fort Ross-Seaview viticultural area is within the existing North Coast (27 CFR 9.30) and Sonoma Coast (27 CFR 9.116) viticultural areas. The area is close to the Pacific Ocean about 65 miles north-northwest of San Francisco. The petitioner states that the proposed