

(b) Any producer entitled to any payment may assign any payments in accordance with regulations governing assignment of payment found at 7 CFR part 1404.

§ 1469.36 Misrepresentation and scheme or device.

(a) If the Department determines that a participant erroneously represented any fact affecting a CSP determination made in accordance with this part, the participant's conservation stewardship contract will be terminated immediately in accordance with § 1469.25(b). The participant will forfeit all rights for future contract payments, and must refund payments received, plus interest, and liquidated damages as described in § 1469.25.

(b) A producer who is determined to have knowingly:

(1) Adopted any scheme or device that tends to defeat the purpose of CSP;

(2) Made any fraudulent representation; or

(3) Misrepresented any fact affecting a CSP determination, must refund to NRCS all payments, plus interest, and liquidated damages as determined in accordance with § 1469.25 received by such participant with respect to all contracts. In addition, NRCS will terminate the participant's interest in all conservation stewardship contracts.

(c) If the producer acquires land subsequent to enrollment in CSP, that land is not considered part of the agricultural operation; however, if the land was previously owned or controlled by them before the date of enrollment and after May 13, 2002, then NRCS will conduct an investigation into the activity to see if there was a scheme or device.

Signed in Washington, DC, on March 18, 2005.

Bruce I. Knight,

Vice President, Commodity Credit Corporation, Chief, Natural Resources Conservation Service.

[FR Doc. 05-5894 Filed 3-24-05; 8:45 am]

BILLING CODE 3410-16-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20514; Directorate Identifier 2005-CE-08-AD; Amendment 39-14025; AD 2005-07-01]

RIN 2120-AA64

Airworthiness Directives; The Cessna Aircraft Company Models C208 and C208B Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all The Cessna Aircraft Company (Cessna) Models 208 and 208B airplanes. This AD requires you to incorporate information into the applicable section of the Airplane Flight Manual (AFM). This AD results from several accidents/incidents of problems with the affected airplanes during operations in icing conditions, including six accidents in the previous two icing seasons and nine events in the past few months. We are issuing this AD to assure that the pilot has enough information to prevent loss of control of the airplane while in-flight during icing conditions.

DATES: This AD becomes effective on March 29, 2005.

We must receive any comments on this AD by April 30, 2005.

ADDRESSES: Use one of the following to submit comments on this AD:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400

Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001.

- *Fax:* 1-202-493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- To get the service information identified in this proposed AD, contact The Cessna Aircraft Company, Product Support, PO Box 7706, Wichita, Kansas 67277-7706; telephone: (316) 517-5800; facsimile: (316) 942-9006.

To view the comments to this AD, go to <http://dms.dot.gov>. The docket number is FAA-2005-20514; Directorate Identifier 2005-CE-08-AD.


FOR FURTHER INFORMATION CONTACT: Paul Pellicano, Aerospace Engineer (Icing), FAA, Small Airplane Directorate, c/o Atlanta Aircraft Certification Office (ACO), One Crown Center, 1985 Phoenix Boulevard, Suite 450, Atlanta, GA 30349; telephone: (770) 703-6064; facsimile: (770) 703-6097.

SUPPLEMENTARY INFORMATION:

What events have caused this AD?

The FAA has received several reports of accidents/incidents concerning problems with Cessna Models C208 and C208B airplanes during operations in icing conditions. This includes a total of six accidents in the previous two icing seasons and nine events in the past few months. Most of the accidents occur on approach and landing. One-third are suspected to be in supercooled large droplets, icing conditions outside the 14 CFR part 25 Appendix C certification envelope. The Cessna Models C208 and C208B are certificated to 14 CFR part 23, but 14 CFR part 23 references 14 CFR part 25 Appendix C for icing certification. The following chart shows the monthly breakdown of the icing accidents/incidents of the affected airplanes:

**U.S. Icing Accidents per Month
since 1983**



The information shows that icing accidents/incidents are just as prevalent or more prevalent during the months of March and April than in November, December, and January. Therefore, the next month is critical for the continued

operational safety of the Cessna Models C208 and C208B in icing conditions.

What is the potential impact if FAA took no action? If the pilot does not have enough information on flight into icing conditions in the Airplane Flight

Manual (AFM), then loss of control of the airplane could occur.

Is there service information that applies to this subject? Cessna has developed revisions to the FAA-approved AFM to address this issue, as follows:

| Document | Affects |
|--|---|
| Temporary Revision 208PHTR04, dated March 2, 2005, to the FAA-approved Airplane Flight Manual. | Cessna Model 208, all models and serial numbers. |
| Revision 5 of the 208 (675 SHP) FAA-approved Flight Supplement 1 "Known Icing Equipment", Cessna document D1352-S1-05, dated March 2, 2005. | Cessna Model C208 airplanes with a Pratt & Whitney Canada Ltd., PT6A-114A turboprop engine installed (675 SHP) or FAA-approved engine of equivalent horsepower installed, except airplanes modified by Supplemental Type Manual Certificate SA00892WI. |
| Revision 5 of the 208B (600 SHP) FAA-approved Flight Manual Supplement S1 "Known Icing Equipment", Cessna document D1307-S1-05, dated March 2, 2005. | Cessna Model C208 airplanes with a Pratt & Whitney Canada Ltd., PT6A-114 turboprop engine installed (600 SHP) or FAA-approved engine of equivalent horsepower approved installed, except airplanes modified by Supplemental Type Certificate SA00892WI. |
| Revision 6 of the 208B (675 SHP) FAA-approved Flight Manual Supplement S1 "Known Icing Equipment", Cessna document D1329-S1-06, dated March 2, 2005. | Cessna Model C208B airplanes with a Pratt & Whitney of Canada Ltd., PT6A-114A turboprop engine installed (675 SHP) or FAA-approved engine of equivalent horsepower installed, except airplanes modified by Supplemental Type Certificate SA00892WI. |
| Revision 5 of the 208B (600 SHP) FAA-approved Flight Manual Supplement S1 "Known Icing Equipment", Cessna document D1309-S1-05, dated March 2, 2005. | Cessna Model C208B airplanes with a Pratt & Whitney of Canada Ltd., PT6A-114 turboprop engine installed (600 SHP) or FAA-approved engine of equivalent horsepower installed, except airplanes modified by Supplemental Type Certificate SA00892WI. |

FAA's Determination and Requirements of the AD

What has FAA decided? We have evaluated all pertinent information and identified an unsafe condition that is

likely to exist or develop on other products of the same type design.

Since the unsafe condition described previously is likely to exist or develop on other type design Cessna Models C208 and C208B airplanes, we are

issuing this AD to assure that the pilot has enough information to prevent loss of control of the airplane while in-flight during icing conditions.

What does this AD require? This AD requires you to incorporate the above-referenced documents into the AFM.

In preparing this rule, we contacted type clubs and aircraft operators to get technical information and information on operational and economic impacts. We did not receive any information through these contacts that influenced our decision. The majority of the respondents supported the dissemination of the information in the revised AFM.

How does the revision to 14 CFR part 39 affect this AD? On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Comments Invited

Will I have the opportunity to comment before you issue the rule? This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-20514; Directorate Identifier 2005-CE-08-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify it. If a person contacts us through a nonwritten communication, and that contact relates to a substantive part of this AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may

amend the AD in light of those comments.

Authority for This Rulemaking

What authority does FAA have for issuing this rulemaking action? Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

Regulatory Findings

Will this AD impact various entities?

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Will this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket FAA-2005-20514;

Directorate Identifier 2005-CE-08-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2005-07-01 The Cessna Aircraft Company:
Amendment 39-14025; Docket No. FAA-2005-20514; Directorate Identifier 2005-CE-08-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on March 29, 2005.

Are Any Other ADs Affected by This Action?

(b) None.

What Airplanes Are Affected by This AD?

(c) This AD affects Models C208 and C208B, all serial numbers, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

(d) This AD results from several accidents/incidents of problems with the affected airplanes during operations in icing condition, including six accidents in the previous two icing seasons and nine events in the past few months. We are issuing this AD to assure that the pilot has enough information to prevent loss of control of the airplane while in-flight during icing conditions.

What Must I Do To Address This Problem?

(e) No later than April 1, 2005 (3 days after March 29, 2005, which is the effective date of this AD), incorporate the following revisions into the Airplane Flight Manual:

| Affected airplanes | Incorporate the following AFM revision document | Revise the Performance Section (Section 5) of the AFM Supplement by inserting the following text (this may be done by inserting a copy of this AD in the AFM Supplement) |
|---|--|--|
| (1) Cessna Model C208 airplanes and Model C208B airplanes, all serial numbers. | <i>Section 2: Limitations and Section 4: Normal Procedures:</i> Temporary Revision 208PHTR04, dated March 2, 2005, to the Pilots Operating Handbook (POH) and FAA-approved Airplane Flight Manual (AFM), except replace the Limitations (Section 2) of the Temporary Revision 208PHTR04 to the POH/FAA-approved AFM with the Appendix to this AD. (This may be done by inserting a copy of this AD into the POH/AFM.). | None. |
| (2) Cessna Model C208 airplanes with a Pratt & Whitney of Canada Ltd., PT6A-114A turboprop engine installed (675 SHP) or FAA-approved engine of equivalent horsepower installed, except airplanes modified by Supplemental Type Certificate SA0892WI. | <i>Section 9: Optional Systems Description and Operating Procedures:</i> Revision 5 of the 208 (675 SHP) POH/FAA-approved AFM Supplement S1 "Known Icing Equipment" Cessna document D1352-S1-05, dated March 2, 2005. | WARNING: The stall warning system has not been tested in all icing conditions and should not be relied upon in icing conditions. |
| (3) Cessna Model C208 airplanes with a Pratt & Whitney of Canada Ltd., PT6A-114 turboprop engine installed (600 SHP) or FAA-approved engine of equivalent horsepower installed, except airplanes modified by Supplemental Type Certificate SA00892WI. | <i>Section 9: Optional Systems Description and Operating Procedures</i> Revision 5 of the Cessna Model 208 (600 SHP) POH/FAA-approved AFM Supplement S1 "Known Icing Equipment", Cessna document D1307-S1-05, dated March 2, 2005, except incorporate the Appendix to this AD into paragraphs "PREFLIGHT" and "VISUAL/TACTILE CHECK" of the Limitations Section of the POH/FAA-approved AFM Supplement S1 "Known Icing Equipment". | WARNING: The stall warning system has not been tested in all icing conditions and should not be relied upon in icing conditions. |
| (4) Cessna Model C208B airplanes with a Pratt & Whitney of Canada Ltd., PT6A-114A turboprop engine installed (675 SHP) or FAA-approved engine of equivalent horsepower installed, except airplanes modified by Supplemental Type Certificate SA00892WI. | <i>Section 9: Optional Systems Description and Operating Procedures</i> Revision 6 of the 208B (675 SHP) POH/FAA-approved AFM Supplement S1 "Known Icing Equipment", Cessna document D1329-S1-06, dated March 2, 2005. | WARNING: The stall warning system has not been tested in all icing conditions and should not be relied upon in icing conditions. |
| (5) Cessna Model C208B airplanes with a Pratt & Whitney of Canada Ltd., PT6A-114A turboprop engine installed (600 SHP) or FAA-approved engine of equivalent horsepower installed, except airplanes modified by Supplemental Type Certificate SA00892WI. | <i>Section 9: Optional Systems Description and Operating Procedures</i> Revision 5 of the 208B (600 SHP) POH/FAA-approved AFM Supplement S1 "Known Icing Equipment", Cessna document D1309-S1-05, dated March 2, 2005. | WARNING: The stall warning system has not been tested in all icing conditions and should not be relied upon in icing conditions. |

(f) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do the flight manual changes requirement of this AD. Make an entry in the aircraft records showing compliance with this portion of the AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

May I Request an Alternative Method of Compliance?

(g) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Staff, Small Airplane Directorate, FAA, c/o Paul Pellicano, Aerospace Engineer (Icing), FAA, Small Airplane Directorate, c/o Atlanta Aircraft Certification Office (ACO), One Crown Center, 1895 Phoenix Boulevard, Suite 450,

Atlanta, GA 30349; telephone: (770) 703-6064; facsimile: (770) 703-6097. For information on any already approved alternative methods of compliance, contact Paul Pellicano at the address and phone number above.

May I Get Copies of the Document Referenced in this AD?

(h) You may obtain the service information referenced in this AD from The Cessna Aircraft Company, Product Support, PO Box 7706, Wichita, Kansas 67277-7706; telephone: (316) 517-5800; facsimile: (316) 942-9006. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC, or on the Internet at <http://dms.dot.gov>. This is docket number FAA-2005-20048; Directorate Identifier 2005-CE-08-AD.

Appendix to AD 2005-07-01, Amendment 39-14025

[Docket No. FAA-2005-20514; Directorate Identifier 2005-CE-08-AD]

Preflight

Takeoff is prohibited with any frost, ice, snow, or slush adhering to the wings, horizontal stabilizer, control surfaces, propeller blades, and engine inlets.

Warning

Even small amounts of frost, ice, and snow, or slush on the wing may adversely change lift and drag. Failure to remove these contaminants will degrade airplane performance and may prevent a safe takeoff and climbout.

Visual/Tactile Check

In addition to a visual check, a tactile check of the wing leading edge, wing upper surface (up to two feet behind the deicing boot at on-span location as a minimum), horizontal tail leading edge, and propeller

blades is required if the outside air temperature (OAT) is below 5° C (41° F) and visible moisture (rain, drizzle, sleet, snow, fog etc.) is present or the airplane was exposed to visible moisture (rain, drizzle, sleet, snow, fog etc.) since the previous landing; or the airplane experienced in-flight ice accretion since the previous takeoff; or the difference between the dew point temperature and the OAT is 3° C (5° F) or less; or water is present on the wing. Reference the preflight procedures in Section 4 of the basic Pilot's Operating Handbook.

Issued in Kansas City, Missouri, on March 21, 2005.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-5915 Filed 3-24-05; 8:45 am]

BILLING CODE 4910-13-P

SOCIAL SECURITY ADMINISTRATION

20 CFR Part 404

[Regulation No. 4]

RIN 0960-AD67

Technical Amendments To Change Cross-References

AGENCY: Social Security Administration.

ACTION: Final rule; correcting amendments.

SUMMARY: This document corrects two cross-references in the final rules we published in the **Federal Register** on November 15, 2004 (69 FR 67017). These final rules revised the criteria in the Listing of Impairments (the listings) that we use to evaluate claims involving malignant neoplastic diseases.

EFFECTIVE DATE: Effective on March 25, 2005.

FOR FURTHER INFORMATION CONTACT: Suzanne DiMarino, Social Insurance Specialist, 6401 Security Boulevard, Baltimore, MD 21235-6401. Call (410) 965-1769 or TTY 1-800-325-0778 for information about these correcting amendments. For information on eligibility or filing for benefits, call our national toll-free number 1-(800) 772-1213 or TTY 1-(800) 325-0778. You may also contact Social Security Online at <http://www.socialsecurity.gov/>.

SUPPLEMENTARY INFORMATION: We are making two corrections to listing 13.00 in appendix 1 of subpart P of part 404 of our regulations that was published in the **Federal Register** on November 15, 2004 (69 FR 67017). The first correction revises the cross-reference in the last sentence of listing 13.00K1b. The second correction revises the cross-references in the heading of listing 13.02.

(Catalog of Federal Domestic Assistance Programs Nos. 96.001, Social Security—Disability Insurance; 96.002, Social Security—Retirement Insurance; 96.004, Social Security—Survivors Insurance)

List of Subjects in 20 CFR Part 404

Administrative practice and procedure, Blind, Disability benefits, Old-Age, Survivors and Disability Insurance, Reporting and recordkeeping requirements, Social Security.

Dated: March 21, 2005.

Martin Sussman,

Regulations Officer.

■ For the reasons set out in the preamble, subpart P of part 404 of chapter III of title 20 of the Code of Federal Regulations is corrected by making the following correcting amendments:

PART 404—FEDERAL OLD-AGE, SURVIVORS AND DISABILITY INSURANCE (1950—)

Subpart P—[Amended]

■ 1. The authority citation for subpart P continues to read as follows:

Authority: Secs. 202, 205(a), (b), and (d)—(h), 216(i), 221(a) and (i), 222(c), 223, 225, and 702(a)(5) of the Social Security Act (42 U.S.C. 402, 405(a), (b), and (d)—(h), 416(i), 421(a) and (i), 422(c), 423, 425, and 902(a)(5)); sec. 211(b), Pub. L. 104-193, 110 Stat. 2105, 2189.

Appendix 1 to Subpart P of Part 404—[Amended]

■ 2. Amend Appendix 1 to subpart P as follows:

■ a. In Listing 13.00K1b, revise the reference “13.55A2a” in the last sentence to read “13.05A2.”

■ b. In the heading of Listing 13.02, revise the references to “13.06” and “13.07” to read “13.08” and “13.09,” respectively.

[FR Doc. 05-5921 Filed 3-24-05; 8:45 am]

BILLING CODE 4191-02-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[TD 9187]

RIN 1545-BA52

Loss Limitation Rules; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correcting amendment.

SUMMARY: This document corrects final regulations (TD 9187) that were

published in the **Federal Register** on Thursday, March 3, 2005 (70 FR 10319), that disallows certain losses recognized on sales of subsidiary stock by members of a consolidated group.

DATES: This correction is effective on April 4, 2005.

FOR FURTHER INFORMATION CONTACT:

Theresa Abell, (202) 622-7700 or Martin Huck, (202) 622-7750 (not toll-free numbers).

SUPPLEMENTARY INFORMATION:

Background

The final and temporary regulations (TD 9187) that is the subject of this correction is under sections 337(d) and 1502 of the Internal Revenue Code.

Need for Correction

As published, (TD 9187) contains an error that may prove to be misleading and is in need of clarification.

List of Subjects in 26 CFR Part 1

Income taxes, Reporting and recordkeeping requirements.

Correction of Publication

■ Accordingly, 26 CFR part 1 is corrected by making the following correcting amendment:

PART 1—INCOME TAXES

■ **Paragraph 1.** The authority citation for part 1 continues to read in part as follows:

Authority: 26 U.S.C. 7805 * * *

§ 1.1502-20 [Corrected]

Section 1.1502-20(i)(3)(viii), second sentence, the language “Any reapportionment of a section 382 limitation made pursuant to the previous sentence shall have the effects described in paragraphs (i)(3)(iii)(D)(ii) and (iii) of this section.” is removed and the language “Any reapportionment of a section 382 limitation made pursuant to the previous sentence shall have the effects described in paragraph (i)(3), (iii)(D)(2) and (3) of this section.” is added in its place.

Cynthia E. Grigsby,

Acting Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedures and Administration).

[FR Doc. 05-5969 Filed 3-24-05; 8:45 am]

BILLING CODE 4830-01-P