

Dated at Rockville, Maryland, this 12th day of April, 2005.

For the Nuclear Regulatory Commission.

Annette L. Vietti-Cook,

Secretary of the Commission.

[FR Doc. 05-7658 Filed 4-15-05; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-352-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 and -145 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD), applicable to certain Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 and -145 series airplanes. That action would have required replacement of the air turbine starters (ATSSs) with modified ATSSs. Since the issuance of the NPRM, we have reviewed the requirements of the proposed AD and determined that the same unsafe condition is addressed in another AD. Accordingly, this proposed AD is withdrawn.

FOR FURTHER INFORMATION CONTACT:

Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add a new airworthiness directive (AD), applicable to certain EMBRAER Model EMB-135 and -145 series airplanes, was published in the **Federal Register** as a Notice of Proposed Rulemaking (NPRM) on December 18, 2003 (68 FR 70475). The proposed rule would have required replacement of the air turbine starters (ATSSs) with modified ATSSs. That action was prompted by notification from the Departamento de Aviacao Civil (DAC), which is the airworthiness authority for Brazil, of an unsafe condition. The DAC advised it had received reports of interference problems between the engine ATSSs' output shafts and the engine accessory gear box (AGB) shafts.

The proposed actions were intended to prevent a sheared ATS output shaft from allowing oil to flow down the engine AGB shafts and dripping into the engine compartments, and consequent oil fire, in-flight shutdown, and/or rejected take-off.

Actions That Occurred Since the NPRM Was Issued

Since we issued the NPRM, we have determined that the DAC issued two Brazilian airworthiness directives that address that same unsafe condition. The DAC issued Brazilian airworthiness directives 2001-09-04, dated October 10, 2001, and 2003-07-01R1, dated December 23, 2003. We issued a parallel proposed AD for each Brazilian airworthiness directive. One proposed AD, Docket Number 2002-NM-352-AD, was published in the **Federal Register** on December 18, 2003 (68 FR 70475). The other proposed AD, Docket Number 2003-NM-237-AD, was published in the **Federal Register** on February 19, 2004 (69 FR 7707). The final rule for Docket Number 2003-NM-237-AD was published in the **Federal Register** on February 17, 2005 (70 FR 8028) as AD 2005-04-05.

FAA's Conclusions

Upon further evaluation, and based on comments received in response to the proposed AD with Docket Number 2002-NM-352-AD, we determined that it was in the best interest of the FAA and the U.S. operators to combine the requirements of both of our proposed ADs into the final rule for Docket Number 2003-NM-237-AD, AD 2005-04-05. The requirements in AD 2005-04-05 adequately address the identified unsafe condition specified in the proposed AD, Docket Number 2002-NM-352-AD. Accordingly, the proposed AD with Docket Number 2002-NM-352-AD is withdrawn. The DAC and the airplane manufacturer support our decision.

Withdrawal of the NPRM does not preclude the FAA from issuing another related action or commit the FAA to any course of action in the future.

Regulatory Impact

Since this action only withdraws a notice of proposed rulemaking, it is neither a proposed nor a final rule and therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, we withdraw the NPRM, Docket Number 2002-NM-352-AD, which was published in the **Federal Register** on December 18, 2003 (68 FR 70475).

Issued in Renton, Washington, on April 11, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-7672 Filed 4-15-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-20969; Directorate Identifier 2005-NM-017-AD]

RIN 2120-AA64

Airworthiness Directives; Raytheon Model DH.125, HS.125, and BH.125 Series Airplanes; Model BAe.125 Series 800A (C-29A and U-125), 800B, 1000A, and 1000B Airplanes; and Model Hawker 800 (including variant U-125A), and 1000 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to certain Raytheon airplanes identified above. The existing AD currently requires a visual inspection to determine whether adequate clearance exists between the fan venturi motor casing and the adjacent equipment, and adjustments, if necessary; and a visual inspection to detect signs of overheating, degradation of insulating materials, and ingestion of debris into the motor, and replacement of discrepant parts with serviceable parts. This proposed AD would instead require that operators replace the fan venturi with a new or modified part. This proposed AD is prompted by reports that the fan venturi overheated and produced smoke while the airplane was on the ground. We are proposing this AD to prevent heat and fire damage to equipment adjacent to the fan venturi, which could result in smoke in the cabin and/or burning equipment.

DATES: We must receive comments on this proposed AD by June 2, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC 20590.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. For service information identified in this proposed AD, contact Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-20969; the directorate identifier for this docket is 2005-NM-017-AD.

FOR FURTHER INFORMATION CONTACT:

Philip Petty, Aerospace Engineer, Electrical Systems and Avionics Branch, ACE-119W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4139; fax (316) 946-4107.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-20969; Directorate Identifier 2005-NM-017-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA

personnel concerning this proposed AD. Using the search function of our docket Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

On May 18, 1994, we issued AD 94-11-03, amendment 39-8919 (59 FR 27231, May 26, 1994), for certain Raytheon Corporate Jets Model DH/BH/HS BAe 125 and Hawker 800 and 1000 series airplanes. That AD requires a visual inspection to determine whether adequate clearance exists between the fan venturi motor casing and the adjacent equipment, and adjustments, if necessary; and a visual inspection to detect signs of overheating, degradation of insulating materials, and ingestion of debris into the motor, and replacement of discrepant parts with serviceable parts. That AD was prompted by reports of smoke emanating from the lavatory due to overheating of the fan venturi motor. We issued that AD to prevent smoke or fire in the cabin while the airplane is in flight.

Actions Since Existing AD Was Issued

Since we issued AD 94-11-03, there have been three additional reports indicating that the fan venturi overheated and produced smoke while the airplane was on the ground. The manufacturer investigated the incidents and found that contamination and corrosion in the fan venturi bearings can jam the rotating assembly and cause the motor to burn out. The airplanes on which the incidents occurred had been

inspected and/or repaired in accordance with AD 94-11-03. These further incidents indicate that the actions in AD 94-11-03 may not be adequate.

Relevant Service Information

We have reviewed Raytheon Service Bulletin SB 21-3669, dated December 2004. The service bulletin describes procedures for two options for corrective action:

Option 1: Replacing the fan venturi with a new fan venturi; or

Option 2: Modifying the fan venturi.

The new or modified fan venturi has a larger bearing area with more lubricant to dissipate heat, higher temperature range lubricant, tighter tolerance bearing parts, and thermal protection. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

The Raytheon Service Bulletin refers to Honeywell Service Bulletin 132322-21-4041, Revision 2, dated August 20, 2004, as an additional source of service information for modifying the fan venturi motor assembly. The Honeywell service bulletin is attached to the Raytheon service bulletin.

FAA's Determination and Requirements of the Proposed AD

The unsafe condition described previously is likely to exist or develop on other airplanes of the same type design that may be registered in the U.S. at some time in the future. We are proposing to supersede AD 94-11-03. This proposed AD would not retain the requirements of the existing AD. This proposed AD would require accomplishing the actions specified in the service bulletins described previously.

Explanation of Change to Model Designation

We have revised the effectivity of the proposed AD to identify model designations as published in the most recent type certificate data sheet for the affected models.

Costs of Compliance

There are about 500 airplanes of the affected design worldwide. This proposed AD would affect about 350 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action hour	Work hours	Average labor rate per	Parts	Cost per hour airplane
Option 1: Replacement	4	\$65	\$12,487	\$12,747
Option 2: Modification	8	65	2,269	2,789

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing amendment 39–8919 (59 FR 27231, May 26, 1994) and adding the following new airworthiness directive (AD):

Raytheon Aircraft Company: Docket No. FAA–2005–20969; Directorate Identifier 2005–NM–017–AD.

Comments Due Date

- (a) The Federal Aviation Administration must receive comments on this AD action by June 2, 2005.

Affected ADs

- (b) This AD supersedes AD 94–11–03, amendment 39–8919 (59 FR 27231, May 26, 1994).

Applicability

- (c) This AD applies to Raytheon Model DH.125, HS.125, and BH.125 series airplanes; Model BAe.125 Series 800A (C–29A and U–125), 800B, 1000A, and 1000B airplanes; and Model Hawker 800 (including variant U–125A), and 1000 airplanes, certificated in any category; as identified in Raytheon Service Bulletin SB 21–3669, dated December, 2004.

Unsafe Condition

- (d) This AD was prompted by reports indicating that the fan venturi overheated and produced smoke while the airplane was on the ground. We are issuing this AD to prevent heat and fire damage to equipment adjacent to the fan venturi, which could result in smoke in the cabin and/or burning equipment.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification or Replacement

- (f) Within 1,200 flight hours or 24 months after the effective date of this AD, whichever occurs first, do the action in either paragraph (f)(1) or (f)(2) of this AD in accordance with the Accomplishment Instructions of Raytheon Service Bulletin SB 21–3669, dated December, 2004.

(1) Modify the existing fan venturi part number (P/N) 132322–2–1 by installing an improved motor, P/N 207640–34.

(2) Replace the existing fan venturi P/N 132322–2–1 with a new fan venturi P/N 132322–3–1.

Note 1: Raytheon Service Bulletin SB 21–3669 refers to Honeywell Service Bulletin 132322–21–4041, Revision 2, dated August 20, 2004, as an additional source of service information for doing the modification. The Honeywell service bulletin is attached to the Raytheon service bulletin.

Parts Installation

- (g) As of the effective date of this AD, no person may install a fan venturi, P/N 132322–2–1, on any airplane unless the fan venturi has been modified in accordance with paragraph (f)(1) of this AD; or unless the fan venturi has a new P/N in accordance with paragraph (f)(2) of this AD.

Alternative Methods of Compliance (AMOCs)

- (h) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on April 12, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05–7673 Filed 4–15–05; 8:45 am]

BILLING CODE 4910–13–P