

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13

by adding the following new airworthiness directive (AD):

LEARJET: Docket No. FAA-2007-28016; Directorate Identifier 2006-NM-227-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by June 11, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Learjet Model 31, 31A, 35, 35A (C-21A), 36, 36A, 55, 55B, and 55C airplanes, and Model 45 airplanes; certificated in any category; as identified in the service information specified in Table 1 of this AD.

TABLE 1.—APPLICABLE SERVICE INFORMATION

Learjet airplane model	Service bulletin	Revision level	Date
31/31A	Bombardier Service Bulletin 31-54-2	1	August 21, 2006.
45	Bombardier Service Bulletin 45-54-3	2	August 15, 2003.
35/35A (C-21A) and 36/36A	Learjet Service Bulletin 35/36-54-3	Original	March 16, 2001.
55/55B/55C	Learjet Service Bulletin 55-54-3	Original	March 16, 2001.

Unsafe Condition

(d) This AD results from a report that unsealed gaps (penetration points) of the engine firewall were discovered during production. We are issuing this AD to prevent penetration of flammable liquids or fire through the engine firewall into the engine pylon, which could lead to fire inside the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspecting, Cleaning, and Sealing of Gaps in Engine Firewall

(f) Within 12 months after the effective date of this AD, do the actions described in paragraphs (f)(1) and (f)(2) of this AD, in accordance with the applicable service information specified in Table 1 of this AD.

(1) For all airplanes: Inspect for unsealed gaps on the pylon side of the engine firewall and clean and seal any unsealed gap.

(2) For Learjet Model 45 airplanes only: Inspect the engine pylon trailing edge for unsealed gaps, and clean and seal any unsealed gap.

Credit for Actions Done Using Previous Service Information

(g) Actions accomplished before the effective date of this AD according to Bombardier Service Bulletin 31-54-2, dated March 16, 2001; or Bombardier Service Bulletin 45-54-3, dated March 16, 2001; or Revision 1, dated December 12, 2001; as applicable; are considered acceptable for compliance with the corresponding action specified in this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on April 19, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-8001 Filed 4-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26353; Directorate Identifier 2006-NM-189-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: The FAA is revising an earlier NPRM for an airworthiness directive (AD) that applies to certain Bombardier Model CL-600-1A11 (CL-600) airplanes, CL-600-2A12 (CL-601) airplanes, and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) airplanes. The original NPRM would have required inspecting to identify the part number and serial number of the selector valves of the nose landing gear (NLG) and the nose gear door; and doing related investigative and corrective actions if necessary. The original NPRM resulted from reports of uncommanded partial retractions of the NLG. This action revises the original NPRM by adding airplanes to the applicability.

We are proposing this supplemental NPRM to prevent internal leakage of the selector valve, which, under certain conditions, could result in an uncommanded retraction of the NLG with consequent damage to the airplane and possible serious injury to ground personnel.

DATES: We must receive comments on this supplemental NPRM by May 21, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this supplemental NPRM.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT:

Daniel Parrillo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; telephone (516) 228-7305; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this supplemental NPRM. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "Docket No. FAA-2006-26353; Directorate Identifier 2006-NM-189-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this supplemental NPRM. We will consider all comments received by the closing date and may amend this supplemental NPRM in light of those comments.

We will post all comments submitted, without change, to <http://dms.dot.gov>, including any personal information you

provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this supplemental NPRM. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level in the Nassif Building at the DOT street address stated in **ADDRESSES**. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

We proposed to amend 14 CFR part 39 with a notice of proposed rulemaking (NPRM) for an airworthiness directive (AD) (the "original NPRM"). The original NPRM applies to certain Bombardier Model CL-600-1A11 (CL-600) airplanes, CL-600-2A12 (CL-601) airplanes, and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) airplanes. The original NPRM was published in the **Federal Register** on November 20, 2006 (71 FR 67079). The original NPRM proposed to require inspecting to identify the part number and serial number of the selector valves of the nose landing gear (NLG) and the nose gear door, and doing related investigative and corrective actions if necessary.

Actions Since Original NPRM Was Issued

Since the original NPRM was issued, Bombardier has determined that additional airplanes are subject to the unsafe condition.

Relevant Service Information

Bombardier has issued Service Bulletin 604-32-021, Revision 02, dated February 20, 2007 (for Model CL-600-2B16 (CL-604) airplanes). The service bulletin adds airplanes to the effectivity; however, Revision 02 is technically identical to Revision 01, dated February 20, 2006. We referred to Revision 01 as the appropriate source of service

information for doing the actions specified in the original NPRM. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Proposed Requirements of the Supplemental NPRM

Certain changes discussed above expand the scope of the original NPRM; therefore, we have determined that it is necessary to reopen the comment period to provide additional opportunity for public comment on this supplemental NPRM.

Difference Between Supplemental NPRM and Canadian Airworthiness Directive

Although Canadian airworthiness directive CF-2006-16, dated July 6, 2006, applies to certain airplanes as identified in Service Bulletin 604-32-021, Revision 01, this supplemental NPRM would apply to those airplanes and certain additional airplanes, as identified in Service Bulletin 604-32-021, Revision 02. This difference has been coordinated with TCCA.

Costs of Compliance

This proposed AD would affect about 502 airplanes of U.S. registry.

The inspection to determine the manufacturer P/N and S/N of the selector valve(s) would take about 1 work hour per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$40,160, or \$80 per airplane.

The general visual inspection of the selector valve(s), if accomplished, would take about 1 work hour per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$80 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this supplemental NPRM and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

BOMBARDIER, INC. (Formerly Canadair):
Docket No. FAA-2006-26353;
Directorate Identifier 2006-NM-189-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by May 21, 2007.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Bombardier Model CL-600-1A11 (CL-600) airplanes, CL-600-2A12 (CL-601) airplanes, and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) airplanes; certificated in any category; having serial numbers (S/Ns) as identified in the service bulletins specified in Table 1 of this AD, as applicable.

TABLE 1.—BOMBARDIER SERVICE BULLETINS

Service Bulletin	Revision level	Date
600-0721 (for Model CL-600-1A11 (CL-600) airplanes)	01	February 20, 2006.
601-0558 (for Model CL-600-2A12 (CL-601) airplanes, and CL-600-2B16 (CL-601-3A and CL-601-3R) airplanes).	01	February 20, 2006.
604-32-021 (for Model CL-600-2B16 (CL-604) airplanes)	02	February 20, 2007.

Unsafe Condition

(d) This AD results from reports of uncommanded partial retractions of the nose landing gear (NLG). We are issuing this AD to prevent internal leakage of the selector valve, which, under certain conditions, could result in an uncommanded retraction of the NLG with consequent damage to the airplane and possible serious injury to ground personnel.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Corrective Actions

(f) Within 500 flight hours or 12 months after the effective date of this AD, whichever occurs first, inspect to determine the manufacturer part number (P/N) and S/N of the selector valves of the NLG and nose gear door. A review of airplane maintenance records is acceptable in lieu of this inspection if the S/Ns of the selector valves can be conclusively determined from that review. For any subject selector valve having Tactair Fluid Controls P/N 750006000 and a S/N from 0001 through 0767 inclusive, before further flight, do related investigative (including a general visual inspection for proper installation of the lock wire of the end cap) and corrective actions; in accordance

with the applicable service bulletins identified in Table 1 of this AD.

Note 1: Operators should be aware that selector valves having Bombardier P/N 601R75146-1 may be supplied by different manufacturers and have different manufacturer part numbers. Only airplanes having selector valves manufactured by Tactair Fluid Controls, having P/N 750006000, are subject to the investigative and corrective actions specified in paragraph (f) of this AD.

Note 2: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Note 3: The service bulletins identified in Table 1 of this AD refer to Tactair Fluid Controls Service Bulletin SB750006000-1, Revision A, dated September 6, 2005, as an additional source of service information for

doing the related investigative and corrective actions required by this AD.

Actions Accomplished According to Previous Issue of Service Bulletin

(g) Actions accomplished before the effective date of this AD according to Bombardier Service Bulletin 604-32-021, Revision 01, dated February 20, 2006 (for Model CL-600-2B16 (CL-604) airplanes), are considered acceptable for compliance with the corresponding actions specified in this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(i) Canadian airworthiness directive CF-2006-16, dated July 6, 2006, also addresses the subject of this AD.

Issued in Renton, Washington, on April 19, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-7979 Filed 4-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27680; Directorate Identifier 2007-CE-026-AD]

RIN 2120-AA64

Airworthiness Directives; AEROTECHNIC Vertriebs-u. Service GmbH Honeywell CAS67A ACAS II Systems Appliances

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It was detected by the STC holder that in earlier installations of the ACASII system there were no isolation diodes installed in the Heading and Attitude Valid lines. The absence of an isolation diode in the valid lines can prevent the valid flag to come up even if a gyro fault exists. The problem has only been detected for Heading Valid lines but could equally affect the Altitude Valid lines.

With installation of the ACASII, the heading and attitude valid lines have to be connected to the TPU67A. On valid state, the signals are +28VDC. On invalid, the signals are open. This condition of direct connection (without an isolation diode installed) of the valid lines to the TPU67A, if not corrected, could cause the TPU67A to feed current into the open stated valid lines. This prevents the flag to appear even if the gyro is invalid, providing the flight crew with erroneous navigation information.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by May 29, 2007.

ADDRESSES: You may send comments by any of the following methods:

- **DOT Docket Web Site:** Go to <http://dms.dot.gov> and follow the instructions

for sending your comments electronically.

- **Fax:** (202) 493-2251.
- **Mail:** Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.
- **Hand Delivery:** Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include "Docket No. FAA-2007-27680; Directorate Identifier 2007-CE-026-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2007-0059 dated March 5, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products.

The MCAI states:

It was detected by the STC holder that in earlier installations of the ACASII system there were no isolation diodes installed in the Heading and Attitude Valid lines. The absence of an isolation diode in the valid lines can prevent the valid flag to come up even if a gyro fault exists. The problem has only been detected for Heading Valid lines but could equally affect the Attitude Valid lines.

With installation of the ACASII, the heading and attitude valid lines have to be connected to the TPU67A. On valid state, the signals are +28VDC. On invalid, the signals are open. This condition of direct connection (without an isolation diode installed) of the valid lines to the TPU67A, if not corrected, could cause the TPU67A to feed current into the open stated valid lines. This prevents the flag to appear even if the gyro is invalid, providing the flight crew with erroneous navigation information.

For the reasons stated above, this Airworthiness Directive (AD) requires the installation of isolation diodes into the signal lines to the TPU67A to prevent reverse feed of the valid lines.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Aerotechnic Vertiebs -u. Service GmbH has issued Service Bulletin No. DO228-119780-0104, Revision 2, dated December 21, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.