

Alternative Methods of Compliance (AMOCs)

(f) The Manager, Chicago Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Wess Rouse, Aerospace Engineer, 2300 East Devon Avenue, Room 107, Des Plaines, Illinois 60018; *telephone*: (847) 294-8113; *fax*: (847) 294-7834. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(g) You must use Cirrus Service Bulletin No. SB 2X-27-14 R3, Revised: October 10, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Cirrus Design Corporation, 4515 Taylor Circle, Duluth, Minnesota 55811; *telephone*: (218) 727-2737; *internet address*: www.cirrusdesign.com.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on January 29, 2008.

John Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-2044 Filed 2-4-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0294 Directorate Identifier 2007-CE-087-AD; Amendment 39-15365; AD 2008-03-14]

RIN 2120-AA64

Airworthiness Directives; Piaggio Aero Industries S.p.A. Model P 180 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results

from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Due to pressurization loads, the fuselage frame of the emergency exit door could suffer from fatigue and develop cracks in its corners. The superseded Italian Airworthiness Directive (AD) 1995-059 was issued to require modification of the emergency door frame in accordance with Piaggio (at the time I.A.M. Rinaldo Piaggio S.p.A.) Service Bulletin 80-0057 original issue. Parts necessary to carry out the modification were a new door pan assembly and a doubler; Since these parts are no longer available, Piaggio Aero Industries S.p.A. (PAI) designed new suitable part numbers introduced by Revision 1 of Service Bulletin 80-0057. The present AD mandates modification of the fuselage emergency door frame in accordance with Revision 1 of Service Bulletin 80-0057 from PAI.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective March 11, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; *telephone*: (816) 329-4145; *fax*: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on December 14, 2007 (72 FR 71089). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Due to pressurization loads, the fuselage frame of the emergency exit door could suffer from fatigue and develop cracks in its corners. The superseded Italian Airworthiness Directive (AD) 1995-059 was issued to require modification of the emergency door frame in accordance with Piaggio (at the time I.A.M. Rinaldo Piaggio S.p.A.) Service Bulletin 80-0057 original issue. Parts necessary to carry out the modification were a new door pan assembly and a doubler; Since these parts are no longer

available, Piaggio Aero Industries S.p.A. (PAI) designed new suitable part numbers introduced by Revision 1 of Service Bulletin 80-0057. The present AD mandates modification of the fuselage emergency door frame in accordance with Revision 1 of Service Bulletin 80-0057 from PAI.

We are issuing this AD to require actions to correct the unsafe condition on these products.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect 31 products of U.S. registry. We also estimate that it will take about 70 work-hours per product to comply with basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$14,105 per product.

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$610,855 or \$19,705 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: "Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that

section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008-03-14 Piaggio Aero Industries S.p.A.:
Amendment 39-15365; Docket No. FAA-2007-0294; Directorate Identifier 2007-CE-087-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective March 11, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to PIAGGIO P-180 airplanes, manufacturer serial numbers (MSN) 1001, 1002, 1004, and MSN 1006 through 1033, that:

- (1) are certificated in any category; and
- (2) have not been modified in accordance with Piaggio Aero Industries Service Bulletin No. 80-0057, dated February 7, 1995.

Subject

(d) Air Transport Association of America (ATA) Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Due to pressurization loads, the fuselage frame of the emergency exit door could suffer from fatigue and develop cracks in its corners. The superseded Italian Airworthiness Directive (AD) 1995-059 was issued to require modification of the emergency door frame in accordance with Piaggio (at the time I.A.M. Rinaldo Piaggio S.p.A.) Service Bulletin 80-0057 original issue. Parts necessary to carry out the modification were a new door pan assembly and a doubler; Since these parts are no longer available, Piaggio Aero Industries S.p.A. (PAI) designed new suitable part numbers introduced by Revision 1 of Service Bulletin 80-0057. The present AD mandates modification of the fuselage emergency door frame in accordance with Revision 1 of Service Bulletin 80-0057 from PAI.

The MCAI requires the modification of the fuselage frame of the emergency door, using the newly designed door pan assembly and doubler, following Piaggio Aero Industries S.p.A. SB 80-0057, Revision 1, dated May 31, 2007.

Actions and Compliance

(f) Unless already done, replace the emergency exit door pan assembly part number (P/N) 80-111152-401 with a new door pan assembly P/N 80-111152-405, and a new doubler reinforcement P/N 80-111604-001, following Piaggio Aero Industries S.p.A. Mandatory Service Bulletin N.: 80-0057, Revision 1, dated May 31, 2007, at whichever of the following occurs later:

- (1) When the airplane reaches 4,500 hours total time-in-service (TIS); or
- (2) Within 6 months after March 11, 2008 (the effective date of this AD) or 500 hours TIS after March 11, 2008 (the effective date of this AD), whichever of these occurs first.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *ATTN: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090.* Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Material Incorporated by Reference

(h) You must use Piaggio Aero Industries S.p.A. Mandatory Service Bulletin N.: 80-0057, Revision 1, dated May 31, 2007 to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Piaggio Aero Industries S.p.A., Via Cibrario, 4—16154 Genoa, Italy; telephone +39 010 06481 741; fax: +39 010 6481 309; e-mail: MMicheli@piaggioaero.it.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on January 29, 2008.

John Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-2040 Filed 2-4-08; 8:45 am]

BILLING CODE 4910-13-P