

The Proposed Amendment

Under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority : 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing Amendment 39–15075 (72 FR 30249, May 31, 2007), and by adding a new airworthiness directive, to read as follows:

General Electric Company: Docket No. FAA–2006–24171; Directorate Identifier 2006–NE–08–AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by August 24, 2009.

Affected ADs

(b) This AD revises AD 2007–11–18, Amendment 39–15075.

Applicability

(c) This AD applies to General Electric Company (GE) CF6–50C, CF6–50C1, CF6–50C2, and CF6–50C2R turbofan engines, with a forward fan stator case, part number (P/N) 9064M53G04, G05, G06, G07, G08, G09, G10, G12, or G13, or P/N 9173M37G01, G02, G03, G04, G05, or G06 installed. These engines are installed on, but not limited to, Airbus A300, McDonnell Douglas DC–10 series, and DC–10–30F (KC–10A, KDC–10) airplanes.

Unsafe Condition

(d) This AD revision results from a review that shows that only one of the service bulletins referenced in the original AD is applicable as a compliance method. We are issuing this AD to prevent uncontained fan blade failures, which can result in separation of airplane hydraulic lines, damage to critical airplane systems, and possible loss of airplane control.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

(f) At the next engine shop visit after the effective date of this AD, but no later than June 30, 2010, rework the forward fan stator case and install the fan module secondary containment shield.

(1) For engines on Airbus 300 series airplanes, use paragraph 3, Accomplishment Instructions, of GE Service Bulletin (SB) No. CF6–50 S/B 72–0985, Revision 2, dated March 21, 2007, to do the rework and installation.

(2) Deleted.

(g) The rework and installation specified in paragraph (f)(1) of this AD can also be done on-wing.

Previous Credit

(h) Previous credit is allowed for fan stator cases reworked and containment shields installed using GE SB No. CF6–50 S/B 72–0985, dated December 2, 1991 or Revision 1, dated September 15, 1998 before the effective date of this AD.

Alternative Methods of Compliance

(i) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(j) European Aviation Safety Agency airworthiness directive 2004–0007, dated December 15, 2004, also addresses the subject of this AD.

(k) Contact James Rosa, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: james.rosa@faa.gov; telephone (781) 238–7152; fax (781) 238–7199, for more information about this AD.

(l) Contact General Electric Company via Lockheed Martin Technology Services, 10525 Chester Road, Suite C, Cincinnati, Ohio 45215, telephone (513) 672–8400, fax (513) 672–8422, for a copy of the service information referenced in this AD.

Issued in Burlington, Massachusetts, on June 17, 2009.

Carlos Pestana,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E9–14815 Filed 6–23–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2009–0143; Directorate Identifier 2009–NE–05–AD]

RIN 2120–AA64

Airworthiness Directives; General Electric Company GE90–110B1, GE90–113B, and GE90–115B Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for General Electric Company (GE) GE90–110B1, GE90–113B, and GE90–115B series turbofan engines with stage 6 low-pressure turbine (LPT) blades, part number (P/N) 1765M37P03 or P/N

1765M37P04, installed. This proposed AD would require initial and repetitive inspections for shroud interlock wear of the stage 6 LPT blades. This proposed AD would also require replacing those blades with stage 6 LPT blades eligible for installation at the next engine shop visit as terminating action to the repetitive blade inspections. This proposed AD results from eight reports of GE90–115B stage 6 LPT single-blade separation events. We are proposing this AD to prevent failure of stage 6 LPT blades, which could result in uncontained engine failure and damage to the airplane.

DATES: We must receive any comments on this proposed AD by August 24, 2009.

ADDRESSES: Use one of the following addresses to comment on this proposed AD.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12–140, Washington, DC 20590–0001.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* (202) 493–2251.

Contact General Electric Company via GE—Aviation, Attn: Distributions, 111 Merchant St., Room 230, Cincinnati, Ohio 45246; telephone (513) 552–3272; fax (513) 552–3329, for a copy of the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT:

Barbara Caufield, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: barbara.caufield@faa.gov; telephone (781) 238–7146; fax (781) 238–7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send us any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2009–0143; Directorate Identifier 2009–NE–05–AD” in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the

proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of the Web site, anyone can find and read the comments in any of our dockets, including, if provided, the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is the same as the Mail address provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

Discussion

Since December of 2007, GE reported eight instances of stage 6 LPT single-blade failures in some GE90 series engines. GE's investigation indicated that excessive wear at the shroud interlock of stage 6 LPT blades, P/N 1765M37P03 or P/N 1765M37P04, caused the failures. The interlock surface wears during operation which results in a loss of axial preload (contact between two surfaces) between two adjacent stage 6 LPT blades. This wear leads to increased tip deflection and blade stress. This condition, if not corrected, could result in failure of stage 6 LPT blades, which could result in uncontained engine failure and damage to the airplane.

Relevant Service Information

We have reviewed and approved the technical contents of GE Service Bulletin No. GE90-100 SB 72-0260, Revision 6, dated May 1, 2009. That SB describes procedures for inspecting stage 6 LPT blades, P/N 1765M37P03, and P/N 1765M37P04, for shroud interlock wear.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design. We are proposing this AD, which would require initial and repetitive inspections for shroud interlock wear of stage 6 LPT blades, P/N 1765M37P03 and P/N 1765M37P04. This proposed AD would also require replacing those blades with stage 6 LPT blades eligible for installation, at the next engine shop visit, as terminating action to the repetitive blade inspections. The proposed AD would require you to use the service information described previously to perform these actions.

Costs of Compliance

We estimate that this proposed AD would affect four GE GE90 series engines installed on airplanes of U.S. registry. We also estimate that it would take about 18 work-hours per engine to perform one inspection of the stage 6 LPT blades, and that the average labor rate is \$80 per work-hour. Replacement stage 6 LPT blades would cost \$258,280 per engine. We estimate that no additional labor costs would be incurred to perform the required blade replacements, because the replacements would be done at the time of the engine shop visit. Based on these figures, we estimate the total cost of the proposed AD for one inspection to U.S. operators to be \$1,038,880.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism

implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. You may get a copy of this summary at the address listed under **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

General Electric Company: Docket No. FAA-2009-0143; Directorate Identifier 2009-NE-05-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by August 24, 2009.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to General Electric Company (GE) GE90-110B1, GE90-113B, and GE90-115B series turbofan engines with stage 6 low-pressure turbine (LPT) blades, part number (P/N) 1765M37P03 or P/N 1765M37P04, installed. These engines are installed on, but not limited to, Boeing 777-200LR, 777-300ER, and 777 Freighter series airplanes.

Unsafe Condition

(d) This AD results from eight reports of GE90-115B stage 6 LPT single-blade separation events. We are issuing this AD to prevent failure of stage 6 LPT blades, which could result in uncontained engine failure and damage to the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Inspections

(f) Before accumulating 3,000 engine operating hours time-since-new, or 400 engine cycles-since-new, whichever occurs first, inspect the stage 6 LPT blades, P/N 1765M37P03 or P/N 1765M37P04 for shroud interlock wear. Thereafter, reinspect within every 1,000 engine operating hours, or within 125 engine cycles-since-last inspection, whichever occurs first. Use paragraphs 3.A. through 3.A.(3)(g)(12) of the Accomplishment Instructions of GE Service Bulletin (SB) No. GE90-100 SB 72-0260, Revision 6, dated May 1, 2009, to do the inspections.

Terminating Action

(g) At the next engine shop visit, replace stage 6 LPT blades, P/N 1765M37P03 or P/N 1765M37P04, with stage 6 LPT blades eligible for installation as terminating action to the repetitive inspections required by this AD.

Installation Prohibition of Affected Stage 6 LPT Blades

(h) After the effective date of this AD, do not install any stage 6 LPT blades, P/N 1765M37P03 or P/N 1765M37P04, onto any engine.

Previous Credit

(i) An inspection performed before the effective date of this AD using GE SB No. GE90-100 SB 72-0260, Revision 4, dated October 8, 2008, or Revision 5, dated November 7, 2008, satisfies the initial inspection requirement of this AD.

Definition

(j) For the purpose of this AD, an engine shop visit is induction of the engine into the shop for any cause.

Alternative Methods of Compliance

(k) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(l) Contact Barbara Caufield, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: barbara.caufield@faa.gov; telephone (781) 238-7146; fax (781) 238-7199, for more information about this AD.

(m) Guidance on stage 6 LPT blades that are eligible for installation can be found in GE Service Bulletin No. 72-0279, Revision 1, dated December 11, 2008, and GE Service Bulletin No. 72-0313, dated March 18, 2009.

(n) Contact General Electric Company via GE—Aviation, Attn: Distributions, 111 Merchant St., Room 230, Cincinnati, Ohio 45246; telephone (513) 552-3272; fax (513) 552-3329, for a copy of the service information identified in this AD.

Issued in Burlington, Massachusetts, on June 17, 2009.

Carlos Pestana,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E9-14807 Filed 6-23-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2009-0362; Airspace Docket No. 09-ASW-10]

Proposed Establishment of Class D Airspace; Arlington, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class D airspace at Arlington, TX. Establishment of an air traffic control tower at Arlington Municipal Airport has made this action necessary for the safety and management of Instrument Flight Rules (IFR) aircraft operations at Arlington Municipal Airport.

DATES: 0901 UTC. Comments must be received on or before August 10, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2009-0362/Airspace Docket No. 09-ASW-10, at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone: (817) 321-7716.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2009-0362/Airspace Docket No. 09-ASW-10." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration (FAA), Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), part 71 by establishing Class D airspace from the surface up to but not including 2,000 feet MSL for IFR operations at Arlington Municipal Airport, Arlington, TX. The area would be depicted on appropriate aeronautical charts.