

## Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 1,600 flight hours or 18 months after the effective date of this AD, whichever occurs first: Do an inspection to determine the serial number and identification markings on the selector valve of the NLG and the door selector valve of the NLG, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-32-104, dated March 3, 2009.

(2) For any airplane having both the selector valve of the NLG and the door selector valve of the NLG that have a serial number outside the range 0001 through 2126 inclusive, suffix "T" identification, or "SB750006000-1" marking, no further action is required for that valve.

(3) For any selector valve of the NLG or any door selector valve of the NLG that does not have any serial number or identification marking specified in paragraph (f)(2) of this AD: Before further flight, after doing the inspection required by paragraph (f)(1) of this AD, inspect to determine the torque value and correct lockwire installation of the valve, and modify (replace, rework, or re-identify) the valve, as applicable, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-32-104, dated March 3, 2009.

## FAA AD Differences

**Note 1:** This AD differs from the MCAI and/or service information as follows: No differences.

## Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7300; fax (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

## Related Information

(h) Refer to MCAI Canadian Airworthiness Directive CF-2009-19, dated April 29, 2009; and Bombardier Service Bulletin 601R-32-104, dated March 3, 2009; for related information.

Issued in Renton, Washington, on December 23, 2009.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9-31290 Filed 1-4-10; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2009-1231; Directorate Identifier 2009-NM-212-AD]

**RIN 2120-AA64**

**Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 170 Airplanes; and Model ERJ 190-100 STD, -100 LR, -100 IGW, -200 STD, -200 LR, and -200 IGW Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as: It has been found the possibility of missing points of sealant application on the vapor barrier assembly in the wing stub rear box. In the event of fuel tank leak in this region associated with an unsealed vapor barrier assembly, migration of flammable vapors and fluids to middle electronic bay may occur, which then could lead to an uncontained fire event if the flammable vapors finds an ignition source. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by February 19, 2010.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227-901 São Jose dos Campos—SP—BRASIL; telephone: +55 12 3927-5852 or +55 12 3309-0732; fax: +55 12 3927-7546; e-mail: [distrib@embraer.com.br](mailto:distrib@embraer.com.br); Internet: <http://www.flyembraer.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

## Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

## FOR FURTHER INFORMATION CONTACT:

Kenny Kaulia, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2848; fax (425) 227-1149.

## SUPPLEMENTARY INFORMATION:

### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-1231; Directorate Identifier 2009-NM-212-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the

closing date and may amend this proposed AD based on those comments.

We have lengthened the 30-day comment period for proposed ADs that address MCAI originated by aviation authorities of other countries to provide adequate time for interested parties to submit comments. The comment period for these proposed ADs is now typically 45 days, which is consistent with the comment period for domestic transport ADs.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

### Discussion

The Agência Nacional de Aviação Civil (ANAC), which is the aviation authority for Brazil, has issued Brazilian Airworthiness Directives 2009–07–01 and 2009–07–02, both effective July 13, 2009 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

It has been found the possibility of missing points of sealant application on the vapor barrier assembly in the wing stub rear box. In the event of fuel tank leak in this region associated with an unsealed vapor barrier assembly, migration of flammable vapors and fluids to middle electronic bay may occur, which then could lead to an uncontained fire event if the flammable vapors finds an ignition source.

\* \* \* \* \*

The required actions include a detailed inspection for gaps, voids, or holes in the sealant. Corrective actions include applying sealant in any gaps, voids, or holes. You may obtain further information by examining the MCAI in the AD docket.

### Relevant Service Information

Embraer has issued Service Bulletin 170–57–0036, dated March 13, 2009; and Service Bulletin 190–57–0027, dated March 18, 2009. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

### FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this

AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a Note within the proposed AD.

### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 197 products of U.S. registry. We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$78,800, or \$400 per product.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a

substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Empresa Brasileira de Aeronautica S.A. (EMBRAER):** Docket No. FAA–2009–1231; Directorate Identifier 2009–NM–212–AD.

#### Comments Due Date

- (a) We must receive comments by February 19, 2010.

#### Affected ADs

- (b) None.

#### Applicability

- (c) This AD applies to the airplanes identified in paragraphs (c)(1) and (c)(2) of this AD; certificated in any category.

(1) Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 170–100 LR, –100 STD, –100 SE, –100 SU, –200 LR, –200 STD, and –200 SU airplanes, serial numbers 17000002, 17000004 through 17000013 inclusive, and 17000015 through 17000235 inclusive.

(2) Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 190–100 STD, –100 LR, –100 IGW, –200 STD, –200 LR, and –200 IGW airplanes, serial numbers 19000002, 19000004, 19000006 through 19000108

inclusive, 19000110 through 19000139 inclusive, 19000141 through 19000158 inclusive, 19000160 through 19000176 inclusive, 19000178 through 19000202 inclusive, 19000204 through 19000213 inclusive, and 19000215.

#### Subject

(d) Air Transport Association (ATA) of America Code 57: Wings.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states: It has been found the possibility of missing points of sealant application on the vapor barrier assembly in the wing stub rear box. In the event of fuel tank leak in this region associated with an unsealed vapor barrier assembly, migration of flammable vapors and fluids to middle electronic bay may occur, which then could lead to an uncontained fire event if the flammable vapors finds an ignition source. The required actions include a detailed inspection for gaps, voids, or holes in the sealant. Corrective actions include applying sealant into any gaps, voids, or holes.

#### Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Actions

(g) Unless already done, do the following actions.

(1) Within 6,000 flight hours or 24 months after the effective date of this AD, whichever occurs first, do a detailed inspection of the vapor barrier assembly in the wing stub rear box for missing sealant which forms gaps, voids or holes, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 170–57–0036, dated March 13, 2009 (for Model ERJ 170–100 LR, –100 STD, –100 SE, –100 SU, –200 LR, –200 STD, and –200 SU airplanes); or Embraer Service Bulletin 190–57–0027, dated March 18, 2009 (for Model ERJ 190–100 STD, –100 LR, –100 IGW, –200 STD, –200 LR, and –200 IGW airplanes).

**Note 1:** For the purposes of this AD, a detailed inspection is: “An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate access procedures may be required.”

(2) If the vapor barrier sealant is found to be correctly applied in accordance with the Accomplishment Instructions of Embraer Service Bulletin 170–57–0036, dated March 13, 2009 (for Model ERJ 170–100 LR, –100 STD, –100 SE, –100 SU, –200 LR, –200 STD, and –200 SU airplanes); or Embraer Service Bulletin 190–57–0027, dated March 18, 2009 (for Model ERJ 190–100 STD, –100 LR, –100 IGW, –200 STD, –200 LR, and –200 IGW airplanes); no further action is required by this AD.

(3) If any vapor barrier sealant is found missing (gaps, voids or holes) during the inspection required by paragraph (f)(1) of this AD, before further flight apply sealant into the applicable gaps, voids, and holes, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 170–57–0036, dated March 13, 2009 (for Model ERJ 170–100 LR, –100 STD, –100 SE, –100 SU, –200 LR, –200 STD, and –200 SU airplanes); or Embraer Service Bulletin 190–57–0027, dated March 18, 2009 (for Model ERJ 190–100 STD, –100 LR, –100 IGW, –200 STD, –200 LR, and –200 IGW airplanes).

#### FAA AD Differences

**Note 2:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Kenny Kaulia, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–2848; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

#### Related Information

(i) Refer to MCAI Brazilian Airworthiness Directives 2009–07–01 and 2009–07–02, both effective July 13, 2009; Embraer Service Bulletin 170–57–0036, dated March 13, 2009; and Embraer Service Bulletin 190–57–0027, dated March 18, 2009; for related information.

Issued in Renton, Washington, on December 28, 2009.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9–31276 Filed 1–4–10; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2009–1228; Directorate Identifier 2009–NM–015–AD]

**RIN 2120–AA64**

#### **Airworthiness Directives; Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Model 382, 382B, 382E, 382F, and 382G Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Model 382, 382B, 382E, 382F, and 382G airplanes. This proposed AD would require repetitive inspections for any damage of the lower surface of the center wing box, and corrective actions if necessary. This proposed AD results from reports of fatigue cracks of the lower surface of the center wing box. We are proposing this AD to detect and correct such cracks, which could result in the structural failure of the wings.

**DATES:** We must receive comments on this proposed AD by February 19, 2010.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Lockheed Martin Corporation/Lockheed Martin Aeronautics Company, Airworthiness Office, Dept. 6A0M, Zone 0252, Column