

Wichita, Kansas 67201-0085; telephone 316-676-8238; fax 316-676-6706; e-mail tmcdc@hawkerbeechcraft.com; Internet https://www.hawkerbeechcraft.com/service_support/pubs.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on January 25, 2011.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011-2442 Filed 2-4-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-1043; Directorate Identifier 2010-NM-200-AD; Amendment 39-16593; AD 2011-03-09]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Model MD-90-30 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD requires installing new fire handle shutoff system wiring. This AD was prompted by a possible latent failure in the fire

handle shutoff relay circuit due to a lack of separation between engine wires. We are issuing this AD to minimize the possibility of a multiple engine shutdown due to single fire handle activation.

DATES: This AD is effective March 14, 2011.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of March 14, 2011.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; e-mail dse.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: William S. Bond, Aerospace Engineer,

Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712; phone: 562-627-5253; fax: 562-627-5210; e-mail: William.Bond@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to the specified products. That NPRM published in the **Federal Register** on November 5, 2010 (75 FR 68245). That NPRM proposed to require installing new fire handle shutoff system wiring.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Explanation of Change Made to the AD

We have revised this AD to identify the legal name of the manufacturer as published in the most recent type certificate data sheet for the affected airplane models.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting the AD with the change described previously. We also determined that this change will not increase the economic burden on any operator or increase the scope of the AD.

Costs of Compliance

We estimate that this AD will affect 25 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Wiring change	8 work-hours × \$85 per hour = \$680	\$489	\$1,169	\$29,225

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a

substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2011-03-09 The Boeing Company:
Amendment 39-16593; Docket No. FAA-2010-1043; Directorate Identifier 2010-NM-200-AD.

Effective Date

- (a) This AD is effective March 14, 2011.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all The Boeing Company Model MD-90-30 airplanes, certificated in any category.

Subject

- (d) Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 74, Ignition.

Unsafe Condition

- (e) This AD was prompted by a possible latent failure in the fire handle shutoff relay circuit due to a lack of separation between engine wires. We are proposing this AD to minimize the possibility of a multiple engine shutdown due to single fire handle activation.

Compliance

- (f) Comply with this AD within the compliance times specified, unless already done.

Wire Installation

- (g) Within 4,200 flight hours after the effective date of this AD, install new fire handle shutoff system wiring, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90-74A002, dated August 17, 2010.

Alternative Methods of Compliance (AMOCs)

- (h)(1) The Manager, Los Angeles Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

Related Information

- (i) For more information about this AD, contact William S. Bond, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5253; fax: 562-627-5210; e-mail: William.Bond@faa.gov.

Material Incorporated by Reference

- (j) You must use Boeing Alert Service Bulletin MD90-74A002, dated August 17, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

- (1) The Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin MD90-74A002, dated August 17, 2010, under 5 U.S.C. 552(a) and 1 CFR part 51.

- (2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; e-mail dse.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

- (3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

- (4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on January 26, 2011.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011-2428 Filed 2-4-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-1108; Directorate Identifier 2010-NM-151-AD; Amendment 39-16592; AD 2011-03-08]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Model CL-215-1A10 (CL-215), CL-215-6B11 (CL-215T Variant), and CL-215-6B11 (CL-415 Variant) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Seven cases of on-ground hydraulic accumulator screw cap or end cap failure have been experienced * * * resulting in loss of the associated hydraulic system and high-energy impact damage to adjacent systems and structure. * * *

A detailed analysis of the systems and structure in the potential line of trajectory of a failed screw cap/end cap for each accumulator has been conducted. It has identified that the worst-case scenarios would be impact damage to various components, potentially resulting in fuel spillage, uncommanded flap movement, or loss of aileron control [and consequent reduced controllability of the airplane].

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective March 14, 2011.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 14, 2011.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the