

Proposed Rules

Federal Register

Vol. 77, No. 67

Friday, April 6, 2012

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF ENERGY

10 CFR Part 1046

[Docket No. DOE-HQ-2012-0002]

RIN 1992-AA40

Protective Force Personnel Medical, Physical Readiness, Training, and Access Authorization Standards

AGENCY: Department of Energy.

ACTION: Proposed rule; notice of extension of public comment period.

SUMMARY: This document announces that the period for submitting comments on the proposed rule to amend the standards for medical, physical performance, training, and access authorizations for protective force (PF) personnel employed by contractors providing security services to the Department will be extended until April 13, 2012.

DATES: The comment period for the proposed rule published March 6, 2012 (77 FR 13206), is extended. The Department of Energy (DOE) will accept comments, data, and information on the proposal received no later than April 13, 2012.

ADDRESSES: You may submit comments, identified by DOE-HQ-2012-0002 and/or 1992-AA40, by any of the following methods:

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Email:* 1992-AA40@hq.doe.gov. Include DOE-HQ-2012-0002 and/or 1992-AA40 in the subject line of the message.

- *Mail:* Mailing Address for paper, disk, or CD-ROM submissions: Department of Energy, Office of Security Policy, (HS-51, Attn: John Cronin), 1000 Independence Ave. SW., Washington, DC 20585-1290.

- *Hand Delivery/Courier:* Street Address: Department of Energy, Office of Security Policy, (HS-51, Attn: John Cronin), 1000 Independence Ave. SW., Washington, DC 20585-1290.

Instructions: All submissions received must include the agency name and docket number or Regulatory Information Number (RIN) for this rulemaking. All comments received will be posted without change to <http://www.regulations.gov>, including any personal information provided.

Docket: For access to the docket to read background documents or comments received, go to <http://www.regulations.gov> or contact John Cronin at (301) 903-6209 prior to visiting Department of Energy, Office of Security Policy, (HS-51), 19901 Germantown Rd., Germantown, MD 20874.

FOR FURTHER INFORMATION CONTACT: Requests for additional information may be sent to Mr. John Cronin, Office of Security Policy at (301) 903-6209; John.Cronin@hq.doe.gov.

SUPPLEMENTARY INFORMATION: On March 6, 2012, DOE published a proposed rule to revise the standards for medical, physical performance, training, and access authorizations for PF personnel employed by contractors providing security services to the Department. (77 FR 13206) Commenters requested an extension of the comment period until April 13, 2012, stating that the extension was needed to allow sufficient time to address many important issues in the proposed revisions. Commenters cited the need to collect information and thoughts from various sites to prepare comments from the National Council of Security Police, and stated that the additional week would allow time to gather all the information and prepare focused comments. DOE has determined that an extension of the public comment period is appropriate based on the foregoing reasons and is hereby extending the comment period. DOE will consider any comments received by April 13, 2012.

Further Information on Submitting Comments

Under 10 CFR 1004.11, any person submitting information that he or she believes to be confidential and exempt by law from public disclosure should submit two copies: One copy of the document including all the information believed to be confidential, and one copy of the document with the information believed to be confidential deleted. DOE will make its own determination about the confidential

status of the information and treat it according to its determination.

Issued in Washington, DC, on April 2, 2012.

Glenn S. Podonsky,

Chief Health, Safety And Security Officer, Office of Health, Safety and Security.

[FR Doc. 2012-8327 Filed 4-5-12; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-24785; Directorate Identifier 2006-NE-20-AD]

RIN 2120-AA64

Airworthiness Directives; Lycoming Engines Reciprocating Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: We are revising an earlier proposed airworthiness directive (AD) for certain Lycoming Engines (L)O-360, (L)IO-360, AEIO-360, O-540, IO-540, AEIO-540, (L)TIO-540, IO-580, and IO-720 series reciprocating engines. That NPRM proposed to require replacing certain crankshafts of affected engine models. This action revises that NPRM by including the IO-390, AEIO-390, and AEIO-580 series engine models having affected crankshafts. We are proposing this supplemental NPRM to prevent failure of the crankshaft, which will result in total engine power loss, in-flight engine failure, and possible loss of the aircraft. Since these actions impose an additional burden over that proposed in the NPRM, we are reopening the comment period to allow the public the chance to comment on these proposed changes.

DATES: We must receive comments on this supplemental NPRM by June 5, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Lycoming, 652 Oliver Street, Williamsport, PA 17701; phone: 570-323-6181; fax: 570-327-7101, or on the internet at www.Lycoming.Textron.com. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Norm Perenson, Aerospace Engineer, New York Aircraft Certification Office, FAA, Engine & Propeller Directorate, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7337; fax: 516-794-5531; email: norman.perenson@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2006-24785; Directorate Identifier 2006-NE-20-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any

personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We issued an NPRM superseding to amend 14 CFR part 39 to include an AD that would apply to Lycoming Engines (L)O-360, (L)IO-360, AEIO-360, O-540, IO-540, AEIO-540, (L)TIO-540, IO-580, and IO-720 series reciprocating engines. That NPRM published in the **Federal Register** on August 12, 2011 (76 FR 50152). That NPRM superseding proposed to retain all of the requirements of AD 2006-20-09 (71 FR 57407, September 29, 2006), and would expand the affected engines by moving the start date of affected engine models back from March 1, 1997, to January 1, 1997. All references to March 1, 1997 in AD 2006-20-09, and the NPRM superseding are, therefore, obsolete and the start date of affected models in this supplemental NPRM superseding is changed to January 1, 1997. Lycoming also changed its Service Instruction No. 1009AS dated May 25, 2006 to Service Instruction No. 1009AU, dated November 18, 2009. The changes to Service Instruction 1009 do not affect the engine overhaul time.

Actions Since Previous NPRM Was Issued

Since we issued the previous NPRM (76 FR 50152, August 12, 2011), Lycoming Engines made us aware of additional engine models with crankshafts affected by the unsafe condition. They are the IO-390, AEIO-390, and AEIO-580 series reciprocating engines. These engine models were considered experimental and did not have a type certificate when we issued AD 2006-20-09 (71 FR 57407, September 29, 2006). These models now have type certificates and so we propose to add them in this supplemental NPRM.

Comments

We gave the public the opportunity to comment on the original NPRM. We received no comments on that NPRM (76 FR 50152, August 12, 2011).

FAA's Determination

We are proposing this supplemental NPRM because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. Certain changes described above expand the scope of the original NPRM (76 FR 50152, August 12, 2011). As a

result, we have determined that it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this supplemental NPRM.

Proposed Requirements of the Supplemental NPRM

This supplemental NPRM would retain all of the requirements of AD 2006-20-09 (71 FR 57407, September 29, 2006). This supplemental NPRM would also change the start date of affected engine models from March 1, 1997, to January 1, 1997, and would add Lycoming Engines IO-390, AEIO-390, and AEIO-580 series reciprocating engines to the applicability.

Costs of Compliance

We estimate that this proposed AD would require no additional costs of compliance over those in the original AD 2006-20-09, which are \$60,384,000. This proposed AD carries over the original costs of compliance. We estimate that this proposed AD would affect 3,774 engines installed on airplanes of U.S. registry. Because the proposed AD compliance interval coincides with engine overhaul or other engine maintenance, we estimate no additional labor hours will be needed to comply with this proposed AD. Parts would cost about \$16,000 per engine. Based on these figures, we estimate the total cost of the proposed AD to be \$60,384,000. Our estimate is independent of any possible warranty coverage.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications

under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Lycoming Engines (formerly Textron

Lycoming): Docket No. FAA-2006-24785; Directorate Identifier 2006-NE-20-AD.

(a) Comments Due Date

We must receive comments by June 5, 2012.

(b) Affected ADs

This AD supersedes AD 2006-20-09, Amendment 39-14778 (71 FR 57407, September 29, 2006).

(c) Applicability

This AD applies to Lycoming Engines (L)O-360, (L)IO-360, AEIO-360, IO-390, AEIO-390, O-540, IO-540, AEIO-540, (L)TIO-540, IO-580, AEIO-580, and IO-720 series reciprocating engines listed by engine model number and serial number in Table 1, Table 2, Table 3, or Table 4 of Lycoming Mandatory Service Bulletin (MSB) 569A, dated April 11, 2006, and those engines with crankshafts listed by crankshaft serial number in Table 5 of Lycoming MSB 569A,

dated April 11, 2006. These applicable engines are manufactured new, rebuilt, overhauled, or had a crankshaft installed after January 1, 1997.

(d) Unsafe Condition

This AD results from Lycoming Engines discovering that the March 1, 1997 start date of affected engine models in MSB No. 569A, is incorrect. This AD also results from the need to include the IO-390, AEIO-390, and AEIO-580 series engine models having affected crankshafts. We are issuing this AD to prevent failure of the crankshaft, which will result in total engine power loss, in-flight engine failure, and possible loss of the aircraft.

(e) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

(f) Credit for Previous Actions

(1) If you previously complied with any of the following ADs, no further action is required:

- (i) AD 2002-19-03 (67 FR 59139, September 20, 2002); or
- (ii) AD 2005-19-11 (70 FR 54618, September 16, 2005); or
- (iii) AD 2006-06-16 (71 FR 14638, March 23, 2006).

(2) If you previously accomplished any of the following Lycoming MSBs, no further action is required:

- (i) MSB No. 552; or
- (ii) MSB No. 553; or
- (iii) Supplement No. 1 to MSB No. 553; or
- (iv) MSB No. 566; or
- (v) Supplement No. 1 to MSB No. 566; or
- (vi) MSB No. 569, MSB No. 569A, and Supplement 1 to MSB No. 569A.

(3) If Lycoming Engines manufactured new, rebuilt, overhauled, or repaired your engine, or replaced the crankshaft in your engine before January 1, 1997, and you have not had the crankshaft replaced, no further action is required.

(4) If Table 1, Table 2, Table 3, or Table 4 of Lycoming MSB No. 569A, dated April 11, 2006, lists your engine serial number (S/N), and Table 5 of MSB No. 569A, dated April 11, 2006, does not list your crankshaft S/N, no further action is required.

(5) For engine model TIO-540-U2A, S/N L-4641-61A, no action is required.

(g) Engines for Which Action Is Required

If you did not previously comply with any of the ADs listed in paragraph (f)(1) of this AD, do the following:

(1) If Table 1, Table 2, Table 3, or Table 4 of Lycoming MSB No. 569A, dated April 11, 2006, lists your engine S/N, and Table 5 of MSB No. 569A, dated April 11, 2006, lists your crankshaft S/N, replace the affected crankshaft with a crankshaft that is not listed in Table 5 of MSB No. 569A at the earliest of the following:

- (i) The time of the next engine overhaul as specified in Lycoming Engines Service Instruction No. 1009AU, dated November 18, 2009; or
- (ii) The next separation of the crankcase, or

(iii) No later than 12 years from the time the crankshaft first entered service or was last overhauled, whichever is later.

(2) If Table 1, Table 2, Table 3, or Table 4 of Lycoming MSB No. 569A, dated April 11, 2006, does not list your engine S/N, and Table 5 of MSB No. 569A does list your crankshaft S/N (an affected crankshaft was installed as a replacement), replace the affected crankshaft with a crankshaft that is not listed in Table 5 of MSB No. 569A at the earliest of the following:

- (i) The time of the next engine overhaul as specified in Lycoming Engines Service Instruction No. 1009AU, dated November 18, 2009; or
- (ii) The next separation of the crankcase, or
- (iii) No later than 12 years from the time the crankshaft first entered service or was last overhauled, whichever is later.

(h) Prohibition Against Installing Certain Crankshafts

After the effective date of this AD, do not install any crankshaft that has a S/N listed in Table 5 of Lycoming MSB No. 569A, dated April 11, 2006, into any engine.

(i) Alternative Methods of Compliance (AMOC)

The Manager, New York Aircraft Certification Office, may approve AMOCs to this AD. Use the procedures in 14 CFR 39.19 to make your request. AMOCs approved for AD 2002-19-03 (67 FR 59139, September 20, 2002) and AD 2006-20-09 (71 FR 57407, September 29, 2006) are approved as AMOCs for this AD.

(j) Related Information

(1) For more information about this AD, contact Norm Perenson, Aerospace Engineer, New York Aircraft Certification Office, FAA, Engine & Propeller Directorate, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7337; fax: 516-794-5531; email: norman.perenson@faa.gov.

(2) For service information identified in this AD, contact Lycoming, 652 Oliver Street, Williamsport, PA 17701; telephone: 570-323-6181; fax: 570-327-7101, or on the internet at www.Lycoming.Textron.com. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on April 2, 2012.

Colleen M. D'Alessandro,

Assistant Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2012-8287 Filed 4-5-12; 8:45 am]

BILLING CODE 4910-13-P