

WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on July 6, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-17391 Filed 7-16-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0619; Directorate Identifier 2007-NM-356-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: We are revising an earlier proposed airworthiness directive (AD) for all The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series airplanes. That NPRM proposed to require performing repetitive operational tests of the engine fuel suction feed of the fuel system, and other related testing if necessary. That NPRM was prompted by reports of two in-service occurrences on Model 737-400 airplanes of total loss of boost pump pressure of the fuel feed system, followed by loss of fuel system suction feed capability on one engine, and in-flight shutdown of the engine. This action revises that NPRM by proposing to require repetitive operational tests, and corrective actions if necessary. We are proposing this supplemental NPRM to detect and correct loss of the engine fuel suction feed capability of the fuel system, which in the event of total loss of the fuel boost pumps could result in dual engine flameout, inability to restart the engines, and consequent forced landing of the airplane. Since these actions impose an additional burden over that proposed in the previous NPRM, we are reopening the comment period to allow the public the chance to comment on these proposed changes.

DATES: We must receive comments on this supplemental NPRM by August 31, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM-140S, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6438; fax: 425-917-6590; email: suzanne.lucier@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0619; Directorate Identifier 2007-NM-356-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will

consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We issued an NPRM to amend 14 CFR part 39 to include an AD that would apply to all The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series airplanes. That NPRM published in the **Federal Register** on June 6, 2008 (73 FR 32245). That NPRM proposed to require performing repetitive operational tests of the engine fuel suction feed of the fuel system, and other related testing if necessary.

Actions Since Previous NPRM (73 FR 32245, June 6, 2008) Was Issued

Since we issued the previous NPRM (73 FR 32245, June 6, 2008), we have received comments from operators indicating a high level of difficulty performing the actions in the previous NPRM during maintenance operations.

Relevant Service Information

We reviewed Boeing Alert Service Bulletin 747-28A2331, dated April 2, 2012. This service information describes procedures for repetitive operational tests of the engine fuel suction feed of the fuel system, and corrective actions if necessary. The corrective actions include isolating the cause of any leakage and repairing the leak.

Comments

We gave the public the opportunity to comment on the previous NPRM (73 FR 32245, June 6, 2008). The following presents the comments received on the previous NPRM and the FAA's response to each comment.

Requests To Clarify the Reason for the Unsafe Condition/Define Risk Assessment

Boeing and Northwest Airlines (NWA) asked that we clarify the reason for the unsafe condition identified in the previous NPRM (73 FR 32245, June 6, 2008) by including all relevant information.

Boeing stated that the description of a report of in-service occurrences of loss of fuel system suction feed capability results from reports of two in-service engine flameout events while operating

on suction feed with undetected air leak failures on Model 737–400 airplanes. Boeing added that there are no known reports of any engine flameout-related events in the Model 747 fleet. Boeing noted that undetected air leaks could exist and the subject maintenance procedure is a proactive measure to ensure engine flameout will not occur due to air leaks while on suction feed operation.

NWA asked for an explanation of what caused the failure that resulted in issuance of the previous NPRM (73 FR 32245, June 6, 2008), and stated that failure analysis could indicate different action than the one proposed. NWA added that the events occurred on twin-engine airplanes, and requested that we provide the basis for the conclusion that Model 747–400 airplanes have the same or greater risk for this unsafe condition to occur as twin-engine airplanes.

We agree that the reason for the unsafe condition should be clarified for the reasons provided. We have changed the language in the reason for the unsafe condition identified in the Summary section and paragraph (e) of this supplemental NPRM to specify that the previous NPRM (73 FR 32245, June 6, 2008) was prompted by reports of two in-service occurrences on Model 737–400 airplanes of total loss of boost pump pressure of the fuel feed system, followed by loss of fuel system suction feed capability on one engine, and in-flight shutdown of the engine.

The cause of the failure is identified in a failure analysis done by Boeing, and incorporates a four-engine airplane in place of a twin-engine airplane. The differences between the four-engine airplane and the twin-engine airplane are reflected in a longer compliance time for the four-engine airplane. Although the Model 747 fuel system differs with respect to the engine fuel feed design, service data of transport category airplanes indicate that multi-engine flameouts have generally resulted from a common cause such as fuel mismanagement, crew action that inadvertently shuts off the fuel supply to the engines, exposure to common environmental conditions, or engine deterioration occurring on all engines of the same type. Successful in-flight restart of these engines depends on adequate fuel being supplied to the engines solely through engine fuel suction feed. Deterioration of the fuel plumbing system “lead-to-line” (vacuum) reduces engine fuel suction feed capability; therefore, directed maintenance is necessary to ensure that this system is available to perform its

function in order to maintain continued safe flight.

In light of the above, we have determined that Model 747–400, –400D, and –400F series airplanes are also affected by the identified unsafe condition, and are considering additional rulemaking for those airplanes.

Request To Issue Certification Maintenance Requirement (CMR) Task Instead of Previous NPRM (73 FR 32245, June 6, 2008)

Japan Airlines (JAL) requested that we withdraw the previous NPRM (73 FR 32245, June 6, 2008). JAL asked that instead of issuing an NPRM, we issue a CMR task. JAL stated that the requirements in the previous NPRM should not be addressed as an AD. JAL did not provide a reason for this request.

We do not agree with the commenter's request. CMRs are developed by the Certification Maintenance Coordination Committee (CMCC) during the type certification process. The CMCC is made up of manufacturer representatives (typically maintenance, design, and safety engineering personnel); operator representatives designated by the Industry Steering Committee chairperson; aircraft certification office specialists, and the maintenance review board (MRB) chairperson. CMRs developed during this process become a part of the certification basis of the airplane upon issuance of the type certificate. We do not have a process for convening the CMCC outside of the type certification process; based on this, the CMR is not an option for replacing this AD. Regardless, the airworthiness limitations (ALI) were not in the maintenance program at the time the previous NPRM (73 FR 32245, June 6, 2008) was issued; therefore, an AD is required to accomplish the ALI task.

Request To Remove or Clarify Certain Language in Paragraph (f) of the Previous NPRM (73 FR 32245, June 6, 2008)

NWA asked that the last sentence in paragraph (f) of the previous NPRM (73 FR 32245, June 6, 2008) be removed or clarified. NWA stated that the intent of that sentence is unclear, and is reiterated as follows: “Thereafter, except as provided in paragraph (h) of this AD, no alternative procedure or repetitive test intervals will be allowed.” NWA added that it is standard practice that once an AD is issued, deviation procedures and intervals are not allowed unless approved by requesting an alternative method of compliance.

We agree with the commenter that including the subject sentence is redundant; however, that sentence is included in paragraph (g) of the supplemental NPRM (paragraph (f) of the previous NPRM (73 FR 32245, June 6, 2008)) merely as a reminder for operators of standard practices. We have made no change to the supplemental NPRM in this regard.

Request To Revise Costs of Compliance Section

NWA stated that the cost estimate specified in the previous NPRM (73 FR 32245, June 6, 2008) is too low, and asked that it be changed. NWA stated that the cost of fuel is not included in the cost estimate and should be included due to the high cost of fuel.

We acknowledge the commenter's request. Although fuel is used during the operational test, we have not received data on the amount of fuel used during the test. In addition, fuel costs vary among operators. Therefore, we do not have definitive data that would enable us to provide a cost estimate for the fuel costs. In any case, we have determined that direct and incidental costs are still outweighed by the safety benefits of the AD. We have made no change to the supplemental NPRM in this regard.

FAA's Determination

We are proposing this supplemental NPRM because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. Certain changes described above expand the scope of the original NPRM (73 FR 32245, June 6, 2008). As a result, we have determined that it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this supplemental NPRM.

Proposed Requirements of the Supplemental NPRM

This supplemental NPRM revises the previous NPRM (73 FR 32245, June 6, 2008) by proposing repetitive operational tests of the engine fuel suction feed of the fuel system, and corrective actions if necessary.

Costs of Compliance

We estimate that this proposed AD would affect 1,080 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Cost per product	Cost on U.S. operators
Operational Test	3 work hours × \$85 per hour = \$255 per engine, per test.	\$255	\$275,400 per engine, per test.

We have received no definitive data that would enable us to provide a cost estimate for the on-condition actions or the optional terminating action specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2008–0619; Directorate Identifier 2007–NM–356–AD.

(a) Comments Due Date

We must receive comments by August 31, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 747–100, 747–100B, 747–100B SUD, 747–200B, 747–200C, 747–200F, 747–300, 747SR, and 747SP series airplanes, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 2800, Aircraft Fuel System.

(e) Unsafe Condition

This AD was prompted by reports of two in-service occurrences on Model 737–400 airplanes of total loss of boost pump pressure of the fuel feed system, followed by loss of fuel system suction feed capability on one engine, and in-flight shutdown of the engine. We are issuing this AD to detect and correct loss of the engine fuel suction feed capability of the fuel system, which in the event of total loss of the fuel boost pumps could result in dual engine flameout, inability to restart the engines, and consequent forced landing of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Operational Test and Corrective Actions

Within 30,000 flight hours after the effective date of this AD: Perform an operational test of the engine fuel suction feed of the fuel system, and all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747–28A2331, dated April 2, 2012. Do all applicable corrective actions before further flight. Repeat the operational test thereafter at intervals not to exceed 30,000 flight hours. Thereafter, except as provided in paragraph (h) of this AD, no alternative procedure or repetitive test intervals will be allowed.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9–ANM–Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM–140S, 1601 Lind Avenue SW., Renton, Washington 98057–3356; phone: 425–917–6438; fax: 425–917–6590; email: suzanne.lucier@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 5, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–17393 Filed 7–16–12; 8:45 am]

BILLING CODE 4910–13–P