

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2017–13–14 The Boeing Company:

Amendment 39–18944; Docket No. FAA–2016–9384; Directorate Identifier 2016–NM–154–AD.

(a) Effective Date

This AD is effective August 9, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777–300ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 777–25A0677, dated April 25, 2016.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by a report that certain galley tripod mount assemblies were not attached to the tie rods in the overhead support structure. We are issuing this AD to detect and correct an unconnected galley tripod mount assembly to the tie rods in the overhead support structure, which can cause a galley to come loose under a high dynamic load, causing a risk of serious injury to passengers and the blocking of evacuation routes.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Actions

Within 12 months after the effective date of this AD: Do a detailed inspection of the area above the A2 and A3 galleys to make sure the hardware (*i.e.*, pin assembly or bolt assembly) that connects the tripod mount assembly to the applicable T53 and T52 tie rods is installed, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777–25A0677, dated April 25, 2016. Do all applicable corrective actions before further flight.

(h) Definition of Detailed Inspection

For the purposes of this AD, a detailed inspection is an intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Allison Buss, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM–150S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6495; fax: 425–917–6590; email: allison.buss@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 777–25A0677, dated April 25, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740; telephone 562–797–1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 22, 2017.

John P. Piccola, Jr.,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–13757 Filed 7–3–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2017–0187; Directorate Identifier 2017–NE–08–AD; Amendment 39–18893; AD 2017–10–19]

RIN 2120–AA64

Airworthiness Directives; Rolls-Royce plc Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Rolls-Royce plc (RR) Trent 1000–A2, Trent 1000–C2, Trent 1000–D2, Trent 1000–E2, Trent 1000–G2, Trent 1000–H2, Trent 1000–J2, Trent 1000–K2, and Trent 1000–L2 turbofan engines. This AD requires initial and repetitive on-wing inspections of affected intermediate pressure compressor (IPC) rotor seals. This AD was prompted by a failure of the IPC rotor seal. We are

issuing this AD to correct the unsafe condition on these products.

DATES: This AD becomes effective July 20, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 20, 2017.

We must receive comments on this AD by August 21, 2017.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Mail:* U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* 202-493-2251.

For service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE24 8BJ; phone: 011-44-1332-242424; fax: 011-44-1332-249936; email: http://www.rolls-royce.com/contact/civil_team.jsp; Internet: <https://customers.rolls-royce.com/public/rollsroycecare>. You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0187.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0187; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be

available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Robert Green, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0187; Directorate Identifier 2017-NE-08-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2017-0017, dated February 1, 2017 (referred to hereinafter as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Recently, a low speed abort (60 to 65 knots) occurred on take-off on a Trent 1000-powered Boeing 787 aeroplane. The pilot performed a commanded engine shutdown and the aeroplane safely returned to the gate. Following investigation, failure and release of the intermediate pressure compressor (IPC) rotor seal was confirmed as having caused this event. RR have confirmed that other IPC rotor seals, Part Number (P/N) KH19098, have been found with cracking at the seal head. This condition, if not detected and corrected, could lead to engine power loss, possibly resulting in reduced control of the aeroplane.

You may obtain further information by examining the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0187.

Related Service Information Under 1 CFR Part 51

RR has issued Alert Non-Modification Service Bulletin (NMSB) Trent 1000 72-AJ467, Revision 1, dated February 13, 2017; and NMSB Trent 1000 72-J353, Revision 1, dated November 24, 2016. The Alert NMSB describes procedures for initial and repetitive inspections of affected IPC rotor seal. The NMSB describes procedures for in-shop inspections of affected IPC rotor seals. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This AD

This product has been approved by EASA, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This AD requires initial and repetitive inspections of affected IPC rotor seal for cracks.

FAA’s Determination of the Effective Date

No domestic operators use this product. Therefore, we find that notice and opportunity for prior public comment are impracticable and that good cause exists for making this amendment effective in less than 30 days.

Costs of Compliance

We estimate that this AD affects 0 engines installed on airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection of IPC rotor seal	12.5 work-hours × \$85 per hour = \$1,062.50	\$0	\$1,062.50	\$0

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2017–10–19 Rolls-Royce plc: Amendment 39–18893; Docket No. FAA–2017–0187; Directorate Identifier 2017–NE–08–AD.

(a) Effective Date

This AD is effective July 20, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Rolls-Royce plc (RR) Trent 1000–A2, Trent 1000–C2, Trent 1000–D2, Trent 1000–E2, Trent 1000–G2, Trent 1000–H2, Trent 1000–J2, Trent 1000–K2, and Trent 1000–L2 turbofan engines with intermediate pressure compressor (IPC) rotor seal, part number (P/N) KH19098, installed.

(d) Subject

Joint Aircraft System Component (JASC) 7230, Turbine Engine, Compressor Section.

(e) Reason

This AD was prompted by failure of the IPC rotor seal. We are issuing this AD to prevent failure of the IPC rotor seal, loss of engine thrust control, and reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Perform an on-wing borescope inspection (BSI) of the IPC rotor seal using paragraph 3, Accomplishment Instructions, of RR Alert Non-Modification Service Bulletin (NMSB) Trent 1000 72–AJ467, Revision 1, dated February 13, 2017 as follows:

- (i) For engines with an IPC rotor seal with 300 flight cycles (FC) or more before August 2017, perform a BSI before August 2017.
- (ii) For engines with an IPC rotor seal with less than 300 FC before August 2017, perform a BSI before the IPC rotor seal accumulates 300 FC.

(2) Depending on the findings of the inspection(s) required by paragraph (g)(1) of this AD, repeat the on-wing BSI at intervals not to exceed those specified in Figures 2 or 4 of RR Alert NMSB Trent 1000 72–AJ467, Revision 1, dated February 13, 2017.

(3) An in-shop inspection in accordance with paragraph 3, Accomplishment Instructions, of RR NMSB Trent 1000 72–J353, Revision 1, dated November 24, 2016, may be substituted for an on-wing BSI as required by paragraphs (g)(1) and (2) of this AD, within the compliance times specified.

(4) After the effective date of this AD, do not operate an aircraft, having two engines installed that are both subject to the 20 FC IPC rotor seal re-inspection interval specified in Figure 4 of RR Alert NMSB Trent 1000 72–AJ467, Revision 1, dated February 13, 2017.

(5) If, during an on-wing inspection as required by paragraphs (g)(1) or (2) of this AD, or an in-shop inspection as specified in

paragraph (g)(3) of this AD, any crack is found on the rear face of the affected IPC rotor seal that is at or beyond the reject limits specified in Figure 4 of RR Alert NMSB Trent 1000 72–AJ467, Revision 1, dated February 13, 2017, replace the IPC rotor seal with a part eligible for installation, before next flight.

(6) Replacing the IPC rotor seal on an engine, as required by paragraph (g)(5) of this AD, is not terminating action for the inspections required by paragraphs (g)(1) and (2) of this AD for that engine.

(7) No reports requested in any of the Alert NMSBs that are referenced in paragraphs (g)(1), (2), and (3) of this AD are required by this AD.

(h) Credit for Previous Actions

You may take credit for inspections and corrective action that are required by paragraph (g) of this AD, if you performed these actions and corrective action before the effective date of this AD, using RR Alert NMSB Trent 1000 72–AJ467, Initial Issue, dated November 9, 2016; or RR NMSB Trent 1000 72–J353, Initial Issue, dated August 25, 2016, or Revision 1, dated November 24, 2016.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(j) Related Information

(1) For more information about this AD, contact Robert Green, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7754; fax: 781–238–7199; email: robert.green@faa.gov.

(2) Refer to MCAI AD 2017–0017, dated February 1, 2017, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA–2017–0187.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce plc (RR) Non-Modification Service Bulletin (NMSB) Trent 1000 72–J353, Revision 1, dated November 24, 2016.

(ii) RR Alert NMSB Trent 1000 72–AJ467, Revision 1, dated February 13, 2017.

(3) For RR service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE24 8BJ; phone: 011–44–1332–242424; fax: 011–44–1332–249936; email: http://www.rolls-royce.com/contact/civil_team.jsp; Internet: <https://customers.rolls-royce.com/public/rollsroycecare>.

(4) You may view this service information at FAA, Engine & Propeller Directorate, 1200

District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on May 11, 2017.

Robert J. Ganley,

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2017-14050 Filed 7-3-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-0461; Directorate Identifier 2014-NM-159-AD; Amendment 39-18937; AD 2017-13-07]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A319, A320, and A321 series airplanes. This AD was prompted by a report that a main landing gear (MLG) door could not be closed due to rupture of the actuator fitting. This AD requires repetitive inspections for cracking of the MLG door actuator fitting and its components, and corrective actions if necessary. This AD also requires eventual replacement of all affected MLG door actuator fittings with new monoblock fittings, which would terminate the repetitive inspections. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 9, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of August 9, 2017.

ADDRESSES: For service information identified in this final rule, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service

information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0461.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0461; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Model A319, A320, and A321 series airplanes. The SNPRM published in the **Federal Register** on April 7, 2017 (82 FR 16948) (“the SNPRM”). We preceded the SNPRM with a notice of proposed rulemaking (NPRM) that published in the **Federal Register** on January 28, 2016 (81 FR 4901) (“the NPRM”). The NPRM proposed to require repetitive inspections for cracking of the MLG door actuator fitting and its components, and corrective actions if necessary. The NPRM also proposed to require eventual replacement of all affected MLG door actuator fittings with new monoblock fittings, which would terminate the repetitive inspections. The NPRM was prompted by a report that an MLG door could not be closed due to rupture of the actuator fitting. The SNPRM proposed to revise the NPRM by reducing the compliance time for replacing the MLG actuator fitting and removing an inspection requirement for certain airplanes. We are issuing this

AD to prevent rupture of the door actuator fittings, which could result in detachment of an MLG door and subsequent exterior damage and consequent reduced structural integrity of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2016-0182, dated September 13, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A319, A320, and A321 series airplanes. The MCAI states:

On one A320 aeroplane, it was reported that one of the main landing gear (MLG) doors could not be closed. Investigations revealed the rupture of the actuator fitting at the actuator attachment area on the door side. The MLG door is attached to the aeroplane by 2 (two) hinge fittings.

This condition, if not corrected, could, under certain circumstances, lead to detachment of a MLG door from the aeroplane, possibly resulting in damage to the aeroplane, and/or injury to persons on the ground.

Prompted by these findings, [Direction Générale de l'Aviation Civile] France issued * * * [an AD] * * *, to require a MLG door actuator fitting inspection for cracks and to check the grain direction on a batch of aeroplanes. Subsequently, DGAC France issued * * * [an AD], retaining the requirements of DGAC France AD * * *, which was superseded, to require an inspection of the lower part of the MLG door actuator fitting.

After that [DGAC] AD was issued, additional investigations revealed that damage could also appear on the nerve area [of the forward monoblock fitting], in the upper part of the MLG door actuator fitting in the area of the hinge.

Consequently, DGAC France issued F-2003-434, dated December 10, 2003 [<http://ad.easa.europa.eu/ad/F-2003-454>] (EASA approval 2003-1436), retaining the requirements of [a] DGAC France AD * * *, which was superseded, to require additional repetitive inspections. That [DGAC] AD also included an optional terminating action, by replacing the MLG door actuator fittings in accordance with the instructions of Airbus Service Bulletin (SB) A320-52-1073.

After DGAC France AD F-2003-434 was issued, in the framework of the extended service goal campaign, it was decided to make replacement of the MLG door actuator fittings a required modification. Consequently, EASA issued AD 2014-0166 * * *, retaining the requirements of DGAC France AD F-2003-434, which was superseded, and requiring replacement of the MLG door actuator fittings with new monoblock fittings, which constitutes terminating action for the repetitive inspections.

After EASA AD 2014-0166 [corresponding to the NPRM] was issued, errors were identified in the compliance time definitions.