

(h) Corrective Actions

If, during any inspection required by paragraph (g) of this AD, any crack, deformation, or damage is found, before further flight do all applicable corrective actions, in accordance with AOT-C212-27-0001, Rev. 0. Where AOT-C212-27-0001, Rev. 0, specifies to contact Airbus for corrective action: Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (k)(2) of this AD.

(i) Optional Modification

Modification of an airplane by replacing the rudder torque tube shaft P/N 212-46237-01 with an improved part, in accordance with the Accomplishment Instructions of EADS CASA Service Bulletin SB-212-27-0058, dated April 25, 2014, constitutes terminating action for the inspections required by paragraphs (g)(1) and (g)(2) of this AD for the modified airplane.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Airbus Military All Operator Letter (AOL) AOL-212-037, Revision 01, dated April 11, 2014.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1112; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or EADS CASA's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2016-0052, dated March 14, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9187.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) EADS CASA Service Bulletin SB-212-27-0058, dated April 25, 2014.

(ii) Airbus Defense & Space Alert Operators Transmission AOT-C212-27-0001, Revision 0, dated July 15, 2015.

(3) For service information identified in this AD, contact Airbus Defense and Space, Services/Engineering Support, Avenida de Aragón 404, 28022 Madrid, Spain; telephone: +34 91 585 55 84; fax: +34 91 585 31 27; email: MTA.TechnicalService@Airbus.com.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 4, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-00407 Filed 1-17-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-9317; Directorate Identifier 2016-CE-029-AD; Amendment 39-18779; AD 2017-01-12]

RIN 2120-AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Diamond Aircraft Industries GmbH Model DA 42 airplanes. This AD results from mandatory continuing

airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as an uncommanded engine shutdown during flight due to failure of the propeller regulating valve caused by hot exhaust gases escaping from fractured engine exhaust pipes. We are issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective February 22, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of February 22, 2017.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No.FAA-2016-9317; or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

For service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A-2700 Wiener Neustadt, Austria, telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; Internet: <http://www.diamondaircraft.com>. You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for Docket No. FAA-2016-9317.

FOR FURTHER INFORMATION CONTACT:

Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Diamond Aircraft Industries GmbH Model DA 42 airplanes. The NPRM was published in the **Federal Register** on October 25, 2016 (81 FR 73360). The NPRM proposed to correct an unsafe condition for the specified products and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of

another country. The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No. 2016–0156R1, dated November 23, 2016 (referred to after this as “the MCAI”). The revised MCAI states:

Two cases were reported of uncommanded engine in-flight shutdown (IFSD) on DA 42 aeroplanes. Subsequent investigations identified these occurrences were due to failure of the propeller regulating valve, caused by hot exhaust gases coming from fractured engine exhaust pipes. The initiating cracks on the exhaust pipes were not detected during previous inspections, since those exhaust pipes are equipped with non-removable heat shields that do not allow inspection for certain sections of the exhaust pipe.

This condition, if not corrected, could lead to further cases of IFSD or overheat damage, possibly resulting in a forced landing, with consequent damage to the aeroplane and injury to occupants.

To address this potential unsafe condition, Diamond Aircraft Industries (DAI) developed an exhaust pipe without a directly attached integral heat shield that allows visual inspection over the entire exhaust pipe length. DAI issued Mandatory Service Bulletin (MSB) 42–120 and relevant Working Instruction (WI) WI–MSB 42–120, providing instructions to install the modified exhaust pipes. As an interim measure, an additional bracket was designed to hold the exhaust pipe in place in case of a pipe fracture.

Consequently, EASA issued AD 2016–0156, requiring replacement of the exhaust pipes with pipes having new design, and prohibiting (re)installation of the previous design pipes.

Since that AD was issued, cracks were identified on modified exhaust pipes during an inspection. Furthermore, it was determined that the additional brackets provide a level of safety equivalent to the modified exhaust pipes. Consequently, DAI revised MSB 42–120, allowing installation of the additional brackets as alternative to the installation of the modified exhaust pipes.

For the reasons described above, this AD is revised to reduce the Applicability, excluding certain post-mod aeroplanes, to allow only installation of the additional brackets as final solution and to remove the prohibition of reinstallation of unmodified exhaust pipes.

The MCAI can be found in the AD docket on the Internet at <https://www.regulations.gov/document?D=FAA-2016-9317-0002>.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the

public interest require adopting this AD as proposed except for the changes discussed above. We have determined that these changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

We reviewed Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 42–120, dated June 24, 2016, Mandatory Service Bulletin MSB 42–120/1, dated November 10, 2016, and Work Instruction WI–MSB 42–120, dated June 24, 2016. In combination, this service information describes procedures for replacing the exhaust pipes with exhaust pipes having a new design. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section of this AD.

Costs of Compliance

We estimate that this AD will affect 130 products of U.S. registry. We also estimate that it will take the following to comply with the requirements of this AD:

It will take about 1 work-hour per product to comply with the installation of additional exhaust clamps required by this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$125 per product.

Based on these figures, we estimate the cost of this AD on U.S. operators for the installation of additional exhaust clamps to be \$27,300, or \$210 per product.

It will take about 4 work-hours per product to comply with the exhaust pipe replacement required by this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$1,990 per product.

Based on these figures, we estimate the cost of this AD on U.S. operators for the exhaust pipe replacement requirement to be \$302,900, or \$2,330 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9317; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647–5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2017-01-12 Diamond Aircraft Industries GmbH: Amendment 39-18779; Docket No. FAA-2016-9317; Directorate Identifier 2016-CE-029-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective February 22, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Diamond Aircraft Industries GmbH DA 42 airplanes, serial numbers 42.004 through 42.427 and 42.AC001 through 42.AC151, that have a TAE 125-02-99 or TAE 125-02-114 engine installed, are equipped with an exhaust pipe, DAI part number (P/N) D60-9078-06-01, or Technify P/Ns 52-7810-H0001 02, 52-7810-H0001 03, or 52-7810-H0001 04, and are certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 78: Engine Exhaust.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as an uncommanded engine shutdown during flight due to failure of the propeller regulating valve caused by hot exhaust gases escaping from fractured engine exhaust pipes. We are issuing this AD to prevent failure of the propeller regulating valve, which could result in forced landing with consequent damage to the airplane.

(f) Actions and Compliance

Unless already done, do one of the actions in either paragraph (f)(1) or (2) of this AD. For the purpose of this AD, if the flight hours accumulated since first installation of an affected exhaust pipe is not known, use the total hours time-in-service (TIS) accumulated on the airplane.

Note 1 to paragraph (f) of this AD: The NPRM for this AD proposed to require both the installation of clamps and the replacement of the exhaust pipes. This AD only requires one or the other.

(1) At the following compliance times, install additional exhaust pipe clamps following section III.2 of the INSTRUCTIONS section of Diamond Aircraft Industries GmbH Work Instruction WI-MSB 42-120, dated June 24, 2016, as specified in the Accomplishments/Instructions paragraph of Diamond Aircraft Industries GmbH

Mandatory Service Bulletin MSB 42-120, dated June 24, 2016, or Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 42-120/1, dated November 10, 2016.

(i) If the affected exhaust pipe has 1,300 hours TIS or less since first installed on an airplane as of February 22, 2017 (the effective date of this AD): Before or upon accumulating 1,500 hours TIS since the affected exhaust pipe was first installed on an airplane.

(ii) If the affected exhaust pipe has more than 1,300 hours TIS since first installed on an airplane as of February 22, 2017 (the effective date of this AD): Within the next 200 hours TIS after February 22, 2017 (the effective date of this AD) or within the next 12 months after February 22, 2017 (the effective date of this AD), whichever occurs first.

(2) At the following compliance times, replace the exhaust pipes listed in paragraph (c) of this AD with an exhaust pipe DAI P/N D60-9078-06-01_01 or Technify P/N 52-7810-H0014 01 following section III.1 of the INSTRUCTIONS section of Diamond Aircraft Industries GmbH Work Instruction WI-MSB 42-120, dated June 24, 2016, as specified in the Accomplishments/Instructions paragraph of Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 42-120, dated June 24, 2016, or Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 42-120/1, dated November 10, 2016.

(i) If the affected exhaust pipe has 1,300 hours TIS or less since first installed on an airplane as of February 22, 2017 (the effective date of this AD): Before or upon accumulating 1,500 hours TIS since the affected exhaust pipe was first installed on an airplane.

(ii) If the affected exhaust pipe has more than 1,300 hours TIS since first installed on an airplane as of February 22, 2017 (the effective date of this AD): Within the next 200 hours TIS after February 22, 2017 (the effective date of this AD) or within the next 12 months after February 22, 2017 (the effective date of this AD), whichever occurs first.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority

(or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2016-0156, dated August 2, 2016, for related information. You may examine the MCAI on the Internet at <https://www.regulations.gov/document?D=FAA-2016-9317-0002>.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 42-120, dated June 24, 2016.

(ii) Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 42-120/1, dated November 10, 2016.

(iii) Diamond Aircraft Industries GmbH Work Instruction WI-MSB 42-120, dated June 24, 2016.

(3) For Diamond Aircraft Industries GmbH service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A-2700 Wiener Neustadt, Austria, telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; Internet: <http://www.diamondaircraft.com>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9317.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov>

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued in Kansas City, Missouri, on January 6, 2017.

Melvin Johnson,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-00502 Filed 1-17-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0831; Directorate Identifier 2014-NM-061-AD; Amendment 39-18778; AD 2017-01-11]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A318 and A319 series airplanes, Model A320-211, -212, -214, -231, -232, and -233 airplanes, and Model A321 series airplanes. This AD was prompted by a report of a rupture of a main landing gear (MLG) sliding tube axle. This AD requires identification of the part number and serial number of the MLG sliding tubes; inspection of affected chromium plates and sliding tube axles for damage; and replacement of the sliding tube if necessary. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 22, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 22, 2017.

ADDRESSES: For service information identified in this final rule, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2015-0831.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0831; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Model A318 and A319 series airplanes, Model A320-211, -212, -214, -231, -232, and -233 airplanes, and Model A321 series airplanes. The SNPRM published in the **Federal Register** on June 28, 2016 (81 FR 41886) (“the SNPRM”). We preceded the SNPRM with a notice of proposed rulemaking (NPRM) that published in the **Federal Register** on April 24, 2015 (80 FR 22939) (“the NPRM”). The NPRM proposed to require an inspection to identify the part number and serial number of the MLG sliding tubes installed on the airplane; an inspection of the axle on certain MLG sliding tubes for damage; and replacement of the sliding tube if necessary. The NPRM was prompted by a report of a rupture of a MLG sliding tube axle. The SNPRM proposed to remove certain service information that does not adequately address the identified unsafe condition and revise the compliance method. We are issuing this AD to detect and correct cracks in the axle and (partial) detachment of the axle and wheel from the sliding tube, which could result in failure of an MLG. The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness

Directive 2014-0058, dated March 11, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A318 and A319 series airplanes, Model A320-211, -212, -214, -231, -232, and -233 airplanes, and Model A321 series airplanes. The MCAI states:

A main landing gear (MLG) sliding tube axle rupture occurred in service. Investigation of the affected part showed that this failure was due to an abnormal grinding operation during overhaul by a certain maintenance and repair organization located in Singapore. A population of MLG sliding tubes was subsequently identified whose axles may have been subject to this grinding operation, which may have resulted in areas of residual stress on the axles on the MLG sliding tubes. In addition, the MSN [manufacturer serial number] of the aeroplanes which are known to have had the affected parts installed have been identified.

This condition, if not detected and corrected, could lead to cracks in the axle and (partial) detachment of axle and wheel from the sliding tube, possibly resulting in failure of a MLG with consequent damage to the aeroplane and injury to occupants.

To address this potential unsafe condition, Messier-Bugatti-Dowty, the MLG gear manufacturer, issued Service Bulletin (SB) 200-32-313 and SB 201-32-62 [both dated February 25, 2013], providing inspection instructions and criteria for removal from service of the affected MLG sliding tubes.

For the reasons described above, this [EASA] AD requires a one-time Special Detailed Inspection (SDI) of the axle on the affected MLG sliding tubes and, depending on findings, replacement of the MLG sliding tube.

The SDI includes a detailed visual inspection of the chromium plate for damage, and a Barkhausen noise inspection of the sliding tube axles for damage.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0831.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the SNPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the SNPRM for correcting the unsafe condition; and