

# Rules and Regulations

Federal Register

Vol. 72, No. 141

Tuesday, July 24, 2007

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## MERIT SYSTEMS PROTECTION BOARD

### 5 CFR Part 1201

#### Practices and Procedures

**AGENCY:** Merit Systems Protection Board.

**ACTION:** Final rule.

**SUMMARY:** The Merit Systems Protection Board (MSPB or the Board) is amending its rules of practice and procedure in this part to reflect the relocation of its Western Regional Office.

**EFFECTIVE DATE:** July 27, 2007.

**FOR FURTHER INFORMATION CONTACT:** Matthew Shannon, Acting Clerk of the Board, (202) 653-7200. The Board is publishing this rule as a final rule pursuant to 5 U.S.C. 1204(h).

**SUPPLEMENTARY INFORMATION:** On July 27, 2007, the Board relocates its Western Regional Office from 250 Montgomery Street, Suite 400, 4th Floor, San Francisco, California 94105-3401, to 201 Mission Street, Suite 2310, San Francisco, California 94105-1831. Appendix II of this part is amended to show the new address. The Western Regional Office telephone number changes to (415) 904-6772 and the facsimile number is changes to (415) 904-0580.

#### List of Subjects in 5 CFR Part 1201

Administrative practice and procedure, Civil rights, Government employees.

■ Accordingly, the Board amends 5 CFR part 1201 as follows:

### PART 1201—PRACTICES AND PROCEDURES

■ 1. The authority citation for part 1201 continues to read as follows:

**Authority:** 5 U.S.C. 1204 and 7701, unless otherwise noted.

### Appendix II to Part 1201 [Amended]

■ 2. Amend Appendix II to Part 1201 in item 5. by removing “250 Montgomery Street, Suite 400, 4th Floor, San Francisco, California 941-3401, Facsimile No.: (415) 705-2945,” and adding, in its place “201 Mission Street, Suite 2310, San Francisco, California 94105-1831 Facsimile No.: (415) 904-0580.”

Dated: July 18, 2007.

**Arlin Winefordner,**  
*Acting Clerk of the Board.*

[FR Doc. E7-14293 Filed 7-23-07; 8:45 am]

**BILLING CODE 7400-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 25

**[Docket No. NM372 Special Conditions No. 25-355-SC]**

### Special Conditions: Boeing Model 787-8 Airplane; Reinforced Flightdeck Bulkhead

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final special conditions.

**SUMMARY:** These special conditions are issued for the Boeing Model 787-8 airplane. This airplane will have novel or unusual design features when compared to the state of technology envisioned in the airworthiness standards for transport category airplanes. The Boeing Model 787-8 airplanes will have a flightdeck bulkhead incorporating ballistic-and intrusion-resistant features. While the regulations include standards for ballistic-and intrusion-resistant flightdeck doors, they do not yet incorporate the same standards for these features in the bulkhead. Therefore, special conditions are needed to address these design features. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing standards. Additional special conditions will be issued for other novel or unusual design features of the Boeing Model 787-8 airplanes.

**EFFECTIVE DATE:** August 23, 2007.

**FOR FURTHER INFORMATION CONTACT:** Jeff Gardlin, FAA, Airframe/Cabin Safety,

ANM-115, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2136; facsimile (425) 227-1320.

### SUPPLEMENTARY INFORMATION:

#### Background

On March 28, 2003, Boeing applied for an FAA type certificate for its new Boeing Model 787-8 passenger airplane. The Boeing Model 787-8 airplane will be an all-new, two-engine jet transport airplane with a two-aisle cabin. The maximum takeoff weight will be 476,000 pounds, with a maximum passenger count of 381 passengers.

#### Type Certification Basis

Under provisions of 14 Code of Federal Regulations (CFR) 21.17, Boeing must show that Boeing Model 787-8 airplanes (hereafter referred to as “the 787”) meet the applicable provisions of 14 CFR part 25, as amended by Amendments 25-1 through 25-117, except §§ 25.809(a) and 25.812, which will remain at Amendment 25-115. If the Administrator finds that the applicable airworthiness regulations do not contain adequate or appropriate safety standards for the 787 because of a novel or unusual design feature, special conditions are prescribed under provisions of 14 CFR 21.16.

In addition to the applicable airworthiness regulations and special conditions, the 787 must comply with the fuel vent and exhaust emission requirements of 14 CFR part 34 and the noise certification requirements of part 36. In addition, the FAA must issue a finding of regulatory adequacy pursuant to section 611 of Public Law 92-574, the “Noise Control Act of 1972.”

The FAA issues special conditions, as defined in § 11.19, under § 11.38 and they become part of the type certification basis under § 21.17(a)(2).

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same or similar novel or unusual design feature, the special conditions would also apply to the other model under § 21.101.

#### Novel or Unusual Design Features

The 787 will incorporate a number of novel or unusual design features.

Because of rapid improvements in airplane technology, the applicable airworthiness regulations do not contain adequate or appropriate safety standards for these design features. These special conditions for the 787 contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

On January 15, 2002, the FAA issued 14 CFR 25.795(a) (Amendment 25-106), which specifies that the flightdeck door of a transport airplane be designed to resist forcible intrusion by unauthorized persons and penetration by small arms fire and fragmentation devices. At the time it was written, the regulation was limited to the flightdeck door to expedite a rapid retrofit of the existing airplanes required by operating rules to have a flightdeck door.

In addition to a reinforced flightdeck door, the 787 will have a flightdeck bulkhead which is reinforced to resist intrusion and ballistic penetration. The regulations do not adequately address the certification requirements for such a bulkhead, and appropriate certification standards are necessary. These special conditions require that the reinforced flightdeck bulkhead meet the same standards as those specified in § 25.795(a) for flightdeck doors. These special conditions contain the minimum standards that the Administrator considers necessary to ensure that safety standards are maintained after the aircraft enters into service.

On December 21, 2006, the FAA issued a notice of proposed rulemaking that proposes amending § 25.795(a) to require that a flightdeck bulkhead—and any other accessible barrier separating the flightcrew compartment from occupied areas—also be designed to resist intrusion or penetration. The methods of compliance described in the preamble of that notice and associated draft advisory material could be used to show compliance with these special conditions. For the 787, the reinforced bulkhead may be comprised of components such as the walls of adjacent lavatories, galleys, or crew rest areas. Those components are covered by these special conditions.

#### Discussion of Comments

Notice of Proposed Special Conditions No. 25-07-08-SC for the 787 was published in the **Federal Register** on April 12, 2007 (72 FR 18412). One comment was received, from Air Line Pilots Association, International (ALPA).

*ALPA Comment:* ALPA recommended that the requirements of these special

conditions apply to future versions of the 787, including possible freighter configurations.

*FAA Response:* These special conditions apply to airplanes that incorporate a reinforced bulkhead. They are not limited to any particular type of operation, nor do they impose operational requirements. Thus, if a future freighter version did incorporate a reinforced bulkhead, these special conditions would apply. These special conditions are adopted as proposed.

#### Applicability

As discussed above, these special conditions are applicable to the 787. Should Boeing apply at a later date for a change to the type certificate to include another model on the same type certificate incorporating the same novel or unusual design features, these special conditions would apply to that model as well.

#### Conclusion

This action affects only certain novel or unusual design features of the 787. It is not a rule of general applicability.

#### List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

■ The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

#### The Special Conditions

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for the Boeing Model 787-8 airplane.

In addition to the requirements of 14 CFR 25.795(a) governing protection of the flightdeck door, the following special conditions apply.

The reinforced bulkhead, including components that comprise the bulkhead, separating the flightcrew compartment from occupied areas must be designed to meet the following standards:

It must resist forcible intrusion by unauthorized persons and be capable of withstanding impacts of 300 Joules (221.3 foot-pounds) at critical locations on the bulkhead as well as a 1113 Newton (250 pound) constant tensile load on accessible handholds.

It must resist penetration by small arms fire and fragmentation devices to a level equivalent to level IIIa of the National Institute of Justice Standard (NIJ) 0101.04.

Issued in Renton, Washington, on July 12, 2007.

**Stephen P. Boyd,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-14333 Filed 7-23-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-28749; Directorate Identifier 2007-NM-079-AD; Amendment 39-15134; AD 2007-15-05]

**RIN 2120-AA64**

**Airworthiness Directives; McDonnell Douglas Model DC-10-10 and DC-10-10F Airplanes, Model DC-10-15 Airplanes, Model DC-10-30 and DC-10-30F (KC-10A and KDC-10) Airplanes, Model DC-10-40 and DC-10-40F Airplanes, Model MD-10-10F and MD-10-30F Airplanes, and Model MD-11 and MD-11F Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all transport category airplanes identified above. This AD requires an inspection to determine if a certain fuel pump housing electrical connector is installed. This AD also requires a revision to the FAA-approved airplane flight manual (AFM) to advise the flightcrew of the appropriate procedures for disabling certain fuel pump electrical circuits following failure of a fuel pump housing electrical connector if applicable. This AD also requires the deactivation of certain fuel tanks or fuel pumps and the installation of placards if applicable. This AD allows the optional replacement of the fuel pump housing electrical connectors with new, improved parts, which would terminate the AFM revisions, deactivation of certain fuel tanks and fuel pumps, and placard installation. This AD results from a report of two failures of the fuel pump housing electrical connector. We are issuing this AD to prevent continued arcing following a short circuit of the fuel pump housing electrical connector, which could damage the conduit that protects the power lead inside the fuel tank; this condition could create an ignition source inside the fuel tank, which, in combination with flammable fuel vapors, could result in a fuel tank