

# Proposed Rules

Federal Register

Vol. 78, No. 138

Thursday, July 18, 2013

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## FARM CREDIT ADMINISTRATION

### 12 CFR Chapter VI

RIN 3052-AC88

#### Statement on Regulatory Burden

**AGENCY:** Farm Credit Administration.

**ACTION:** Notice of intent; request for comment.

**SUMMARY:** The Farm Credit Administration (FCA, our, or we) issues this notice in order to consider whether our existing regulations are inefficient or burdensome. We seek public comment on the appropriateness of the requirements we impose on Farm Credit System (System) institutions, including the Federal Agricultural Mortgage Corporation (Farmer Mac). We ask for comments on our regulations that may duplicate other requirements, are ineffective, are not based on law, or impose burdens that are greater than the benefits received.

**DATES:** Please send your comments to FCA by November 15, 2013.

**ADDRESSES:** We offer a variety of methods for you to submit comments on this notice. For accuracy and efficiency reasons, commenters are encouraged to submit comments by email or through FCA's Web site. As facsimiles (fax) are difficult for us to process and achieve compliance with section 508 of the Rehabilitation Act, we are no longer accepting comments submitted by fax. Regardless of the method you use, please do not submit your comment multiple times via different methods. You may submit comments by any of the following methods:

- *Email:* Send us an email at [reg-comm@fca.gov](mailto:reg-comm@fca.gov).
- *FCA Web site:* <http://www.fca.gov>. Select "Public Commenters," then "Public Comments," and follow the directions for "Submitting a Comment."
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Mail:* Barry F. Mardock, Deputy Director, Office of Regulatory Policy,

Farm Credit Administration, 1501 Farm Credit Drive, McLean, VA 22102-5090.

You may review copies of all comments we receive at our office in McLean, Virginia, or on our Web site at <http://www.fca.gov>. Once you are in the Web site, select "Public Commenters," then "Public Comments," and follow the directions for "Reading Submitted Public Comments." We will show your comments as submitted, but for technical reasons we may omit items such as logos and special characters. Identifying information that you provide, such as phone numbers and addresses, will be publicly available. However, we will attempt to remove email addresses to help reduce Internet spam.

**FOR FURTHER INFORMATION CONTACT:** Lori Markowitz, Policy Analyst, Office of Regulatory Policy, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4487, TTY (703) 883-4056, or Mary Alice Donner, Senior Counsel, Office of General Counsel, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4020, TTY (703) 883-4056.

#### SUPPLEMENTARY INFORMATION:

##### I. Objective

The objective of this notice is to continue our comprehensive review of regulations governing the System and to eliminate, consistent with law and safety and soundness, all regulations that are unnecessary, unduly burdensome or costly, or not based on the law.

The notice requests public comment on FCA regulations that:

- Are not currently under review;
- Were effective prior to January 1, 2012;
- May duplicate other requirements;
- Are ineffective;
- Are not based on law; or
- Impose burdens that are greater than the benefits received.

##### II. Background

FCA is the independent Federal agency in the executive branch of the Government responsible for examining and regulating System institutions. System banks and associations primarily provide loans to farmers, ranchers, aquatic producers and harvesters, agricultural cooperatives, and rural utilities. Farmer Mac provides a secondary market for agricultural and

rural housing mortgages and eligible rural utility cooperative loans.

### III. Our Continuing Efforts To Reduce Unnecessary Regulatory Burdens

The regulations of FCA that are subject to regulatory review described in this notice are codified in title 12, chapter VI, of the Code of Federal Regulations. We are requesting your comments on any FCA regulations or policies that may duplicate other governmental requirements, are not effective in achieving stated objectives, are not based on law, or create a burden that is perceived to be greater than the benefits received. Please do not respond to this solicitation with comments concerning proposed regulations that are currently under review, or final regulations that did not become effective until after January 1, 2012.

Your comments will assist us in our continuing efforts to identify and reduce unnecessary regulatory burdens on System institutions. We will also continue our efforts to maintain and adopt regulations and policies that are necessary to implement the Farm Credit Act of 1971, as amended, and ensure the safety and soundness of the System. These actions will enable the System institutions to better serve the credit needs of its customers, *i.e.*, America's farmers, ranchers, aquatic producers and harvesters, cooperatives, and rural residents, in the changing agricultural credit markets.

Dated: July 12, 2013.

**Dale L. Aultman,**

*Secretary, Farm Credit Administration Board.*

[FR Doc. 2013-17181 Filed 7-17-13; 8:45 am]

**BILLING CODE 6705-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2013-0548; Directorate Identifier 2013-NM-008-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model BD-700-1A11 airplanes. This proposed AD was prompted by a report that certain lanyards for the passenger oxygen masks are longer than the specified length, possibly leading to inactive oxygen masks in an emergency. This proposed AD would require replacing certain oxygen mask lanyards. We propose this AD to detect and correct lanyards of incorrect length, which might not activate the flow of oxygen in an emergency, resulting in injury to passengers.

**DATES:** We must receive comments on this proposed AD by September 3, 2013.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems

Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7318; fax (516) 794-5531.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2013-0548; Directorate Identifier 2013-NM-008-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

##### Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2012-31, dated December 7, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

The aeroplane manufacturer has determined that the Oxygen Dispensing Unit (ODU) lanyards, in several locations throughout the aeroplane cabin, are excessively long. In an emergency situation where oxygen is required, it is possible that certain occupants may put their oxygen mask on without automatically activating the oxygen flow which could result in a fatal injury.

This [Canadian] AD mandates the replacement of the existing ODU lanyards with lanyards of the correct length.

You may obtain further information by examining the MCAI in the AD docket.

##### Relevant Service Information

Bombardier, Inc. has issued Service Bulletin 700-1A11-35-009, dated October 22, 2012. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

##### FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another

country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

##### Differences Between This AD and the MCAI or Service Information

This AD applies only to airplanes that have been modified by FAA Supplemental Type Certificate (STC) ST02140NY, issued October 14, 2005. Internet: [http://rgl.faa.gov/Regulatory\\_and\\_Guidance\\_Library/rgstc.nsf/0/6B8CF26D01F5E6DE862570C7006DCD7E?OpenDocument&Highlight=st02140ny](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/6B8CF26D01F5E6DE862570C7006DCD7E?OpenDocument&Highlight=st02140ny).

##### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 22 products of U.S. registry. We also estimate that it would take about 16 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$0 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$29,920, or \$1,360 per product.

##### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

**Bombardier, Inc.:** Docket No. FAA–2013–0548; Directorate Identifier 2013–NM–008–AD.

#### (a) Comments Due Date

We must receive comments by September 3, 2013.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier, Inc. Model BD–700–1A11 airplanes, certificated in any category, modified by FAA Supplemental Type Certificate (STC) ST02140NY, issued October 14, 2005. Internet: <http://rgl.faa.gov/>

*Regulatory and Guidance Library/rgstc.nsf/0/6B8CF26D01F5E6DE862570C7006DCD7E?OpenDocument&Highlight=st02140ny.*

#### (d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

#### (e) Reason

This AD was prompted by a report that certain lanyards for the passenger oxygen masks are longer than the specified length, possibly leading to inactive oxygen masks in an emergency. We are issuing this AD to detect and correct lanyards of incorrect length, which might not activate the flow of oxygen in an emergency, resulting in injury to passengers.

#### (f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### (g) Replacement

Within 750 flight hours or 15 months after the effective date of this AD, whichever occurs first: Replace lanyards having part numbers (PN) B431564–503 and –505 for all passenger oxygen dispensing units, with lanyards having PN B431564–507, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 700–1A11–35–009, dated October 22, 2012.

#### (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### (i) Related Information

(1) Refer to Canadian Airworthiness Directive CF–2012–31, dated December 7, 2012, for related information.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9,

Canada; telephone 514–855–5000; fax 514–855–7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 5, 2013.

**Jeffrey E. Duven,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2013–17255 Filed 7–17–13; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2013–0547; Directorate Identifier 2013–NM–028–AD]

RIN 2120–AA64

### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 727–200 and 727–200F series airplanes. This proposed AD is intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. This proposed AD would require a one-time inspection for cracking of the pressure floor of both main wheel wells, and related investigative and corrective actions if necessary; and would require modifying the pressure floor of both main wheel wells. We are proposing this AD to prevent fatigue cracking in the pressure floor of the main wheel wells, which could lead to rapid loss of cabin pressurization.

**DATES:** We must receive comments on this proposed AD by September 3, 2013.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations,