

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2014-04-14, Amendment 39-17773 (79 FR 11699, March 3, 2014), and adding the following new AD:

2015-05-05 Agusta S.p.A.: Amendment 39-18115; Docket No. FAA-2014-0579; Directorate Identifier 2014-SW-020-AD.

(a) Applicability

This AD applies to the following helicopters, certificated in any category:

- (1) Agusta S.p.A. (Agusta) Model A109S and AW109SP helicopters, with a main rotor lag damper assembly (lag damper), part number (P/N) 109-0112-39-103 or 109-0112-39-105, installed on rod end assembly, P/N M004-01H007-041 with a serial number (S/N) 1 through 202; or rod end assembly, P/N M004-01H007-045 with a S/N 1RW through 202RW or 4964 through 5011.

- (2) Agusta Model A119 and AW119 MKII helicopters, with a lag damper, P/N 109-0112-05-105 or 109-0112-05-107, installed on rod end assembly, P/N 109-0112-11-101 with a S/N 1 through 78; or rod end assembly, P/N 109-0112-11-105 with a S/N 1RW through 78RW; or rod end assembly, P/N M004-01H007-045 with a S/N 1RW through 202RW or 4964 through 5011.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in a rod end assembly, which could result in fracture of the rod end assembly, damage to the main rotor, and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD supersedes AD 2014-04-14, amendment 39-17773 (79 FR 11699, March 3, 2014).

(d) Effective Date

This AD becomes effective April 23, 2015.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

- (1) Within 25 hours time-in-service or the next time maintenance of the helicopter involves removing the rod end assembly, whichever occurs first, remove the rod end assembly from service.

- (2) Do not install a rod end assembly, P/N M004-01H007-041 with a S/N 1 through 202; P/N M004-01H007-045 with a S/N 1RW through 202RW or 4964 through 5011; P/N 109-0112-11-101 with a S/N 1 through 78; or P/N 109-0112-11-105 with a S/N 1RW through 78RW, on any helicopter.

(g) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email robert.grant@faa.gov.

- (2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

(1) AgustaWestland S.p.A. Bollettino Tecnico (BT) No. 109S-49, BT No. 109SP-052, and BT No. 119-50, all Revision A, and all dated December 3, 2013, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact AgustaWestland, Product Support Engineering, Via del Gregge, 100, 21015 Lonate Pozzolo (VA) Italy, ATTN: Maurizio D'Angelo; telephone 39-0331-664757; fax 39-0331-664680; or at <http://www.agustawestland.com/technical-bulletins>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(2) The subject of this AD is addressed in the European Aviation Safety Agency (EASA) AD No. 2013-0290, dated December 9, 2013. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2014-0579.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor System.

Issued in Fort Worth, Texas, on March 4, 2015.

Bruce E. Cain,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2015-05715 Filed 3-18-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-1001; Directorate Identifier 2014-CE-034-AD; Amendment 39-18103; AD 2015-04-01]

RIN 2120-AA64

Airworthiness Directives; Short Brothers & Harland Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that published in the **Federal Register**. That AD applies to all Short Brothers & Harland Ltd. Model SC-7 Series 3 airplanes. The amendment number in the Agency Identification Numbers in the preamble section of the AD is incorrect. Although no other part of the preamble or regulatory information has been corrected, we are publishing the entire rule in the **Federal Register**.

DATES: This final rule is effective March 30, 2015.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>

www.regulations.gov by searching for and locating Docket No. FAA–2014–1001; or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

For service information identified in this AD, contact Short Brothers & Harland Ltd. service information identified in this proposed AD, contact Airworthiness, Short Brothers PLC, P.O. Box 241, Airport Road, Belfast, BT3 9DZ Northern Ireland, United Kingdom; phone: +44–2890–462469, fax: 44–2890–733647, email: michael.mulholland@aero.bombardier.com, internet: None; and for SAFRAN Messier-Buggatti-Dowty service information contact Messier-Dowty Limited, Cheltenham Road, Gloucester GL2 9QH, ENGLAND; phone: +44(0)1452 712424; fax: +44(0)1452 713821; email: americacsc@safranmbd.com, Internet: <http://www.safranmbd.com>. You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–1001.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:

Airworthiness Directive 2015–04–01, Amendment 39–18003 (80 FR 9382, February 23, 2015), currently requires a visual inspection of the NLG sliding tube and a fluorescent penetrant inspection of the sliding tube. If any crack is detected during either inspection, before further flight, obtain FAA-approved repair instructions approved specifically for compliance with this AD by reporting the findings, and incorporating those instructions for Short Brothers & Harland Ltd. Model SC–7 Series 3 airplanes, all serial numbers, certificated in any category.

As published, the amendment number in the Agency Identification Numbers in the preamble section of the AD is incorrect. It has been corrected in this document.

Although no other part of the preamble or regulatory information has

been corrected, we are publishing the entire rule in the **Federal Register**.

The effective date of this AD remains March 30, 2015.

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2015–04–01 Short Brothers & Harland Ltd:
Amendment 39–18103; Docket No. FAA–2014–1001; Directorate Identifier 2014–CE–034–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective on March 30, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Short Brothers & Harland Ltd. Model SC–7 Series 3 airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 32: Landing Gear.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as fatigue cracking which could lead to structural failure of the nose landing gear (NLG). We are issuing this AD to detect and correct fatigue cracking which, if not detected and corrected, could lead to structural failure of the NLG, possibly resulting in loss of control of the airplane during take-off or landing.

(f) Actions and Compliance

Unless already done, comply with this AD within the compliance times specified in paragraphs (f)(1) through (f)(5) of this AD.

(1) Within 30 days after March 30, 2015 (the effective date of this AD), accomplish a visual inspection of the NLG sliding tube following the instructions of paragraph 3.A of SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32–17M, dated November 1, 2014.

Note 1 to paragraphs (f)(1), (f)(2), (f)(4), and (f)(5) of this AD: Instructions provided by SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32–17M, dated November 1, 2014, are referenced in Shorts Service Bulletin Number 32–74, dated November 1, 2014.

(2) Within 90 days after March 30, 2015 (the effective date of this AD), do a fluorescent penetrant inspection of the sliding tube following the instructions of

paragraph 3.B of SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32–17M, dated November 1, 2014.

(3) If any crack is detected during the inspection required by paragraph (f)(1) or (f)(2) of this AD, before further flight, obtain FAA-approved repair instructions approved specifically for compliance with this AD by reporting the findings to Short Brothers & Harland Ltd. and incorporating those instructions. You can find contact information for Short Brothers & Harland Ltd. in paragraph (h) of this AD.

(4) Within 30 days after any inspection required by paragraphs (f)(1) and (f)(2) of this AD or within 30 days after March 30, 2015 (the effective date of this AD), whichever occurs later, report the inspection results to Short Brothers & Harland Ltd. by completing the Inspection Results Proforma following the instructions of paragraph 3.C.(2) of SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32–17M, dated November 1, 2014. You can find contact information for Short Brothers & Harland Ltd. in paragraph (h) of this AD.

(5) From March 30, 2015 (the effective date of this AD), you may install a sliding tube on an NLG provided that, before next flight after installation, the NLG sliding tube passes the inspections in paragraphs (f)(1) and (f)(2) of this AD following the instructions of paragraph 3 of SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32–17M, dated November 1, 2014.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to

be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2014-0246, dated November 12, 2014; and Shorts Service Bulletin Number 32-74, dated November 1, 2014, for related information. The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#!documentDetail;D=FAA-2014-1001-0002>. For Short Brothers & Harland Ltd. service information identified in this AD, contact Airworthiness, Short Brothers PLC, P.O. Box 241, Airport Road, Belfast, BT3 9DZ Northern Ireland, United Kingdom; phone: +44-2890-462469, fax: 44-2890-733647, email: michael.mulholland@aero.bombardier.com, internet: None.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32-17M, dated November 1, 2014.

(ii) Reserved.

(3) For SAFRAN Messier-Buggatti-Dowty service information identified in this AD, contact Messier-Dowty Limited, Cheltenham Road, Gloucester GL2 9QH, ENGLAND; phone: +44(0)1452 712424; fax: +44(0)1452 713821; email: americacsc@safranmbd.com, Internet: <http://www.safranmbd.com>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1001.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 11, 2015.

Robert Busto,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-06235 Filed 3-18-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF LABOR

Employee Benefits Security Administration

29 CFR Part 2550

RIN 1210-AB68

Fiduciary Requirements for Disclosure in Participant-Directed Individual Account Plans—Timing of Annual Disclosure

AGENCY: Employee Benefits Security Administration, Department of Labor.

ACTION: Direct final rule.

SUMMARY: This direct final rule amends the Department of Labor's "participant-level fee disclosure" regulation. The amendment makes a technical adjustment to a timing requirement in the current regulation. As amended, the regulation provides plan administrators with flexibility as to when they must furnish annual disclosures to participants and beneficiaries.

DATES: *Effective date:* This rule is effective June 17, 2015, without further action or notice, unless significant adverse comment is received by April 20, 2015. If significant adverse comment is received, the Employee Benefits Security Administration (EBSA) will publish a timely withdrawal of the rule in the **Federal Register**.

Applicability date: The amendment is applicable to disclosures made on or after June 17, 2015.

ADDRESSES: You may submit comments, identified by RIN 1210-AB68, by one of the following methods:

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Email:* e-ORI@dol.gov. Include RIN 1210-AB68 in the subject line of the message.

- *Mail or personal delivery:* Office of Regulations and Interpretations, Employee Benefits Security Administration, Room N-5655, U.S. Department of Labor, 200 Constitution Avenue NW., Washington, DC 20210.

Instructions: All submissions received must include the agency name and Regulation Identifier Number (RIN) for this rulemaking. Comments received, including any personal information provided, will be posted without change to <http://www.regulations.gov> and <http://www.dol.gov/ebsa>, and made available for public inspection at the Public Disclosure Room, N-1513, Employee Benefits Security Administration, 200 Constitution Avenue NW., Washington, DC 20210. Persons submitting comments

electronically are encouraged not to submit paper copies.

FOR FURTHER INFORMATION CONTACT: Eric A. Raps, Office of Regulations and Interpretations, Employee Benefits Security Administration, Department of Labor, at (202) 693-8532. This is not a toll-free number.

SUPPLEMENTARY INFORMATION:

In General

On October 20, 2010, the Department of Labor (Department) published a final regulation requiring plan administrators to disclose certain plan and investment-related information, including fee and expense information, to participants and beneficiaries in participant-directed individual account plans.¹ The regulation requires certain information to be furnished on or before the date on which a participant can first direct his or her investments and "at least annually thereafter." The regulation defines this term as "at least once in any 12-month period, without regard to whether the plan operates on a calendar or fiscal year basis."² The regulation was effective on December 20, 2010, but was not applicable until plan years beginning on or after November 1, 2011.³

On July 30, 2012, the Department's Employee Benefits Security Administration (EBSA) issued Field Assistance Bulletin 2012-02R (FAB 2012-02R) providing guidance on frequently asked questions. Q&A 35 clarified that, for most plans, including calendar year plans, the first initial disclosures under the new regulation were required no later than August 30, 2012. FAB 2012-02R did not, however, specifically address the deadline for subsequent annual disclosures.⁴

In Field Assistance Bulletin 2013-02, issued July 22, 2013, the Department made clear that the regulation requires annual disclosures to be made no more than one year exactly (e.g., 365 days) after the prior annual disclosures. Specifically, FAB 2013-02, in relevant part, states "[f]or example, a plan administrator that furnished the first required chart on August 25, 2012, must furnish the next comparative chart no

¹ 29 CFR 2550.404a-5; 75 FR 64910.

² 29 CFR 2550.404a-5(h)(1).

³ The specified applicability date was subsequently delayed by amendment published on July 19, 2011. 76 FR 42539. Under the amendment, the initial disclosures required on or before the date on which a participant or beneficiary can first direct his or her investments must be furnished no later than the later of 60 days after such applicability date or 60 days after the effective date of 29 CFR 2550.408b-2(c). 29 CFR 2550.404a-5(j)(3)(i)(A).

⁴ FAB 2012-02R supersedes FAB 2012-02 issued on May 7, 2012. Changes in the superseding bulletin did not affect Question 35.