

(i) Governance (including incorporation, bylaws, boards of directors, shareholders, and distribution of dividends);

(ii) Consolidation, merger, dissolution, conversion (including conversion to a stock bank or to another charter), conservatorship, and receivership;

(iii) Provisions of law applicable only to Federal mutual savings associations;

(iv) Offers and sales of securities at an office of a Federal savings association;

(v) Inclusion of subordinated debt securities and mandatorily redeemable preferred stock as Federal savings association supplementary (tier 2) capital;

(vi) Increases in permanent capital of a Federal stock savings association;

(vii) Rules of practice and procedure in adjudicatory proceedings;

(viii) Rules for investigative proceedings and formal examination proceedings;

(ix) Removals, suspensions, and prohibitions where a crime is charged or proven;

(x) Security procedures;

(xi) Maintenance of records and recordkeeping and confirmation requirements for securities transactions;

(xii) Nondiscrimination; and

(xiii) Advertising.

(b) *Existing branches.* A covered savings association may continue to operate any branch or agency that the covered savings association operated on the effective date of the election.

§ 101.5 Nonconforming subsidiaries, assets, and activities.

(a) *Divestiture, conformance, or discontinuation.* A covered savings association shall divest, conform, or discontinue a nonconforming subsidiary, asset, or activity at the earliest time that prudent judgment dictates but not later than two years after the effective date of the election. The OCC may require a covered savings association to submit a plan to divest, conform, or discontinue a nonconforming subsidiary, asset, or activity.

(b) *Extension.* The OCC may grant a covered savings association extensions of not more than two years each up to a maximum of eight years if the OCC determines that:

(1) The covered savings association has made a good faith effort to divest, conform, or discontinue the nonconforming subsidiary, asset, or activity;

(2) Divestiture, conformance, or discontinuation would have a material adverse financial effect on the covered savings association; and

(3) Retention or continuation of the nonconforming subsidiary, asset, or activity is consistent with the safe and sound operation of the covered savings association.

(c) *Applicable law.* Until a covered savings association divests, conforms, or discontinues a nonconforming subsidiary, asset, or activity, the nonconforming subsidiary, asset, or activity shall continue to be subject to the same provisions of law that applied to the nonconforming subsidiary, asset, or activity on the day before the effective date of the election.

§ 101.6 Termination.

(a) *Termination.* A covered savings association may terminate its election to operate as a covered savings association, after an appropriate period of time as determined by the OCC, by submitting a notice to the appropriate OCC supervisory office.

(b) *Procedures.* A covered savings association wishing to terminate its election shall comply with, and shall be subject to, the provisions of §§ 101.2, 101.3, and 101.5, except that:

(1) The provisions of §§ 101.3 and 101.5 shall be applied by substituting “covered savings association” for “Federal savings association” and “Federal savings association” for “covered savings association” each place those terms appear in those sections;

(2) Section 101.3(a)(1) and (2)(ii) shall not apply; and

(3) Sections 101.3 and 101.5 shall be applied by substituting “effective date of the termination” for “effective date of the election.”

(c) *Applicable law.* On and after the effective date of the termination, a Federal savings association that has terminated its election to operate as a covered savings association shall be subject to the same provisions of law as a Federal savings association that has not made an election under this part.

§ 101.7 Reelection.

(a) *Reelection.* A Federal savings association that has terminated its election to operate as a covered savings association may submit a notice to reelect to operate as a covered savings association, if at least five years have elapsed since the effective date of the termination. Upon determining that good cause exists, the OCC may permit a Federal savings association to reelect to operate as a covered savings association prior to the expiration of the five-year period.

(b) *Procedures and treatment.* A Federal savings association reelecting to operate as a covered savings association

shall comply with, and shall be subject to, the provisions of this part as if it were making an election for the first time.

§ 101.8 Evasion.

The OCC may disapprove any notice submitted pursuant to this part if the OCC has reasonable cause to believe the notice is made for the purpose of evading § 101.5, including as that section applies to a covered savings association terminating an election.

Dated: September 10, 2018.

Joseph M. Otting,

Comptroller of the Currency.

[FR Doc. 2018–19955 Filed 9–17–18; 8:45 am]

BILLING CODE 4810–33–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0796; Product Identifier 2018–NM–104–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes. This proposed AD was prompted by reports of drainage holes on the belly fairing forward and middle access panels being obstructed with sealant. This proposed AD would require inspecting for and removing all sealant blocking the drainage holes on the belly fairing forward and middle access panels. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by November 2, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; internet: <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0796; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA-2018-0796; Product Identifier 2018-NM-104-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory,

economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2018-14, dated May 1, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. The MCAI states:

Bombardier Aerospace (BA) has informed Transport Canada that the drainage holes on the belly fairing forward and middle access panels may be obstructed with sealant. The purpose of the drainage holes is to allow for drainage of a limited quantity of fluids due to any leaks, should they occur. This condition, if not corrected, may prevent the timely detection of fluid leakage that could lead to the accumulation of flammable fluids/vapors, beyond the design capacity of the belly fairing venting provisions [which could ignite if an ignition source (*i.e.*, spark, static discharge, heat, etc.) is present].

This [Canadian] AD is issued to mandate the removal of all sealant blocking the drainage holes on the belly fairing forward and middle access panels.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0796.

Related Service Information Under 1 CFR Part 51

Bombardier, Inc., has issued the following service information for

Bombardier Model BD-700-1A10 airplanes.

- Service Bulletin 700-53-051, dated May 17, 2017.
- Service Bulletin 700-53-6009, dated May 17, 2017.

Bombardier, Inc., has issued the following service information for Bombardier Model BD-700-1A11 airplanes.

- Service Bulletin 700-1A11-53-026, dated May 17, 2017.
- Service Bulletin 700-53-5010, dated May 17, 2017.

This service information describes procedures for inspecting for and removing sealant blocking the drainage holes on the belly fairing forward and middle access panels. These documents are distinct since they apply to different airplane models and configurations. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 376 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
6 work-hours × \$85 per hour = \$510 per airplane	\$0	\$510	\$191,760

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA–2018–0796; Product Identifier 2018–NM–104–AD.

(a) Comments Due Date

We must receive comments by November 2, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11

airplanes, certificated in any category, serial numbers 9001 through 9707 inclusive, 9709 through 9717 inclusive, 9719 through 9726 inclusive, 9728, 9730, 9732 through 9734 inclusive, 9736 through 9740 inclusive, 9742 through 9745 inclusive, 9749, 9751, 9757, and 9998.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of drainage holes on the belly fairing forward and middle access panels being obstructed with sealant. We are issuing this AD to address fluid leakage that could lead to the accumulation of flammable fluids/vapors, beyond the design capacity of the belly fairing venting provisions, which could ignite if an ignition source (*i.e.*, spark, static discharge, heat, etc.) is present.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Sealant Removal

Within 375 flight hours or 12 months, whichever occurs first, after the effective date of this AD, do a general visual inspection for and remove all sealant blocking the drainage holes on the belly fairing forward and middle access panels, in accordance with the Accomplishment Instructions of the applicable service information listed in Figure 1 to paragraph (g) of this AD.

Figure 1 to paragraph (g) of this AD – Service bulletins

Airplane Model	Bombardier Service Bulletin	Issue Date
BD-700-1A10	700-53-051	May 17, 2017
BD-700-1A10	700-53-6009	May 17, 2017
BD-700-1A11	700-1A11-53-026	May 17, 2017
BD-700-1A11	700-53-5010	May 17, 2017

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your

request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO Branch, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228 7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector,

or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design

Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2018-14, dated May 1, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0796.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516 228 7323; fax 516 794 5531; email 9-avs-nyacos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; internet: <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on September 7, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-20098 Filed 9-17-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0833; Product Identifier 2018-CE-031-AD]

RIN 2120-AA64

Airworthiness Directives; Weatherly Aircraft Company

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Weatherly Aircraft Company (Weatherly) Models 201, 201A, 201B, 201C, 620, 620A, 620B, 620B-TG, and 620TP airplanes. This proposed AD was prompted by reports of fatigue cracking of the center wing and outer wing spar hinge brackets due to corrosion pitting. This proposed AD would require repetitive inspections of the wing hinge brackets, pins, and wing spar structure with repair or replacement of parts as

necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by November 2, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Weatherly Aircraft Company, 2034 West Potomac Avenue, Chicago, Illinois 60622-3152; telephone: (424) 772-1812; email: garybeck@cox.net. You may review copies of the referenced service information at the FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0833; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Mike Lee, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, 3960 Paramount Blvd., Suite 100, Lakewood, California, 90712; phone: (562) 627-5325; fax: (562) 627-5210; email: mike.s.lee@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2018-0833; Product Identifier 2018-CE-018-AD" at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

In 2015, we were notified of a fatal accident caused by the in-flight structural failure of a wing on a Weatherly Model 620B airplane. The accident investigation found multiple fatigue cracks in the center wing front spar lower hinge bracket. As a result of operator inspections, a cracked hinge bracket in the center wing to outer wing joint was also reported on a different airplane. The hinge bracket from the second report had completely failed, and the airplane was relying on the second failsafe hinge bracket to carry the wing loads. This condition, if not addressed, could result in failure of the wing front spar lower hinge brackets and lead to in-flight separation of the wing with consequent loss of control of the airplane.

To correct this unsafe condition, we issued AD 2016-07-11 (81 FR 18461, March 31, 2016) ("AD 2016-07-11"), which requires a one-time visual inspection of the center and outer wing front spar lower hinge brackets for cracks and corrosion and corrective action as necessary. AD 2016-07-11 also requires sending a report of the inspection results to the FAA.

Since we issued AD 2016-07-11, Weatherly has developed improved center wing hinge brackets manufactured from corrosion resistant material. Weatherly also issued new service information for repetitive visual and detailed inspections. Since the cause of the fatigue cracks were attributed to corrosion pits on the accident airplane, we propose to issue this new AD to require those repetitive visual and detailed inspection actions.

Related Service Information Under 14 CFR Part 51

We reviewed Weatherly 201/620 Service Bulletin SB-201/620-18001, Revision C, dated May 21, 2018. The service information describes procedures for initial and repetitive inspections of the wing hinge brackets, pins, and wing spar structure for corrosion and/or cracks with repair or replacement as necessary. This service