

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2016-0177, dated September 8, 2016. You may view the EASA AD on the internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2017-0619.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6520, Tail Rotor Gearbox.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Leonardo Helicopters Bollettino Tecnico No. 189-114, dated September 6, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Matteo Ragazzi, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-711756; fax +39-0331-229046; or at <http://www.leonardocompany.com/-/bulletins>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on September 6, 2018.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2018-20107 Filed 9-20-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2017-0688; Product Identifier 2017-NE-23-AD; Amendment 39-19353; AD 2018-16-13]

RIN 2120-AA64

Airworthiness Directives; Zodiac Seats France, Cabin Attendant Seats

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Zodiac Seats France, 537-Series Cabin Attendant Seats. This AD was prompted by operator reports that safety belt wear was found at the attachment to the cabin attendant seat. This AD requires inspecting the safety belt webbing, and modifying and re-marking each affected cabin attendant seat. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 26, 2018.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 26, 2018.

ADDRESSES: For service information identified in this final rule, contact Zodiac Seats France, Rue Robert Marechal Senior B.P. 69, 36100 Issoudun, France; phone: +33 (0) 9 70 83 08 30; fax: +33 (0) 2 54 03 39 00; email: zs.tac@zodiac aerospace.com; internet: <http://www.services.zodiac aerospace.com>. You may view this service information at the FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0688.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0688; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-

5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Dorie Resnik, Aerospace Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7693; fax: 781-238-7199; email: dorie.resnik@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Zodiac Seats France, 537-Series Cabin Attendant Seats. The NPRM published in the **Federal Register** on December 11, 2017 (82 FR 58137). The NPRM was prompted by operator reports that safety belt wear was found at the attachment to the cabin attendant seat. The NPRM proposed to require inspecting the safety belt webbing, and modifying and re-marking each affected cabin attendant seat. We are issuing this AD to address the unsafe condition on these products.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2016-0163, dated August 10, 2016 (referred to after this as "the MCAI"), to address the unsafe condition on these products. The MCAI states:

Cases were reported by operators of finding safety belt worn out at the attachment to the cabin attendant seat. This kind of belt damage is due to chafing between the belt and the surrounding metal lap belt fitting of the cabin attendant seat. This condition, if not detected and corrected, could lead to failure of the attendant seat to perform its intended function, possibly resulting in injury to the seat occupant. Prompted by these occurrences, Zodiac Seats France issued Service Bulletin (SB) No. 537-25-003, providing instructions to modify the affected seats. For the reason described above, this [EASA] AD requires a modification of the seat pan shaft by installing new seat pan spacers, and subsequent re-identification with a new P/N.

You may obtain further information by examining the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0688.

Comments

We gave the public the opportunity to participate in developing this final rule. We received no comments on the NPRM or on the determination of the cost to the public.

Zodiac Seats France Service Bulletin No. 537–25–003, Revision 1, dated August 29, 2016.

(h) Installation Prohibition

After the effective date of this AD, do not install any affected Zodiac Seats France cabin attendant seat on any aircraft.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Boston ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Boston ACO Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Dorie Resnik, Aerospace Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7693; fax: 781–238–7199; email: dorie.resnik@faa.gov.

(2) Refer to European Aviation Safety Agency (EASA) AD 2016–0163, dated August 10, 2016, for more information. You may examine the EASA AD in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0688.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Zodiac Seats France Service Bulletin No. 537–25–003, Revision 1, dated August 29, 2016.

(ii) Zodiac Seats France Service Information Letter 537–01, dated July 31, 2015.

(3) For service information identified in this AD, contact Zodiac Seats France, Rue Robert Marechal Senior B.P. 69, 36100 Issoudun, France; phone: +33 (0) 9 70 83 08 30; fax: +33 (0) 2 54 03 39 00; email: zs.tac@zodiacaeospace.com; internet: <http://www.services.zodiacaeospace.com>.

(4) You may view this service information at FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781–238–7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://>

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued in Burlington, Massachusetts, on September 7, 2018.

Robert J. Ganley,

Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2018–20551 Filed 9–20–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF COMMERCE

National Oceanic and Atmospheric Administration

15 CFR Part 902

50 CFR Parts 300 and 679

[Docket No. 161222999–8773–02]

RIN 0648–BG57

Fisheries of the Exclusive Economic Zone Off Alaska; Authorize Recreational Quota Entity To Participate in the Halibut IFQ Program

AGENCY: National Marine Fisheries Service (NMFS), National Oceanic and Atmospheric Administration (NOAA), Commerce.

ACTION: Final rule.

SUMMARY: NMFS issues regulations that authorize formation of a recreational quota entity (RQE) that could participate in the Pacific Halibut and Sablefish Individual Fishing Quota Program in International Pacific Halibut Commission Regulatory Areas 2C and 3A in the Gulf of Alaska. The RQE is authorized to purchase and hold a limited amount of commercial halibut quota share that will yield additional pounds of recreational fishing quota on an annual basis to augment the amount of halibut available for harvest in the charter halibut fishery. The RQE will provide a mechanism for a compensated reallocation of a portion of commercial halibut quota share to the charter halibut fishery. This final rule is necessary to promote social and economic flexibility in the charter halibut fishery, and is intended to promote the goals and objectives of the Northern Pacific Halibut Act of 1982, and other applicable laws.

DATES: This rule is effective on October 22, 2018.

ADDRESSES: Electronic copies of the Regulatory Impact/Initial Regulatory Flexibility Analysis/Environmental Assessment (collectively, Analysis) prepared for this action are available from <http://www.regulations.gov> or from the NMFS Alaska Region website at <http://alaskafisheries.noaa.gov>.

Written comments regarding the burden-hour estimates or other aspects of the collection-of-information requirements contained in this final rule may be submitted to NMFS, Alaska Region, P.O. Box 21668, Juneau, AK 99082–1668, Attn: Ellen Sebastian, Records Officer, in person at NMFS, Alaska Region, 709 West 9th Street, Room 420A, Juneau, AK; by email to OIRA_Submission@omb.eop.gov; or by fax to 202–395–5806.

FOR FURTHER INFORMATION CONTACT: Kurt Iverson, 907–586–7228.

SUPPLEMENTARY INFORMATION: This final rule implements regulatory amendments to authorize an RQE to participate in the Pacific Halibut and Sablefish Individual Fishing Quota Program (IFQ Program) in International Pacific Halibut Commission (IPHC) Regulatory Areas 2C and 3A in the Gulf of Alaska. NMFS published the proposed rule to authorize an RQE on October 3, 2017 (82 FR 46016). The comment period on the proposed rule ended on November 17, 2017. NMFS received 18 comment letters on the proposed rule. One of the comment letters was outside the scope of this action. Of the remaining 17 comment letters, NMFS identified and considered 19 unique, relevant comments. A summary of the comments and NMFS' responses is provided in the Comments and Responses section of this preamble.

A detailed review of this rule and the rationale for these regulations is provided in the preamble to the proposed rule (82 FR 46016, October 3, 2017). Electronic copies of the proposed rule and the Analysis may be obtained from www.regulations.gov or from the NMFS Alaska Region website at <http://alaskafisheries.noaa.gov>. All public comment letters submitted during the comment period may be obtained from www.regulations.gov.

Background

Authority for Action

The IPHC and NMFS manage fishing for Pacific halibut (*Hippoglossus stenolepis*) through regulations established under authority of the Northern Pacific Halibut Act of 1982 (Halibut Act). The IPHC adopts regulations governing the Pacific halibut (halibut) fishery under the Convention between the United States and Canada for the Preservation of the Halibut Fishery of the North Pacific Ocean and Bering Sea (Convention), signed at Ottawa, Ontario, on March 2, 1953, as amended by a Protocol Amending the Convention (signed at Washington, DC, on March 29, 1979). For the United States, regulations developed by the