repairing the cracking using a method approved in accordance with the procedures specified in paragraph (p) of this AD.

## No Reporting Requirement

(m) Although Boeing Service Bulletin and ASB 747–53A2465 specify that operators should report inspection results to the manufacturer, this AD does not require those inspection results to be reported.

## New Requirements of This AD

### Terminating Action

(n) For Group 1 and 3 airplanes identified in Boeing Service Bulletin 747–53A2562, Revision 1, dated July 28, 2005: Before accumulating 22,000 total flight cycles or within 48 months after the effective date of this AD, whichever occurs later, replace the NWW side and top panels with new panels in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747– 53A2562, Revision 1, dated July 28, 2005. Doing the replacement terminates the requirements of this AD.

(o) For Group 2 airplanes identified in Boeing Service Bulletin 747–53A2562, Revision 1, dated July 28, 2005, and Model 747 airplanes not identified in the service bulletin: Before accumulating 22,000 total flight cycles or within 57 months after the effective date of this AD, whichever occurs later, replace the NWW side and top panels using a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Doing the replacement terminates the requirements of this AD.

# Alternative Methods of Compliance (AMOCs)

(p)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

(4) AMOCs approved previously according to AD 2005–09–02 are approved as AMOCs for the corresponding provisions of paragraphs (f) through (j) and (l) of this AD.

(5) AMOCs approved previously according to AD 2004–25–23 are approved as AMOCs for the corresponding provisions of paragraph (f) of this AD.

# Material Incorporated by Reference

(q) You must use Boeing Alert Service Bulletin 747–53A2465, Revision 4, dated February 24, 2005; and Boeing Service Bulletin 747–53A2562, Revision 1, dated July 28, 2005; as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise. (1) The Director of the Federal Register approved the incorporation by reference of Boeing Service Bulletin 747–53A2562, Revision 1, dated July 28, 2005, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On May 10, 2005 (70 FR 21141, April 25, 2005), the Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 747–53A2465, Revision 4, dated February 24, 2005.

(3) Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, WA 98124–2207, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at *http://dms.dot.gov*; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741–6030, or go to *http:// www.archives.gov/federal\_register/ code\_of\_federal\_regulations/ ibr\_locations.html.* 

Issued in Renton, Washington, on October 25, 2006.

#### Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. E6–18465 Filed 11–3–06; 8:45 am] BILLING CODE 4910–13–P

## DEPARTMENT OF TRANSPORTATION

## **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2006-25501; Airspace Docket No. 06-ACE-9]

# Establishment of Class D Airspace; Ft. Riley, KS

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule.

**SUMMARY:** This notice amends Part 71 of the Federal Aviation Regulations (14 CFR part 71) by establishing a Class D airspace area extending upward from the surface to and including 3,600 feet above sea level within a 3.7-mile radius of Fort Riley, Marshall Army Airfield, KS. The establishment of an air traffic control tower has made this action necessary.

**DATES:** *Effective Date:* 0901 UTC, November 23, 2006.

# FOR FURTHER INFORMATION CONTACT:

Grant Nichols, System Support, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas, City, MO 64106; telephone: (816) 329–2522.

#### SUPPLEMENTARY INFORMATION:

# History

On Friday, August 11, 2006, the FAA proposed to amend Part 71 of the Federal Aviation Regulations (14 CFR part 71) to establish Class D airspace at Ft. Riley, KS (71 FR 46130). The proposal was to establish a Class D airspace area to provide controlled airspace for flight operations due to the establishment of an air traffic control tower. Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. A comment was received regarding the size of Class D airspace area. The size of the Class D airspace area is determined by FAA Order 7400.2F Procedures for Handling Airspace Matters, Chapter 17, Section 2. Class D Airspace Standards.

#### The Rule

This notice amends Part 71 of the Federal Aviation Regulations (14 CFR part 71) by establishing a Class D airspace area extending upward from the surface to and including 3,600 feet above sea level within a 3.7-mile radius of Fort Riley, Marshall Army Airfield, KS. The establishment of an air traffic control tower has made this action necessary. The intended effect of this action is to provide controlled airspace for flight operations at Fort Riley, Marshall Army Airfield, KS. The are will be depicted on appropriate aeronautical charts.

Class D airspace areas extending upward from the surface of the earth are published in Paragraph 5000 of FAA Order 7400.9P, Airspace Designations and Reporting Points, dated September 1, 2006, and effective September 16, 2006, which is incorporated by reference in 14 CFR 71.1. of the same Order. The Class D airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation-(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT **Regulatory Policies and Procedures (44** FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial

number of small entities under the criteria of the Regulatory Flexibility Act.

This rulemaking is promulgated under the authority described in subtitle VII, part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority since it contains flight operations at Fort Riley, Marshall Army Airfield, KS.

# List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

# Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTINES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

# §71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9P, dated September 1, 2006, and effective September 16, 2006, is amended as follows:

Paragraph 5000. Class D Airspace

## ACE KS D Fort Riley, KS

Fort Riley, Marshall Army Airfield, KS (Lat. 39°03′19″ N., long. 96°45′52″ W.) Junction City, Freeman Field, KS

(Lat. 39°02′36″ N., long. 96°50′36″ W.)

That airspace extending upward from the surface to and including 3,600 feet MSL within a 3.7-mile radius of the Marshall Army Airfield excluding that airspace within R-3602B and excluding that airspace within a 1-mile radius of Junction City, Freeman Field, KS. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

Issued in Forth Worth, Texas on October 17, 2006.

# Donald R. Smith,

Manager, System Support Group, ATO Central Service Area.

[FR Doc. 06–9073 Filed 11–3–06; 8:45 am] BILLING CODE 4910–13–M

# DEPARTMENT OF HOMELAND SECURITY

# **Coast Guard**

33 CFR Part 117

[CGD11-06-042]

# Drawbridge Operation Regulations; Cerritos Channel, Los Angeles, CA

**AGENCY:** Coast Guard, DHS. **ACTION:** Notice of temporary deviation from regulations.

**SUMMARY:** The Commander, Eleventh Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the Henry Ford Drawbridge across the Cerritos Channel, mile 4.8 at Los Angeles, CA. This deviation allows the bridge to remain in the closed-to-navigation position during the deviation period. The deviation is necessary for the bridge owner, the Port of Los Angeles, to perform critical repairs which involve modifications to allow for the inspection of the bridge's counterweight wire ropes.

**DATES:** This deviation is effective from 8 a.m. on November 6, 2006 to 4 p.m. on December 8, 2006.

**ADDRESSES:** Materials referred to in this document are available for inspection or copying at Commander (dpw), Eleventh Coast Guard District, Building 50–2, Coast Guard Island, Alameda, CA 94501–5100, between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays. The telephone number is (510) 437–3515. The Bridge Section office maintains the public docket for this temporary deviation.

FOR FURTHER INFORMATION CONTACT: David H. Sulouff, Chief, Bridge Section, Eleventh Coast Guard District, telephone (510) 437–3516.

SUPPLEMENTARY INFORMATION: On October 5, 2006, The Port of Los Angeles requested a temporary change to the operation of the Henry Ford Drawbridge, mile 4.8, Cerritos Channel, at Los Angeles, CA. The Henry Ford Drawbridge navigation span provides a vertical clearance of 7 feet above Mean High Water in the closed-to-navigation position. Presently, the drawspan is maintained in the fully open position, except when a train is crossing or for maintenance. When the drawspan is in the closed position, it opens on signal as required by 33 CFR 117.147(b). Navigation on the waterway is mainly commercial traffic, servicing ships entering and leaving the port. The Port of Los Angeles requested the drawbridge be allowed to remain closed to

navigation, Monday through Friday, from 8 a.m. on November 6, 2006 to 4 p.m. on December 8, 2006. During this time, critical repairs will be made which involves modifications to allow for the inspection of the bridge's counterweight wire ropes. This temporary deviation has been coordinated with waterway users. No objections to the proposed temporary rule were raised. While the bridge is in the closed-to-navigation position, vessels can transit around Terminal Island to reach the other side of the bridge.

In accordance with 33 CFR 117.35(c), this work will be performed with all due speed in order to return the bridge to normal operation as soon as possible. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: October 24, 2006.

# J.A. Breckenridge,

Rear Admiral, U.S. Coast Guard, Commander, Eleventh Coast Guard District.

[FR Doc. E6–18602 Filed 11–3–06; 8:45 am] BILLING CODE 4910–15–P

# ENVIRONMENTAL PROTECTION AGENCY

# 40 CFR Part 52

[EPA-R07-OAR-2006-0837; FRL-8239-3]

# Approval and Promulgation of Implementation Plans; State of Missouri

AGENCY: Environmental Protection Agency (EPA).

ACTION: Direct final rule.

**SUMMARY:** EPA is taking direct final action to approve a revision to the State Implementation Plan (SIP) revision submitted by the State of Missouri to add a test method for compliance testing to the rule that will reduce emissions of nitrogen oxides (NO<sub>X</sub>) of major sources in the St. Louis ozone nonattainment area.

**DATES:** This direct final rule will be effective January 5, 2007, without further notice, unless EPA receives adverse comment by December 6, 2006. If adverse comment is received, EPA will publish a timely withdrawal of the direct final rule in the **Federal Register** informing the public that the rule will not take effect.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA–R07–OAR–2006–0837, by one of the following methods:

1. *http://www.regulations.gov.* Follow the on-line instructions for submitting comments.