

its place the phrase “give our approval in writing”; and

■ iii. In paragraph (d) by removing the phrase “wet, in-shell” and adding in its place the phrase “wet in-shell”;

■ h. In section 7:

■ i. By removing the phrase “(Insurable Acreage)”; and

■ ii. By removing the comma after the phrase “Basic Provisions (§ 457.8)”;

■ i. In section 8:

■ i. By removing the phrase “(Insurance Period)” in paragraphs (a) introductory text and (b) introductory text; and

■ ii. By revising paragraph (a)(2);

■ j. Amend section 9 by removing the phrase “(Causes of Loss)” in paragraphs (a) introductory text and (b) introductory text;

■ k. Amend section 10 introductory text by removing the phrase “(Duties in the Event of Damage or Loss)”;

■ l. In section 11:

■ i. In paragraph (b)(4) by removing the phrase “if applicable, (see section 11(c))” and adding in its place the phrase “if applicable (see section 11(c)),”;

■ ii. Adding a settlement of claim example after paragraph (b)(7); and

■ iii. In paragraph (c) by removing the phrase “(wet, in-shell pounds)” and adding in its place the phrase “(we in-shell pounds)”.

The revisions and additions read as follows:

§ 457.131 Macadamia nut crop insurance provisions.

* * * * *

1. Definitions

* * * * *

*Floater*s. Inedible, husked “field run” nuts identified by water floatation.

* * * * *

Peewees. Mature and immature wet in-shell nuts that are smaller than 16 mm (5/8 inch) in diameter, or as otherwise specified in the Special Provisions.

* * * * *

Wet in-shell. The weight of the macadamia nuts as they are removed from the orchard with the nut meats in the shells after removal of the husk and excluding floaters and peewees but prior to being dried.

2. Unit Division

Provisions in the Basic Provisions that allow optional units by section, section equivalent, or FSA farm serial number and by irrigated and non-irrigated practices are not applicable. Optional units may be established only if each optional unit is located on non-contiguous land, unless otherwise allowed by written agreement.

3. Insurance Guarantees, Coverage Levels, and Prices for Determining Indemnities

* * * * *

(d) Instead of reporting your macadamia nut production for the previous crop year, as required by section 3 of the Basic Provisions, there is a one-year lag period. Each crop year you must report your production from two crop years ago, e.g., on the 2016 crop year production report, you will provide your 2014 crop year production.

* * * * *

8. Insurance Period

(a) * * *

(2) The calendar date for the end of the insurance period for each crop year is the second June 30th after insurance attaches, or as specified in the Special Provisions.

* * * * *

11. Settlement of Claim

* * * * *

(b) * * *

(7) * * *

For example:

You select 65 percent coverage level and 100 percent of the price election on 10 acres of macadamia nuts in the unit. Your share is 100 percent. Your production guarantee (per acre) is 4,000 pounds. The price election is \$0.78. You are able to harvest 25,000 pounds. Your indemnity would be calculated as follows:

(1) 10 acres × 4,000 pounds = 40,000 pounds guarantee;

(2) 40,000 pounds × \$0.78 price election = \$31,200 total value of guarantee;

(4) 25,000 pounds production to count × \$0.78 price election = \$19,500 value of production to count;

(6) \$31,200 total value of guarantee – \$19,500 value of production to count = \$11,700 loss; and

(7) \$11,700 loss × 100 percent share = \$11,700 indemnity payment.

* * * * *

Signed in Washington, DC, on July 23, 2014.

Brandon Willis,

Manager, Federal Crop Insurance Corporation.

[FR Doc. 2014–17997 Filed 7–31–14; 8:45 am]

BILLING CODE 3410–08–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2014–0516; Directorate Identifier 2014–CE–021–AD]

RIN 2120–AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Pacific Aerospace Limited Model 750XL airplanes that would supersede AD 2014–04–03. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as broken control column attachment bolts failing in service. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by September 15, 2014.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493–2251.
- Mail: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Pacific Aerospace Limited, Hamilton Airport, Private Bag 3027 Hamilton 3240, New Zealand; telephone: +64 7 843 6144; fax: +64 7 843 6134; email: pacific@aerospace.co.nz; Internet: <http://www.aerospace.co.nz/>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the

availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0516; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4123; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0516; Directorate Identifier 2014-CE-021-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On February 10, 2014, we issued AD 2014-04-03, Amendment 39-17761 (79 FR 10344, February 25, 2014). That AD required actions intended to address an unsafe condition on all Pacific Aerospace Limited Model 750XL airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 2014-04-03, Amendment 39-17761 (79 FR 10344, February 25, 2014), Pacific Aerospace Limited revised the related service information.

The Civil Aviation Authority (CAA), which is the airworthiness authority for New Zealand, has issued AD DCA/750XL/15A, dated June 26, 2014 (referred to after this as "the MCAI"), to correct an unsafe condition for Pacific Aerospace Limited Model 750XL airplanes. The MCAI states:

DCA/750XL/15A revised to mandate the embodiment of modification PAC/XL/0627 to the control column attachment per the instructions in Pacific Aerospace Limited Service Bulletin (SB) PACSB/XL/070 issue 2, dated 3 June 2014.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0516.

Relevant Service Information

Pacific Aerospace Limited has issued Service Bulletin PACSB/XL/070, Issue 2, dated June 3, 2014. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 17 products of U.S. registry. We also estimate that it would take about 6 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$200 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$12,070, or \$710 per product.

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

The cost difference between AD 2014-04-03, Amendment 39-17761 (79 FR 10344, February 25, 2014), and this

proposed AD is the increase in work-hours from 1.5 to 6 and the increase in cost for parts from \$100 to \$200, for an overall cost difference on U.S. operators to be \$8,202.50, or \$482.50 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Amend § 39.13 by removing Amendment 39–17761 (79 FR 10344, February 25, 2014), and adding the following new AD:

Pacific Aerospace Limited: Docket No. FAA–2014–0516; Directorate Identifier 2014–CE–021–AD.

(a) Comments Due Date

We must receive comments by September 15, 2014.

(b) Affected ADs

This AD supersedes AD 2014–04–03, Amendment 39–17761 (79 FR 10344, February 25, 2014).

(c) Applicability

This AD applies to Pacific Aerospace Limited Model 750XL airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 27: Flight Controls.

(e) Reason

This AD was prompted from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as control column attachment bolts failing in service. We are issuing this AD to prevent failure of the control column attachment bolt, which could result in control column detachment and cause loss of control.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) and (f)(2) of this AD:

(1) As of February 24, 2014 (the effective date of AD 2014–04–03, Amendment 39–17761 (79 FR 10344, February 25, 2014)), if the left hand and the right hand control column attachment bolts have been replaced following the ACCOMPLISHMENT INSTRUCTIONS in Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/070, Issue 1, dated January 24, 2014, then within the next 150 hours time-in-service (TIS) after the effective date of this AD, replace the left hand and the right hand control column attachment bolts following the ACCOMPLISHMENT INSTRUCTIONS in Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/070, Issue 2, dated June 3, 2014.

(2) As of February 24, 2014 (the effective date of AD 2014–04–03, Amendment 39–17761 (79 FR 10344, February 25, 2014)), if the left hand and the right hand control column attachment bolts have not been replaced following the ACCOMPLISHMENT INSTRUCTIONS in Pacific Aerospace

Limited Mandatory Service Bulletin PACSB/XL/070, Issue 1, dated January 24, 2014, then within the next 10 hours TIS after the effective date of this AD, replace the left hand and the right hand control column attachment bolts following the ACCOMPLISHMENT INSTRUCTIONS in Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/070, Issue 2, dated June 3, 2014.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):*

(i) The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4123; fax: (816) 329–4090; email: karl.schletzbaum@faa.gov.

(ii) AMOCs approved for AD 2014–04–03, Amendment 39–17761 (79 FR 10344, February 25, 2014) are not approved as AMOCs for this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI Civil Aviation Authority (CAA) AD DCA/750XL/15A, dated June 26, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–0516. For service information related to this AD, contact Pacific Aerospace Limited, Hamilton Airport, Private Bag 3027 Hamilton 3240, New Zealand; telephone: +64 7 843 6144; fax: +64 7 843 6134; email: pacific@aerospace.co.nz; Internet: <http://www.aerospace.co.nz/>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on July 28, 2014.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014–18144 Filed 7–31–14; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[Docket No. USCG–2014–0367]

RIN 1625–AA09

Drawbridge Operation Regulation; Darby Creek, Essington, PA

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to change the operating regulation that governs the Conrail railroad bridge over Darby Creek in Essington, PA. The bridge owner, Conrail, is modifying the existing remote operating system which controls the bridge operations. Cameras will be installed and the remote operating site will move from its current location in Delair, NJ to Mt. Laurel, NJ. Train crews will no longer be required to stop and check the waterway for approaching vessel traffic prior to initiating a bridge closure, and mariners requesting an opening for the bridge will have to contact the new remote location.

DATES: Comments and related material must be received by the Coast Guard on or before September 15, 2014.

ADDRESSES: You may submit comments identified by docket number USCG–2014–0367 using any one of the following methods:

(1) *Federal eRulemaking Portal:* <http://www.regulations.gov>.

(2) *Fax:* 202–493–2251.

(3) *Mail or Delivery:* Docket Management Facility (M–30), U.S. Department of Transportation, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590–0001. Deliveries accepted between 9 a.m. and 5 p.m., Monday through Friday, except federal holidays. The telephone number is 202–366–9329.

See the “Public Participation and Request for Comments” portion of the **SUPPLEMENTARY INFORMATION** section below for instructions on submitting comments. To avoid duplication, please use only one of these methods.

FOR FURTHER INFORMATION CONTACT: If you have questions on this proposed rule, call or email Mrs. Jessica Shea, Fifth Coast Guard District Bridge Administration Division, Coast Guard; telephone 757–398–6422, email jessica.c.shea2@uscg.mil. If you have questions on viewing the docket, call Cheryl Collins, Program Manager,