

rate of \$60 per work hour. Based on these figures, the cost impact of the proposed inspection on U.S. operators is estimated to be \$21,120, or \$480 per airplane.

It would take approximately 8 work hours per airplane to accomplish the proposed replacement of earth posts, at an average labor rate of \$60 per work hour. Required parts would be provided by the manufacturer at no charge. Based on these figures, the cost impact of the proposed replacement on U.S. operators is estimated to be \$21,120, or \$480 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Jetstream Aircraft Limited: Docket 96-NM-97-AD.

Applicability: Model 4101 airplanes having constructor number 41004 through 41074 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent overheating of the electrical ground posts ("earth posts") for the direct current (DC) power generation and de-icing systems of the left and right engines, which could result in such things as failure of these systems, accomplish the following:

(a) Within 300 hours time-in-service after the effective date of this AD, accomplish the actions specified in paragraphs (a)(1) and (a)(2) of this AD on both the left and right engines:

(1) Inspect each earth post and earth post bracket to detect damage caused by arcing, signs that it has been overheated, and lateral movement of the earth post, in accordance with Part A of Jetstream Service Bulletin J41-24-033, Revision 2, dated January 24, 1996. If any discrepancy is detected, prior to further flight, accomplish both paragraphs (a)(1)(i) and (a)(1)(ii) of this AD:

(i) Repair any damage and lateral movement in accordance with a method approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate; and

(ii) Replace the earth post with a new earth post in accordance with Part B of the service bulletin.

(2) Inspect each ground cable (earth cable) for the DC power generation and propeller de-icing systems to detect damage caused by arcing, and signs that the terminal tags and cable insulation have been overheated, in accordance with Part A of the service bulletin. If any discrepancy is detected, prior to further flight, replace the earth cable with a new or serviceable cable, in accordance with Part A of the service bulletin.

(b) Within 6 months after the effective date of this AD, replace each earth post with a

new earth post, in accordance with Part B of Jetstream Service Bulletin J41-24-033, Revision 2, dated January 24, 1996. Any earth post that is replaced in accordance with paragraph (a)(1)(ii) of this AD need not be replaced again under the requirements of this paragraph.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 13, 1996.

James V. Devany, Acting Manager,
Transport Airplane Directorate, Aircraft
Certification Service.

[FR Doc. 96-29606 Filed 11-19-96; 8:45 am]
BILLING CODE 4910-13-P

14 CFR Part 71

[Airspace Docket No. 95-AWP-26]

Proposed Establishment of Class D Airspace; Victorville, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document proposes to establish the Class D airspace area at Victorville, CA. The extension of Southern California International Airport Air Traffic Control Tower operating hours has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Southern California International Airport, Victorville, CA.

DATES: Comments must be received on or before November 30, 1996.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, Operations Branch, AWP-530, Docket No. 95-AWP-26, Air Traffic Division, P.O. Box 92007, Worldway Postal Center, Los Angeles, California 90009.

The official docket may be examined in the Office of the Assistant Chief

Counsel, Western Pacific Region, Federal Aviation Administration, Room 6007, 15000 Aviation Boulevard, Lawndale, California 90261.

An informal docket may also be examined during normal business at the Office of the Manager, Operations Branch, Air Traffic Division at the above address.

FOR FURTHER INFORMATION CONTACT: William Buck, Airspace Specialist, Operations Branch, AWP-530, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California 90261, telephone (310) 725-6556.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with the comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Airspace Docket No. 95-AWP-26." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the Operations Branch, Air Traffic Division, at 15000 Aviation Boulevard, Lawndale, California 90261, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Operations Branch, P.O. Box 92007, Worldway

Postal Center, Los Angeles, California 90009. Communications must identify the notice number of this NPRM.

Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedures.

The Proposal

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR part 71) to establish the Class D airspace area at Victorville, CA. The extension of Southern California International Airport Air Traffic Control Tower operating hours has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for IFR operations at Southern California International Airport, Victorville, CA. Class D airspace designations are published in Paragraph 5000 of FAA Order 7400.9D dated September 4, 1996, and effective September 16, 1996, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document would be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 10034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—[AMENDED]

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., 389; 14 CFR 11.69.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9D, Airspace Designations and Reporting Points, dated September 4, 1996, and effective September 16, 1996, is amended as follows:

Paragraph 5000 Class D Airspace

* * * * *

AWP CA D Victorville, CA [New]

Victorville, Southern California International Airport, CA

(Lat. 34°35.67' N, long. 117°22.93' W)

That airspace extending upward from the surface to 5,400 feet MSL within a 6-mile radius of the Victorville, Southern California International Airport, CA. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in Los Angeles, California, on November 4, 1996.

Sabra W. Kaulia,

Assistant Manager, Air Traffic Division, Western-Pacific Region.

[FR Doc. 96-29684 Filed 11-19-96; 8:45 am]

BILLING CODE 4910-13-M

14 CFR Part 71

[Airspace Docket No. 96-AWP-8]

Proposed Establishment of Class E Airspace; Hemet, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document proposes to establish Class E airspace area at Hemet, CA. The development of a Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 05 has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Hemet-Ryan Airport, Hemet, CA.

DATES: Comments must be received on or before December 16, 1996.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, Operations Branch, AWP-530, Docket No. 96-AWP-8, Air Traffic Division, P.O. Box 92007, Worldway Postal Center, Los Angeles, California 90009.