

64106; telephone: (816) 426-6932; facsimile: (816) 426-2169.

**SUPPLEMENTARY INFORMATION:** The FAA published this direct final rule with request for comments in the **Federal Register** on December 31, 1998 (63 FR 72139). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA anticipates that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, was received within the comment period, the regulation would become effective on March 19, 1999. No adverse comments were received, and thus this notice confirms that this final rule will become effective on that date.

Issued in Kansas City, Missouri, on February 22, 1999.

**Marvin R. Nuss,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-4890 Filed 2-26-99; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98-CE-99-AD; Amendment 39-10973; AD 99-01-06]

RIN 2120-AA64

#### Airworthiness Directives; British Aerospace Jetstream Model 3101 Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Direct final rule; confirmation of effective date.

**SUMMARY:** This action confirms the effective date of Airworthiness Directive (AD) 99-01-06, which applies to certain British Aerospace Jetstream Model 3101 airplanes. AD 99-01-06 requires installing a standard bonding socket that is fitted flush with the upper surface of each wing at the fueling points (Station 297). This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified in this AD are intended to correct a potentially insufficient ground contact between the refueler hose nozzle and the aircraft, which, if not corrected before the fuel cap is removed, could result in sparks

with a consequent fire and/or explosion in the fuel tank.

**EFFECTIVE DATE:** March 19, 1999.

**FOR FURTHER INFORMATION CONTACT:** Mr. S.M. Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6932; facsimile: (816) 426-2169.

**SUPPLEMENTARY INFORMATION:** The FAA published this direct final rule with request for comments in the **Federal Register** on December 31, 1998 (63 FR 72141). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA anticipates that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, was received within the comment period, the regulation would become effective on March 19, 1999. No adverse comments were received, and thus this notice confirms that this final rule will become effective on that date.

Issued in Kansas City, Missouri, on February 22, 1999.

**Marvin R. Nuss,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-4889 Filed 2-26-99; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 29475; Amdt. No. 1918]

#### Standard Instrument Approach Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

**ADDRESSES:** Availability of matter incorporated by reference in the amendment is as follows:

#### For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

#### For Purchase—

Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

#### By Subscription—

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, US Government Printing Office, Washington DC 20402.

**FOR FURTHER INFORMATION CONTACT:** Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd, Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 14 CFR part 51, and § 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

#### The Rule

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained in the content of the following FDC/P NOTAM for each SIAP. The SIAP information in some previously designated FDC/Temporary (FDC/T) NOTAMs is of such duration as to be permanent. With conversion to FDC/P NOTAMs, the respective FDC/T NOTAMs have been canceled.

The FDC/P NOTAMs for the SIAPs contained in this amendment are based

on the criteria contained in the U.S. Standard for Terminal Instrument Approach Procedures (TERPS). In developing these chart changes to SIAPs by FDC/P NOTAMs, the TERPS criteria were applied to only these specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a National flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Further, the SIAPs contained in this amendment are based on the criteria contained in the TERPS. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

#### Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive order 12866; (2) is not a “significant rule” under DOT

Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Navigation (Air).

Issued in Washington, DC on February 19, 1999.

**L. Nicholas Lacey,**

*Director, Flight standards Service.*

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, part 97 of the Federal Aviation Regulations (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

#### PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

1. The authority citation for part 97 is revised to read as follows:

**Authority:** 49 U.S.C. 40103, 40113, 40120, 44701; 49 U.S.C. 106(g); and 14 CFR 11.49(b)(2).

2. Part 97 is amended to read as follows:

#### §§ 97.23, 97.25, 97.27, 97.29, 97.31, 97.33, 97.35 [Amended]

By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, ISMLS, MLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAVA SIAPs; and § 97.35 COPTER SIAPs, identified as follows:

\* \* \* Effective Upon Publication

FDC date	State	City	Airport	FDC No.	SIAP
02/04/99/ .....	CA	Van Nuys .....	Van Nuys .....	FDC 9/0759	ILS Rwy 16R Amdt 5.
02/04/99/ .....	CA	Van Nuys .....	Van Nuys .....	FDC 9/0761	VOR or GPS—A Amdt 3.
02/04/99/ .....	CA	Van Nuys .....	Van Nuys .....	FDC 9/0764	VOR/DME or GPS—B Amdt 2.
02/05/99/ .....	AK	Kake .....	Kake .....	FDC 9/0774	NDB/DME Rwy 10, Orig
02/05/99/ .....	AK	Kake .....	Kake .....	FDC 9/0775	GPS Rwy 10, Orig
02/08/99/ .....	PA	Washington .....	Washington County .....	FDC 9/0816	NDB or GPS Rwy 27 Orig-A
02/08/99/ .....	PA	Washington .....	Washington County .....	FDC 9/0817	VOR or GPS—B Amdt 6A
02/08/99/ .....	PA	Washington .....	Washington County .....	FDC 9/0818	LOC Rwy 27 Amdt 1
02/09/99/ .....	FL	Vero Beach .....	Vero Beach Muni .....	FDC 9/0830	VOR/DME or GPS Rwy 29L, Amdt 2B
02/09/99/ .....	FL	Vero Beach .....	Vero Beach Muni .....	FDC 9/0831	VOR or GPS Rwy 11R, Amdt 12A
02/09/99/ .....	IA	Waterloo .....	Waterloo Muni .....	FDC 9/0826	ILS Rwy 12, Amdt 8
02/10/99/ .....	PA	Bradford .....	Bradford Regional .....	FDC 9/0840	ILS Rwy 32 Amdt 10
02/12/99/ .....	IN	Indianapolis .....	Indianapolis Downtown-Heliport .....	FDC 9/0865	COPTER VOR/DME 287, Amdt 1
02/12/99/ .....	MA	Hyannis .....	Barstable Muni-Boardman/Polando Field.	FDC 9/0859	ILS Rwy 15 Amdt 2B
02/12/99/ .....	MA	Hyannis .....	Barstable Muni-Boardman/Polando Field.	FDC 9/0860	VOR or GPS Rwy 6 Amdt 7A
02/12/99/ .....	MA	Hyannis .....	Barstable Muni-Boardman/Polando Field.	FDC 9/0861	NDB or GPS Rwy 24 Amdt 9B

FDC date	State	City	Airport	FDC No.	SIAP
02/12/99/ .....	MA	Hyannis .....	Barstable Muni-Boardman/Polando Field.	FDC 9/0862	ILS Rwy 24 Amdt 16D
02/12/99/ .....	NE	Hartington .....	Hartington Muni .....	FDC 9/0875	VOR/DME Rwy 31, Orig
02/12/99/ .....	OK	Ardmore .....	Ardmore Downtown Executive .....	FDC 9/0879	VOR/DME RNAV Rwy 35, Amdt 5
02/16/99/ .....	OK	Grove .....	Grove Muni .....	FDC 9/0918	GPS Rwy 18, Orig
02/16/99/ .....	TX	Austin .....	Austin-Bergstrom Intl .....	FDC 9/0911	ILS Rwy 35L, Amdt 1

[FR Doc. 99-4997 Filed 2-26-99; 8:45 am]

BILLING CODE 4910-13-M

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 29474; Amdt. No. 1917]

#### Standard Instrument Approach Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference—approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

#### For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

#### For Purchase—

Individually SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

#### By Subscription—

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

**FOR FURTHER INFORMATION CONTACT:** Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd, Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260-3, 8260-4, and 8260-5. Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials.

Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

#### The Rule

The amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (NFDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Approach Procedures (TERPS). In developing these SIAPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making some SIAPs effective in less than 30 days.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT