

VI. Public Participation

A. Submission of Comments

DOE will accept comments, data, and information regarding this notice of proposed determination no later than the date provided at the beginning of this notice. After the close of the comment period, DOE will review the comments received and determine whether set-top boxes and network equipment is a covered product under EPCA.

Comments, data, and information submitted to DOE's e-mail address for this proposed determination should be provided in WordPerfect, Microsoft Word, PDF, or text (ASCII) file format. Submissions should avoid the use of special characters or any form of encryption, and wherever possible comments should include the electronic signature of the author. No telefacsimiles (faxes) will be accepted.

According to 10 CFR 1004.11, any person submitting information that he or she believes to be confidential and exempt by law from public disclosure should submit two copies: One copy of the document should have all the information believed to be confidential deleted. DOE will make its own determination as to the confidential status of the information and treat it according to its determination.

Factors of interest to DOE when evaluating requests to treat submitted information as confidential include (1) a description of the items; (2) whether and why such items are customarily treated as confidential within the industry; (3) whether the information is generally known or available from public sources; (4) whether the information has previously been made available to others without obligations concerning its confidentiality; (5) an explanation of the competitive injury to the submitting persons which would result from public disclosure; (6) a date after which such information might no longer be considered confidential; and (7) why disclosure of the information would be contrary to the public interest.

B. Issues on Which DOE Seeks Comments

DOE welcomes comments on all aspects of this proposed determination. DOE is particularly interested in receiving comments from interested parties on the following issues related to the proposed determination for set-top boxes and network equipment:

- Definition(s) of set-top boxes and network equipment;
- Whether classifying set-top boxes and network equipment as a covered

product is necessary or appropriate to carry out the purposes of EPCA;

- Calculations and values for household and national energy consumption; and
- Availability or lack of availability of technologies for improving energy efficiency of set-top boxes and network equipment.

The Department is interested in receiving views concerning other relevant issues that participants believe would affect DOE's ability to establish test procedures and energy conservation standards for set-top boxes and network equipment. The Department invites all interested parties to submit in writing by July 15, 2011, comments and information on matters addressed in this notice and on other matters relevant to consideration of a determination for set-top boxes and network equipment.

After the expiration of the period for submitting written statements, the Department will consider all comments and additional information that is obtained from interested parties or through further analyses, and it will prepare a final determination. If DOE determines that set-top boxes and network equipment qualify as a covered product, DOE will consider a test procedure and energy conservation standards for set-top boxes and network equipment. Members of the public will be given an opportunity to submit written and oral comments on any proposed test procedure and standards.

List of Subjects in 10 CFR Part 430

Administrative practice and procedure, Confidential business information, Energy conservation, Reporting and recordkeeping requirements.

Issued in Washington, DC, on June 8, 2011.

Henry Kelly,

Acting Assistant Secretary, Energy Efficiency and Renewable Energy.

[FR Doc. 2011-14825 Filed 6-14-11; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-0567; Directorate Identifier 2010-NM-272-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Model 767 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD would require modification of the fluid drain path in the leading edge area of the wing. This proposed AD was prompted by a design review following a ground fire incident and reports of flammable fluid leaks from the wing leading edge area onto the engine exhaust area. We are proposing this AD to prevent flammable fluid from leaking onto the engine exhaust nozzle which could result in a fire.

DATES: We must receive comments on this proposed AD by August 1, 2011.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, *Attention:* Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; *phone:* 206-544-5000, extension 1; *fax:* 206-766-5680; *e-mail:* me.boecom@boeing.com; *Internet:* <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (*phone:* 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tung Tran, Aerospace Engineer,

Propulsion Branch, ANM-140S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; phone: 425-917-6505; fax: 425-917-6590; e-mail: Tung.Tran@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-0567; Directorate Identifier 2010-NM-272-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of fuel leaking from the wing leading edge area

at the inboard end of the number 5 leading edge slot of a Model 737 airplane. The leak was discovered during a post-flight inspection with a fuel quantity of over 2,500 pounds. Subsequent investigation found that the leak occurred in an area of the front spar that does not have a proper drain path. This led to the fuel draining onto the engine exhaust nozzle. The leak appears to have been caused by a loose retaining nut of the slot track down stop. We are proposing this AD to prevent flammable fluid from leaking onto the engine exhaust nozzle which could result in a fire.

A Model 767 design review revealed that some of the design features in the Model 737 wing leading edge area also exist in Model 767 airplanes. Additional design reviews have led to similar findings in Model 757 and Model 747 airplanes. We have issued AD 2010-23-13, Amendment 39-16502 (75 FR 68688, November 9, 2009), for Model 757 airplanes, and are considering rulemaking for Model 737 and Model 747 airplanes.

Relevant Service Information

We reviewed Boeing Special Attention Service Bulletin 767-57-0121, dated October 7, 2010. This service information describes procedures for modifying the fluid drain

path in the leading edge area of the wing. The modification consists of changing the leading edge of the lower wing skin panels and the seal doors at outboard slot station (OSS) 424.097, and the wing ribs at OSS 464.475, through repairs and new parts installation. Additionally, the service information specifies applying sealant, hole filling compound, and leveling compound to the wing leading edge; and applying sealant to the wing ribs.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 361 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Leading edge fluid drainage modification	22 work-hours × \$85 per hour = \$1,870	\$651	\$2,521	\$910,081

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. *Subtitle VII: Aviation Programs*, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations

for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2011–0567; Directorate Identifier 2010–NM–272–AD.

Comments Due Date

(a) We must receive comments by August 1, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to The Boeing Company Model 767–200, –300, –300F, and –400ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 767–57–0121, dated October 7, 2010.

Subject

(d) Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 57, Wings.

Unsafe Condition

(e) This AD was prompted by a design review following a ground fire incident and reports of flammable fluid leaks from the wing leading edge area onto the engine exhaust area. We are issuing this AD to prevent flammable fluid from leaking onto the engine exhaust nozzle, which could result in a fire.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Drain Path Modification

(g) Within 60 months after the effective date of this AD, modify the fluid drain path in the leading edge area of the wing, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767–57–0121, dated October 7, 2010.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be e-mailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector,

or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

Related Information

(i) For more information about this AD, contact Tung Tran, Aerospace Engineer, Propulsion Branch, ANM–140S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; *phone:* 425–917–6505; *fax:* 425–917–6590; *e-mail:* Tung.Tran@faa.gov.

(j) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, Washington 98124–2207; *phone:* 206–544–5000, extension 1; *fax:* 206–766–5680; *e-mail:* me.boecom@boeing.com; *Internet:* <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on June 7, 2011.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 2011–14698 Filed 6–14–11; 8:45 am]

BILLING CODE 4910–13–P

SECURITIES AND EXCHANGE COMMISSION

17 CFR Parts 230, 240 and 260

[Release Nos. 33–9222; 34–64639; 39–2474;
File No. S7–22–11]

RIN 3235–AL16

Exemptions for Security-Based Swaps Issued by Certain Clearing Agencies

AGENCY: Securities and Exchange Commission.

ACTION: Proposed rules.

SUMMARY: We are proposing exemptions under the Securities Act of 1933, the Securities Exchange Act of 1934, and the Trust Indenture Act of 1939 for security-based swaps issued by certain clearing agencies satisfying certain conditions. The proposed rules would exempt transactions by clearing agencies in these security-based swaps from all provisions of the Securities Act, other than the Section 17(a) anti-fraud provisions, as well as exempt these security-based swaps from Exchange Act registration requirements and from the provisions of the Trust Indenture Act, provided certain conditions are met.

DATES: Comments on the proposed rules should be received on or before July 25, 2011.

ADDRESSES: Comments may be submitted by any of the following methods:

Electronic Comments

- Use the Commission's Internet comment form (<http://www.sec.gov/rules/proposed.shtml>);
- Send an e-mail to rule-comments@sec.gov. Please include File Number S7–22–11 on the subject line; or
- Use the Federal Rulemaking Portal (<http://www.regulations.gov>). Follow the instructions for submitting comments.

Paper Comments

- Send paper comments in triplicate to Elizabeth M. Murphy, Secretary, Securities and Exchange Commission, 100 F Street, NE., Washington, DC 20549–1090.

All submissions should refer to File Number S7–22–11. This file number should be included on the subject line if e-mail is used. To help us process and review your comments more efficiently, please use only one method. We will post all comments on the Commission's Internet Web site (<http://www.sec.gov/rules/proposed.shtml>). Comments are also available for public inspection and copying in the Commission's Public Reference Room, 100 F Street, NE., Washington, DC 20549, on official business days between the hours of 10 a.m. and 3 p.m. All comments received will be posted without change; we do not edit personal identifying information from submissions. You should submit only information that you wish to make available publicly.

FOR FURTHER INFORMATION CONTACT:

Tamara Brightwell, Senior Special Counsel to the Director, Michael J. Reedich, Special Counsel, Office of Chief Counsel, or Andrew Schoeffler, Special Counsel, Office of Capital Market Trends, Division of Corporation Finance, at (202) 551–3500, U.S. Securities and Exchange Commission, 100 F Street, NE., Washington, DC 20549–4561.

SUPPLEMENTARY INFORMATION: We are proposing new Rule 239 under the Securities Act of 1933 (“Securities Act”).¹ We are also proposing new Rule 12a–10 and an amendment to Rule 12h–1 under the Securities Exchange Act of 1934 (“Exchange Act”) ² and Rule 4d–11 under the Trust Indenture Act of 1939 (“Trust Indenture Act”).³

¹ 15 U.S.C. 77a et seq.

² 15 U.S.C. 78a et seq.

³ 15 U.S.C. 77aaa et seq.