

## Costs of Compliance

We estimate that this AD will affect about 232 engines installed on aircraft of U.S. registry. We also estimate that it will take about 24 hours per engine to comply with this AD. The average labor rate is \$85 per hour. Required parts will cost about \$9,268 per engine. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$2,623,456.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2014-08-05 Rolls-Royce Deutschland Ltd & Co KG (Type Certificate previously held by Rolls-Royce Deutschland GmbH and BMW Rolls-Royce GmbH):** Amendment 39-17829; Docket No. FAA-2013-0884; Directorate Identifier 2013-NE-31-AD.

### (a) Effective Date

This AD becomes effective May 23, 2014.

### (b) Affected ADs

None.

### (c) Applicability

This AD applies to all Rolls-Royce Deutschland Ltd & Co KG (RRD) BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines.

### (d) Reason

This AD was prompted by a report of a partial de-bonding of the low-pressure compressor (LPC) case ice impact panels during an engine shop visit. We are issuing this AD to prevent failure of the LPC case ice impact panels, which could result in damage to the engine and loss of control of the airplane.

### (e) Actions and Compliance

Unless already done, after the effective date of this AD, at the next engine shop visit or within 12,500 engine flight cycles since the last shop visit, whichever occurs first, replace the four LPC ice impact panels with panels eligible for installation.

### (f) Definitions

(1) For the purposes of this AD, an "engine shop visit" is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges. The separation of engine flanges solely for the purpose of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(2) For the purposes of this AD, a panel that is "eligible for installation" is a new LPC impact panel or one that has been repaired using RRD Alert Non-Modification Service Bulletin (NMSB) No. ALERT SB-BR700-72-A900281, dated July 1, 2013.

## (g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use the procedures found in 14 CFR 39.19 to make your request.

## (h) Related Information

(1) For more information about this AD, contact Rose Len, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: [rose.len@faa.gov](mailto:rose.len@faa.gov).

(2) Refer to MCAI European Aviation Safety Agency AD 2013-0231, dated September 24, 2013, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/>!

*#!documentDetail;D=FAA-2013-0884-0002.*

(3) RRD Alert NMSB No. ALERT SB-BR700-72-A900281, dated July 1, 2013, which is not incorporated by reference in this AD, can be obtained from RRD using the contact information in paragraph (h)(4) of this AD.

(4) For service information identified in this AD, contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, Dahlewitz, 15827 Blankenfelde-Mahlow, Germany; phone: 49 33-7086-1944; fax: 49 33-7086-3276.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

## (i) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on April 8, 2014.

**Ann C. Mollica,**

*Acting Assistant Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2014-08733 Filed 4-17-14; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 71

[Docket No. FAA-2013-0588; Airspace Docket No. 13-ASW-12]

### Amendment of Class E Airspace; Paragould, AR

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends Class E airspace at Paragould, AR. Decommissioning of the Paragould non-directional radio beacon (NDB) at Kirk Field Airport has made reconfiguration necessary for standard instrument approach procedures and for the safety

and management of Instrument Flight Rule (IFR) operations at the airport. Geographic coordinates are also updated.

**DATES:** *Effective date:* 0901 UTC, July 24, 2014. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone 817–321–7716.

#### SUPPLEMENTARY INFORMATION:

##### History

On January 8, 2014, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to amend Class E airspace for the Paragould, AR, area, modifying controlled airspace at Kirk Field Airport (79 FR 1344) Docket No. FAA–2013–0588. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9X dated August 7, 2013, and effective September 15, 2013, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

##### The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by amending Class E airspace extending upward from 700 feet above the surface for standard instrument approach procedures at Kirk Field Airport, Paragould, AR. Airspace reconfiguration is necessary due to the decommissioning of the Paragould NDB and the cancellation of the NDB approach. The segment northeast of the airport is now within 2.5 miles each side of the 062° bearing from the airport. Controlled airspace is necessary for the safety and management of IFR operations at the airport. Geographic coordinates are also adjusted to coincide with the FAA's aeronautical database.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a “significant regulatory action”

under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends controlled airspace at Kirk Field, Paragould, AR.

##### Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1E, “Environmental Impacts: Policies and Procedures,” paragraph 311a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

##### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

##### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

#### **PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### **§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9X, Airspace Designations and Reporting Points, dated August 7, 2013, and effective September 15, 2013, is amended as follows:

*Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface.*

\* \* \* \* \*

#### **ASW AR E5 Paragould, AR [Amended]**

Paragould, Kirk Field, AR  
(Lat. 36°03'50" N., long. 90°30'33" W.)

That airspace extending upward from 700 feet above the surface within a 6.4-mile radius of Kirk Field, and within 2.5 miles each side of the 218° bearing from the airport extending from the 6.4-mile radius to 9.5 miles southwest of the airport, and within 2.5 miles each side of the 062° bearing from the airport extending from the 6.4-mile radius to 7.5 miles northeast of the airport.

Issued in Fort Worth, Texas, on April 2, 2014.

**Kent M. Wheeler,**

*Manager, Operations Support Group, ATO Central Service Center.*

[FR Doc. 2014–08771 Filed 4–17–14; 8:45 am]

**BILLING CODE 4910–13–P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 71**

[Docket No. FAA–2013–0587; Airspace Docket No. 13–ACE–8]

#### **Amendment of Class E Airspace; Jefferson City, MO**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends Class E airspace at Jefferson City, MO. Decommissioning of the Noah non-directional radio beacon (NDB) at Jefferson City Memorial Airport has made reconfiguration necessary for standard instrument approach procedures and for the safety and management of Instrument Flight Rule (IFR) operations at the airport.

**DATES:** *Effective date:* 0901 UTC, July 24, 2014. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** Scott Enander, Central Service Center, Operations Support Group, Federal