#### **Federal Communications Commission**

apparatus having a homing capability in accordance with § 80.824.

[51 FR 31213, Sept. 2, 1986, as amended at 63 FR 29960, June 1, 1998. Redesignated at 68 FR 46973, Aug. 7, 2003]

### §80.289 Requirements for radio direction finder.

- (a) The radio direction finding apparatus must:
- (1) Be capable of receiving signals A1A, A2B and R2B emission, on each frequency within the band 285-515 kHz assigned by the Radio Regulations for distress and direction finding and for maritime radio beacons, and be calibrated to take bearings on such signals from which the true bearing and direction may be determined; and
- (2) Possess a sensitivity, sufficient to permit the taking of bearings on a signal having a field strength of 50 microvolts per meter.
- (b) The calibration of the direction finder must be verified by check bearings or by a further calibration whenever any changes are made in the physical or electrical characteristics or the position of any antennas, and whenever any changes are made in the position of any deck structures which might affect the accuracy of the direction finder. In addition, the calibration must be verified by check bearings at yearly intervals. A record of the calibrations, and of the check bearings made of their accuracy and the accuracy of the check bearings must be kept on board the ship for a period of not less than 1 year.

[51 FR 31213, Sept. 2, 1986, as amended at 63 FR 29660, June 1, 1998. Redesignated at 68 FR 46973, Aug. 7, 2003]

### §80.290 Auxiliary receiving antenna.

An auxiliary receiving antenna must be provided when necessary to avoid unauthorized interruption or reduced efficiency of the required watch because the normal receiving antenna is not available because a radio direction finder on board the vessel is operated.

 $[51\ FR\ 31213,\ Sept.\ 2,\ 1986.\ Redesignated\ at\ 68\ FR\ 46973,\ Aug.\ 7,\ 2003]$ 

#### § 80.291 Installation of direction finder.

- (a) The direction finder must be located to minimize interference from noise.
- (b) The direction finder antenna system must be erected so that the determination of bearings will not be hindered by the proximity of other antennas, cranes, wire halyards, or large metal objects.

## §80.292 Contingent acceptance of direction finder calibration.

When the required calibration can not be made before departure from a harbor or port for a voyage in the open sea, the direction finder may be tentatively approved on condition that the master certifies in writing that the direction finder will be calibrated by a competent technician.

 $[63\ FR\ 29660,\ June\ 1,\ 1998.\ Redesignated\ at\ 68\ FR\ 46973,\ Aug.\ 7,\ 2003]$ 

# §80.293 Check bearings by authorized ship personnel.

The requirement for calibration by check bearings is met if:

- (a) The required verification by check bearings are made not more than 90 days prior to the date of the annual detailed inspection of the radiotelegraph station;
- (b) The verification consists of a comparison of simultaneous visual and radio direction finder bearings. At least one comparison bearing must be taken in each quadrant, within plus or minus 20 degrees from the following bearings relative to the ship's heading: 45 degrees; 135 degrees; 225 degrees; 315 degrees;
- (c) The verification shows the visual bearing relative to the ship's heading and the difference between the visual and radio direction finder bearing, and the date each check bearing is taken.

 $[51\ FR\ 31213,\ Sept.\ 2,\ 1986.\ Redesignated\ at\ 68\ FR\ 46973,\ Aug.\ 7,\ 2003]$