

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****Proposed Advisory Circular 25.1435-1,  
Hydraulic System Certification Tests  
and Analysis**

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Notice of availability of  
proposed advisory circular (AC)  
25.1435-1 and request for comments;  
correction.

**SUMMARY:** This document contains a  
correction to the Notice of availability of  
proposed advisory circular AC 25.1435-  
1 and request for comments, published  
in the Federal Register on July 3, 1996

(61 FR 35062). In the "Discussion"  
section of that notice, the FAA  
inadvertently left out the Notice No. of  
the Notice of proposed rulemaking  
(NPRM) to which the proposed AC  
relates. This action corrects that  
omission.

**FOR FURTHER INFORMATION CONTACT:**  
Jan Thor, Regulations Branch, ANM-  
114, Transport Airplane Directorate,  
Aircraft Certification Service, 1601 Lind  
Ave. SW, Renton, Washington 98055-  
4056, telephone: 206-227-2127.

**SUPPLEMENTARY INFORMATION:****Correction of Publication**

In the notice document (FR Doc. 96-  
17035) published in the Federal

Register on July 3, 1996 (61 FR 35062),  
make the following correction: On page  
35062, column 3, third paragraph, insert  
the number "6" in place of "[insert  
notice number of NPRM entitled,  
"Revision of Hydraulic Systems  
Airworthiness Standards to Harmonize  
with European Airworthiness Standards  
for Transport Category Airplanes"]".

Issued in Renton, Washington, on July 23,  
1996.

Stewart R. Miller,

*Acting Manager, Transport Airplane  
Directorate, Aircraft Certification Service,  
ANM-100*

[FR Doc. 96-20387 Filed 8-9-96; 8:45 am]

**BILLING CODE 4910-13-M**